

QUOTATION FOR VEHICLE SHF 1583 B

PARTS				
1	1	REAR BUMPER <i>broken</i>	\$	996.72 ✓
2	1	REAR BUMPER CENTRE GRILLE <i>broken</i>	\$	199.63 ✓
3	2	REAR BUMPER SENSOR <i>Dem</i>	\$	210.62 ✓
4	2	REAR BUMPER SENSOR BRACKET <i>Nec</i>	\$	36.80 ✓
5	1	REAR BUMPER REINFORCEMENT <i>Discontinued</i>	\$	605.22 ✓
6	2	REAR BUMPER REINFORCEMENT BRACKET(RH/LH) <i>N/S Kt o/s</i>	\$	360.00 360.00 ✓
7	1	REAR BUMPER SIDE REFLECTOR (RH)(RED) <i>broken</i>	\$	43.20 ✓
8	1	REAR BUMPER SIDE REFLECTOR CHROME (RH) <i>NH</i>	\$	16.20 X
9	1	REAR END PANEL <i>regr</i>	\$	1,151.95 X
		SUB TOTAL	\$	3,620.34
		LESS 10%	\$	362.03
		DISCOUNTED SUB TOTAL	\$	3,258.31
S/NETT				
1	1	REAR BUMPER ADVERTISEMENT LOGO <i>Nec</i>	\$	100.00 ✓
		SUB TOTAL	\$	100.00
LABOUR				
1		PANEL BEATING	\$	700.00 <i>300/-</i> 400/-
2		SPRAYPAINTING CHARGES	\$	500.00 <i>200/-</i> 400/-
3		WIRING CHARGES	\$	40.00 <i>NH</i>
4		TUFF KOTE	\$	100.00 <i>NH</i>
5		REMOVE/REFIX REAR BUMPER SENSOR	\$	80.00 <i>40/-</i>
		SUB TOTAL	\$	1,420.00
		GRAND TOTAL	\$	<u>4,778.31</u>

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE. THEREFORE SHOULD THERE BE ANY ADDITIONAL PARTS REQUIRE OR DISCOVER DAMAGE DURING OUR COURSE OF REPAIRS. WE WOULD INFORM YOU ACCORDINGLY FOR THE NECESSARY ACTIONS. PRICES OF PARTS QUOTED ARE SUBJECT TO CHANGE WITHOUT NOTICE.

SOON HOCK MOTOR PTE LTD
 Blk 10 Ang Mo Kio Industrial Park 2
 #01-05/06 AMK Autopoint
 Singapore 568047
 6483 6016 (3 Lines) Fax: 6483 6011
 Reg. No. 199804869H

09/05/2019 @ 1000hrs
 Alit Antun
 2/5mm 3 days.

Ryan
 LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: