

AC: PVE BY

REF CS/FCI/9008210/^E7d3⁷²

Spec of Incident Form

SA/Ven/01

ASSIGNMENT (Office)

CWS

Sitharan

of

FCI

Date/Time: 5:05pm @ 9/3/19

Estimated Cost

Bill to:

OD ④ WS/TP RES / OD RES / EVA / INV / MY/CS

To Inspect Vehicle No

SMF 49774

Insured

SHC 7151R

at Workshop no/

Hua Hong

Tel

66619688

of

25D Sungai Kadut Street 1

Policy No

Claim No

D1900 2997MFSH

Sum Insured

Excess

Make of Vch
(Client's Record)

D.O.A. 07/05/2019

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement

Date/Time: 10:18am @ 9/3/19

Person Contacted

Yvonne

Vehicle IN/OUT ④

Date/Time	Action/Instruction (✓) Estimate
	SMF 49774-X
	SHC 7151R-CC3 / AIG 12014199 / Hlg 2y
30/5 @ 4:02pm	Revised protli advise via email.
	lump sum 1850+ cred: 1855.44; 50%) confirm with Ashley.

JVA: 18/7/2012

28/11/19

Surveyor Alex Lee

REF: FCI

ASSIGNMENT

From:

Date: 28.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMF 4977 U

at Workshop m/s Hua Hong

of 25D Sungei Kadu Street 1

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh: 11.00 a.m Owner Waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

rup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMF 4977 U

Yr Regn: 14 Nov 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

c.c 1492

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading:

31899

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6BN22A8K0251421

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 7/5/19

D.O.I. 28/5/19

Survey held at

Hua Hong

Des. of Damages: Frt / Rear / O/S N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

☒

Final Report

1) 30/8 Typist

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

130

50

50

22

252

Report Format:

TP

Lump Sum / I.B.I. (\$))



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002997MFSH

Date: 30/5/2019

Our Ref: CS/FCI19008210/Jtd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMF 4977U

Please be informed that we had conducted the inspection of the abovementioned vehicle 28/05/2019 at the premises of M/s Hua Hong have the following to report: -

Workshop Estimate Amount	: S\$	<u>3,705.44</u>
Revised Estimate Amount	: S\$	<u>2,319.60</u>
"Check" Items Amount	: S\$	<u>0.00</u>
Market Value	: S\$	<u> </u>
LTA Reimbursement Value	: S\$	<u> </u>
Nett Value	: S\$	<u> </u>

Description of Damage:

The vehicle sustained damages at the
o/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Hwee Jie

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	07-05-2019	Our Ref No. D19002997MFSH
Accident Date	07-05-2019	Claim Type. Third Party
Insured Vehicle	SHC7151R	Third Party Vehicle. SMF4977U
Survey Location	25D SUNGEI KADUT STREET 1	
Contact Person.	JERLEEN TANG	
Contact No.	66619688/ 0	Fax No. 66619699
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUA HONG PRIVATE LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Ashley Tan <ashley@huahong.com.sg>
Sent: Friday, 30 August 2019 1:39 PM
To: Denise Tay (LKKAUTO)
Subject: RE: Finalisation for Vehicle No. SMF4977U

Dear Denise

Confirmed LS\$1850/-, 5 days.

Will submit LOD to First Cap.

Thanks & Regards

Ashley Tan



HUA HONG PRIVATE LIMITED
25D SUNGEI KADUT STREET 1 SINGAPORE 729332
T. 6661 9690 | M. 9816 4151 | F. 6661 9699
Follow us @ huahong.com.sg
   

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Friday, 30 August 2019 10:12 AM
To: Ashley Tan <ashley@huahong.com.sg>
Subject: RE: Finalisation for Vehicle No. SMF4977U

Dear Ashley,

Offer at Lump sum \$1850, 5days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ashley Tan <ashley@huahong.com.sg>
Sent: Friday, 30 August 2019 9:50 AM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Subject: FW: Finalisation for Vehicle No. SMF4977U

Dear Denise

As forwarded.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 30 May 2019 4:02 PM
To: Admin-D (LKKAuto); 'Jerleen Tang'; assignments; SUR
Cc: yvonne@huahong.com.sg
Subject: RE: SURVEYOR APPOINTED; OUR REF : D19002997MFSH ; YOUR REF: SMF4977U
Attachments: PRELI ADVISED SMF 4977U.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SMF 4977U**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 24 May 2019 4:13 PM
To: 'Jerleen Tang' <jerleen@huahong.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: yvonne@huahong.com.sg
Subject: RE: SURVEYOR APPOINTED; OUR REF : D19002997MFSH ; YOUR REF: SMF4977U

Dear Jerleen,

Appointment confirmed.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Friday, 24 May, 2019 4:11 PM
To: 'Jerleen Tang' <jerleen@huahong.com.sg>; 'assignments' <assignments@lkkauto.com>; 'SUR' <sur@lkkauto.com>
Cc: 'yvonne@huahong.com.sg' <yvonne@huahong.com.sg>
Subject: RE: SURVEYOR APPOINTED; OUR REF : D19002997MFSH ; YOUR REF: SMF4977U

Dear Sir / Mdm,

Thank you for the assignment.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0309M
Vehicle Details	
Vehicle No.:	SMF4977U
Vehicle to be Exported:	No
Intended Deregistration Date:	29 May 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	P520550830
Chassis No.:	JM6BN22A8K0251421
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,466.00
Original Registration Date:	14 Nov 2018
First Registration Date:	14 Nov 2018
Transfer Count:	1
Actual ARF Paid:	\$14,466.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Nov 2028
PARF Rebate Amount:	\$10,849.00
Intended COE Rebate Details	
COE Expiry Date:	13 Nov 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$28,199.00
COE Rebate Amount:	\$26,671.00
Total Rebate Amount:	\$37,520.00

The information contained herein is correct as at 29 May 2019

OK



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

08 May 2019

QUOT201905-000021
HHTPCLAIMS19-72

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON RD, #16-01
CITY HOUSE
SINGAPORE 068877

Attn: Motor Claims Department

ACCIDENT INVOLVING SMF4977U & SHC7151R ON 07/05/2019 ALONG BUKIT PANJANG RING ROAD AT ABOUT 0015 HOURS

Insured : HUA HONG PTE LTD
Vehicle Registration No. : SMF4977U
Vehicle Make : MAZDA
Vehicle Model : MAZDA3 SEDAN 1.5 AT EU6
Vehicle Chassis No. : JM6BN22A8K0251421
Policy No. : 5087272209-03
Date of Accident : 07/05/2019

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Front Door (RH) Repair X		\$ 1,200.00
2	1	Front Door Tape (RH) n x		\$ 68.00
3	1	Rear Door (RH) DD ✓		\$ 1,049.00
4	1	Rear Door Tape (RH) n x ✓		\$ 138.00
5	1	Rear Door Weather Strip (RH) n x		\$ 126.80
				\$ 2,581.80
Less 20%				\$ 516.36
				\$ 2,065.44

To dismantle & change front RH door, rear RH door, knocking & pull straight rear RH fender, RH side rocker panel and all area affected by accident

\$ 600.00 ✓

To perform wire checking

\$ 20.00 ✓

To dismantle & transfer front RH door, rear RH door mechanism and fitting to new door

\$ 120.00 SD

To spray front RH door, rear RH door, rear RH fender, RH side rocker panel and rear bumper

\$ 900.00 700

\$ 3,705.44

7% GST \$ 259.38

Total \$ 3,964.82



Signature

Authorised by Claims Dept

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Co. Reg. No. 200900309M | huahong.com.sg | GST Reg. No. 200900309M

Hwee Jia - LKK
28/5/19
P/P 5 days
Signature



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19008210/Etd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 04-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7151R	Veh. Inspected	SMF 4977U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002997MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	09/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JM6BN22A8K0251421	Colour	BLACK	
Odometer	31899	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/05/2019	Inspection Date	28/05/2019	
Survey held at	HUA HONG PTE LTD 25D SUNGEI KADUT STREET 1 SINGAPORE 729332			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 4977U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR (RH)	TO REPAIR SEE LABOUR	1,200.00	-
1	FRONT DOOR TAPE (RH)	NOT NECESSARY	68.00	-
1	REAR DOOR (RH)	DENTED	1,049.00	1,049.00
1	REAR DOOR TAPE (RH)	NECESSARY	138.00	138.00
1	REAR DOOR WEATHER STRIP (RH)	NOT NECESSARY	126.80	-
	LESS 20% DISCOUNT		-516.36	-237.40
			2,065.44	949.60
	LABOUR			
	TO DISMANTLE & CHANGE FRONT RH DOOR, REAR RH DOOR, KNOCKING & PULL STRAIGHT REAR RH FENDER, RH SIDE ROCKER PANEL AND ALL AREA AFFECTED BY ACCIDENT.		600.00	600.00
	TO PERFORM WIRE CHECKING.		20.00	20.00
	TO DISMANTLE & TRANSFER FRONT RH DOOR, REAR RH DOOR MECHANISM AND FITTING TO NEW DOOR.		120.00	50.00
	TO SPRAY FRONT RH DOOR, REAR RH DOOR, REAR RH FENDER, RH SIDE ROCKER PANEL AND REAR BUMPER.		900.00	700.00
			1,640.00	1,370.00
	GRAND TOTAL		3,705.44	2,319.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,850.00

Report Ref No. CS/FCI19008210/Etd3n2

CHEN TSUE YEE
Automotive Assessor

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.