

PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762

Tel : 6271 4618 Fax : 6273 2632

ESTIMATE REPAIR

BIKE NO.: FE 6565A

DATE ACCIDENT : 06.05.2019

MAKE / MODEL : YAMAHA/RXZ

S/No	DESCRIPTION	AMOUNT
1	HEADLIGHT	\$ <i>CH</i> 165.00
2	HEADLIGHT COVER	\$ <i>ms</i> 85.00
3	HEADLIGHT STAY	\$ <i>bt</i> 110.00
4	METER ASSY	\$ <i>CH</i> 585.00
5	HANDLE BAR	\$ <i>bt</i> 98.00
6	HANDLE BAR CLAMP	\$? 215.00
7	UNDER BRACKET	\$? 265.00
8	STEERING CON	\$? 110.00
9	FORK INNER TUBE x2	\$? 350.00
10	FORK OIL SEAL	\$? 60.00
11	SIGNAL LIGHT x2	\$ <i>CH</i> 120.00
12	TAIL LIGHT ASSY	\$ <i>CH</i> 230.00
13	EXHAUST PIPE	\$ <i>dg</i> 480.00
14	FRONT WHEEL RIM	\$? 385.00
15	FRONT BRAKE DISK	\$? 185.00
16	SIDE COVER x2	\$ <i>CH</i> 180.00
17	TAIL COVER	\$ <i>CH</i> 98.00
18	FUEL TANK	\$ <i>dg</i> 520.00
19	REAR BOX	\$ <i>dg</i> 285.00
20	BOX BRACKET	\$ <i>bt</i> 180.00
21	PRESS BODY	\$ <i>150</i> 280.00
22	IU UNIT	\$ <i>CH</i> 165.00
	TRANSPORT	\$ ✓ 60.00
	LABOUR	\$ <i>250</i> 350.00
	<i>Tanpin 9749549</i> <i>12/5/19 R 1645</i> <i>Resurvey after repair</i> <i>5 days</i> <i>shop (hh auto)</i>	
	Total	\$ 5,561.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: