

# EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

AIG

Owner : Leong Mun Wai

Accident Date : 4-May-19

Vehicle No : JSE 2369

Vehicle Model : Yamaha LC135

## Estimated Repair Costs

| Qty | Description                | Amount S(\$) |
|-----|----------------------------|--------------|
|     | <u>List Items</u>          |              |
| 1   | Front cowl inner bracket   | \$ 55.00     |
| 2   | Front fork tube assy       | \$ 640.00    |
| 1   | Front wheel rim            | \$ 280.00    |
| 1   | Fork under bracket         | \$ 185.00    |
| 1   | Front rim shaft            | \$ 45.00     |
| 1   | Front rim bearing          | \$ 38.00     |
| 1   | Front brake disc           | \$ 155.00    |
| 1   | Handle-bar                 | \$ 88.00     |
| 2   | Handle-bar ends            | \$ 64.00     |
| 1   | Hand grip (1 set)          | \$ 55.00     |
| 1   | Handle-bar inner bracket   | \$ 68.00     |
| 2   | Side mirrors               | \$ 110.00    |
| 2   | Front signals              | \$ 140.00    |
| 1   | Front signal lower garnish | \$ 95.00     |
| 1   | Headlamp                   | \$ 185.00    |
| 1   | Meter assy                 | \$ 385.00    |
| 1   | Fairing assy (1 set)       | \$ 495.00    |
| 1   | Engine cover -L/H          | \$ 145.00    |
| 1   | Front footrest bracket     | \$ 65.00     |
| 1   | Front footrest rubber -L/H | \$ 35.00     |
| 1   | Gear pedal                 | \$ 42.00     |
| 1   | Socket cover               | \$ 95.00     |
| 1   | Rear footrest -L/H         | \$ 40.00     |
| 1   | Rear footrest bracket -L/H | \$ 78.00     |
| 1   | Horn                       | \$ 48.00     |
| 1   | Rear signal -L/H           | \$ 68.00     |
| 1   | Side stand                 | \$ 75.00     |
| 1   | Main stand                 | \$ 95.00     |
| 1   | Rear taillamp              | \$ 135.00    |
| 1   | Basket                     | \$ 50.00     |
|     |                            | \$ 4,054.00  |
|     | Less 10%                   | \$ 405.40    |
|     |                            | \$ 3,648.60  |

c/f: \$ 3,648.60

**Special Nett Items**

|   |                         |    |     |          |     |
|---|-------------------------|----|-----|----------|-----|
| 1 | Number plate ( 1 set )  | \$ | net | 28.00    | 20  |
| 2 | Fork oils               | \$ | 11  | 30.00    | x   |
| 2 | Fork oil seals          | \$ | 11  | 56.00    | x   |
| 1 | Steering cone ( 1 set ) | \$ | 11  | 90.00    | x   |
| 1 | Engine oil              | \$ | net | 25.00    | ✓   |
| 1 | Engine cover gasket     | \$ | net | 28.00    | ✓   |
| 1 | Rear box                | \$ | cut | 250.00   | 180 |
| 1 | Rear box bracket        | \$ | 34  | 100.00   | ✓   |
| 1 | Front tyre              | \$ | 11  | 120.00   | x   |
| 1 | Helmet                  | \$ | one | 120.00   | 60  |
| 1 | ERP IU                  | \$ | 310 | 175.00   | ✓   |
| 1 | Sticker ( 1 set )       | \$ | net | 95.00    | ✓   |
|   |                         | \$ |     | 1,117.00 |     |

**S/No.      Labour**

|   |                                             |    |     |        |   |
|---|---------------------------------------------|----|-----|--------|---|
| 1 | To provide towing service.                  | \$ | 35  | 50.00  |   |
| 2 | To check wiring and reset headlamp focusing | \$ | 11  | 80.00  | x |
| 3 | To provide labour.                          | \$ | 300 | 380.00 |   |
| 4 | To repair body frame.                       | \$ | 300 | 350.00 |   |
|   |                                             | \$ |     | 860.00 |   |

**Grand Total**      **\$ 5,625.60**

  
EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: