

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 May 2019 Edit Reg		08 May 2019 00:00 Edit Adj Rpt	S\$1,850.00 Edit Estimates	S\$1,850.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD., Co. Reg. No.: 199803778Z								
Main Claimant:	ANG CHING SENG, ID: S6907833H								
Vehicle Reg. No.:	SMF6643U	Date of Loss:	02/05/2019 16:00 - :59 [5 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3240625929SG	Policy/Cover Note No.:	0999994164 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBJ1611D	Policy No. (Claimant):	CN021359						
		Excess:							
Repairer:	Cas Garage Pte Ltd (HQ) No.1, Kaki Bukit Ave 6, #02-22 Autobay, 417883 Kaki Bukit - Tel: 9090 1222								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Goh, Jeremy-CX] Jeremy.Goh@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMF6643U (3240625929SG)**
[GBJ1611D]

TP

ANG CHING SENG

May 2 2019 4:00PM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]

Cas Garage Pte Ltd

Upload Documents
Upload Photos
Compose New Letter
Upload Video
Upload Audio

View View in Browser ▼

Letters/Correspondences

1 per page ▼ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit	

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	31/03/20 16:33	General View	1	Load JPG	☒
2	31/03/20 16:33	General View	1	Load JPG	☒
3	31/03/20 16:33	General View	1	Load JPG	☒
4	31/03/20 16:33	General View	1	Load JPG	☒
5	31/03/20 16:33	General View	1	Load JPG	☒
6	31/03/20 16:33	General View	1	Load JPG	☒
7	31/03/20 16:33	General View	1	Load JPG	☒
8	31/03/20 16:33	General View	1	Load JPG	☒
9	31/03/20 16:33	General View	1	Load JPG	☒
10	31/03/20 16:33	General View	1	Load JPG	☒
11	31/03/20 16:33	General View	1	Load JPG	☒
12	31/03/20 16:33	General View	1	Load JPG	☒
13	31/03/20 16:33	General View	1	Load JPG	☒
14	31/03/20 16:33	General View	1	Load JPG	☒
15	31/03/20 16:33	General View	1	Load JPG	☒
16	31/03/20 16:33	General View	1	Load JPG	☒
17	31/03/20 16:33	General View	1	Load JPG	☒
18	31/03/20 16:33	General View	1	Load JPG	☒
19	31/03/20 16:33	General View	1	Load JPG	☒
20	31/03/20 16:33	General View	1	Load JPG	☒
21	31/03/20 16:33	General View	1	Load JPG	☒
22	31/03/20 16:33	General View	1	Load JPG	☒
23	31/03/20 16:33	General View	1	Load JPG	☒
24	31/03/20 16:33	General View	1	Load JPG	☒
25	31/03/20 16:33	General View	1	Load JPG	☒
26	31/03/20 16:33	General View	1	Load JPG	☒
27	31/03/20 16:33	General View	1	Load JPG	☒
28	31/03/20 16:33	Chassis Number	1	Load JPG	☒
29	31/03/20 16:33	Odometer Reading	1	Load JPG	☒
30	31/03/20 16:33	Dismantled Parts	1	Load JPG	☒
31	31/03/20 16:33	Dismantled Parts	1	Load JPG	☒
32	31/03/20 16:33	Dismantled Parts	1	Load JPG	☒
33	31/03/20 16:33	Dismantled Parts	1	Load JPG	☒
34	31/03/20 16:33	Dismantled Parts	1	Load JPG	☒
35	31/03/20 16:33	Dismantled Parts	1	Load JPG	☒
36	31/03/20 16:33	Dismantled Parts	1	Load JPG	☒
37	31/03/20 16:33	Dismantled Parts	1	Load JPG	☒

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
38	31/03/20 16:33	Dismantled Parts		Load JPG ☒
39	31/03/20 16:33	Dismantled Parts		Load JPG ☒
40	31/03/20 16:33	Dismantled Parts		Load JPG ☒
41	31/03/20 16:33	Dismantled Parts		Load JPG ☒
42	31/03/20 16:33	Dismantled Parts		Load JPG ☒
43	31/03/20 16:33	Dismantled Parts		Load JPG ☒
44	31/03/20 16:33	Dismantled Parts		Load JPG ☒
45	31/03/20 16:33	Dismantled Parts		Load JPG ☒
46	31/03/20 16:34	Dismantled Parts		Load JPG ☒
47	31/03/20 16:34	Dismantled Parts		Load JPG ☒
48	31/03/20 16:34	Dismantled Parts		Load JPG ☒
49	31/03/20 16:34	Dismantled Parts		Load JPG ☒
50	31/03/20 16:34	Dismantled Parts		Load JPG ☒
51	31/03/20 16:34	Dismantled Parts		Load JPG ☒
52	31/03/20 16:34	Dismantled Parts		Load JPG ☒
53	31/03/20 16:34	Dismantled Parts		Load JPG ☒
54	31/03/20 16:34	Dismantled Parts		Load JPG ☒
55	31/03/20 16:34	Dismantled Parts		Load JPG ☒
56	31/03/20 16:34	Dismantled Parts		Load JPG ☒
57	31/03/20 16:34	After Repair Photo		Load JPG ☒
58	31/03/20 16:34	After Repair Photo		Load JPG ☒
59	31/03/20 16:34	After Repair Photo		Load JPG ☒
60	31/03/20 16:34	After Repair Photo		Load JPG ☒
61	31/03/20 16:34	After Repair Photo		Load JPG ☒
62	31/03/20 16:34	After Repair Photo		Load JPG ☒

Documentation			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	09/05/19 16:12	EMAIL FROM AIG DD 08052019		Load PDF ☐
2	09/05/19 16:12	TP GIA REPORT		Load PDF ☐
3	10/05/19 15:46	TP ESTIMATE- MARKED		Load PDF ☐
4	15/04/20 09:37	LETTER TO OI		Load PDF ☐
5	28/04/20 17:03	Authorisation to Act		Load PDF ☐
6	28/04/20 17:03	LOD		Load PDF ☐
7	28/04/20 17:03	LTA SEARCH		Load PDF ☐
8	28/04/20 17:03	Release Voucher		Load PDF ☐
9	28/04/20 17:03	RENTAL RECEIPT		Load PDF ☐
10	28/04/20 17:03	WORKSHOP INVOICE		Load PDF ☐
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	10/05/19 11:15	OI GIA report		Load PDF ☐

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBJ1611D (Insd veh)	Model:	HYUNDAI ELANTRA 1.6 (A)
	SMF6643U (TP veh)		
Date of Accident:	02/05/2019		

Global Sum Settlement	:	[]	Yes	[X]	No	
Repair Estimate	:	\$				8,214.08
Final Repair Cost	:	\$				1,850.00
Loss of Use	:	\$				days at \$0.00 per day
Rental (if any)	:	\$				535.00 5 days
LTA / GIA Search Fee	:	\$				7.45
Others:	:	\$				
	:	\$				
Final Settlement Sum	:	\$				2,392.45

Is Third Party Workshop GIA Registered?				[]	YES	[X]	NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:				Agreed Liability _____ 100 _____ (%)				
B) For GIA Registered Workshop:				BOLA Applicable: Yes/ No BOLA Scenario No: _____				
BOLA Liability: _____ (%)				Assessed Liability (*): _____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.								
Remarks _____								

Payment Instruction: Payee's Breakdown			
1)	Cas Garage Pte Ltd	: \$	1,850.00
2)	Cas Garage Pte Ltd	: \$	535.00
3)	Cas Garage Pte Ltd	: \$	7.45
4)	Cas Garage Pte Ltd	: \$	0.00

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

28 Apr
2020

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19008214/GEA3S2**Date:** 28/04/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994164
Claimant Vehicle No :	SMF6643U	Insured Vehicle No :	GBJ1611D
Date of Loss:	02/05/2019	Nature of Claim:	TP
		Claim No:	3240625929SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF6643U	Engine No:	G4FGHU118046
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)	Chassis No:	KMHD841CMJU767825
Reg. Date:	21/11/2018 (Man. Year: 2018)	Odometer:	16100 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 8 mm	Rear Left Side:	Nexen 8 mm
Front Right Side:	Nexen 8 mm	Rear Right Side:	Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,764.08	1,839.28	3,924.80	68.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	470.00	1,980.00	80.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,214.08	2,309.28	5,904.80	71.89
Approved Total (Overridden) (S\$)		1,850.00		
Nett Amount (S\$)	8,214.08	1,850.00	6,364.08	77.48
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,392.45		

INSPECTION

Date of Assignment:	08/05/2019	
Date Inspected:	08/05/2019	Inspected At: Cas Garage Pte Ltd (HQ) No.1, Kaki Bukit Ave 6, #02-22 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	1,620.40 FL	*- FL
2	1		*BOOTLID SMART KEY ANTENNA	Not Necessary	206.50 FL	*- FL
3	1		*BOOTLID INNER TRIM	Not Necessary	326.20 FL	*- FL
4	1		*BOOTLID REFLECTORS	N/s Scratched/O/s NotNecessary	759.60 FL	*330.00 FL
5	1		*BOOTLID EMBLEM ELANTRA	Not Necessary	90.30 FL	*- FL
6	1		*BOOTLID EMBLEM S	Not Necessary	55.60 FL	*- FL
7	1		*BOOTLID LOGO	Not Necessary	60.50 FL	*- FL
8	1		*BOOTLID TOP LOCK	Not Necessary	223.60 FL	*- FL
9	1		*BOOTLID LOWER CATCH	Not Necessary	35.80 FL	*- FL
10	1		*BOOTLID WEATHERSTRIP	Not Necessary	212.90 FL	*- FL
11	1		*REAR BUMPER	Cracked	628.20 FL	*459.00 FL
12	2		*REAR BUMPER BOTTOM COVERS	Not Necessary	521.40 FL	*- FL
13	1		*REAR BUMPER REFLECTORS	N/s Scratched/O/s NotNecessary	166.80 FL	*47.10 FL
14	2		*REAR BUMPER RETAINERS	Not Necessary	126.60 FL	*- FL
15	1		*REAR BUMPER BOTTOM	Broken	360.80 FL	*360.80 FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	378.10 FL	*378.10 FL
17	2		*REAR BUMPER REINFORCEMENT BRACKET	Bent 1pc Only	117.20 FL	*58.60 FL
18	1		*TAILLAMPS	N/S Scratched/O/s NotNecessary	864.60 FL	*378.00 FL
19	1		*SET REAR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
20	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
21	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	30.00 FS	*- FS
22	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,115.10	2,241.60
- List Item Discount on L Items 20.00/20.00% (\$)	1,351.02	402.32
Total Parts (\$)	5,764.08	1,839.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGN ALL PARTS.	New	1,000.00	200.00
2	TO RESPRAY AFFECTED AREAS.	New	800.00	200.00
3	TO TUFF COAT AFFECTED AREA.	New	200.00	0.00
4	TO REMOVE / REPLACE REVERSE SENSORS AND DISTANCE SETTLING.	New	150.00	40.00
5	WIRING CHECK. TO REMOVE AND ADJUST TAILLAMPS.	New	150.00	30.00
6	TO REMOVE AND REPLACE BOOTLID MECHANISM.	New	150.00	0.00
Gross Labour Cost (\$\$)			2,450.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >