



Pte Ltd

TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
Register number : 201015366H
REPAIR PERFORMA INVOICE

AIG Asia Pacific Insurance Pte. Ltd
78 Shenton Way
#08-16
Singapore(079120)

Vehicle number	SLX5953Z
Make / Model	TOYOTA HARRIER
Chassis number	ZSU600077354
Accident date	28/4/19
Reference	1905-13

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT RH DOOR PANEL	1790.32 <i>ht</i>
1	FRONT RH CHROME PROTECTOR	282.30 <i>ad</i>
1	FRONT RH DOOR LOCK	201.50 <i>x</i>
1	FRONT RH INNER TRIM BOARD	512.10 <i>x</i>
1	REAR RH DOOR PANEL	1784.44 <i>Rv</i>
1	REAR RH DOOR CHROME PROTECTOR	282.30 <i>x</i>
1	SILL GARNISH	583.50 <i>x</i>
		5436.46
	Less 25%	1359.11
	Subtotal	4077.35
	Balance C/F	
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	4077.35
1 BOT	BRAKE FULD	50.00 <i>x</i>
		50.00
	Subtotal	50.00
	Balance C/F	4127.35
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	4127.35
1	TRANSFER PARTS ATTACHMENT FROM FRONT DOOR TO NEW	200.00 <i>60</i>
2	TRANSFER PARTS ATTACHMENT FROM REAR DOOR TO NEW	200.00 <i>xun</i>
3	PANEL BEATING ON AFFECTED AREAS	800.00 <i>200</i>
4	SPRAY PAINTING ON AFFECTED AREAS	800.00 <i>H00</i>
5	APPLY ANTI RUST ON AFFECTED AREAS	150.00 <i>30</i>
		2150.00
	Subtotal	2150.00
	Grand total	6277.35

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jiah 97493749

- WP

Resurvey after repair

02 days

tanjiah@lkkauto.com