



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR YAP KOK SENG
BLK. 853 WOODLANDS ST. 83
#03-124 SINGAPORE 730853

POLICY NO : THIRD PARTY CLAIMS
YOUR REF : XE 4676 M (LONPAC)
OUR REF : TP 6022
VEHICLE NO : SJJ 9114 A
MAKE/MODEL : MERCEDES C230
DATE OF ACCIDENT : 06.05.19

SURVEY BY

DATE : 08.05.19

2	PCS HEADREST REPAIR KIT	Activated /	895.00	S\$	1,790.00
1	PC BOOTLID	Buc /			1,660.00
1	PC BOOTLID CENTRE EMBLEM	nec /			50.00
1	PC BOOTLID CHROME HANDLE	DEF /			210.00
2	PCS BOOTLID HINGES	nux	155.00		310.00
1	PC BOOTLID TOP LOCK	SUC x			320.00
1	PC BOOTLID LOWER LOCK	nux			48.00
1	PC BOOTLID WEATHERSTRIP	DEF /			173.00
2	PCS TAILLAMP ASSY	?	555.00		1,110.00
1	PC REAR BUMPER	DEF /			1,455.00
1	PC REAR BUMPER REINFORCEMENT (WITH BRACKETS)	?			695.00
1	PC REAR BUMPER TOW COVER	nux			67.00
3	PCS REAR BUMPER CENTRE SPONGE	?	142.00		426.00
1	PC REAR BUMPER CENTRE CHROME MOULDING	SCR-			112.00
2	PCS REAR BUMPER SIDE CHROME MOULDING	nec /	105.00		210.00
2	PCS REAR BUMPER REVERSE SENSOR	Shorted /			2,090.00 300
1	PC REAR END PANEL	DD /			1,680.00
1	PC REAR END PANEL TOP GARNISH	CRA /			456.00
2	PCS REAR FENDER SIDE GARNISH	CRA /	28.00		56.00
			LESS 10%	S\$	12,918.00
					1,291.80
				S\$	11,626.20
1	SET REAR BUMPER CLIPS	nec /		S\$	30.00 S/ NETT
10	PCS REAR FENDER SIDE GARNISH CLIPS	nec /	9.00		30 00.00 "
				S\$	120.00

TO DISMANTLE AND REFIX REVERSE CAMERA

TO DISMANTLE AND REFIX REVERSE CAMERA/ REVERSE SENSOR

TO REMOVE AND REFIX CUSHION SEAT AND REAR FENDER INNER TRIM BOARD

TO COMPUTER RESET

TO CHECK WIRING FUNCTION

TO APPLY RUSTING AND PROOFING ON REPLACED AND REPAIR PANEL

LABOUR CHARGES

TO PUTTY AND SPRAY PAINTING CHARGES

S\$	80.00	30
	40.00	30
	80.00	50
	150.00	120
	50.00	30
	100.00	20
	800.00	700
	1,000.00	700
S\$	14,046.20	

SIN DOLLARS: FOURTEEN THOUSAND FORTY-SIX AND CENTS TWENTY ONLY
YOUR FAITHFULLY,

Three Jia-Lkk
9/5/19
L/s 6 days.

38 Woodlands Industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700

CYS AUTOMOBILE SERVICES PTE LTD Tel: 6219 2096 (3 Lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: