

Quotation


DATE: 07/05/19
VEHICLE NO: PA9871Z
DRIVER: ZHU CHEN SHENG
ATTENTION TO:
PREPARED BY: Chan Soo Lye


LOCATION: Gul Workshop
Q REF No: Q19/05/1015
DEPARTMENT: WTS Bus Department
ACCIDENT DATE: 02/05/19
REF No: JW-0519-308


S/N	Description	Qty	Cost per Unit	Amount S\$
Spare Parts				
1	FRONT PASSENGER DOOR RUBBER MUDGUARD	1	320	320.00
Labour Costs				
1	TO REMOVE AND REPLACE FRONT PASSENGER DOOR RUBBER MUDGUARD	1	400	400.00
Spray Paint				
1	Spray Painting TO SPRAY PAINTING FRONT BUMPER.	1	350	350.00
TOTAL:				1,070.00
Total Amount				SGD 1,070.00

Remarks:


Signature of Workshop Dpt


Signature of Department Head


Signature of Claim Department

Surveyor Sign: 
Surveyor Name: Tanphim
Date: 16/5/19 @ 945sqm

Tanphim 97495749
'w'p'
w/5/19 @ 945sqm
Resurvey after painting
o/d day
tanphim @ (Manda) or.
LKK

N.V: rha
68411972

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

1 / 1

Acknowledged by Repairer

Signature:

Date: