

**WORLD AUTO PTE LTD**

47 Jalan Pemimpin #01-02/03  
 Halcyon 2, S'pore 577200  
 Tel No. : 6451 3933 Fax No. : 6455 7576  
 E-Mail : worldaut@singnet.com.sg  
 Website : www.worldauto.com.sg  
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

**INDIA INTERNATIONAL INSURANCE PTE LTD**  
 64 CECIL ST #04-05 IOB BUILDING  
 049711

Attention : Motor Claim Department  
 Contact : 6223 8122

**Estimate : ES190080**

Date : 01/05/2019  
 Vehicle Num. : SLK 1595T (LCR)  
 Make/Model : HONDA VEZEL HYBRID  
 Chassis/Eng# :  
 Accident Date : 01/05/2019  
 Claim No. :  
 Reference :  
 Policy No. :

| S/N                   | Quantity | Particular                                 | Unit Price | Amount S\$ |
|-----------------------|----------|--------------------------------------------|------------|------------|
| LIST ITEMS :          |          |                                            |            |            |
| 1.                    | 1        | FRONT DOOR - RH BUC ✓ ?                    |            | 1,042.00   |
| 2.                    | 1        | FRONT DOOR INNER TRIM BOARD RH             |            | 526.00     |
| 3.                    | 1        | FRONT DOOR INNER LOCK RH Jam ✓             |            | 288.90     |
| 4.                    | 1        | FRONT DOOR POWER WINDOW REGULATOR RH ?     |            | 382.60     |
| 5.                    | 2        | FRONT DOOR HINGE RH BT ✓                   | 98.60      | 197.20     |
| 6.                    | 1        | FRONT DOOR CHECKER RH ?                    |            | 96.50      |
| 7.                    | 1        | FRONT DOOR FRAME WEATHERSTRIP RH ?         |            | 85.00      |
| 8.                    | 1        | REAR DOOR - RH BUC ✓                       |            | 1,080.00   |
| 9.                    | 2        | REAR DOOR HINGE RH BT ✓                    | 98.20      | 196.40     |
| 10.                   | 1        | REAR DOOR CHECKER RH ?                     |            | 95.40      |
| 11.                   | 1        | REAR DOOR SUB RUBBER SEAL RH CENTRE CUT ✓  |            | 45.00      |
| 12.                   | 1        | DOOR FRAME PANEL RH Repair x               |            | 882.00     |
| 13.                   | 1        | SIDE SKIRT RH DEF ✓                        |            | 258.60     |
| 14.                   | 1        | ROOF INNER LINING DEF ✓                    |            | 733.80     |
| 15.                   | 1        | SIDE CURTAIN AIRBAG RH Activated ✓         |            | 935.20     |
| 16.                   | 1        | DRIVER SEAT AIRBAG Activated ✓             |            | 680.00     |
| 17.                   | 1        | DRIVER SEAT CUSHION COVER ?                |            | 450.00     |
| 18.                   | 1        | AIRBAG CONTROL MODULE nec ✓                |            | 936.20     |
| 19.                   | 1        | SIDE AIRBAG IMPACT SENSOR, FRONT RH nec ✓  |            | 243.80     |
| 20.                   | 1        | SIDE AIRBAG IMPACT SENSOR, REAR RH nec ✓   |            | 243.80     |
| 21.                   | 1        | FRONT SEATBELT RH Jam ✓                    |            | 588.60     |
| 22.                   | 1        | FRONT SEATBELT BUCKLE RH nn x              |            | 225.60     |
| 23.                   | 1        | FRONT DOOR SUB RUBBER SEAL RH, LOWER DEF ✓ |            | 35.00      |
| 24.                   | 1        | FRONT DOOR SUB RUBBER SEAL RH, FRT nn x    |            | 35.00      |
| 25.                   | 1        | DOOR FRAME PILLAR RUBBER SEAL RH nn x      |            | 80.00      |
| 26.                   | 1        | FRONT DOOR GLASS OUTER MOULDING RH nec ✓   |            | 89.30      |
| List TotalS\$ :       |          |                                            |            | 10,451.90  |
| 20.00% Discount S\$ : |          |                                            |            | 2,090.38   |
|                       |          |                                            |            | 8,361.52   |

CONTINUE / ...

# WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03  
 Halcyon 2, S'pore 577200  
 Tel No. : 6451 3933 Fax No. : 6455 7576  
 E-Mail : worldaut@singnet.com.sg  
 Website : www.worldauto.com.sg  
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD  
 64 CECIL ST #04-05 IOB BUILDING  
 049711

Attention : Motor Claim Department  
 Contact : 6223 8122

Estimate : ES190080

Date : 01/05/2019  
 Vehicle Num. : SLK 1595T (LCR)  
 Make/Model : HONDA VEZEL HYBRID  
 Chassis/Eng# :  
 Accident Date : 01/05/2019  
 Claim No. :  
 Reference :  
 Policy No. :

| S/N                         | Quantity | Particular                                                                                                                                                                 | Unit Price | Amount S\$ |
|-----------------------------|----------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|------------|
| <b>SPECIAL NETT ITEMS :</b> |          |                                                                                                                                                                            |            |            |
| 1.                          | 1SET     | FRONT DOOR INNER TRIM BOARD CLIPS <i>necc ✓</i>                                                                                                                            | 20         | 300.00     |
| 2.                          | 1SET     | SIDE SKIRT CLIPS <i>necc ✓</i>                                                                                                                                             |            | 20.00      |
| 3.                          | 1SET     | REAR DOOR INNER TRIM BOARD CLIPS <i>necc ✓</i>                                                                                                                             | 20         | 300.00     |
| 4.                          | 1        | TOWING CHARGE ( KING DOLLY ) <i>Invoice provided ✓</i>                                                                                                                     |            | 120.00     |
| Special Nett Total S\$ :    |          |                                                                                                                                                                            |            | 200.00     |
| <b>LABOUR :</b>             |          |                                                                                                                                                                            |            |            |
|                             |          | TRANSFER DOOR MECHANISM (X2 DOORS)                                                                                                                                         | 120        | 360.00     |
|                             |          | WIRINGS CHECK AND RECTIFY WHERE NECESSARY                                                                                                                                  | 40         | 180.00     |
|                             |          | REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD DOOR PILLAR PANELS, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS | 1600       | 2,200.00   |
|                             |          | REMOVE INTERIOR UPHOLSTERY INCLUDING ROOF INNER LINING, FLOOR PANEL LINING, FRONT AND REAR CAR SEATS IN ORDER TO FACILITATE REPAIRS, REPLACE AAND REFIT ABOVE PARTS        | 120        | 480.00     |
|                             |          | REMOVE AND REPLACE DAMAGED SRS COMPONENTS INCLUDING SRS CONTROL MODULE                                                                                                     | 80         | 380.00     |
|                             |          | DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)                                                   |            | 450.00 X   |
|                             |          | PERFORM VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT                                                                                                                       | 120        | 450.00     |

CONTINUE / ...

**WORLD AUTO PTE LTD**

47 Jalan Pemimpin #01-02/03  
 Halcyon 2, S'pore 577200  
 Tel No. : 6451 3933 Fax No. : 6455 7576  
 E-Mail : worldaut@singnet.com.sg  
 Website : www.worldauto.com.sg  
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

**INDIA INTERNATIONAL INSURANCE PTE LTD**  
 64 CECIL ST #04-05 IOB BUILDING  
 049711

Attention : Motor Claim Department  
 Contact : 6223 8122

**Estimate : ES190080**

Date : 01/05/2019  
 Vehicle Num. : SLK 1595T (LCR)  
 Make/Model : HONDA VEZEL HYBRID  
 Chassis/Eng# :  
 Accident Date : 01/05/2019  
 Claim No. :  
 Reference :  
 Policy No. :

| S/N | Quantity | Particular                                                                                                       | Unit Price | Amount S\$ |
|-----|----------|------------------------------------------------------------------------------------------------------------------|------------|------------|
|     |          | CODES, REINITIALISE HV HYBRID SYSTEM, PERFORM SRS<br>FUNCTIONALITY CHECK<br>(HV HYBRID SYSTEM SAFETY PROCEDURES) |            |            |
|     |          | PUTTY AND SPRAY PAINT ALL AFFECTED AREAS                                                                         | 1400       | 1,800.00   |
|     |          | Labour Total S\$ :                                                                                               |            | 6,300.00   |

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Hwee Jie - LKK  
 9/5/19

P/P 8 days.

*[Signature]*

**E. & O.E.**

**Total S\$ : 14,861.52**

=====

for WORLD AUTO PTE LTD