

Sheet1

HO BENG TRADING

Block 3020A Ubi Road 1 # 01-33 Singapore 408714
Tel : (65) 69664526 HP: 92712214 Fax: (65) 69664526
Email : chris_chanbebe@hotmail.com

7th May 2019

NG HOCK HAI
Blk 3020A Ubi Road 1
01-33
Singapore 408717

TP FWD
Vivian

Accident date: 28th Feb 2018
Estimated repair cost for vehicle no: SGR9804K KIA RIO

S/n	Qty	Items	U/price	Amount
1	1	Front L/H Fender <i>Regis</i>		\$642.80 <i>x</i>
2	1	Front L/H Fender Cowling <i>2 all</i>		\$75.00 <i>x</i>
3	1	Front L/H Fender Cowling Clips <i>5 new</i>		\$52.00 <i>x</i>
4	1	Front L/H Head Lamp <i>cracked</i>		\$555.00 <i>✓</i>
5	2	Front head lamp lower bracket <i>new</i>	\$43.90	\$87.80 <i>x</i>
6	1	Front bumper <i>deland</i>		\$520.00 <i>✓</i>
7	2	Front bumper side bracket <i>LH new</i>	\$28.00	\$56.00 <i>28</i>
8	8	Front bumper clips <i>new</i>	\$5.00	\$40.00 <i>30</i>

1133

1018.70

Subtotal :- \$2,028.60

Labour charges

Tuff kote

To Check Wiring System

Towing charges

Panel beating

Spray painting

\$80.00 *x*

\$60.00 *30*

630

\$0.00 *x*

\$500.00 *200*

\$600.00 *400*

Subtotal :- \$1,240.00

Total:- \$3,268.60

total: 1645.70

L/S: 1-31C

03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: