

HO BENG TRADING

Block 3020A Ubi Road 1 # 01-33 Singapore 408714

Tel : (65) 69664526 HP: 92712214 Fax: (65) 69664526

Email : chris_chanbebe@hotmail.com

7th May 2019

NG HOCK HAI
Blk 3020A Ubi Road 1
01-33
Singapore 408717

Accident date: 28th Feb 2018
Estimated repair cost for vehicle no: SGR9804K KIA RIO

S/n	Qty	Items	U/price	Amount
				\$642.80
1	1	Front L/H Fender		\$75.00
2	1	Front L/H Fender Cowling		\$52.00
3	1	Front L/H Fender Cowling Clips		\$555.00
4	1	Front L/H Head Lamp		\$87.80
5	2	Front head lamp lower bracket	\$43.90	\$520.00
6	1	Front bumper		\$56.00
7	2	Front bumper side bracket	\$28.00	\$40.00
8	8	Front bumper clips	\$5.00	
Subtotal :-				\$2,028.60
<u>Labour charges</u>				\$80.00
Tuff kote				\$60.00
To Check Wiring System				\$0.00
Towing charges				\$500.00
Panel beating				\$600.00
Spray painting				
Subtotal :-				\$1,240.00
Total:-				\$3,268.60