

ASS. REC. BY:

REF: CS/FCI 19008231/Eg,d3n2 Special Instruction:

Surveyor: Steve ASSIGNMENT (Office)From (Person): Sithara of FCI Date/Time: 9.5.19 3:22p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLQ 6122K Insured: SHD 8842Tat Workshop m/s N-51 Automotive Tel: 68420051of 2 Kaki Bukit Ave 2 #01-18Policy No: _____ Claim No: D19003058 MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 7.5.2019(Client's Record) "wp" 10.5.2019

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____

Date/Time: 9.5.19 4:05p.m Person Contacted: Zi Ting Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	SLQ 6122K-x
	SHD 8842T - CS/FCI 18007091/ Arbn 2 DOA-13/04/2018
14/5/19 @ 4.15pm	Informed Sithara, we are pending for estimate from repairer.
15/5/19 @ 11.36am	informed to Sithara by email.

Steve

REF:

ASSIGNMENT

17/7/17
17/07/19

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop n/s: _____
nl _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 6 days Res.: Yes or No
Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLQ 6122K Vt Regn: 1496
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Honda Vezel
Colour: Black A/C Insured / Std / NI / N/A
Sp. Reading: 123851 T/Radio: Insured / Std / NI / N/A
Eng/No: _____
C/No: R431248471
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rlm / STD A/Rlm or
Tyre Size: F: 215/60R16
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or SJHTT
Front: _____ Rear: 6
R/Bal. 6 mm R/Bal. _____ mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 10/5/19
Survey held at N-51
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
The UIC / Chassis frame / Body Structure affected due to collision

Date / Time / Action / Instruction

MV-75K

15/5/19 Finalize \$5200 CL/5.6 days (Rad \$4756.64, 48%)

RECEIVED 16 MAY 2019

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Report Format: TP

Lump Sum / I.B.T: 5200

Survey Fee:
Transportation

170
50
50+50
143

16/5/19

463



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003058MFSH
Our Ref: CS/FCI19008231/Eqd3

Date: 15 May 2019

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLQ 6122K

Please be informed that we had conducted the inspection of the abovementioned vehicle on 10/05/2019 at the premises of M/s N-51 AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: S\$ 9,956.64 .
Revised Estimate Amount	: S\$ 6,532.40 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

Steve
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	09-05-2019	Our Ref No. D19003058MFSH
Accident Date	07-05-2019	Claim Type. Third Party
Insured Vehicle	SHD8842T	Third Party Vehicle. SLQ6122K
Survey Location	2 KAKI BUKIT AVENUE 2 #01-18 KAKI BUKIT AUTOHUB	
Contact Person.	ZI TING	
Contact No.	68420051/ 0	Fax No. 67410510
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	N-51 AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 15 May 2019 11:36 AM
To: 'CWS Motor Claims'; assignments; SUR
Cc: 'Sithara'
Subject: RE: SURVEY ASSESSMENT - D19003058MFSH/1
Attachments: CSFCI19008231Eqd3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SLQ 6122K.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 14 May 2019 4:15 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19003058MFSH/1

Dear Sithara,

Please be informed that we have inspected the vehicle SLQ 6122K on 10/05/2019.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 9 May 2019 4:05 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19003058MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed that repairer agreed to survey on 10/5/2019.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 14 May 2019 4:15 PM
To: 'CWS Motor Claims'; assignments; SUR
Cc: 'Sithara'
Subject: RE: SURVEY ASSESSMENT - D19003058MFSH/1

Dear Sithara,

Please be informed that we have inspected the vehicle SLQ 6122K on 10/05/2019.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 9 May 2019 4:05 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19003058MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed that repairer agreed to survey on 10/5/2019.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 9 May, 2019 3:22 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003058MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Budget Direct Insurance

Car insurance due?
Pay Less or Get \$100*, even if you don't buy.

Get a Quote >

*Terms and conditions apply

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Renewal Cae Toyota Vios 1.5A



2,500 P.A. 50 Admin Fee/Car
Finance 2 Years Warranty \$1500
Down Monthly From \$448
GV Credit Pte Ltd - Sionfu

Think One Automobile

NEW & USED COMMERCIAL VEHICLES

Browse by Category

Sort by Date Posted

20 results/page

18 vehicles

Honda Vezel

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Vezel	Any	Any	2017	Any	Any	Any	Available
	Honda Vezel Hybrid 1.5A RS Honda Sensing	\$85,800	\$10,870 /yr	10-Jan-2017	1,496 cc	47,002 km	SUV	Available
Fuel Type: Petrol-Electric Sheltered Car Park Everyday. Only Hand Wash By Owner And No One Else. Car Exterior Shiny Even Without Wax Or Clear Coat Because I Use Sonax Products For Washing. Average Petrol Consumption = 16.6km/...								
Posted: 21-Apr-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda Vezel Hybrid 1.5A X	\$80,000	\$10,070 /yr	20-Jan-2017	1,496 cc	64,153 km	SUV	Available
Fuel Type: Petrol-Electric 1 Owner Only! Low Mileage Done! Not A Private Hire Unit, Very Well Kept In Rare Condition. View And Believe, Buy It From Us With A Peace Of Mind, Discover The Greatness Of This Car, Consignment Unit!...								
Prem Roy Motoring Posted: 15-Mar-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda Vezel 1.5A X	\$73,500	\$8,880 /yr	25-Jan-2017	1,496 cc	-	SUV	Available
Elegant Silver SUV, One Owner Only, Low Maintenance Cost, Comes With Warranty, Very Well Maintained, Easy Financing, Flexible In-House Loan Packages Available.								
Prime Motor & Leasing Posted: 03-May-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda Vezel Hybrid 1.5A X Honda Sensing	\$83,800	\$10,550 /yr	26-Jan-2017	1,496 cc	53,800 km	SUV	Available
Fuel Type: Petrol-Electric Most Popular SUV With Honda Sensing, \$2000 Republic Auto Warranty Workshop Credits, Enjoy Exclusive Interest Rates At 2.48%, Please Call/SMS/Whatsapp Now For Enquiries And Viewing Appointment.								
Republic Auto Posted: 25-Apr-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	COE Bidding Results	Find out more about the latest results of our Certificate of Entitlement (COE). Find out more!						
	Honda Vezel 1.5A X	\$69,800	\$8,110 /yr	02-Feb-2017	1,496 cc	-	SUV	Available
Balloon Scheme Available! We Are sgCarMart Premium Dealer! Buy With No Worries! No Hidden Costs! Car In Original Condition! Low Mileage! Accident Free! In House Loan Or Bank Loan Available! No Need Gu...								
88 Motor Trading Posted: 09-May-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda Vezel 1.5A X	\$69,800	\$8,210 /yr	03-Feb-2017	1,496 cc	-	SUV	Available
Full Loan Available At \$1.1k+/ Month We Can Help To Convert To Z10 Usage If Needed, In House Loan / Bank Loan Available! Balloon Scheme Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart...								
88 Motor Trading Posted: 04-May-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda Vezel Hybrid 1.5A X	\$82,800	\$10,260 /yr	10-Mar-2017	1,496 cc	4,900 km	SUV	Available
Fuel Type: Petrol-Electric 3 Years On 100000km Warranty. High Trade In.								
Prime Motor & Leasing Posted: 07-May-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda Vezel 1.5A X Honda Sensing	-	N.A	27-Mar-2017	1,496 cc	22,289 km	SUV	Available
Lowest Price And Genuinely Low Mileage In sgCarMart. Selling Due To Upgrading To A Bigger SUV. Under Utilized Due To Frequent Outstation. Accident Free And Car In Very Good Conditions Too.								
Posted: 30-Apr-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								

Compare

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7200G
Vehicle Details	
Vehicle No.:	SLQ6122K
Vehicle to be Exported:	No
Intended Deregistration Date:	13 May 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	LEB5948488
Chassis No.:	RU31248471
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$26,472.00
Original Registration Date:	17 Jul 2017
First Registration Date:	17 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Jul 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	16 Jul 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,110.00
COE Rebate Amount:	\$40,963.00
Total Rebate Amount:	\$44,713.00

The information contained herein is correct as at 13 May 2019

OK



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 96666053

15/5/19
Steve CLKK) with
10/5/19, 2.00pm
L/S
Ry AL spy
6 days

ESTIMATE

Repair Code : CLM15224

Date in : 07/05/2019

Vehicle Num. : SLQ6122K

Model : HONDA VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31248471/LEB5948488

CRU - crushed

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMOER SIDE RETAINER L/R / BR	2	23.00	46.00 /
REAR BUMPER / DD	1	762.70	762.70 /
REAR BUMPER LOWER COVER / CRU	1	250.00	250.00 /
REAR BUMPER REFLECTOR L/R X NM	2	141.10	282.20 X
REAR BUMPER SIDE L/R / BR	2	195.00	390.00 /
REAR END PANEL / DD	1	415.60	415.60 /
REAR END PANEL ANTENNA SENSOR / BR	1	60.10	60.10 /
REAR END PANEL BUZZLE SENSOR / BR	1	85.20	85.20 /
REAR END PANEL INNER TOP GARNISH / CRU	1	98.00	98.00 /
REAR EXHAUST CHROME TAIL PIPE / CRU	1	135.00	135.00 /
REAR EXHAUST GASKET X NM	1	48.30	48.30 X
REAR EXHAUST RUBBER MOUNTING X NM	2	16.50	33.00 X
REAR EXHAUST SILENCER BOX X NM	1	517.70	517.70 X
REAR FENDER INNER TRIM GARNISH L/R / CRU	2	295.00	590.00 /
REAR FLOOR PANEL COMPARTMENT TRAY GARNISH / CRU	1	485.30	485.30 /
REAR FLOOR PANEL INNER TOP BOARD COVER / CRU	1	195.00	195.00 /
REAR TAILGATE / DD	1	953.30	953.30 /
REAR TAILGATE 'HYBRID' EMBLEM / NEC	1	75.80	75.80 /

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 96666053

ESTIMATE

Repair Code : CLM15224

Date in : 07/05/2019

Vehicle Num. : SLQ6122K

Model : HONDA VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31248471/LEB5948488

REAR TAILGATE 'VEZEL' EMBLEM / <i>NIEC</i>	1	56.20	56.20 /
REAR TAILGATE HINGES L/R X <i>NAI</i>	2	50.00	100.00 X
REAR TAILGATE INNER PULL GARNISH / <i>CRU</i>	1	27.50	27.50 /
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R X <i>NAI</i>	2	18.50	37.00 X
REAR TAILGATE INNER TRIM BOARD / <i>BR</i>	1	153.40	153.40 /
REAR TAILGATE MECHANISM LOCK / <i>BT</i>	1	180.00	180.00 /
REAR TAILGATE MECHANISM LOCK STRIKER X <i>NAI</i>	1	27.50	27.50 X
REAR TAILGATE OUTER GARNISH X <i>NAI</i>	1	220.00	220.00 X
REAR TAILGATE OUTER GARNISH 'H' LOGO EMBLEM X <i>NAI</i>	1	25.00	X 25.00
REAR TAILGATE WEATHER STRIP / <i>CRU</i>	1	96.80	96.80 /
REAR TAILGATE WINDSCREEN INNER SEAL / <i>NIEC</i>	2	50.00 <i>30</i>	60 / 100.00
REAR TAILGATE WINDSCREEN MOULDING / <i>NIEC</i>	2	50.00	100.00 /
REAR TAILLAMP L/R / <i>BR</i>	2	474.60	949.20 <i>474.60</i>
Subtotal before discount		<i>5699.50</i>	7,495.80
Percentage discount 20%		<i>-72%</i>	1,499.16
Sub-total 1		<i>4552.40</i>	5,996.64
REAR BUMPER CLIPS - SET / <i>NIEC</i>	1	80.00 <i>30</i>	80.00
REAR BUMPER REVERSE SENSOR / <i>BR</i>	1	350.00 <i>20</i>	350.00

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 96666053

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

Repair Code : CLM15224

Date in : 07/05/2019

Vehicle Num. : SLQ6122K

Model : HONDA VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31248471/LEB5948488

REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	30.00	10 /	30.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET	2	50.00	15 30 /	100.00
REAR FLOOR PANEL INSULATOR MAT	1	300.00	X	300.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	50.00	15 /	50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET	1	40.00	10 /	40.00
REAR TAILGATE WINDSCREEN SEALANT	1	60.00	40 /	60.00
REAR TAILLAMP CLIPS L/R - SET	2	30.00	15 /	60.00
Subtotal before discount				350 / 1,070.00
Percentage discount 0%				0.00
Sub-total 2				1,070.00
Parts-total				7,066.64

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	30	100.00
To remove, reinstall tailgate windscreen	100	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)		140.00 60
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	700 /	1,100.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	50 /	100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	600 /	1,100.00
To apply anti-rust chemical on repaired and replaced panel.	40	120.00

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 96666053

ESTIMATE

Repair Code : CLM15224

Date in : 07/05/2019

Vehicle Num. : SLQ6122K

Model : HONDA VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31248471/LEB5948488

To transfer rear bootlid mechanism lock outer handle reflector

Labour Total

Parts & Labour Total

30 80.00

1610 ✓ 2,890.00

9,956.64

*** This is a computer-generated document which requires no signature.***

page 4

P- 4552.40

M- 350

L- 1610

6512.40

LIS- 5209.92

= 5200 ✓



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19008231/Eqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 17-05-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 8842T	Veh. Inspected	SLQ 6122K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003058MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	09/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU31248471	Colour	BLACK	
Odometer	123851	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	SJHTT	6 mm	
L/H Front Tyre	215/60 R16	SJHTT	6 mm	
R/H Rear Tyre	215/60 R16	SJHTT	6 mm	
L/H Rear Tyre	215/60 R16	SJHTT	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/05/2019	Inspection Date	10/05/2019	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 6122K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	REAR BUMPER SIDE RETAINER L/R @\$23.00	BROKEN	46.00	46.00
1	REAR BUMPER	DENTED	762.70	762.70
1	REAR BUMPER LOWER COVER	CRUSHED	250.00	250.00
2	REAR BUMPER REFLECTOR L/R @\$141.10	NOT NECESSARY	282.20	-
2	REAR BUMPER SIDE L/R @\$195.00	BROKEN	390.00	390.00
1	REAR END PANEL	DENTED	415.60	415.60
1	REAR END PANEL ANTENNA SENSOR	BROKEN	60.10	60.10
1	REAR END PANEL BUZZLE SENSOR	BROKEN	85.20	85.20
1	REAR END PANEL INNER TOP GARNISH	CRUSHED	98.00	98.00
1	REAR EXHAUST CHROME TAIL PIPE	CUT	135.00	135.00
1	REAR EXHAUST GASKET	NOT NECESSARY	48.30	-
2	REAR EXHAUST RUBBER MOUNTING @\$16.50	NOT NECESSARY	33.00	-
1	REAR EXHAUST SILENCER BOX	NOT NECESSARY	517.70	-
2	REAR FENDER INNER TRIM GARNISH L/R @\$295.00	CRUSHED	590.00	590.00
1	REAR FLOOR PANEL COMPARTMENT TRAY GARNISH	CRUSHED	485.30	485.30
1	REAR FLOOR PANEL INNER TOP BOARD COVER	CRUSHED	195.00	195.00
1	REAR TAILGATE	DENTED	953.30	953.30
1	REAR TAILGATE "HYBRID" EMBLEM	NECESSARY	75.80	75.80
1	REAR TAILGATE "VEZEL" EMBLEM	NECESSARY	56.20	56.20
2	REAR TAILGATE HINGES L/R @\$50.00	NOT NECESSARY	100.00	-
1	REAR TAILGATE INNER PULL GARNISH	CRUSHED	27.50	27.50
2	REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R @\$18.50	NOT NECESSARY	37.00	-
1	REAR TAILGATE INNER TRIM BOARD	BROKEN	153.40	153.40
1	REAR TAILGATE MECHANISM LOCK	BENT	180.00	180.00
1	REAR TAILGATE MECHANISM LOCK STRIKER	NOT NECESSARY	27.50	-
1	REAR TAILGATE OUTER GARNISH	NOT NECESSARY	220.00	-
1	REAR TAILGATE OUTER GARNISH "H" LOGO EMBLEM	NOT NECESSARY	25.00	-
1	REAR TAILGATE WEATHER STRIP	CRUSHED	96.80	96.80
2	REAR TAILGATE WINDSCREEN INNER SEAL @\$50.00	NECESSARY	100.00	60.00
2	REAR TAILGATE WINDSCREEN MOULDING @\$50.00	NECESSARY	100.00	100.00

Report Ref No. CS/FCI19008231/Eqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR TAILLAMP L/R @\$474.60	BROKEN (1 PC ONLY)	949.20	474.60
	LESS 20% DISCOUNT		-1,499.16	-1,138.10
			5,996.64	4,552.40
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	BROKEN	350.00	200.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	30.00	10.00
2	SET REAR FENDER INNER TRIM GARNISH CLIPS L/R @\$50.00 (SN)	NECESSARY	100.00	30.00
1	REAR FLOOR PANEL INSULATOR MAT (SN)	NOT NECESSARY	300.00	-
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	50.00	15.00
1	SET REAR TAILGATE OUTER GARNISH CLIPS (SN)	NECESSARY	40.00	10.00
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
2	SET REAR TAILLAMP CLIPS L/R @\$30.00 (SN)	NECESSARY (1 PC ONLY)	60.00	15.00
			1,070.00	350.00
	<u>LABOUR</u>			
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,AND REWIRE FOR PARKING SENSOR.		100.00	30.00
	TO REMOVE,REINSTALL TAILGATE WINDSCREEN.		150.00	100.00
	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR).		140.00	60.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID,REAR END PANEL,REAR FENDER (L/R),SPARE TYRE PANEL AND REAR BUMPER.		1,100.00	700.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.		100.00	50.00
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		1,100.00	600.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	40.00

Report Ref No. CS/FCI19008231/Eqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER REAR BOOTLID MECHANISM LOCK OUTER HANDLE REFLECTOR.		80.00	30.00
			2,890.00	1,610.00
GRAND TOTAL			9,956.64	6,512.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,200.00

Report Ref No. CS/FCI19008231/Eqd3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.