

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0572/2019/DY/TF
Date : 3-May-19

Vehicle not IN workshop. Kindly arrange for survey.

Your insured vehicle is : SMG 4519 D

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street

#19-00 The Octagon

Singapore 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Mr. Chua Kian Tiong, Peter
Address : 28B Jalan Lempeng
#21-19
Singapore 128809
Telephone : HP +65 92711433
Type of Claim : Third Party Claims
Policy No. : 1800070073
Vehicle No : **SKT 0523 Y**
Model Code : A3 Sedan 1.0 TFSI 8V
Model / Year : Jun-18
Engine No : CHZ 907563
Chassis No : WAUZZZ8V0J1057518
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 30-Apr-19
Place of Accident : Holland Rd/North Buona Vista Rd-

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKT 0523 Y

S/N	Nature of Jobs	Estimated Charges
1	To remove and reinstall rear parking aid. Check function.	S/N \$ 280.00 ✓
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,050.00 700
3	To respray rear bumper.	\$ 900.00 700
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u><u>\$ 2,422.00</u></u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No SKT 0523 Y

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Rehd</i>	\$ 1,793.00	✓
2	REAR BUMPER STICKY PAD <i>Free</i>	\$ 21.00	X
3	REAR BUMPER FIXING PARTS <i>Free</i>	\$ 175.00	X
4	REAR BUMPER TOP GUIDE SECTION - LH / RH <i>Free</i>	\$ 30.00	+
5	REAR BUMPER TOP GUIDE SECTION PIN <i>Free</i>	2 \$ 53.00	+
6	REAR BUMPER SPOILER <i>Free</i>	\$ 216.00	+
7	REAR BUMPER REINFORCEMENT <i>Free</i>	\$ 522.00	+
8	REAR BUMPER BRACKET - LH / RH	\$ 51.00	X
9	REAR BUMPER SENSOR <i>Free</i>	2 \$ 462.00	+
10	REAR BUMPER SENSOR SEAL RING <i>Free</i>	4 \$ 12.00	+
11	SUNDRIES ?	\$ 400.00	?
TOTAL SPARE PARTS		:	\$ 3,735.00
TOTAL LABOUR CHARGE		:	\$ 2,422.00
GRAND TOTAL		:	\$ 6,157.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 08/05/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant