

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 May 2019 Edit Reg		09 May 2019 00:00 Edit Adj Rpt	S\$18,000.00 Edit Estimates	S\$18,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	G M C MARBLE SPACIALIST PTE LTD, Co. Reg. No.: 200206172H		
Vehicle Reg. No.:	GBH1983R	Date of Loss:	07/05/2019 22:00 - :59 [13 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT19050186	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHC8715H	Policy No. (Claimant):	A29116011MKC
		Excess:	
Repairer:	Premium Carz Services Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki, 417883 Kaki Bukit - Tel: 66369100		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/05/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (31/01/2020): Alert - Adj Mandate Approved (S\$19305.85) - GBH1983R - Claim Handler: Priya
- III_SG (16/01/2020): Alert - Adj Mandate Maintained - GBH1983R - Claim Handler: Priya
- III_SG (24/12/2019): Alert - Adj Mandate Maintained - GBH1983R - Claim Handler: Priya
- III_SG (12/12/2019): Alert - Adj Mandate Maintained - GBH1983R - Claim Handler: Priya
- III_SG (21/11/2019): Alert - Adj Mandate Maintained - GBH1983R - Claim Handler: Priya
- III_SG (18/11/2019): Alert - Adj Mandate Maintained - GBH1983R - Claim Handler: Priya
- III_SG (20/08/2019): Alert - Adj Mandate Approved (S\$0.00) - GBH1983R - Claim Handler: Priya
- III_SG (05/08/2019): Alert - Adj Mandate Approved (S\$0.00) - GBH1983R - Claim Handler: Priya
- III_SG (12/06/2019): Alert - Adj Mandate Approved (S\$0.00) - GBH1983R - Claim Handler: Priya
- III_SG (17/05/2019): Alert - Adj Mandate Maintained - GBH1983R - Claim Handler: Priya

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBH1983R (MCT19050186)**
[SHC8715H]
TP
G M C MARBLE SPACIALIST PTE LTD
May 7 2019 10:00PM
[COMFORT TRANSPORTATION PTE LTD]
Premium Carz Services Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

[View](#) |
 [View in Browser](#) ▼

Video			1 per page ▼	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	31/01/20 17:07	Video - Accident-iv	 Load MP4	☒
Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/05/19 14:14	General View	 Load JPG	☒
2	15/05/19 14:14	General View	 Load JPG	☒
3	15/05/19 14:14	Chassis Number	 Load JPG	☒
4	15/05/19 14:14	General View	 Load JPG	☒
5	15/05/19 14:14	General View	 Load JPG	☒
6	15/05/19 14:14	General View	 Load JPG	☒
7	15/05/19 14:14	General View	 Load JPG	☒
8	15/05/19 14:14	General View	 Load JPG	☒
9	15/05/19 14:14	General View	 Load JPG	☒
10	15/05/19 14:14	General View	 Load JPG	☒
11	15/05/19 14:14	General View	 Load JPG	☒
12	15/05/19 14:14	General View	 Load JPG	☒
13	15/05/19 14:14	General View	 Load JPG	☒
14	15/05/19 14:14	General View	 Load JPG	☒
15	15/05/19 14:14	General View	 Load JPG	☒
16	15/05/19 14:14	General View	 Load JPG	☒
17	15/05/19 14:14	General View	 Load JPG	☒
18	15/05/19 14:14	General View	 Load JPG	☒
19	15/05/19 14:14	General View	 Load JPG	☒
20	15/05/19 14:14	General View	 Load JPG	☒
21	15/05/19 14:14	General View	 Load JPG	☒
22	15/05/19 14:14	General View	 Load JPG	☒
23	15/05/19 14:14	General View	 Load JPG	☒
24	15/05/19 14:14	General View	 Load JPG	☒
25	15/05/19 14:14	General View	 Load JPG	☒
26	15/05/19 14:14	General View	 Load JPG	☒
27	15/05/19 14:14	General View	 Load JPG	☒
28	15/05/19 14:14	General View	 Load JPG	☒
29	15/05/19 14:14	General View	 Load JPG	☒
30	15/05/19 14:14	General View	 Load JPG	☒
31	15/05/19 14:14	General View	 Load JPG	☒
32	15/05/19 14:14	General View	 Load JPG	☒

Video			1 per page	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
33	15/05/19 14:14	General View	 Load JPG	☒
34	15/05/19 14:14	General View	 Load JPG	☒
35	15/05/19 14:14	General View	 Load JPG	☒
36	15/05/19 14:14	General View	 Load JPG	☒
37	15/05/19 14:14	General View	 Load JPG	☒
38	15/05/19 14:14	General View	 Load JPG	☒
39	15/05/19 14:14	General View	 Load JPG	☒
40	15/05/19 14:14	General View	 Load JPG	☒
41	15/05/19 14:14	General View	 Load JPG	☒
42	15/05/19 14:14	General View	 Load JPG	☒
43	15/05/19 14:14	General View	 Load JPG	☒
44	15/05/19 14:14	General View	 Load JPG	☒
45	15/05/19 14:14	General View	 Load JPG	☒
46	15/05/19 14:14	General View	 Load JPG	☒
47	15/05/19 14:14	General View	 Load JPG	☒
48	15/05/19 14:14	General View	 Load JPG	☒
49	15/05/19 14:14	General View	 Load JPG	☒
50	15/05/19 14:14	General View	 Load JPG	☒
51	15/05/19 14:14	General View	 Load JPG	☒
52	15/05/19 14:14	General View	 Load JPG	☒
53	15/05/19 14:14	General View	 Load JPG	☒
54	15/05/19 14:14	General View	 Load JPG	☒
55	15/05/19 14:14	General View	 Load JPG	☒
56	15/05/19 14:14	General View	 Load JPG	☒
57	15/05/19 14:14	General View	 Load JPG	☒
58	15/05/19 14:14	General View	 Load JPG	☒
59	15/05/19 14:14	General View	 Load JPG	☒
60	15/05/19 14:14	General View	 Load JPG	☒
61	15/05/19 14:14	General View	 Load JPG	☒
62	15/05/19 14:14	General View	 Load JPG	☒
63	15/05/19 14:14	General View	 Load JPG	☒
64	15/05/19 14:14	General View	 Load JPG	☒
65	15/05/19 14:14	General View	 Load JPG	☒
66	15/05/19 14:14	General View	 Load JPG	☒
67	15/05/19 14:14	General View	 Load JPG	☒
68	15/05/19 14:14	General View	 Load JPG	☒
69	15/05/19 14:14	General View	 Load JPG	☒
70	15/05/19 14:14	General View	 Load JPG	☒
71	15/05/19 14:14	General View	 Load JPG	☒
72	15/05/19 14:14	General View	 Load JPG	☒
73	15/05/19 14:14	General View	 Load JPG	☒
74	15/05/19 14:14	General View	 Load JPG	☒
75	15/05/19 14:14	General View	 Load JPG	☒
76	15/05/19 14:14	General View	 Load JPG	☒
77	15/05/19 14:14	General View	 Load JPG	☒
78	15/05/19 14:14	General View	 Load JPG	☒
79	15/05/19 14:14	General View	 Load JPG	☒
80	15/05/19 14:14	General View	Load JPG	☒

Video			1 per page ▼	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
81	15/05/19 14:14	General View	 Load JPG	☒
82	15/05/19 14:14	General View	 Load JPG	☒
83	15/05/19 14:14	General View	 Load JPG	☒
84	15/05/19 14:14	General View	 Load JPG	☒
85	15/05/19 14:14	General View	 Load JPG	☒
86	15/05/19 14:14	General View	 Load JPG	☒
87	15/05/19 14:14	General View	 Load JPG	☒
88	15/05/19 14:14	General View	 Load JPG	☒
89	15/05/19 14:14	General View	 Load JPG	☒
90	15/05/19 14:14	General View	 Load JPG	☒
91	15/05/19 14:14	General View	 Load JPG	☒
92	15/05/19 14:14	General View	 Load JPG	☒
93	15/05/19 14:14	General View	 Load JPG	☒
94	15/05/19 14:14	General View	 Load JPG	☒
95	15/05/19 14:14	General View	 Load JPG	☒
96	15/05/19 14:14	General View	 Load JPG	☒
97	15/05/19 14:14	General View	 Load JPG	☒
98	15/05/19 14:14	General View	 Load JPG	☒
99	15/05/19 14:14	General View	 Load JPG	☒
100	15/05/19 14:14	General View	 Load JPG	☒
101	15/05/19 14:14	General View	 Load JPG	☒
102	15/05/19 14:14	General View	 Load JPG	☒
103	15/05/19 14:14	General View	 Load JPG	☒
104	15/05/19 14:14	General View	 Load JPG	☒
105	15/05/19 14:14	General View	 Load JPG	☒
106	15/05/19 14:14	General View	 Load JPG	☒
107	15/05/19 14:14	General View	 Load JPG	☒
108	15/05/19 14:14	General View	 Load JPG	☒
109	15/05/19 14:14	General View	 Load JPG	☒
110	15/05/19 14:14	General View	 Load JPG	☒
111	15/05/19 14:14	General View	 Load JPG	☒
112	15/05/19 14:14	General View	 Load JPG	☒
113	15/05/19 14:14	General View	 Load JPG	☒
114	15/05/19 14:14	General View	 Load JPG	☒
115	15/05/19 14:14	General View	 Load JPG	☒
116	15/05/19 14:14	General View	 Load JPG	☒
117	15/05/19 14:14	General View	 Load JPG	☒
118	15/05/19 14:14	General View	 Load JPG	☒
119	15/05/19 14:14	General View	 Load JPG	☒
120	15/05/19 14:14	General View	 Load JPG	☒
121	15/05/19 14:14	General View	 Load JPG	☒
122	15/05/19 14:14	General View	 Load JPG	☒
123	15/05/19 14:14	General View	 Load JPG	☒
124	15/05/19 14:14	General View	 Load JPG	☒
125	15/05/19 14:14	General View	 Load JPG	☒
126	15/05/19 14:14	General View	 Load JPG	☒
127	15/05/19 14:14	General View	 Load JPG	☒
128	15/05/19 14:14	General View	Load JPG	☒

Video			1 per page		
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
129	15/05/19 14:14	General View	1	Load JPG	☒
130	15/05/19 14:14	General View	1	Load JPG	☒
131	15/05/19 14:14	General View	1	Load JPG	☒
132	15/05/19 14:14	General View	1	Load JPG	☒
133	15/05/19 14:14	General View	1	Load JPG	☒
134	15/05/19 14:14	General View	1	Load JPG	☒
135	15/05/19 14:14	General View	1	Load JPG	☒
136	15/05/19 14:14	General View	1	Load JPG	☒
137	15/05/19 14:14	General View	1	Load JPG	☒
138	15/05/19 14:14	General View	1	Load JPG	☒
139	15/05/19 14:14	General View	1	Load JPG	☒
140	15/05/19 14:14	General View	1	Load JPG	☒
141	15/05/19 14:14	General View	1	Load JPG	☒
142	15/05/19 14:14	General View	1	Load JPG	☒
143	15/05/19 14:14	General View	1	Load JPG	☒
144	15/05/19 14:14	General View	1	Load JPG	☒
145	15/05/19 14:14	General View	1	Load JPG	☒
146	15/05/19 14:14	General View	1	Load JPG	☒
147	15/05/19 14:14	General View	1	Load JPG	☒
148	15/05/19 14:14	General View	1	Load JPG	☒
149	15/05/19 14:14	General View	1	Load JPG	☒
150	15/05/19 14:14	General View	1	Load JPG	☒
151	15/05/19 14:14	General View	1	Load JPG	☒
152	15/05/19 14:14	General View	1	Load JPG	☒
153	15/05/19 14:14	General View	1	Load JPG	☒
154	15/05/19 14:14	General View	1	Load JPG	☒
155	15/05/19 14:14	General View	1	Load JPG	☒
156	29/07/19 16:27	Reinspection Photo	1	Load JPG	☒
157	29/07/19 16:27	Reinspection Photo	1	Load JPG	☒
158	29/07/19 16:27	Reinspection Photo	1	Load JPG	☒
159	29/07/19 16:27	Reinspection Photo	1	Load JPG	☒
160	29/07/19 16:27	Reinspection Photo	1	Load JPG	☒
161	29/07/19 16:27	Reinspection Photo	1	Load JPG	☒
162	29/07/19 16:27	Reinspection Photo	1	Load JPG	☒
163	29/07/19 16:27	Reinspection Photo	1	Load JPG	☒
164	29/07/19 16:27	Reinspection Photo	1	Load JPG	☒
165	29/07/19 16:27	Reinspection Photo	1	Load JPG	☒
166	29/07/19 16:27	Reinspection Photo	1	Load JPG	☒
167	29/07/19 16:27	Reinspection Photo	1	Load JPG	☒
168	29/07/19 16:27	Reinspection Photo	1	Load JPG	☒
169	29/07/19 16:27	Reinspection Photo	1	Load JPG	☒
170	29/07/19 16:27	Reinspection Photo	1	Load JPG	☒
171	29/07/19 16:27	Reinspection Photo	1	Load JPG	☒
172	29/07/19 16:27	Reinspection Photo	1	Load JPG	☒
173	29/07/19 16:27	Reinspection Photo	1	Load JPG	☒
174	29/07/19 16:27	Reinspection Photo	1	Load JPG	☒
175	29/07/19 16:27	Reinspection Photo	1	Load JPG	☒
176	29/07/19 16:27	Reinspection Photo	1	Load JPG	☒

Video			1 per page	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
177	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
178	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
179	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
180	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
181	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
182	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
183	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
184	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
185	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
186	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
187	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
188	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
189	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
190	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
191	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
192	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
193	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
194	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
195	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
196	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
197	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
198	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
199	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
200	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
201	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
202	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
203	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
204	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
205	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
206	29/07/19 16:27	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/05/19 18:01	TP GIA REPORT	 Load PDF	
2	18/09/19 10:37	LOD AND OTHER DOCUMENTS	 Load PDF	
3	08/10/19 16:14	LTA SEARCH	 Load PDF	
4	08/10/19 16:14	RENTAL RECEIPT	 Load PDF	
5	08/10/19 16:14	TOWING FEE	 Load PDF	
6	12/02/20 12:09	Authorisation to Act	 Load PDF	
7	12/02/20 12:09	DISCHARGE VOUCHER	 Load PDF	
8	12/02/20 12:09	WORKSHOP INVOICE	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	10/05/19 08:53	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19008248/AGS3S2

Date: 12/02/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: MCOM0015

Claimant Vehicle No: GBH1983R

Insured Vehicle No: SHC8715H

Date of Loss: 07/05/2019

Nature of Claim: TP

Claim No: MCT19050186

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBH1983R

Make & Model: TOYOTA DYNA 1.5T, 3.0 (A)

Engine No: 1KD2768707

Reg. Date: 09/03/2018 (Man. Year: 2017)

Chassis No: JTFAT35Y70K209646

Colour: Silver

Odometer: 69056 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 155 R12C

Front Left Side: OHTSU 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: OHTSU 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,571.75	18,851.22	19,720.53	51.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,560.00	4,960.00	4,600.00	48.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	48,131.75	23,811.22	24,320.53	50.53
Approved Total (Overridden) (S\$)		18,000.00		
Nett Amount (S\$)	48,131.75	18,000.00	30,131.75	62.60
+ Car Rental (14.0 x S\$85.60/day) (S\$)		1,198.40		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		100.00		
Nett Liability (S\$)		19,305.85		
Global Sum Settlement (S\$)		19,200.00		

INSPECTION

Date of Assignment: 09/05/2019

Date Inspected: 09/05/2019 Inspected At:

Premium Carz Services Pte Ltd (HQ)

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki

Singapore 417883

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Feb 2020)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH1983R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Distorted	2,250.00 FL	*1,645.00 FL
2	4		*TAIL GATE HINGES	Bent	342.40 FL	*342.40 FL
3	1		*TAIL GATE TOYOTA STICKER	Necessary	226.60 FL	*226.60 FL
4	1		*TAIL GATE DYNA STICKER	Necessary	46.50 FL	*46.50 FL
5	2		*TAIL GATE STOPPER	Not Necessary	243.20 FL	*- FL
6	1		*TAIL GATE STOPPER BRACKET RH	Bent	183.20 FL	*183.20 FL
7	1		*TAIL GATE STOPPER BRACKET LH	Bent	183.20 FL	*183.20 FL
8	1		*TAIL GATE LOCK RH	Not Necessary	154.30 FL	*- FL
9	1		*TAIL GATE LOCK LH	Not Necessary	154.30 FL	*- FL
10	1		*LOWER LEVER LOCK RH	Distorted	264.20 FL	*264.20 FL
11	1		*LOWER LEVER LOCK LH	Distorted	264.20 FL	*264.20 FL
12	1		*TOW HOOK	Not Necessary	242.00 FL	*- FL
13	1		*TAIL LAMP RH	Smashed	334.20 FL	*291.00 FL
14	1		*TAIL LAMP LH	Smashed	334.20 FL	*291.00 FL
15	1		*TAIL LAMP BRACKET RH	Distorted	109.80 FL	*109.80 FL
16	1		*TAIL LAMP BRACKET LH	Distorted	109.80 FL	*109.80 FL
17	1		*REAR NUMBER PLATE LAMP	Smashed	57.20 FL	*57.20 FL
18	1		*REAR NUMBER PLATE BASE	Bent	65.00 FL	*65.00 FL
19	1		*REAR FENDER RH	Not Necessary	180.00 FL	*- FL
20	1		*REAR FENDER LH	Buckled	180.00 FL	*180.00 FL
21	1		*REAR MUDFLAP RH	Not Necessary	98.00 FL	*- FL
22	1		*REAR MUDFLAP LH	Not Necessary	98.00 FL	*- FL
23	1		*EXHAUST TAIL PIPE	Bent	594.80 FL	*594.80 FL
24	1		*EXHAUST CENTRE PIPE	Bent	971.20 FL	*971.20 FL
25	2		*EXHAUST MOUNTING	Torn	116.00 FL	*116.00 FL
26	2		*EXHAUST BRACKET	Bent	196.00 FL	*196.00 FL
27	1		*FRONT EXHAUST COVER	Not Necessary	78.00 FL	*- FL
28	1		*SPARE TYRE BRACKET	Not Necessary	252.50 FL	*- FL
29	1		*SPARE TYRE RETAINER	Damaged	352.50 FL	*352.50 FL
30	1		*REAR PROPELLAR SHAFT	Not Necessary	1,860.00 FL	*- FL
31	2		*REAR PROPELLAR SHAFT COUPLING		-	*- FL
32	1		*SPRING RH W/BUSH	Bent	1,541.00 FL	*1,541.00 FL
33	1		*SPRING LH W/BUSH	Bent	1,541.00 FL	*1,541.00 FL
34	4		*SPRING BRACKET	Bent	1,156.00 FL	*1,156.00 FL
35	1		*REAR AXLE	Bent	3,785.80 FL	*3,785.80 FL
36	2		*REAR AXLE SPRING BUSH	Damaged	136.00 FL	*136.00 FL
37	1		*BRAKE PIPE RH	Dented	183.10 FL	*183.10 FL
38	1		*REAR CHASSIS RH	Repair	7,152.00 FL	*- FL
39	1		*REAR CHASSIS LH	Repair	7,152.00 FL	*- FL
40	1		*SIDE GATE RH	Dented	1,550.00 FL	*1,550.00 FL
41	1		*SIDE GATE LH	Dented	1,550.00 FL	*1,550.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*GEARBOX (NPA)	Not Necessary	0.00 FL	*- FL
43	1		*DASHBOARD (NPA)	Not Necessary	0.00 FL	*- FL
44	1		*CABIN REAR PANEL (NPA)	Repair	0.00 FL	*- FL
45	1		*CABIN REAR PANEL WEATHERSTRIP	Not Necessary	181.00 FL	*- FL
46	1		*CABIN REAR PILLAR RH	Repair	1,392.00 FL	*- FL
47	1		*CABIN REAR PILLAR LH	Repair	1,392.00 FL	*- FL
48	1		*TOYOTA D-4D EMBLEM RH	Necessary	85.90 FL	*85.90 FL
49	1		*TOYOTA D-4D EMBLEM LH	Necessary	85.90 FL	*85.90 FL
50	1		*REAR CANOPY ASSEMBLY	Damaged	3,500.00 FS	*2,000.00 FS
51	1		*REAR DECK COMPLETE SET	Distorted	2,500.00 FS	*2,500.00 FS
52	1		*REAR NUMBER PLATE	Bent	35.00 FS	*35.00 FS
53	1		*BRAKE OIL	Necessary	80.00 FS	*40.00 FS
54	1		*GEAR OIL	Necessary	80.00 FS	*60.00 FS
55	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
56	1		*SPARE TYRE (195 75 15)	Cut	450.00 FS	*180.00 FS
57	1		*SPARE TYRE (155 12)	Cut	350.00 FS	*120.00 FS
58	2		*REAR TYRE INNER LH (155 12)	Not Necessary	700.00 FS	*- FS
59	2		*REAR RIM LH	Not Necessary	900.00 FS	*- FS
60	1		*TAIL LAMP RH BULB 6pcs	Smashed	30.00 FS	*10.00 FS
61	1		*FAULTY SIGN BOARD	Damaged	98.00 FS	*98.00 FS
62	1		*13 PAX STICKER	Necessary	15.00 FS	*15.00 FS
63	1		*70KM/H STICKER	Necessary	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	48,428.00	23,377.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	9,856.25	4,526.08
Total Parts (\$\$)	38,571.75	18,851.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING.	New	180.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS.	New	3,800.00	1,800.00
3	SPRAY PANTING ALL AFFECTED PARTS & AREAS.	New	2,600.00	1,800.00
4	TO REMOVE AND REFIT DASHBOARD TO FACILITATE REPAIR.	New	350.00	0.00
5	TO REMOVE AND REPLACE REAR CANOPY.	New	350.00	200.00
6	TO REMOVE AND REPLACE EXHAUST SILENCER.	New	280.00	160.00
7	TO REMOVE; DIAGNOSE AND INSTALL GEARBOX.	New	450.00	0.00
8	TO REMOVE AND REPLACE REAR CHASSIS.	New	550.00	550.00
9	TO CHECK WHEELS WITH COMPUTERIZED WHEEL ALIGNMENT.	New	120.00	80.00
10	TO REMOVE AND REPLACE REAR AXLE.	New	350.00	280.00
11	TO REMOVE AND REPLACE PROPELLER SHAFT, PROPELLER SHAFT COUPLING AND SPRINGS.	New	350.00	0.00
12	TO SPRAY ANTI-RUST UNDERCOAT.	New	180.00	60.00
Gross Labour Cost (S\$)			9,560.00	4,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >