



Your Ref: 17/18/18/VP00/253637

Date: 30th May 2019

Our Ref: CS1/LPC19008265/Jqd3s2

M/s Lonpac Insurance Bhd

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKH 1696M
INSURED VEHICLE: WSX 1154 ACCIDENT DATE: 17/01/2019**

We thank you for your instruction on 08/05/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKH 1696M from M/s HM Motor Appraisal.
- b) Polis Diraja Malaysia Statement of Vehicle SKH 1696M.
- c) Colour damaged vehicle photographs of SKH 1696M.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKH 1696M
Make & Model	: Toyota Harrier 2.4 A
Year of Registration	: 2006
Chassis Number	: ACU300059404
Engine Capacity	: 2362 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.