

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0597/2019/TF
Date : 22-Jan-19

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd ✓

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Wan Wei Hwang
Address : 28 Jalan Datoh
#07-10
: Singapore 329426
Telephone : 94516500
Type of Claim : Own damage Claim
Policy No. : 2100495067-02
Vehicle No : **SLJ 7314 D** ✓
Model Code : Audi A3 SB 1.0 TFSI (A)
Model / Year : 22/12/2016
Engine No : CHZ136097
Chassis No : WAUZZZ8V4HA025195
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-May-19

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLJ 7314 D.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00	✓
2	To remove and transfer rear lid's convenience lock system, wire harness for tail lights and rear wiper assy.	S/N \$ 480.00	✗
3	To renew rear windscreen	S/N \$ 480.00	✗
4	To dismantle and renew rear bumper and rear lid. To inspect rhs rear fender and rhs tail lamp panel for further damages. Re-organise rear crash management components. Reinstall all parts removed. ✓	\$ 2,100.00	500
5	To respray rear bumper, rear lid and rhs rear fender. ✓	\$ 2,700.00	1100
6	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 3,340.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 7314 D

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	REAR BUMPER <i>torn</i>	\$1,708.00	✓
2	REAR BUMPER STICKY PAD <i>new</i>	\$11.00	+
3	REAR BUMPER FIXING PARTS <i>new</i>	\$175.00	+
4	REAR BUMPER LOCKING MECHANISM - LH / RH <i>new</i>	\$24.00	+
5	REAR BUMPER ADAPTER - LH / RH <i>new</i>	\$68.00	+
6	REAR BUMPER SPOILER <i>new</i>	\$216.00	+
7	REAR BUMPER REFLECTOR - RH <i>new</i>	\$27.00	+
8	REAR BUMPER REINFORCEMENT	\$522.00	+
9	REAR BUMPER BRACKET - LH / RH	\$51.00	+
10	REAR BUMPER GUIDE SECTION - RH	\$60.00	+
11	REAR BUMPER SENSOR	\$462.00	+
12	REAR BUMPER SENSOR SEAL RING	\$12.00	+
13	REAR LID <i>Repair</i>	\$1,864.00	+
14	REAR LID ATTACHMENT PARTS	\$267.00	+
15	REAR LID GASKET	\$185.00	+
16	REAR LID LOCK	\$164.00	+
17	REAR LID FLAP COVER	\$7.00	+
18	REAR LID ADHESIVE <i>new</i>	\$18.00	✓
19	AUDI EMBLEM	\$113.00	✓
20	A3 EMBLEM	\$87.00	✓

SUB TOTAL SPARE PARTS CHARGES

\$6,041.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 7314 D

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	TFSI EMBLEM <i>Net</i>	\$87.00	✓
22	REAR WINDOW <i>Net</i>	\$742.00	✗
23	PRIMER <i>Net</i>	\$38.00	+
24	REAR LID SPOILER ATTACHMENT PARTS <i>Net</i>	\$152.00	+
25	REAR LID LAMP - RH OUTER	\$800.00	✓
26	REAR LID LAMP - RH INNER } <i>included</i>	\$800.00	✓
27	REAR NO. PLATE <i>Net</i>	\$40.00	✗
28	REAR WINDSCREEN SEALANT <i>Net</i>	\$200.00	✗
29	SUNDRIES ?	\$600.00	?
TOTAL SPARE PARTS CHARGES		\$9,500.00	
TOTAL LABOUR CHARGES		\$ 3,340.00	
GRAND TOTAL		\$12,840.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adrian Ling
: 09/05/19.
:
:
:
:
: Authorised Repairs, 04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant