

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0585/2019/DY/TF
Date : 7-May-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Leong Tuck Fook
Address : Blk 332 Tampines Street 32
#09-548
Singapore 520332
Telephone : HP +65 9012 5818
Type of Claim : Own Damage Claims
Policy No. : 2100510352-01
Vehicle No : **SDY 6818 P**
Model Code : Audi A5 SportBack 2.0 TFS
Model / Year : Jun-17
Engine No : CVK 034720
Chassis No : WAUZZZF55HA033826
Mileage : -
Date In : 7-May-19
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 7-May-19
Place of Accident : Along Clemenceau Ave North Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDY 6818 P

S/N	Nature of Jobs	Estimated Charges	
1	To tow and recover vehicle from scene of accident.	S/N	AIG
2	To carry out first measurement test on car o-liner	S/N	\$ 800.00 ?
3	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00 ✓
4	To remove and renew aircon condenser, charged air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$ 1,200.00 ✓
5	To remove centre console, instrument panels and clusters. Renew dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining and both curtain air bags.	S/N	\$ 3,600.00 ✓
SUB-TOTAL LABOUR CHARGES		:	\$ <u>6,080.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

SDY 6818P

Estimated Labour Charges for Accident Vehicle SMD 8483 L

S/N	Nature of Jobs	Estimated Charges
6	To remove and reinstall engine assy with gearbox assy to facilitate car o-liner repairs.	S/N \$ 2,800.00 ?
7	To remove and reinstall front suspension assy with subframe to facilitate car o-liner repairs. Inspect for damages and renew if necessary.	S/N \$ 2,400.00 ?
8	To place vehicle on car o-liner.	S/N \$ 1,800.00 ?
9	To dismantle both front door panel trims. To remove and and reinstall both wing mirror assy.	S/N \$ 600.00 X
10	To dismantle and renew front bumper, bonnet, lhs front fender, both headlights. To repair lhs upper A-pillar. Cut out and reweld lhs fender support and closing element. Align both front chassis frames to specification of origin. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$ 11,600.00 4000 . without chassis Repairs.
SUB-TOTAL LABOUR CHARGES		: \$ 25,280.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDY 6818 P

S/N	Nature of Jobs	Estimated Charges
11	To respray front bumper, both front fenders, bonnet, both upper A-pillar, hinges, engine compartment, lhs front fender top support and both front doors. To carry out joint sealant work and stone chip treatment.	4400 8 x 550 = 4400 \$ 9,500.00
12	To carry out wheel alignment.	S/N \$ 240.00 ?
13	To carry out diagnostic check.	S/N \$ 384.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>35,404.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDY 6818 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	\$ 2,073.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 368.00	✓
3	FRONT BUMPER GRILLE - CENTER <i>new</i>	\$ 178.00	x
4	FRONT BUMPER SECURING STRIP <i>new</i>	\$ 64.00	x
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 207.00	x
6	FRONT BUMPER SPOILER <i>new</i>	\$ 489.00	x
7	FRONT BUMPER AIR GUIDE - LH <i>Distorted</i>	\$ 56.00	✓
8	RADIATOR GRILLE <i>new</i>	\$ 2,131.00	✓
9	RADIATOR GRILLE SENSOR SUPPORT <i>new</i>	2 \$ 96.00	✓
10	RADIATOR GRILLE COVER - UPPER <i>new</i>	\$ 174.00	✓
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>LH Distorted</i>	\$ 862.00 431	✓
12	FRONT BUMPER CARRIER <i>new</i>	\$ 733.00	✓
13	FRONT BUMPER BRACKET - LH <i>new</i>	\$ 195.00	✓
14	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	\$ 33.00	✓
15	FOAM FILLER PIECE - LH / CENTRE <i>Distorted</i>	2 \$ 129.00	✓
16	FRONT BUMPER TOP COVER <i>new</i>	\$ 116.00	✓
17	CAUTION STICKER <i>3</i>	\$ 13.00	✓
18	A/C STICKER <i>1</i>	\$ 7.00	✓
19	LOCK CARRIER BRACKET <i>new</i>	\$ 125.00	✓
20	FRONT BUMPER SUPPORT - LH / RH <i>new</i>	\$ 52.00 26.52	✓
SUB-TOTAL SPARE PARTS		\$ 8,101.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDY 6818 P

		<u>Damage Parts & Prices</u>	
S/N	Parts Description	S/NETT	REMARKS
21	FRONT BUMPER SENSOR <i>Engd</i>	2 \$	462.00 ✓
22	FRONT BUMPER SENSOR SEAL RING <i>re</i>	\$	12.00 ✓
23	FRONT BUMPER WIRING SET ?	\$	470.00 ?
24	HORN - HIGH TONE <i>Engd</i>	\$	37.00 ✓
25	HORN BRACKET <i>Bent</i>	\$	26.00 ✓
26	FRONT FENDER - LH <i>Distorted</i>	\$	968.00 ✓
27	FRONT FENDER ATTACHMENT PART <i>re</i>	\$	48.00 ✓
28	FRONT FENDER CLOSING ELEMENT - LH ?	\$	68.00 ✓
29	FRONT FENDER BRACKET - LH <i>re</i>	\$	32.00 ✓
30	FRONT FENDER BRACE - LH	\$	107.00 ✓
31	FRONT FENDER DEFORMATION BRACKET - LH <i>Engd</i>	\$	45.00 ✓
32	FRONT WHEEL HOUSING LINER - LH <i>re</i>	\$	256.00 ✓
33	FRONT WHEEL HOUSING LINER ATTACHMENT ?	\$	82.00 ?
34	FRONT WHEEL SPOILER - LH <i>cut</i>	\$	66.00 ✓
35	FRONT WHEEL SPOILER TRIM - LH <i>cut</i>	\$	32.00 ✓
36	FRONT FENDER STONE CHIP GUARD - LH <i>re</i>	\$	46.00 ✓
37	BONNET <i>Distorted</i>	\$	2,602.00 ✓
38	BONNET ATTACHMENT PARTS ?	\$	111.00 ?
39	BONNET IMPACT PROTECTION <i>re</i>	3 \$	75.00 ✓
40	BONNET SOUND ABSORBER ?	\$	311.00 ?
SUB-TOTAL SPARE PARTS		\$	5,856.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDY 6818 P

		<u>Damage Parts & Prices</u>	
S/N	Parts Description	S/NETT	REMARKS
41	FRONT FENDER TOP COVER - LH <i>lh</i>	\$ 32.00	✓
42	FRONT HEADLIGHT TOP COVER - LH <i>lh</i>	\$ 14.00	✓
43	FRONT FENDER COVER - LH <i>lh</i> ?	\$ 66.00	?
44	BONNET GAS FILLED STRUT ?	2 \$ 217.00	?
45	BONNET STRIKER - LH / RH ?	\$ 92.00	?
46	BONNET HINGE - LH / RH ?	\$ 762.00	?
47	BONNET LOCK <i>Joined</i>	2 \$ 391.00	✓
48	BONNET BOWDEN CABLE <i>Joined</i>	2 \$ 106.00	✓
49	BONNET BOWDEN CABLE COVER ?	\$ 9.00	?
50	BONNET RELEASE LEVER ?	\$ 12.00	?
51	BONNET LOCK CABLE ?	\$ 67.00	?
52	PLENUM CHAMBER COVER <i>new</i>	\$ 89.00	✓
53	HEADLIGHT - LH / RH <i>LH Smashed</i>	\$ 14,408.00 7204.	?
54	HEADLIGHT POWER MODULE - LH ?	\$ 693.00	?
55	HEADLIGHT CONTROL UNIT - LH ?	\$ 685.00	?
56	HEADLIGHT HEAT SINK - LH ?	\$ 1,053.00	?
57	HEADLIGHT VENTILATION HOSE - LH ?	\$ 32.00	?
58	HEADLIGHT LIFT CYLINDER - LH <i>Smashed</i>	\$ 181.00	✓
59	HEADLIGHT LIFT CYLINDER HOSE <i>cut</i>	2 \$ 113.00	✓
60	HEADLIGHT LIFT CYLINDER BRACKET - LH <i>Ref</i>	\$ 13.00	✓
SUB-TOTAL SPARE PARTS		\$ 19,035.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDY 6818 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	WATER RESERVOIR ?	\$ 130.00	?
62	WATER RESERVOIR PUMP ?	2 \$ 265.00	?
63	LOCK CARRIER <i>2nd</i>	\$ 928.00	✓
64	A/C CONDENSER ?	TBC	?
65	REFRIGERANT LINE ?	3 \$ 688.00	?
66	RADIATOR ?	\$ 676.00	?
67	COOLANT <i>me</i>	\$ 84.00	✓
68	INTERCOOLER ?	\$ 535.00	?
69	INTER COOLAR PRESSURE PIPE ?	TBC	?
70	RADIATOR FAN ?	\$ 242.00	?
71	RADIATOR FAN CONTROL UNIT ?	\$ 2,107.00	?
72	LOCK CARRIER AIR GUIDE - LH / UPPER / LOWER ?	4 \$ 77.00	?
73	INTAKE AIR DUCT ?	\$ 19.00	?
74	INTAKE AIR DUCT GUIDE ?	\$ 48.00	?
75	INTAKE AIR DUCT HOSE ?	\$ 85.00	?
76	AIR MASS METER ?	\$ 533.00	?
77	AIR FILTER ?	\$ 339.00	?
78	FRONT CONNECTING PLATE - LH ?	\$ 337.00	?
79	FRONT FENDER CORNER CHROME TRIM - LH / RH <i>me</i>	\$ 290.00	✓
80	FRONT DOOR CORNER CHROME TRIM - LH / RH <i>2nd</i>	\$ 290.00	145
SUB-TOTAL SPARE PARTS		\$ 7,673.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDY 6818 P

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
81	ROOF MOLDING CHROME - LH / RH <i>see in</i>	\$ 1,148.00	X
82	FRONT DOOR WINDOW SLOW SEAL CHROME - LH / RH <i>see in</i>	\$ 728.00	X
83	STEERING WHEEL AIR BAG	\$ 3,384.00	✓
84	AIRBAG - PASSENGER SIDE	\$ 4,019.00	✓
85	HEAD AIRBAG - LH / RH	\$ 3,416.00	✓
86	AIRBAG CONTROL UNIT	\$ 1,927.00	✓
87	AIR BAG CRASH SENSOR - FRONT	\$ 1,145.00	✓
88	BATTERY CENTRAL FUSE PROTECTION	\$ 485.00	✓
89	FRONT SEAL BELT - LH / RH	\$ 2,010.00	✓
90	FRONT SEAL BELT HEAD ADJUSTER ?	2 \$ 322.00	?
91	STEERING WHEEL ?	\$ 2,169.00	?
92	DASHBOARD <i>torn</i>	\$ 4,838.00	✓
93	AIRCOND AIR VENT ?	\$ 153.00	?
94	AIRCOND AIR VENT FOR WINDSCREEN ?	\$ 113.00	?
95	ROOF LINER <i>crumpled.</i>	\$ 1,872.00	✓
96	A PILLAR TRIM <i>behind</i>	2 \$ 374.00	✓
97	LH HANDLE - FRONT / REAR ?	\$ 258.00	?
98	RH HANDLE - REAR ?	\$ 129.00	?
99	FRONT NO. PLATE <i>new</i>	\$ 40.00	✓
100	ACYLIC SEALANT ?	\$ 180.00	?
101	CRAVITY WAX ?	\$ 140.00	?
102	STONE CHIP TREATMENT ?	\$ 180.00	?
103	SUNDRIES ?	\$ 1,500.00	?
TOTAL SPARE PARTS		\$ 71,195.00	
TOTAL LABOUR CHARGES		\$ 35,404.00	
GRAND TOTAL		\$ 106,599.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 05/05/190
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 21 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant