

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 10 May 2019

Preliminary Advice

Vehicle No	: SDY6818P	Accident Date	: 07/05/2019
Make	: AUDI A5	Policy No.	: 2100510352-01
Assignment Date	: 10/05/2019	Excess	: S\$0.00
Date of Inspection	: 09/05/2019	Est. Duration of Repair	: 21.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	106,599.00
Revised Amount	:S\$	58,689.00
Check Items (Estimated)	:S\$	23,927.00
Total	:S\$	82,616.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	200,000.00
Pre-Accident Value	:S\$	150,000.00
COE / PARF Rebate	:S\$	70,257.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	129,743.00
Margin for Repair (Pre-Accident Value)	:S\$	79,743.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please take note on the margin for Repair New for Old and Pre-Accident Value. Kindly advised.