

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699


Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. PA/OD/0585/2019/DY/TF Date 27-May-19 Service Advisor Chang Pages 1 of 1 Regn No SDY 6818 P Model No Audi A5 SportBack 2.0 TFSI	
Quantity	Description	Unit Price	Amount
Parts			
1	FRONT LOCK CARRIER AIR GUIDE - LH OUTER	\$ 15.00	de ✓
2	FAN RING	\$ 242.00	cus ✓
3	RADIATOR RUBBER BUSH SET	\$ 41.00	fis ✓
4	FRONT FENDER BRACKET - LH REAR	\$ 53.00	ht ✓
5	BONNET BUNGS	\$ 37.00	ms ✓
6	RADIATOR SUPPORT - LH/RH	\$ 69.00	dis ✓
7	OUTER TEMP. SENSOR BRACKET	\$ 17.00	cus ✓
8	FRONT LOCK CARRIER AIR GUIDE - LH INNER	\$ 28.00	de ✓
9	HEADLIGHT WASHER CYLINDER - RH	\$ 181.00	cus ✓
Total parts :		\$ 683.00	
LABORS			
Total labours :		\$ -	
Grand total :		\$ 683.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0585/2019/DY/TF 14-Jun-19 George Wong 1 of 1 SDY 6818 P Audi A5 SportBack 2.0 TFSI
Quantity	Description	Unit Price	Amount
LABORS	TO SUPPLY& INSTALL FRONT WINDSCREEN SOLAR FILM (3M) <i>scr 2</i>	\$ 400.00	
	Total labours :	\$ 400.00	
	Grand total :	\$ 400.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling
PL
14/06/19