

15/02/2010

INS. CASE OWNER:

CC 4/EG1900 8299, 28/6/10

LJK:
IDAC:

Surveyor:

Mh

DOI:

ASSIGNMENT

10/05/10

Date / Time:

9/5/10

Registered in Merit:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GDD 7787D

Claim No.:

Name of Insured:

HIS INTERSECURE SOLUTIONS (S) P/L

Policy No.:

DMC61A007891

Insured Tel No.:

HP:

Make / Model:

ALISAN

Excess Sec II :SS

D.O.A.:

8/5/10

Place of Accident:

BDFIC WITH KO TMS

Is driver the owner?

(YES / NO)

Nature of Accident:

BANKLEY KO BMS

If NO, Driver Name / Age: VOW THUMM HIE

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

% Final ? Yes / No

SEQ 88703

INSRS:
WSP:
Tel:
Liability:
RMKS:mh
solutionINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time:

SEQ 88703 - 2

GDD 7787D - 4

28/5

Email Steve to ask for OI AVF if any.
Validity unclear send to TP ask for AVF as OI
Validated that AVF is what TP w/c.

29-08-10

FILE PASS TO TP/TP TO PREPARE REPORT.

STAGE

DATE / PIC

Non-Reporting hr (1st)

Non-Reporting hr (2nd)

Non-Reporting hr (Final)

Notification hr (if non-pickup):

Call OI

29/08/10

After call hr to OI

Documentation Check List: Handler Typist

Notification hr (if non-pickup)

After call hr to OI

Authorisation To Act

Release Voucher: (NO NEED)

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GIA

Medical Bill

PDR

Mandate/Reject Instruction

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

Confirm by: LJK

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

45

SS 11,050

6 days Reduction:

49

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with SA

WONG

Email

Call

Final Liability:

10/100

SS 11,823.50

(Agreed / Assessed) BOLA S/N No.:

31

If NO or B 28, Ass. Lia:

Repair Cost:

10/100

SS 11,823.50

O/D REPAIR ENDED TP

Loss of Rental (LOR):

SS 1,240.00

9 days x 140

Loss of Use (LOU):

SS -

(5 x days)

Loss of Income (LOI):

SS -

(5 x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOU ☐

(Tick only one)

GIA/LTA Search

SS 7.45

Medical:

SS -

Disbursement:

SS 100.00

(e.g. Tow/ Independent)

Legal Cost:

SS -

Total:

SS 13,190.95

Global Sum SS: 13,190

FINAL PAYMENT

Date/Time:

Confirm with SA

WONG

Email

Call

Payee 1:

SS 13,190.00

Name 1:

MH SOLUTION PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
15/10/10

REF: ERGD

9

ASSIGNMENT

From: _____ Date: 10.5.19

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKQ 8830Z

at Workshop m/s MG Solution

of 23 Kaki Bukit Ave 4 (South wing) #02-08

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS "up"

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKQ8830Z Vi Regn: 2014 March

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 420i Coupe. cc 1997

Colour: Brown. A/C: Insured / Std / NI / NA

Sp. Reading: 65951 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA3N12040F994681

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/30R19.

R: 275/30R19.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 06 mm R/Bal: 06 mm

L/Bal: 06 mm L/Bal: 06 mm

D.O.A: _____ D.O.I: 10/05/19.

Survey held at: MG Solution.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: TP Ego.

43: + 4,050 (RED: + 10,399.91 49%)

MV: 100k.

PV: 75.6k

Nett: 24.4k

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) \$ + R5. 50

) Photos

) Others

)

(TOTAL)

Report Format :

* Lump Sum / L.B.J: (\$

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing)#02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO : ERGO DATE : 8-May-19
ATTENTION : MOTOR CLAIMS DEPT JOB TYPE : T/P CLAIM
ESTIMATE REPORT :

VEHICLE DETAILS

VEHICLE NO : SKQ8830Z
MODEL : B.M.W. 420i
CHASSIS NO

Cecilia

ACCIDENT DETAILS DATE : 8-May-19
TIME : 07:40HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>Dented</i>	1	\$ 2,320.50	\$ 2,320.50 ✓
2	BOOT LID LOGO <i>see</i>	1	\$ 103.00	\$ 103.00 ✓
3	BOOT LID TOP LOCK <i>Dangd</i>	1	\$ 380.00	\$ 380.00 ✓
4	BOOTLID DETECTOR <i>Dangd</i>	1	\$ 280.00	\$ 280.00 ✓
5	BOOT LID REFLECTOR <i>cracked</i>	2	\$ 520.00	\$ 1,040.00 ✓
6	BOOT LID WEATHERSTRIP <i>see</i>	1	\$ 280.00	\$ 280.00 ✓
7	REAR SMART OPENER HOUSING <i>Dangd</i>	1	\$ 320.00	\$ 320.00 ✓
8	REAR SMART OPENER ASSY <i>Dangd</i>	1	\$ 680.00	\$ 680.00 ✓
9	REAR SMART OPPENER SENSOR TOP <i>Dangd</i>	1	\$ 130.00	\$ 130.00 ✓
10	REAR SMART OPPENER SENSOR LOWER	1	\$ 130.00	\$ 130.00 ✓
11	REAR BUMPER <i>Disturbed</i>	1	\$ 1,655.80	\$ 1,655.80 ✓
12	REAR BUMPER SIDE RETAINER <i>see</i>	2	\$ 195.00	\$ 390.00 ✓
13	REAR BUMPER REFLECTOR <i>cracked</i>	2	\$ 150.00	\$ 300.00 ✓
14	REAR BUMPER TOW HOOK COVER <i>missing</i>	1	\$ 80.00	\$ 80.00 ✓
15	REAR BUMPER BEAM <i>cracked</i>	1	\$ 430.00	\$ 430.00 ✓ 225
16	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 715.00	\$ 715.00 ✓
17	REAR BUMPER REINFORCEMENT COVER <i>cracked</i>	1	\$ 69.00	\$ 69.00 ✓
18	REAR BUMPER SENSOR <i>2 pieces dangd</i>	4	\$ 240.00	\$ 960.00 ✓ 480
19	REAR BUMPER SENSOR HOLDER <i>2 pieces see</i>	4	\$ 60.00	\$ 240.00 ✓ 60

Rear Bumper side under cover 95 ✓
cracked

20	REAR BUMPER SENSOR WIRE HARNESS <i>scraped in</i>	1	\$ 220.00	\$ 220.00	✓
21	TAIL LAMP <i>cracked</i>	2	\$ 640.00	\$ 1,280.00	✓
22	REAR END PANEL <i>Repair</i>	1	\$ 820.00	\$ 820.00	✓
23	REAR END PANEL TOP GARNISH <i>cracked</i>	1	\$ 230.00	\$ 230.00	✓
24	EXHAUST PIPE INSULATION <i>cracked</i>	1	\$ 380.00	\$ 380.00	✓

1162330
10460-97

TOTAL PRICE \$ 13,433.30
LESS 10% \$ 1,343.33
SUB TOTAL PRICE \$ 12,089.97

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>cracked</i>	1	\$ 50.00	\$ 50.00	✓
2	BOOTLID SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	✓
3	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
4	REAR BUMPER LOWER LID <i>cracked</i>	1	\$ 850.00	\$ 850.00	650
5	TAIL LAMP CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
6	REAR END PANEL TOP GARNISH (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	✓
7	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	✓
8	EXHAUST PIPE <i>Repair</i>	1	\$ 4,500.00	\$ 4,500.00	✓
9	COATING <i>new</i>	1	\$ 850.00	\$ 850.00	400

1140

TOTAL \$ 6,550.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	700.	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	750	
3	TUFF COAT	\$ 250.00	x	
4	WIRING CHECK	\$ 150.00	30	
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00	60.	
6	REMOVE AND REFIX EXHAUST PIPE	\$ 280.00	100.	
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 220.00	100.	

1740

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing)#02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO : ERGO DATE : 8-May-19
ATTENTION : MOTOR CLAIMS DEPT JOB TYPE : T/P CLAIM
ESTIMATE REPORT :

VEHICLE DETAILS

VEHICLE NO : SKQ8830Z
MODEL : B.M.W. 420i
CHASSIS NO

ACCIDENT DETAILS DATE : 8-May-19
TIME : 07:40HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID LOCK WITH REVERSE CAMERA	1	\$ 550.00	\$ 550.00

Ang

550

495

ABSOLUST CARCARE LLP
5 Soon Lee Street, #04-17
Pioneer Point, Singapore 627607
UEN: T17LL0242F
HP: +65 8363 8893

CASH SALE

No. 7390

Sold to: JOEL KOO SKQ88307

Date: 23 MARCH 2019

Item	Quantity	Description	Unit Price	Amount
1.	ONE	QUARTZ UK30 + TAC SYSTEM TOP COAT PACKAGE		SGD850/-
* FREE	ONE SESSION	OF COATING MAINTENANCE.		
* WARRANTY	ONE YEAR	AGAINST COATING FADE.		
REMARK: 1) ADVISE TO WASH REGULARLY TO AVOID WATER SPOT.				

E. & O. E.

Sub Total :

~~GST Tax~~ :

Total :

SGD850/-

Received by:

Issued by:

CROWN

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8349Z
Vehicle Details	
Vehicle No.:	SKQ8830Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 May 2019
Vehicle Make:	B.M.W.
Vehicle Model:	420i COUPE AT D/AB SR HID NAV
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	A2600685N20B20B
Chassis No.:	WBA3N12040F994681
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$45,054.00
Original Registration Date:	31 Mar 2014
First Registration Date:	31 Mar 2014
Transfer Count:	1
Actual ARF Paid:	\$50,076.00
Intended PARF/COE Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Mar 2024
PARF Rebate Amount:	\$35,053.00
Intended COE Details	
COE Expiry Date:	30 Mar 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$82,900.00
COE Rebate Amount:	\$40,514.00
Total Rebate Amount:	\$75,567.00

The information contained herein is correct as at 10 May 2019

OK

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

 Post an Ad  Advertiser Login  Ways of Selling

May 2015 Mercedes-Benz C-Class C180 Avantgarde



Cheapest C180 In Market! 1
Owner, Full Servicing By C&C
Near New Car Condition!
Addition of Service StarAd

Lake View
Credit Pte Ltd

view our cars

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category

Save Search

Print

Sort by Date Posted

20 results/page

3 vehicles

Search

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

bmw 420

Any

Any

2014

Any

Any

Any

Available



☐ BMW 4 Series 420i Coupe
Sport

\$104,800

\$16,070 /yr

15-Apr-2014

1,997 cc

70,000 km

Sports

Available

Head Turner Sporty 420i Coupe Sport! Class Of It Own, PML Full Serviced History! 100% Original And All Round Superb Condition. High Loan/Trade In Available! Call Now To View And Make Us A Offer Before...

☆ Posted: 09-May-2015 Tags: 2014 BMW 420i, 2014 BMW 420i, BMW 420i, BMW 420i, BMW 420i, Used BMW



☐ BMW 4 Series 420i Coupe
sport

\$105,800

\$15,850 /yr

26-Jun-2014

1,997 cc

65,000 km

Sports

Available

1 Owner. We Are Open! Accident-Free. Reliable, Efficient, Immaculate Condition! Loan Available! Warranty And Servicing Package Will Be Provided. Call Now For Viewing.

☆ Posted: 28-Apr-2015 Tags: 2014 BMW 420i, 2014 BMW 420i, BMW 420i, BMW 420i, BMW 420i, Used BMW



☐ BMW 4 Series 420i Gran
Coupe

\$114,800

\$16,930 /yr

27-Aug-2014

1,997 cc

60,000 km

Luxury

Available

5 Years/200,000Km Warranty & 5 Years/100,000Km Free Servicing By Agent PML. Free Titan X! Beautiful Kalahari Beige Metallic Paintwork And Dakota Leather Interior! Trade In Available, View The Car At D...

Supreme Cars Pte Ltd

☆ Posted: 05-May-2015 Tags: 2014 BMW 420i, 2014 BMW 420i, BMW 420i, BMW 420i, BMW 420i, Used BMW

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired Ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars. Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, station cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to CTE cars & CPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used bmw 420i, bmw 420i Singapore, used bmw 420i Singapore, used bmw 420i, used vehicles Singapore or even buy used bmw 420i Singapore. We have now car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, travel, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com


[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Nivitha (LKK Auto)

From: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>
Sent: Thursday, 9 May 2019 2:14 PM
To: admin-d@lkkauto.com
Cc: sur@lkkauto.com; Jeannie Cheng; Tracy Tan; Survey Report (ERGO Insurance Pte. Ltd.)
Subject: FW: PRS IRO SKQ8830Z | OI : GBD7383D | DOA: 08/05/2019| ERGO REF: CDMCG19000869/SL/jc
Attachments: PRI for SKQ8830Z.PDF; GBD7383D OI.PDF

p: Sharon
T: 3:10 PM
V: in
E: ✓

Hi LKK,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company (**Adrian Ling**) to be the "Single Joint Expert".

Please conduct this survey request on without prejudice basis and try to finalize with the repairer on the repairs. Their client's vehicle can be surveyed at the location as stated in the email below.
(Note: No repair estimate was provided to us)

Attached are the necessary documents for your further actions.

Kindly acknowledge receipt of this email.

(Please assist to quote our ref as the subject matter, when forwarding the Preliminary Reports / Survey Reports.)

Thank you.

Warmest Regards,
Jeannie Cheng
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID: +65 6829 9199 x 194
jeannie.cheng@ergo.com.sg

www.ergo.com.sg

ERGO

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Sharon [mailto:mg3solution@gmail.com]
Sent: Thursday, May 09, 2019 9:47 AM
To: ERGO Insurance Pte. Ltd. (Claims Department); Steve Lim
Subject: OUR Ref: SKQ8830Z-(PRE-INSPECTION) ; YOUR REF : GBD7383D -DOA ON 08/05/2019

Dear Person In Charge,

Please refer to attach file and arrange for pre-inspection.

we prefer our single joint expert as below:

ADRIAN LING WAI PING	LKK AUTO CONSULTANTS PTE LTD
----------------------	------------------------------

Thank You.

Best Regards,
Sharon Chia

MG SOLUTION PTE LTD
23 Kaki Bukit Avenue 4 (South Wing)
#02-03B Vicom Inspection Centre
Singapore 415933
Tel : 6744 4165
Fax : 6744 4604



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s ERGO INSURANCE PTE LTD

Date: 15/11/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GBD 7383D (Insd Veh)	Your Ref. No. : DMCG19002391
	SKQ 8830Z (TP Veh)	Our Ref. No. : CC4/EG19008299/Aeb3q2
Date of Accident	08/05/219	

Liability	100%	
Final Repair Cost	: \$ 11,823.50	
Loss of Use	: \$	days
Rental (If any)	: \$ 1,260.00	9 days
Others:	: \$ 7.45	
Towing Fee	: \$ 100.00	
	13,190.95	
Final Settlement Sum	: \$ 13,190.00	GLOBAL SUM
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	MG SOLUTION PTE LTD	: \$ 13,190.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CC4/EG19008299/Aeb3q2	
5 TEMASEK BOULEVARD #04-05 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 15-11-2019	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 7383D	Veh. Inspected	SKQ 8830Z	
Policy No.	DMCG19002391	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	JEANNIE	Assign Date	09/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	BMW 420I COUPE	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WBA3N12040F994681	Colour	BROWN	
Odometer	65951	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/30 R19	MICHELIN	6 mm	
L/H Front Tyre	275/30 R19	MICHELIN	6 mm	
R/H Rear Tyre	275/30 R19	MICHELIN	6 mm	
L/H Rear Tyre	275/30 R19	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/05/2019	Inspection Date	10/05/2019	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 8830Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOT LID	DENTED	2,320.50	2,320.50
1	BOOT LID LOGO	NECESSARY	103.00	103.00
1	BOOT LID TOP LOCK	DAMAGED	380.00	380.00
1	BOOTLID DETECTOR	DAMAGED	280.00	280.00
2	BOOT LID REFLECTOR @\$520.00	CRACKED	1,040.00	1,040.00
1	BOOT LID WEATHERSTRIP	NECESSARY	280.00	280.00
1	REAR SMART OPENER HOUSING	DAMAGED	320.00	320.00
1	REAR SMART OPENER ASSY	DAMAGED	680.00	680.00
1	REAR SMART OPENER SENSOR TOP	DAMAGED	130.00	130.00
1	REAR SMART OPENER SENSOR LOWER	DAMAGED	130.00	130.00
1	REAR BUMPER	DISTORTED	1,655.80	1,655.80
2	REAR BUMPER SIDE RETAINER @\$195.00	NECESSARY	390.00	390.00
2	REAR BUMPER REFLECTOR @\$150.00	CRACKED	300.00	300.00
1	REAR BUMPER TOW HOOK COVER	MISSING	80.00	80.00
1	REAR BUMPER BEAM	CRACKED	430.00	225.00
1	REAR BUMPER REINFORCEMENT	BENT	715.00	715.00
1	REAR BUMPER REINFORCEMENT COVER	CRACKED	69.00	69.00
4	REAR BUMPER SENSOR @\$240.00	DAMAGED (2 PCS ONLY)	960.00	480.00
4	REAR BUMPER SENSOR HOLDER @\$60.00	NECESSARY (2 PCS ONLY)	240.00	60.00
1	REAR BUMPER SIDE UNDER COVER	CRACKED	95.00	95.00
1	REAR BUMPER SENSOR WIRE HARNESS	NOT NECESSARY	220.00	-
2	TAIL LAMP @\$640.00	CRACKED	1,280.00	1,280.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	820.00	-
1	REAR END PANEL TOP GARNISH	CRACKED	230.00	230.00
1	EXHAUST PIPE INSULATION	CRUMPLED	380.00	380.00
1	BOOT LID LOCK WITH REVERSE CAMERA (ADDITIONAL)	DAMAGED	550.00	550.00
	LESS 10% DISCOUNT		-1,407.83	-1,217.33
			12,670.47	10,955.97

Report Ref No. CC4/EGI19008299/Aeb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	CRACKED	50.00	50.00
1	BOOTLID SEALANT (SN)	NOT NECESSARY	80.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	20.00	20.00
1	REAR BUMPER LOWER LID (SN)	DISTORTED	850.00	650.00
1	SET TAIL LAMP CLIPS (SN)	NECESSARY	20.00	20.00
1	SET REAR END PANEL TOP GARNISH (SN)	NOT NECESSARY	30.00	-
1	REAR END PANEL INSULATION SEAL (SN)	NOT NECESSARY	150.00	-
1	EXHAUST PIPE (SN)	TO REPAIR SEE LABOUR	4,500.00	-
1	COATING (SN)	NECESSARY	850.00	400.00
			6,550.00	1,140.00
	<u>LABOUR</u>			
	PANEL BEATING ,REMOVING AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND EXHAUST PIPE .		1,400.00	700.00
	SPRAY PAINTING TO AFFECTED AREA.		1,400.00	750.00
	TUFF COAT.	NOT NECESSARY	250.00	-
	WIRING CHECK.		150.00	30.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		120.00	60.00
	REMOVE AD REFIX EXHAUST PIPE.		280.00	100.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC.		220.00	100.00
			3,820.00	1,740.00
	GRAND TOTAL		23,040.47	13,835.97
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			11,050.00

Report Ref No. CC4/EG19008299/Aeb3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.