

LKK
JELAC®

КСС

10	5119
----	------

अ/त/म

Registered in Merimen

Pre-assign / CCU / FTE



SDF 137k

Name of Insured

HEL THIEF LEAF WISDOM.

Insured Tel No. _____

1119

Excess Sec II :S5

D.O.A. 8/4/61

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age

Driver Tel. No. _____

(VAL: YES / NO)

DI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final? Yes / No

৬৪৬ ফাফাউ.



INSRS
WSP:
Tel :
Liabilit:
RMKS

Optima
WEBZ



INSRS:
WSP:
Tel :
Liability
RMKS:



INSRS:
WSP:
Tel :
Liability
RMKS:



INSRS:
WSP:
Tel :
Liability
RMKS:

Date/Time	STAGE	DATE / PIC
06/09/19	Non-Reporting Itr (1st)	
	Non-Reporting Itr (2nd)	
	Non-Reporting Itr (Final)	
	Notification Itr (if non-pickup)	
	Call OE	
	After call Itr to OE	
	Documentation Check List:	Handler Typist
	Notification Itr (if non-pickup)	☐ ☐
	After call Itr to OE	☐ ☐
	Authorisation To Act	☒ ☐
	Release Voucher	☒ ☐
	Final Repair Bill	☒ ☐
	Car Rental Invoice	☒ ☐
	Towing Invoice	☐ ☐
	LTA / GLA :	☒ ☐
	Medical Bill	☐ ☐
	PIR	☐ ☐
	Mandate/Reject Instruction	☒ ☐
	LOD	☒ ☐
	Payment Breakdown Form	☐ ☐
	Post-Repair Photos	☒ ☐
	Others	☐ ☐

FINALIZATION	Date/Time: 06-11-19	Confirm with: 06-11-19	Confirm by: RSC
Repair Cost: \$5,397.50	1	5 days Reduction: 24	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: 06-11-19	Confirm with: 06-11-19	Email ☒ Call ☐
Final Liability: \$0 (w) (Agreed / Assessed) BOLA S/N No.: 27	If NO or B 2R. Ass. Lia:		
Repair Cost: \$5,397.50			
Loss of Rental (LOR): \$5,397.50	1	6 days x 100	COPY SENT 6/11/19
Loss of Use (LOU): \$5 -	15	x days	
Loss of Income (LOI): \$5 -	15	x days	
LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LO ☐ (Tick only one)			
GIA/LTA Search	\$0.00		
Medical:	\$5 -	1) Claim status: Normal/Reject/Private Settle	
Disbursement:	\$5 -	(e.g. Tow/ Independent)	2) Report format: T
Legal Cost:	\$5 -	3) Survey fee: +450	
Total:	\$5,397.50	Global Sum \$5:	
FINAL PAYMENT	Date/Time: 06-11-19	Confirm with: 06-11-19	Email ☒ Call ☐
Payee 1: \$5,397.50	Name 1: OPTIMA KERRY PTE LTD		
Payee 2: (Strike if N.A.)	Name 2:		
Payee 3: (Strike if N.A.)	Name 3:		

From: Date: 10/5/19

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

GBG 74534
Optima works

at Workshop m/s

of 9A Serunian North Ave 5

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

10cm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days Res.: Yes or No

Lum Sum:

1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBG 74534 Regn: 10 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy (m) Proau cc 1997

Colour:

White A/C: Insured / Std / NI / NA

Sp. Reading:

43198 T/Radio: Insured / Std / NI / NA

Eng/No:

YARVFAHKG Z 068896

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215/65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

7 mm

R/Bal.

7 mm

L/Bal.

7 mm

L/Bal.

7 mm

D.O.A.

8/5/19

D.O.I.

10/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

PP: 3,997.50 (Red: 6,296.81 24%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Inva (\$

☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC19008300/Kpb3

Date: 13.05.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GBG7453U

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 10.05.2019 at the premises of M/s Optima Werkz Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	3,067.28
Revised Estimate Amount	: S\$	2,677.28
"Check" Items Amount	: S\$	60.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Business

Owner ID:

0200C

Vehicle Details

Vehicle No:

GBG7453U

Vehicle to be Exported:

No

Intended Deregistration Date:

09 May 2019

Vehicle Make:

TOYOTA

Vehicle Model:

PROACE COMFORT MEDIUM 2.0M

Primary Colour:

White

Manufacturing Year:

2016

Engine No:

AH014011356

Chassis No:

YARVFAHKHGGZ068896

Maximum Power Output:

-

Open Market Value:

\$31,108.00

Original Registration Date:

20 Oct 2017

First Registration Date:

20 Oct 2017

Transfer Count:

0

Actual ARF Paid:

\$1,556.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

19 Oct 2027

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

PQP Paid:

\$36,356.00

COE Rebate Amount:

\$30,697.00

Total Rebate Amount:**\$30,697.00**

The information contained herein is correct as at 09 May 2019

OK

Date: 10.05.2019
Vehicle No: GBG7453M
Model: TOYOTA PROACE COMFORT 2.0M
Chassis: YARVFAHKGZ068896 - 2016
Reg Year: 2017

Third Party Insurer: LONPAC
Third Party Veh No: SDF137K
Date of Accident: 08.05.2019

Not Authorised
Assessing 84 points
5 days
83997.50

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1	L R	849.70
2	REAR TAILGATE EMBLEM 'TOYOTA'	1	PC	562.50
3	REAR TAILGATE EMBLEM 'PROACE'	1	PC	558.40
4	REAR TAILGATE EMBLEM LOGO	1	PC	565.00
5	REAR BUMPER	1	CM	5528.50
6	REAR BUMPER REFLECTOR LH	1	CM	5125.60
7	REAR END PANEL	1		REPAIR
SUB TOTAL				\$1,689.70
LESS 25%				5422.41
PARTS TOTAL				\$1,267.28

250.00
1594.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE STICKER '70 km/h'	1	PC	515.00
2	REAR TAILGATE STICKER '8 PAX'	1	PC	515.00
3	REAR TAILGATE WINDSCREEN SEALANT	1	PC	5100.00
4	REAR BUMPER CLIPS	1 SET	PC	560.00
5	REAR END PANEL JOINT SEALANT	1	PC	560.00
S/N TOTAL				\$250.00

X
X

LABOUR CHARGES:

LABOUR CHARGES FOR REMOVE, REPLACE & READJUST REAR ACCIDENT AREAS & ETC.
BACK TO ORIGINAL CONDITIONS

\$600.00

LABOUR CHARGES FOR SPRAY PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS
AT REAR ACCIDENT AREAS & ETC

\$700.00

LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE INNER TRIM PART & ETC.
BACK TO ORIGINAL CONDITIONS

\$200.00

LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE WINDSCREEN TO
PERFORM WATER LEAK TEST

\$150.00

LABOUR TOTAL \$1,550.00

FEITING TOTAL \$3,067.28

BRANCH OFFICE

5 Hong Chong Road Singapore 151142
Tel: (435) 6472 1818 Fax: (435) 6472 2112

BRANCH

88 Serangoon North Ave 5 Singapore 554597
Tel: (435) 6486 9919 Fax: (435) 6481 1811

BRANCH

357 Upper Thomson Road Singapore 574115
Tel: (435) 6432 6666 Fax: (435) 6432 9228



Date: 17.06.2019
Vehicle No: GBG7453M
Model: TOYOTA PROACE COMFORT 2.0M
Chassis: YARVFAHKHGX068896 - 2016
Reg. Year: 2017

Third Party Insurer: LQNPAC
Third Party Veh No: SDF137K
Date of Accident: 08.05.2019

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT \$S	AMOUNT \$S
1	REAR TAILGATE OUTER HANDLE GARNISH COVER	1		C/M \$169.00
2	REAR TAILGATE INNER TRIM	1		Pm \$495.00
3	REAR TAILGATE INNER TRIM CLIPS	8	\$5.80	wr \$46.40
4	REAR TAILGATE INNER LOCK	1		Tm \$162.50
5	REAR BUMPER REINFORCEMENT	1		Rf \$525.00
6	REAR BUMPER REINFORCEMENT INNER RETAINER GUIDE	1		C/R \$175.00
7	REAR QUARTER PANEL LINER LH	1		Jm \$98.00
8	REAR TAILGATE RUBBER	1		M/LC \$232.00
			SUB TOTAL	\$1,902.90
			LESS 25%	\$475.73
			PARTS TOTAL	\$1,427.17

ONE	TOTAL	\$1,427.18
-----	-------	------------

Date: 10.05.2019
 Vehicle No: GBG7453M
 Model: TOYOTA PROACE COMFORT 2.0M
 Chassis: YARVFAHKHGX068896 - 2016
 Reg.Year: 2017

Third Party Insurer: LONPAC
 Third Party Veh No: SDF137K
 Date of Accident: 08.05.2019

*Not withstanding
 Reserving 84 points*

ESTIMATE

5 days

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>Bz</i> \$849.70
2	REAR TAILGATE EMBLEM 'TOYOTA'	1		<i>Ne</i> ✓ \$62.50
3	REAR TAILGATE EMBLEM 'PROACE'	1		<i>Ne</i> ✓ \$18.40
4	REAR TAILGATE EMBLEM LOGO	1		<i>Ne</i> ✓ \$65.00
5	REAR BUMPER	1		<i>CM</i> \$528.50
6	REAR BUMPER REFLECTOR LH	1		<i>CM</i> \$125.60
7	REAR END PANEL	1		REPAIR
SUB TOTAL				\$1,689.70
LESS 25%				-\$422.43
PARTS TOTAL				\$1,267.28

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE STICKER '70 km/h'	1		<i>Ne</i> \$15.00
2	REAR TAILGATE STICKER '8 PAX'	1		<i>Ne</i> \$15.00
3	REAR TAILGATE WINDSCREEN SEALANT	1		<i>Ne</i> \$100.00
4	REAR BUMPER CLIPS	1 SET		<i>Ne</i> \$60.00
5	REAR END PANEL JOINT SEALANT	1		\$60.00
S/N TOTAL				\$250.00

LABOUR CHARGES:

LABOUR CHARGES FOR REMOVE, REPLACE & READJUST REAR ACCIDENT AREAS & ETC.
 BACK TO ORIGINAL CONDITIONS

\$600.00 *500*

LABOUR CHARGES FOR SPRAY PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS
 AT REAR ACCIDENT AREAS & ETC

\$700.00 *600*

LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE INNER TRIM PART & ETC.
 BACK TO ORIGINAL CONDITIONS

\$100.00 *60*

LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE WINDSCREEN TO
 PERFORM WATER LEAK TEST

\$150.00 *120*

LABOUR TOTAL \$1,550.00

PEI TING TOTAL \$3,067.28

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 8868 | Fax: (+65) 6452 9223



Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 9 May 2019 5:01 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: FW: PRI - GBG7453U CLAIM AGAINST SDF137K DOA: 08/05/2019 (LONPAC)
[External Confidential]
Attachments: GBG7453U GIA.pdf

9.09am @ 14/5/19
vehicle in
sharon
Kenefer.

Lonpac External - Confidential

Our Ref : 19/19/19/VP05/021771

Dear Nivitha,

Kindly proceed to survey as arranged.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Lily.loi@ow.sg [mailto:Lily.loi@ow.sg]
Sent: Thursday, 9 May, 2019 4:56 PM
To: MT_Claim_SG
Cc: 'Sharon'; angela.tan@ow.sg; 'puitheng.chong'; hockkong.ong@ow.sg
Subject: PRI - GBG7453U CLAIM AGAINST SDF137K DOA: 08/05/2019 (LONPAC)

Dear Officer,

Please arrange PRI on 10/05/2019, 10am at Serangoon branch.

Owner waiting.

Thank you.

--

Best Regards,

Lily Loi (Ms.)

Senior Claims Executive, Motor Claims Department

D: +65 6481 1522 | F: +65 6481 1011

OPTIMA WERKZ PTE. LTD.

Head office: 6 Kung Chong Road Singapore 159143

Branch: 9A Serangoon North Ave 5 Singapore 554500

Branch: 551 Upp Thomson Road Singapore 574415

Tel: (+65) 6472 1313

Tel: (+65) 6484 9919

Tel: (+65) 6452 8868

Fax: (+65) 6472 2112

Fax: (+65) 6481 1011

Fax: (+65) 6452 9223

www.ow.sg | www.facebook.com/OptimaWerkz

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, you must not copy, distribute or use it for any purpose, nor disclose its contents to any other person.

Please notify the sender if you receive this email in error, and delete the email and its content immediately after which,

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 14 May 2019 12:48 PM
To: Lily.loi@ow.sg
Cc: 'Sharon'; angela.tan@ow.sg; Admin A
Subject: RE: Check Liability - GBG7453U CLAIMING AGAINST SDF137K DOA: 08/05/19 (LONPAC) *LKK REF: CC4/LPC19008300/Kpb3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lily.loi@ow.sg <Lily.loi@ow.sg>
Sent: Monday, 13 May 2019 3:45 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: 'Sharon' <sharon@ow.sg>; angela.tan@ow.sg
Subject: Check Liability - GBG7453U CLAIMING AGAINST SDF137K DOA: 08/05/19 (LONPAC)

Dear Hsiao Tong,

We already conducted PRI on 10/05/2019.
Kindly advice on liability.
Thank you

--
Best Regards,

Lily Loi (Ms.)

Senior Claims Executive, Motor Claims Department
D: +65 6481 1522 | F: +65 6481 1011

OPTIMA//WERKZ PTE. LTD.

Head office: 8 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313

Fax: (+65) 6472 2112

Branch: 9A Serangoon North Ave 5 Singapore 554800

Tel: (+65) 6484 9919

Fax: (+65) 6481 1011

Branch: 551 Upp Thomson Road Singapore 574415

Tel: (+65) 6452 9868

Fax: (+65) 6452 9223

www.ow.sg | www.facebook.com/OptimaWerkz

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, you must not copy, distribute or use it for any purpose, nor disclose its contents to any other person.
Please notify the sender if you receive this email in error, and delete the email and its content immediately after which.

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Thursday, 10 October 2019 11:51 AM
To: ONG LI LI; GERALD POH WEE BIN
Cc: MT_Claim_SG
Subject: [MANDATE REQUEST] Your Ref: 19/19/19/VP05/021771, ACCIDENT INVOLVING SDF 137K (OI) AND GBG 7453U (TP) ON 08/05/2019
Attachments: TP LOD.pdf; LKK INSPECTION.pdf; LKK ADJUSTMENT.pdf; LKK SURVEY PHOTO.pdf; LKK RESURVEY PHOTO.pdf; LKK RESURVEY PHOTO 1.pdf

Your Ref: 19/19/19/VP05/021771

Dear Sirs,

We refer to the above matter.

ACCIDENT INVOLVING SDF 137K (OI) AND GBG 7453U (TP) ON 08/05/2019

We have highlighted to your good office on 10/05/2019 of Third-Party's request to do Direct Settlement with our Principal, Lonpac Insurance Bhd.

The accident occurred when our insured rear ended third party vehicle.

Basing on the reports of the circumstance of the accident, we propose to settle third-party claim at 100% liability.

Summary to offer to repairer **OPTIMA WERKZ PTE LTD** is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 5,664.91	\$ 4,277.32
2. Loss of Rental (7days x \$100)(w/GST)	\$ 749.00	\$ 749.00 (7days x \$100)
3. LTA/GIA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 6,415.91	\$ 5,028.32

**5 days recommendation for repair.

Relevant supporting claim documents are attached herewith for your perusal and reference.

The above is for your approval please.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC19008300/Keb3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 04-12-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDF 137K	Veh. Inspected	GBG 7453U	
Policy No.	Z19VP05023289	Coverage (\$)	0.00	
Claim No.	19/19/19/VP05/021771	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	09/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PROACE (M)	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	YARVFAHKHGZ068896	Colour	WHITE	
Odometer	43198	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/65 R16	CONTINENTAL	7 mm	
L/H Front Tyre	215/65 R16	CONTINENTAL	7 mm	
R/H Rear Tyre	215/65 R16	CONTINENTAL	7 mm	
L/H Rear Tyre	215/65 R16	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/05/2019	Inspection Date	10/05/2019	
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 7453U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE EMBLEM 'TOYOTA'	NECESSARY	62.50	62.50
1	REAR TAILGATE EMBLEM 'PROACE'	NECESSARY	58.40	58.40
1	REAR TAILGATE EMBLEM LOGO	NECESSARY	65.00	65.00
1	REAR BUMPER	CRACKED	1,594.99	1,594.99
1	REAR BUMPER REFLECTOR LH	CRACKED	125.60	125.60
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR TAILGATE OUTER HANDLE GARNISH COVER (ADDITIONAL)	CRACKED	169.00	169.00
1	REAR TAILGATE INNER TRIM (ADDITIONAL)	SERVICEABLE	495.00	-
8	REAR TAILGATE INNER TRIM CLIPS @\$5.80 (ADDITIONAL)	NOT NECESSARY	46.40	-
1	REAR TAILGATE INNER LOCK (ADDITIONAL)	JAMMED	162.50	162.50
1	REAR BUMPER REINFORCEMENT (ADDITIONAL)	BENT	525.00	525.00
1	REAR BUMPER REINFORCEMENT INNER RETAINER GUIDE (ADDITIONAL)	CRACKED	175.00	175.00
1	REAR QUARTER PANEL LINER LH (ADDITIONAL)	SERVICEABLE	98.00	-
1	REAR TAILGATE RUBBER (ADDITIONAL)	DENTED / CUT	232.00	232.00
	LESS 25% DISCOUNT		-952.35	-792.49
			2,857.04	2,377.50
1	REAR TAILGATE (LOCAL REPAIR) (SN)	BENT	849.70	250.00
	LESS 25% DISCOUNT		-212.43	-
			637.27	250.00
SPECIAL NETT ITEMS				
1	REAR TAILGATE STICKER '70KM/H' (SN)	NECESSARY	15.00	15.00
1	REAR TAILGATE STICKER '8 PAX' (SN)	NECESSARY	15.00	15.00
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NOT NECESSARY	100.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	60.00
1	REAR END PANEL JOINT SEALANT (SN)	NOT NECESSARY	60.00	-
			250.00	90.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	LABOUR CHARGES FOR REMOVE ,REPLACE & READJUST REAR ACCIDENT AREAS & ETC BACK TO ORIGINAL CONDITIONS.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		600.00	500.00
	LABOUR CHARGES FOR SPRAY PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREAS & ETC.		700.00	600.00
	LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE INNER TRIM PART & ETC.BACK TO ORIGINAL CONDITIONS.		100.00	60.00
	LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE WINDSCREEN TO PERFORM WATER LEAK TEST.		150.00	120.00
			1,550.00	1,280.00
	GRAND TOTAL		5,294.31	3,997.50
RECOMMENDED COST OF REPAIRS				3,997.50

Report Ref No. CC4/LPC19008300/Keb3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC19008300/Kpb3

Date: 13.05.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GBG7453U

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 10.05.2019 at the premises of M/s Optima Werkz Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	3,067.28
Revised Estimate Amount	: S\$	2,677.28
"Check" Items Amount	: S\$	60.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business
Owner ID: 0200C

Vehicle Details

Vehicle No.: GBG7453U
Vehicle to be Exported: No
Intended Deregistration Date: 09 May 2019
Vehicle Make: TOYOTA
Vehicle Model: PROACE COMFORT MEDIUM 2.0M
Primary Colour: White
Manufacturing Year: 2016
Engine No.: AH014011356
Chassis No.: YARVFAHKGZ068896
Maximum Power Output: -
Open Market Value: \$31,108.00
Original Registration Date: 20 Oct 2017
First Registration Date: 20 Oct 2017
Transfer Count: 0
Actual ARF Paid: \$1,556.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 19 Oct 2027
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
PQP Paid: \$36,356.00
COE Rebate Amount: \$30,697.00
Total Rebate Amount: \$30,697.00

The information contained herein is correct as at 09 May 2019

OK

Date: 10.05.2019
Vehicle No: GBG7453M
Model: TOYOTA PROACE COMFORT 2.0M
Chassis: YARVFAHKHGZ068896 - 2016
Reg Year: 2017

Third Party Insurer: LONPAC
Third Party Veh No: SDF137K
Date of Accident: 08.05.2019

Not Authorised
Assessing 84 points
83997.50
5 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1	L R 1504	\$849.70
2	REAR TAILGATE EMBLEM 'TOYOTA'	1	100	\$62.50
3	REAR TAILGATE EMBLEM 'PROACE'	1	100	\$58.40
4	REAR TAILGATE EMBLEM LOGO	1	100	\$65.00
5	REAR BUMPER	1	CM	\$528.50
6	REAR BUMPER REFLECTOR LH	1	CM	\$125.60
7	REAR END PANEL	1		REPAIR
SUB TOTAL				\$1,689.70
LESS 25%				\$422.41
PARTS TOTAL				\$1,267.28

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE STICKER '70 km/h'	1	100	\$15.00
2	REAR TAILGATE STICKER '8 PAX'	1	100	\$15.00
3	REAR TAILGATE WINDSCREEN SEALANT	1	100	\$100.00
4	REAR BUMPER CLIPS	1 SET	100	\$60.00
5	REAR END PANEL JOINT SEALANT	1	100	\$60.00
S/N TOTAL				\$250.00

LABOUR CHARGES:

LABOUR CHARGES FOR REMOVE, REPLACE & READJUST REAR ACCIDENT AREAS & ETC.
BACK TO ORIGINAL CONDITIONS

\$600.00

LABOUR CHARGES FOR SPRAY PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS
AT REAR ACCIDENT AREAS & ETC

\$700.00

LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE INNER TRIM PART & ETC
BACK TO ORIGINAL CONDITIONS

\$200.00

LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE WINDSCREEN TO
PERFORM WATER LEAK TEST

\$150.00

LABOUR TOTAL \$1,550.00

PEITING TOTAL \$3,067.28

HEAD OFFICE

1 Hong Kong Road Singapore 10142
Tel: (65) 6472 1818 Fax: (65) 6472 2112

BRANCH

8A Serangoon North Ave 5 Singapore 554880
Tel: (65) 6888 9919 Fax: (65) 6881 1811

BRANCH

881 Upper Thomson Road Singapore 574471
Tel: (65) 6452 8888 Fax: (65) 6452 8822



Date: 17.06.2019
Vehicle No: GBG7453M
Model: TOYOTA PROACE COMFORT 2.0M
Chassis: YARVFAHKHGZ068896 - 2016
Reg. Year: 2017

Third Party Insurer: LONPAC
Third Party Veh No: SDF137K
Date of Accident: 08.05.2019

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE OUTER HANDLE GARNISH COVER	1		CM \$169.00
2	REAR TAILGATE INNER TRIM	1		Sm \$495.00
3	REAR TAILGATE INNER TRIM CLIPS	8	\$5.80	nm \$46.40
4	REAR TAILGATE INNER LOCK	1		Tm \$162.50
5	REAR BUMPER REINFORCEMENT	1		Bz \$525.00
6	REAR BUMPER REINFORCEMENT INNER RETAINER GUIDE	1		CRZ \$175.00
7	REAR QUARTER PANEL LINER LH	1		Sm \$98.00
8	REAR TAILGATE RUBBER	1		Red/Gr \$232.00
SUB TOTAL				\$1,902.90
LESS 25%				\$475.73
PARTS TOTAL				\$1,427.18

OWK TOTAL \$1,427.18

Date: 10.05.2019
 Vehicle No: GBG7453M
 Model: TOYOTA PROACE COMFORT 2.0M
 Chassis: YARVFAHKHGZ068896 - 2016
 Reg.Year: 2017

Third Party Insurer: LONPAC
 Third Party Veh No: SDF137K
 Date of Accident: 08.05.2019

*Not withstanding
 Resuming 84 paint*

ESTIMATE

5 day

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>Bz</i> \$849.70
2	REAR TAILGATE EMBLEM 'TOYOTA'	1		<i>Ne</i> ✓ \$62.50
3	REAR TAILGATE EMBLEM 'PROACE'	1		<i>Ne</i> ✓ \$18.40
4	REAR TAILGATE EMBLEM LOGO	1		<i>Ne</i> ✓ \$65.00
5	REAR BUMPER	1		<i>CM</i> \$528.50
6	REAR BUMPER REFLECTOR LH	1		<i>CM</i> \$125.60
7	REAR END PANEL	1		REPAIR
SUB TOTAL				\$1,689.70
LESS 25%				-\$422.43
PARTS TOTAL				\$1,267.28

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE STICKER '70 km/h'	1		<i>Ne</i> \$15.00
2	REAR TAILGATE STICKER '8 PAX'	1		<i>Ne</i> \$15.00
3	REAR TAILGATE WINDSCREEN SEALANT	1		<i>Ne</i> \$100.00
4	REAR BUMPER CLIPS	1 SET		<i>Ne</i> \$60.00
5	REAR END PANEL JOINT SEALANT	1		\$60.00
S/N TOTAL				\$250.00

LABOUR CHARGES:

LABOUR CHARGES FOR REMOVE, REPLACE & READJUST REAR ACCIDENT AREAS & ETC.
 BACK TO ORIGINAL CONDITIONS

\$600.00 *500*

LABOUR CHARGES FOR SPRAY PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS
 AT REAR ACCIDENT AREAS & ETC

\$700.00 *600*

LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE INNER TRIM PART & ETC.
 BACK TO ORIGINAL CONDITIONS

\$100.00 *60*

LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE WINDSCREEN TO
 PERFORM WATER LEAK TEST

\$150.00 *120*

LABOUR TOTAL \$1,550.00

PEI TING TOTAL \$3,067.28

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 8868 Fax: (+65) 6452 9223



Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 9 May 2019 5:01 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: FW: PRI - GBG7453U CLAIM AGAINST SDF137K DOA: 08/05/2019 (LONPAC)
[External Confidential]
Attachments: GBG7453U GIA.pdf

9.09am @ 10/5/19
vehicle in
Sharon
Kien's

Lonpac External - Confidential

Our Ref : 19/19/19/VP05/021771

Dear Nivitha,

Kindly proceed to survey as arranged.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Lily.loi@ow.sg [mailto:Lily.loi@ow.sg]
Sent: Thursday, 9 May, 2019 4:56 PM
To: MT_Claim_SG
Cc: 'Sharon'; angela.tan@ow.sg; 'puiheng.chong'; hockkong.ong@ow.sg
Subject: PRI - GBG7453U CLAIM AGAINST SDF137K DOA: 08/05/2019 (LONPAC)

Dear Officer,

Please arrange PRI on 10/05/2019, 10am at Serangoon branch.

Owner waiting.

Thank you.

--
Best Regards,

Lily Loi (Ms.)

Senior Claims Executive, Motor Claims Department

D: +65 6481 1522 | F: +65 6481 1011

OPTIMA WERKZ PTE. LTD.

Head office: 8 Kung Chong Road Singapore 159143

Branch: 9A Serangoon North Ave 5 Singapore 554500

Branch: 551 Upp Thomson Road Singapore 574415

Tel: (+65) 6472 1313

Fax: (+65) 6472 2112

Tel: (+65) 6484 9919

Fax: (+65) 6481 1011

Tel: (+65) 6452 6868

Fax: (+65) 6452 9223

www.ow.sg | www.facebook.com/OptimaWerkz

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, you must not copy, distribute or use it for any purpose, nor disclose its contents to any other person.
Please notify the sender if you receive this email in error, and delete the email and its content immediately after which.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 14 May 2019 12:48 PM
To: Lily.loi@ow.sg
Cc: 'Sharon'; angela.tan@ow.sg; Admin A
Subject: RE: Check Liability - GBG7453U CLAIMING AGAINST SDF137K DOA: 08/05/19 (LONPAC) *LKK REF: CC4/LPC19008300/Kpb3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lily.loi@ow.sg <Lily.loi@ow.sg>
Sent: Monday, 13 May 2019 3:45 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: 'Sharon' <sharon@ow.sg>; angela.tan@ow.sg
Subject: Check Liability - GBG7453U CLAIMING AGAINST SDF137K DOA: 08/05/19 (LONPAC)

Dear Hsiao Tong,

We already conducted PRI on 10/05/2019.
Kindly advice on liability.
Thank you

--

Best Regards,

Lily Loi (Ms.)

Senior Claims Executive, Motor Claims Department
D: +65 6481 1522 | F: +65 6481 1011

OPTIMA/ERKZ PTE. LTD.

Head office: 8 Kung Chong Road Singapore 159143

Branch: 9A Serangoon North Ave 5 Singapore 554800

Branch: 551 Upp Thomson Road Singapore 574415

Tel: (+65) 6472 1313

Tel: (+65) 6484 9919

Tel: (+65) 6452 8868

Fax: (+65) 6472 2112

Fax: (+65) 6481 1011

Fax: (+65) 6452 9223

www.ow.sg | www.facebook.com/OptimaWerkz

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, you must not copy, distribute or use it for any purpose, nor disclose its contents to any other person.

Please notify the sender if you receive this email in error, and delete the email and its content immediately after which.

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Thursday, 10 October 2019 11:51 AM
To: ONG LI LI; GERALD POH WEE BIN
Cc: MT_Claim_SG
Subject: [MANDATE REQUEST] Your Ref: 19/19/19/VP05/021771, ACCIDENT INVOLVING SDF 137K (OI) AND GBG 7453U (TP) ON 08/05/2019
Attachments: TP LOD.pdf; LKK INSPECTION.pdf; LKK ADJUSTMENT.pdf; LKK SURVEY PHOTO.pdf; LKK RESURVEY PHOTO.pdf; LKK RESURVEY PHOTO 1.pdf

Your Ref: 19/19/19/VP05/021771

Dear Sirs,

We refer to the above matter.

ACCIDENT INVOLVING SDF 137K (OI) AND GBG 7453U (TP) ON 08/05/2019

We have highlighted to your good office on 10/05/2019 of Third-Party's request to do Direct Settlement with our Principal, Lompac Insurance Bhd.

The accident occurred when our insured rear ended third party vehicle.

Basing on the reports of the circumstance of the accident, we propose to settle third-party claim at 100% liability.

Summary to offer to repairer **OPTIMA WERKZ PTE LTD** is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 5,664.91	\$ 4,277.32
2. Loss of Rental (7days x \$100)(w/GST)	\$ 749.00	\$ 749.00 (7days x \$100)
3. LTA/GIA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 6,415.91	\$ 5,028.32

**5 days recommendation for repair.

Relevant supporting claim documents are attached herewith for your perusal and reference.

The above is for your approval please.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC19008300/Keb3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 04-12-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDF 137K	Veh. Inspected	GBG 7453U	
Policy No.	Z19VP05023289	Coverage (\$)	0.00	
Claim No.	19/19/19/VP05/021771	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	09/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PROACE (M)	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	YARVFAHKHGZ068896	Colour	WHITE	
Odometer	43198	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/65 R16	CONTINENTAL	7 mm	
L/H Front Tyre	215/65 R16	CONTINENTAL	7 mm	
R/H Rear Tyre	215/65 R16	CONTINENTAL	7 mm	
L/H Rear Tyre	215/65 R16	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/05/2019	Inspection Date	10/05/2019	
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 7453U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE EMBLEM 'TOYOTA'	NECESSARY	62.50	62.50
1	REAR TAILGATE EMBLEM 'PROACE'	NECESSARY	58.40	58.40
1	REAR TAILGATE EMBLEM LOGO	NECESSARY	65.00	65.00
1	REAR BUMPER	CRACKED	1,594.99	1,594.99
1	REAR BUMPER REFLECTOR LH	CRACKED	125.60	125.60
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR TAILGATE OUTER HANDLE GARNISH COVER (ADDITIONAL)	CRACKED	169.00	169.00
1	REAR TAILGATE INNER TRIM (ADDITIONAL)	SERVICEABLE	495.00	-
8	REAR TAILGATE INNER TRIM CLIPS @\$5.80 (ADDITIONAL)	NOT NECESSARY	46.40	-
1	REAR TAILGATE INNER LOCK (ADDITIONAL)	JAMMED	162.50	162.50
1	REAR BUMPER REINFORCEMENT (ADDITIONAL)	BENT	525.00	525.00
1	REAR BUMPER REINFORCEMENT INNER RETAINER GUIDE (ADDITIONAL)	CRACKED	175.00	175.00
1	REAR QUARTER PANEL LINER LH (ADDITIONAL)	SERVICEABLE	98.00	-
1	REAR TAILGATE RUBBER (ADDITIONAL)	DENTED / CUT	232.00	232.00
	LESS 25% DISCOUNT		-952.35	-792.49
			2,857.04	2,377.50
1	REAR TAILGATE (LOCAL REPAIR) (SN)	BENT	849.70	250.00
	LESS 25% DISCOUNT		-212.43	-
			637.27	250.00
SPECIAL NETT ITEMS				
1	REAR TAILGATE STICKER '70KM/H' (SN)	NECESSARY	15.00	15.00
1	REAR TAILGATE STICKER '8 PAX' (SN)	NECESSARY	15.00	15.00
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NOT NECESSARY	100.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	60.00
1	REAR END PANEL JOINT SEALANT (SN)	NOT NECESSARY	60.00	-
			250.00	90.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	LABOUR CHARGES FOR REMOVE ,REPLACE & READJUST REAR ACCIDENT AREAS & ETC BACK TO ORIGINAL CONDITIONS.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		600.00	500.00
	LABOUR CHARGES FOR SPRAY PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREAS & ETC.		700.00	600.00
	LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE INNER TRIM PART & ETC.BACK TO ORIGINAL CONDITIONS.		100.00	60.00
	LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE WINDSCREEN TO PERFORM WATER LEAK TEST.		150.00	120.00
			1,550.00	1,280.00
	GRAND TOTAL		5,294.31	3,997.50
RECOMMENDED COST OF REPAIRS				3,997.50

Report Ref No. CC4/LPC19008300/Keb3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.