

22/03/2002

ASS. REC. BY:

REF: CS/FCI 19008302/ Asds n2 Special Instruction:

Survivor: Adnan

ASSIGNMENT (Office)

From (Person): Karent

of FCI

Date/Time: 10.5.19 10.37a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGP 4185G

Insured: SHC 1926L

at Workshop m/s Hug mang spray

Tel: 67478064

of Autobay @ Bani Babil 1 Kaka Bukit Meru b Bk c #01-61

Policy No:

Claim No: D19003061 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 8.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 10.5.19 10.50am

Person Contacted: June

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SGP 4185G - X
	SHC 1926L - CS/FCI 180/6545 / kvd3n2 D.O.A. - 25/04/2018
10/05/19	@ 17:24 pm revert pending estimate from repair to Karen via email.

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC / Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: SGP4185 G. Yr Regn: 2006, Dec.Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Stream c.c. 1758Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 168866 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RN61011620Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/50R16R: 205/50R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 10/05/19Survey held at Hua mengDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 1st CapCOE Expiry: 15/12/21Confirmed HS \$ 4,600/- @ 7 days with Adrian.(\$ 4,790.32 Red - 51%)MV: 19KPV: 14.31cNett: 4.7K.MV - \$ 19KLTA - \$ 14,301.00Nett - \$ 4,699.00

RECEIVED 28 AUG 2019

Resurvey No. of Trip - 1

Date/Time, File Pass to?

28/08/19

Date/Time, File Return to?

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

170505091361

1)

2)

3)

4)

5)

Preli. Report:

Final Report:

\$ 4,600/- HS

MOTOR SURVEY ASSIGNMENT

Date	09-05-2019	Our Ref No. D19003061MFSH
Accident Date	08-05-2019	Claim Type. Third Party
Insured Vehicle	SHC1926L	Third Party Vehicle. SGP4185G
Survey Location	AUTOBAY@KAKIBUKIT 1 KAKI BUKIT AVENUE 6BLK C #01-61/01-34	
Contact Person.	JUNE	
Contact No.	67478064/ 67465519	Fax No. 67434896
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUA MENG SPRAY PAINTING WORKSHOP	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 10 May 2019 5:24 PM
To: 'Karen Tan'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19003061MFSH/1

Dear Karen,

Please be informed that we have inspected the vehicle SGP 4185G on 10/05/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 10 May 2019 10:53 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19003061MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 10 May, 2019 10:37 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003061MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Low Mileage Facelifted BMW 528i Luxury Sunroof!

Facelifted LED Luxury Edition!
Full PML Record With Receipt
Proven, 1 Owner Only
Seng Hup Auto StarAd

Free VICOM evaluation
Free grooming and 6 months maintenance
In-house workshop ensures quality service
Member of SYTA and hire purchase association
100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category [Save Search](#) [Print](#) [Back \(1 2 3 4 5 \) Next](#) Sort by Date Posted 20 results/page

82 vehicles **Search** [Advanced Search](#) [Search](#) [View All](#)

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection	honda stream	Any	Any	> 10 year(s) old	Any	Any	Any	Available
------------------	--------------	-----	-----	------------------	-----	-----	-----	-----------



☐ **Honda Stream 1.8A (COE till 04/2024)**

\$34,800

\$7,090 /yr

06-Apr-2009

1,799 cc

-

MPV

Available

2.98% Per Annum. \$638 Monthly. \$0 Admin Fees For All GV Purchase. Extra Add On Items: New 2 Years Warranty For Engine And Gearbox. New 2k Metallic Paint. New Pure Leather. New Rims, 16" Tyres. New Pl...

2.98%P.A \$0 Admin Fees@Gv Finance.2 Years Warranty.\$2500 Down Monthly From \$638

GV Credit Pte Ltd

☆ Posted: 10-May-2019 Tags: 2009 Honda Stream, 2009 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda



☐ **Honda Stream 1.8A (COE till 12/2021)**

\$18,800

\$7,180 /yr

22-Dec-2006

1,799 cc

-

MPV

Available

Well Maintained, Excellent Condition, Accident Free, Bank And In House Loan Available, Trade In Are Welcome, Powerful Engine And Smooth Transmission, Buy With Confidence! Call Us Now To Make An Appoin...

Car Search

☆ Posted: 21-Apr-2019 Tags: 2006 Honda Stream, 2006 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda



☐ **Honda Stream 1.8A (COE till 01/2022)**

\$21,700

\$8,060 /yr

18-Jan-2007

1,799 cc

-

MPV

Available

Cheapest Unit In Market. Don't Risk To Take Up High Financing Commitment. Very Reliable MPV With Great Aerodynamics, Combined With Space And Comfort. Regularly Serviced And Maintained.Selling Due To U...

☆ Posted: 13-Apr-2019 Tags: 2007 Honda Stream, 2007 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda



☐ **Honda Stream 1.8A (COE till 02/2022)**

\$22,700

\$8,250 /yr

08-Feb-2007

1,799 cc

120,000 km

MPV

Available

100% Loan Approval! Bank And In House Loan Available! No Gimmicks! Trade In Welcome! Priced Lowest In The Market Yet Comes With Accessories! Well Maintained, Excellent Condition! Don't Miss It, View T...

☆ Posted: 17-Apr-2019 Tags: 2007 Honda Stream, 2007 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



☐ **Honda Stream 1.8A (COE till 03/2022)**

\$21,800

\$7,560 /yr

29-Mar-2007

1,799 cc

-

MPV

Available

Well Kept Condition. Excellent Condition Interior And Exterior. Low Mileage Done. View To Believe. In House/Bank Loan Available, Call Now For Viewing.

☆ Posted: 08-May-2019 Tags: 2007 Honda Stream, 2007 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda



☐ **Honda Stream 1.8A (COE till 05/2022)**

\$28,800

\$9,600 /yr

10-May-2007

1,799 cc

178,866 km

MPV

Available

Very Reliable MPV With Great Aerodynamics, Combined With Space And Comfort. Regularly Serviced And Maintained. Selling Due To Upgrading. Consignment Unit! Trade In Welcome! Loan And Insurance Availabl...

Prem Roy Motoring

☆ Posted: 03-Apr-2019 Tags: 2007 Honda Stream, 2007 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda

SHORTLISTED HISTORY

Compare [3]

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7783I
Vehicle Details	
Vehicle No.:	SGP4185G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 May 2019
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8 A
Primary Colour:	Blue
Manufacturing Year:	2006
Engine No.:	R18A1713188
Chassis No.:	RN61011620
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$16,955.00
Original Registration Date:	14 Dec 2006
First Registration Date:	14 Dec 2006
Transfer Count:	0
Actual ARF Paid:	\$18,651.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Dec 2021
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$27,594.00
COE Rebate Amount:	\$14,301.00
Total Rebate Amount:	\$14,301.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 10 May 2019

OK

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

RN61011620

CHONG YIN KIAT
BLK 302 HONGANG AVE 5
#06-431
S 530302

TP 1st Cap
Shirley

Date :16.05.2019
Vehicle No :SGP 4185G
Make/Model :HONDA STREAM
Accident date :08.05.2019

No	DESCRIPTION	Qty	Amount (\$\$)
----	-------------	-----	---------------

List Items

1	Rear windscreen rubber <i>new</i>	1	\$ 39.27 ✓
2	Rear tailgate <i>Dented</i>	1	\$ 1202.14 -903
3	Rear tailgate hinges@54.90 <i>3 NP</i>	2	\$ 109.80 *
4	Rear tailgate shock absorber@130.40 <i>3 NP</i>	2	\$ 260.80 +.
5	Rear tailgate upper lock <i>Dented</i>	1	\$ 203.50 ✓
6	Rear tailgate lower lock <i>new</i>	1	\$ 30.14 +
7	Rear tailgate inner board <i>cracked</i>	1	\$ 333.52 ✓
8	Rear tailgate inner handle <i>new</i>	1	\$ 24.20 +
9	Rear tailgate handle <i>3 NP</i>	1	\$ 207.90 +
10	Rear tailgate H emblem <i>new</i>	1	\$ 75.35 +
11	Rear tailgate weatherstrip <i>cut</i>	1	\$ 147.73 ✓
12	Rear end panel <i>Dented</i>	1	\$ 339.13 ✓
13	Rear end panel inner top garnish <i>cracked</i>	1	\$ 134.09 ✓
14	Rear bumper <i>Dented</i>	1	\$ 1303.50 688.90
15	Rear bumper side holder@33.20 <i>new</i>	2	\$ 66.40 ✓
16	Rear bumper towing hook cover <i>Dented</i>	1	\$ 19.80 ✓
17	Rear bumper clips <i>new</i>	1	\$ 55.00 30
18	Rear bumper bracket@53.40 <i>LH Best</i>	2	\$ 106.80 45
19	Rear lamp@644.50 <i>LH cracked</i>	2	\$ 1289.00 338.60
20	Rear spare tyre carriage <i>best</i>	1	\$ 359.15 ✓
21	Rear LH fender inner garnish <i>cracked</i>	1	\$ 345.68 ✓

Less 20% Disc

Total

\$ 6652.90
\$ 1330.58
\$ 5322.32

Special Nett Items

- 1 Rear bumper reverse sensor *Dented*

1
Total

\$ 418.00 260
\$ 418.00

S.N:200

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

CHONG YIN KIAT

BLK 302 HONGANG AVE 5

#06-431

S 530302

Date :16.05.2019

Vehicle No :SGP 4185G

Make/Model :HONDA STREAM

Accident date :08.05.2019

No	DESCRIPTION	Qty	Amount (\$\$)
Labour Cost			
1	To supply rear windscreen sealant <i>rec</i>		\$ 50.00 ✓
2	To supply rear end panel inner sealant <i>rec</i>		\$ 200.00 60
3	Remove & reinstall reverse sensor		\$ 150.00 50
4	Remove & reinstall bootlid inner garnish		\$ 200.00 80
5	Remove & reinstall rear windscreen		\$ 150.00 120
6	Remove ,replace & repair consistent to the accident	2250	\$ 1500.00 750
7	Respray painting		\$ 1300.00 900
8	Tuff kote		\$ 100.00 60
9	Remove and reinstall upholstery <i>150 80</i>		
Total			\$ 3650.00
Grand Total			\$ 9390.32

9540.32

total: 5745.01

4/s: 4.61K

07 Days

4.61K 07 Days

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19008302/Asd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1926L	Veh. Inspected	SGP 4185G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003061MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	10/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA STREAM	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	RN61011620	Colour	BLUE	
Odometer	168866	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/50 R16	GOODYEAR	6 mm	
L/H Front Tyre	205/50 R16	GOODYEAR	6 mm	
R/H Rear Tyre	205/50 R16	GOODYEAR	6 mm	
L/H Rear Tyre	205/50 R16	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/05/2019	Inspection Date	10/05/2019	
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGP 4185G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN RUBBER	NECESSARY	39.27	39.27
1	REAR TAILGATE	DENTED	1,202.14	903.00
2	REAR TAILGATE HINGES @\$54.90	NOT NECESSARY	109.80	-
2	REAR TAILGATE SHOCK ABSORBER @\$130.40	NOT NECESSARY	260.80	-
1	REAR TAILGATE UPPER LOCK	DAMAGED	203.50	203.50
1	REAR TAILGATE LOWER LOCK	NOT NECESSARY	30.14	-
1	REAR TAILGATE INNER BOARD	CRACKED	333.52	333.52
1	REAR TAILGATE INNER HANDLE	NOT NECESSARY	24.20	-
1	REAR TAILGATE HANDLE	NOT NECESSARY	207.90	-
1	REAR TAILGATE H EMBLEM	NOT NECESSARY	75.35	-
1	REAR TAILGATE WEATHERSTRIP	CUT	147.73	147.73
1	REAR END PANEL	DENTED	339.13	339.13
1	REAR END PANEL INNER TOP GARNISH	CRACKED	134.09	134.09
1	REAR BUMPER	DEFORMED	1,303.50	688.90
2	REAR BUMPER SIDE HOLDER @\$33.20	NECESSARY	66.40	66.40
1	REAR BUMPER TOWING HOOK COVER	DEFORMED	19.80	19.80
1	REAR BUMPER CLIPS	NECESSARY	55.00	30.00
2	REAR BUMPER BRACKET @\$53.40	N/S BENT	106.80	45.00
2	REAR LAMP @\$644.50	N/S CRACKED	1,289.00	338.60
1	REAR SPARE TYRE CARRIAGE	BENT	359.15	359.15
1	REAR LH FENDER INNER GARNISH	CRACKED	345.68	345.68
	LESS 20% DISCOUNT		-1,330.58	-798.75
			5,322.32	3,195.02
SPECIAL NETT ITEMS				
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	418.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR END PANEL INNER SEALANT (SN)	NECESSARY	200.00	60.00
			668.00	310.00
LABOUR				
	REMOVE & REINSTALL REVERSE SENSOR.		150.00	50.00

Report Ref No. CS/FCI19008302/Asd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & REINSTALL BOOTLED INNER GARNISH.		200.00	80.00
	REMOVE & REINSTALL REAR WINDSCREEN.		150.00	120.00
	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT.		1,500.00	950.00
	RESPRAY PAINTING.		1,300.00	900.00
	TUFF KOTE.		100.00	60.00
	REMOVE AND REINSTALL UPHOLSTERY.		150.00	80.00
			3,550.00	2,240.00
GRAND TOTAL			9,540.32	5,745.02
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,600.00

Report Ref No. CS/FCI19008302/Asd3n2

MARKET VALUE: \$19,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,301.00=NETT VALUE: \$4,699.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.