

Ally
Kenneth



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.eesteemperf.com.sg

Repair Estimates

SLP 4779 J

Parts	(a) Cost / List Price Items	\$	5,020.27
	Plus/Less 25%	\$	1,255.07
	Total of Cost / List	\$	3,765.20
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
Total Parts Cost		\$	3,965.20
Labour		\$	2,620.00
Total		\$	6,585.20

Not authorized
Recovery B4 painting

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 10/5/19 at

Remarks By Surveyor

(a) The repair of this vehicle is ☒ authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 2-4 day(s)

(c) Resurvey : Required / ☒ Not Required

(d) Excess : \$

(e) Signature of surveyor :  Date: 10/5/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLP 4779 J**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FUX03559343**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>Not listed</i>	1	\$200.00	S.N	✓
2	Rear bumper <i>CMA</i>	1	\$497.50		✓
3	Rear bumper clip <i>na</i>	10	\$40.00		✓
4	Rear bumper side retainer LH <i>SL</i>	1	\$112.70		X
5	Rear bumper side retainer RH <i>SL</i>	1	\$112.70		X
6	Rear bumper reinforcement	1	\$398.90		?
7	Rear bumper lower garnish centre <i>BA/CMA</i>	1	\$582.60		✓
8	Rear bumper lower garnish LH <i>SL</i>	1	\$149.70		X
9	Rear bumper lower garnish RH <i>SL</i>	1	\$149.70		X
10	Rear bumper tow cover <i>Per</i>	1	\$31.70		X
11	Rear bumper under cover <i>SL</i>	1	\$355.20		X
12	Rear bumper under cover clip <i>na</i>	4	\$14.00		✓
13	Tail door lock <i>R</i>	1	\$487.70		X
14	Tail door emblem <i>na</i>	1	\$61.70		X
15	Wording "PRIUS" <i>na</i>	1	\$51.90		X
16	Wording "HYBRID" <i>na</i>	1	\$55.47		X
17	Tail door plate garnish <i>SL</i>	1	\$782.50		X
18	Tail end panel	1	\$596.60		?
19	Tail end panel garnish	1	\$151.60		?
20	Tail end panel garnish clip	10	\$35.00		?
21	Boot weatherstrip <i>SL</i>	1	\$353.10		X
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

