

AKG
Kenneth

Kd



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLP 4779 J

Finalised

Parts	(a) Cost / List Price Items	\$ 1514.00	5,020.27
	Plus/Less 25%	\$ 379.75	1,255.07
	Total of Cost / List	\$ 1134.25	3,765.20
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$ 200.00	200.00
	Total Parts Cost	\$ 1334.25	3,965.20
	Labour	\$ 815.00	2,620.00
	Total	\$ 2154.25	6,585.20

Not Authorised
Recovery By Repair

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kenneth

Company

UICK

Survey conducted on

10/5/19

at

Remarks By Surveyor

(a) The repair of this vehicle is ☒ authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 3 ~~2~~ day(s)

(c) Resurvey : Required / ☒ Not Required

(d) Excess : \$

(e) Signature of surveyor

Sc

Date:

10/5/19



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLP 4779 J

TOYOTA PRIUS
JTDKB3FUX03559343

Submit By :
Year Manufacture :
Engine No. :
Cost / List

Carmen Lim
2017

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	✓
2	Rear bumper	1	\$497.50		✓
3	Rear bumper clip	10	\$40.00		✓
4	Rear bumper side retainer LH	1	\$112.70		X
5	Rear bumper side retainer RH	1	\$112.70		X
6	Rear bumper reinforcement	1	\$398.90		✓
7	Rear bumper lower garnish centre	1	\$582.60		X
8	Rear bumper lower garnish LH	1	\$149.70		X
9	Rear bumper lower garnish RH	1	\$149.70		X
10	Rear bumper tow cover	1	\$31.70		X
11	Rear bumper under cover	1	\$355.20		X
12	Rear bumper under cover clip	4	\$14.00		X
13	Tail door lock	1	\$487.70		X
14	Tail door emblem	1	\$61.70		X
15	Wording "PRIUS"	1	\$51.90		X
16	Wording "HYBRID"	1	\$55.47		X
17	Tail door plate garnish	1	\$782.50		X
18	Tail end panel	1	\$596.60		X
19	Tail end panel garnish	1	\$151.60		X
20	Tail end panel garnish clip	10	\$35.00		X
21	Boot weatherstrip	1	\$353.10		X
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

1519
200 SN

ESTEEM PERFORMANCE PTE LTD