

AKG
Kenneth

Kd



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLP 4779 J

Finalised

Parts (a) Cost / List Price Items	\$ 1514.00	5,020.27
Plus/Less 25%	\$ 379.75	1,255.07
Total of Cost / List	\$ 1134.25	3,765.20
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items	\$ 700.00	200.00
Total Parts Cost	\$ 1334.25	3,965.20
Labour	\$ 815.00	2,620.00
Total	\$ 2154.25	6,585.20

Not Authorised
Recovery B4 Repairing

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kenneth

Company

LKK

Survey conducted on

10/5/19

at

Remarks By Surveyor

(a) The repair of this vehicle is ☒ authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 2-3 day(s)

(c) Resurvey : Required / ☒ Not Required

(d) Excess : \$ _____

(e) Signature of surveyor

Kc

Date:

10/5/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLP 4779 J

TOYOTA PRIUS

JTDKB3FUX03559343

Submit By :
Year Manufacture :
Engine No. :
Cost / List

Carmen Lim

2017

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>Not listed</i>	1	\$200.00	S.N	✓
2	Rear bumper <i>CMA</i>	1	\$497.50		✓
3	Rear bumper clip <i>un</i>	10	\$40.00		✓
4	Rear bumper side retainer LH <i>un</i>	1	\$112.70		X
5	Rear bumper side retainer RH <i>un</i>	1	\$112.70		X
6	Rear bumper reinforcement <i>BI</i>	1	\$398.90		✓
7	Rear bumper lower garnish centre <i>BI/CMA</i>	1	\$582.60		✓
8	Rear bumper lower garnish LH <i>un</i>	1	\$149.70		X
9	Rear bumper lower garnish RH <i>un</i>	1	\$149.70		X
10	Rear bumper tow cover <i>un</i>	1	\$31.70		X
11	Rear bumper under cover <i>un</i>	1	\$355.20		X
12	Rear bumper under cover clip <i>un</i>	4	\$14.00		X
13	Tail door lock <i>R</i>	1	\$487.70		X
14	Tail door emblem <i>un</i>	1	\$61.70		✓
15	Wording "PRIUS" <i>un</i>	1	\$51.90		✓
16	Wording "HYBRID" <i>un</i>	1	\$55.47		✓
17	Tail door plate garnish <i>un</i>	1	\$782.50		X
18	Tail end panel <i>R</i>	1	\$596.60		X
19	Tail end panel garnish <i>un</i>	1	\$151.60		X
20	Tail end panel garnish clip <i>un</i>	10	\$35.00		X
21	Boot weatherstrip <i>un</i>	1	\$353.10		X
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

1519

200 SN

