|      | Surveyor:                       | Adisan        |                    | ASSIG  | ENMEN   | T (Office) |          |                            |         |    |
|------|---------------------------------|---------------|--------------------|--|---------|------------|----------|----------------------------|---------|----|
| Minu | From (Person): Elaine Cheong    |               |                    | 1 of C11   |         |            | 1        | Date/Time: 10-5-19 13-59 p |         |    |
|      | Estimated Coat:                 |               |                    | E  | ill to: |            |          |                            |         |    |
|      | To Inspect Vehicle No: Sty 4194 |               |                    |  |         |            | Insured: | skl                        | 93284   |    |
|      | at Workshop                     |               | notorspa<br>Nu 6 i | and the same of th | @ B     |            | Tel:     | -                          | 6996    | 14 |
|      | Policy No:                      |               |                    |  |         | Claim No:  | SNM19    | 00000                      | (02     |    |
|      | Sum Insured:                    |               |                    |  |         | Excess:    |          |                            |         |    |
|      | Make of Veh: (Client's Record)  |               |                    |  |         |            |          | D.O.A 6                    | 5- 2010 |    |
|      | CA / REV                        | REP. / REV    | flen m             | erson Contr  |         | Jade       | V        | H.O.D. End                 |         |    |
|      | Date/Time                       | Action/Instru |                    | ) Esti   | mate    |            |          |                            | -       |    |
|      |                                 | SkH 932       | 8A-<               |  |         |            |          |                            |         | •  |
|      | 12/7/19                         | Adrian        | Confise            | red LS   | . \$    | 5150       | (Red     | 11,472.                    | 0, 69%  | )  |

|                 |               | 41-1-61 |
|-----------------|---------------|---------|
| ASSET           | GNM           | E OUT   |
| / A . M . S . E | * * 1 4 1 4 4 | 1 1 7 7 |

| Estimated Cost:  OD TB/WS/TP RES/OD RES/EVA/INV/MV  Truck/Trailer or   |        |
|--|--------|
| DDI 197 Wa) if hear op hear entries  |        |
| To Inspect Vehicle No: SKW 4194 X Make: Volkswagen-Sports Van ec 1355  |        |
| AC Insured / Std / NI / N  | A      |
| of 62 kaki Bulcit Ne 6 ARKO KB Sp. Residing 8/163  | IA:    |
| Insured: Eng/No: WVWZZZA4Z6W508055   |        |
| Policy No.   |        |
| Claims No. Gen. Cond. Good / Fair / Poor / Burnt   |        |
| Sum Insured: Excess: Sleering: Inorder / Jammed / Leaked / Burnit or   |        |
| (Client's Record)  Brake: Iporder / Jammed / Leaked / Burnt or   |        |
| Make of Veb: Modi: Nil / SRim / STD A/Rim or   |        |
| Make of Veh:  Tyre Size: F: 225/45 R17.  (Policy Condition)  R: 225/45 R17.  | -      |
| (Policy Condition) R: 225/45R17.   |        |
| Remark: The veh had commenced its N/S O/S BS / DUN / EXNOVA / GY / FS / LIZA (MIC) OHTSU / PIR / SUMI /  |        |
| repair at the time of inspection. TOYO / YOKO or   |        |
| Front Report   |        |
| Ball of Market Value: R/Ball Ob min R/Ball ob  | mm     |
| DAC ACCIDENT PROFILE OF MIN LIBRAL OF MIN LI | mm     |
| GIA / PR Seen: D.O.I. (0) 05/18  |        |
| Est. Repairs: days Res. Yes or No Survey held at SC March 152075   |        |
| Lum sum.   |        |
| CA / REV / REP. / 24 HRS 100   |        |
| Venicle: IN / OUT  | ision. |
|  |        |
| Date / Time   Action / Instruction   TP China  |        |
|  |        |
| Avd. Total   |        |
| 7V : 50-4K RECEIVED 1 2 111 2019   |        |
| Nett. 19.61C.  |        |
| Well . 17.00 7   |        |
|  |        |
| Date/Tens. File Pass 897 : Prelli. Report Days Of Repair:  |        |
| Resurvey No. of Trip:   Survey Fee:  |        |
| 1) Date/Time, File Return to? Transportation.  |        |
| 2 1 1 m - 1  |        |
| and ree: Site map (\$ ) Photos   |        |
| Report Format : Merinen Tech. Inva (\$ ) Omers   |        |
| Lump Sum / L.B.I: (\$ 5\50 2 ) Weekend (\$   |        |
| 10TAL 22   | 0      |

# ...CLAIM SUBFOLDER...(New Assignment)

| Case             | Notified           | Est Submitted | Adj Assigned   | Adj Rpt     | Adj S           | ubmitted               | Ins Auth'ed    | Status           |            |
|------------------|--------------------|---------------|--|-------------|-----------------|------------------------|----------------|------------------|------------|
| Main             | 07 May 2019        |               | 10 May 2019<br>13:53   |             |                 |                        | TAIL COLLEGE   | New Assign       | ment       |
|                  | Main               | Ref           | erence   | C           | laim Details    |                        | Documen        | ts               | Show All   |
| CLAIM S          | UBFOLDER DET       | AILS          |  |             |                 |                        | [Crea          | ited by insure   | er]        |
| Main Clair       | mant:              | HOD W         | EL KUN. ID: S  | B309140A    |                 |                        |                |                  |            |
| Vehicle R        | eg. No.:           | SKW4          | The second secon |             | Date of Loss:   |                        | 06/05          | /2019 07:00 -    | 50         |
| Claim Typ        | e:                 | TP/S          | NM19D202001  | C02         | Palicy/Cover N  | lote No.:              |                | SN1335321805     | 17.7       |
| Vehicle R        | eg. No. (Insured): | 5KH93         | ISA  |             | Policy No. (Cla | Control of the Control |                |                  |            |
| No. II. and Park |                    |               |  |             | Excess:         |                        | 5\$500         |                  |            |
| Repairer:        |                    | 96 Mot        | orsports Pte Ltd   | (HQ) 62 K   | aki Bukit Aver  | nue 6, The A           | rk@KB, 417893  | Caki Bukit - Tel | 6702 6996  |
| Handling         |                    | China T       | aiping Insurant  | ce (Singape | ore) Pte. Ltd.  | (HQ) - Tel             | 6389 6111 [    | Handled by Ela   | ine Cheong |
| Adjuster:        | s Insurer:         |               | nsurance (Singa  |             |                 |                        |                |                  |            |
| Adjuster:        |                    | LKK AU        | to Consultants   | Pte Ltd (HC | ) - Tel: 6256   | -3561 [F               | inal Rpt due : | 22/05/2019]      |            |
| ASSOCIA          | ATED MAIL REC      | EIVED         |  |             |                 |                        | View All       | Compace          | Case Mail  |
| There are        | no mail for this c | ase.          |  |             |                 |                        | Alem Wil       | Compose          | Case Mail  |
|                  |                    |               |  |             |                 |                        |                |                  |            |
| B                |                    |               |  |             |                 |                        |                |                  |            |
|                  | OCIATED TASK       | s             |  |             | View All        | Search T               | asks Const     | e New Task       | Complete   |
| Due Da           |                    | Type Task Gr  | oup Subject  | t Handle    | -               |                        | Completed On   | Created 0        |            |

# Nivitha (LKK Auto)

From:

Elaine Cheong <elaine.cheong@sg.cntaiping.com>

Sent:

Friday, 10 May 2019 1:49 PM

To:

claims@96motorsports.com; 'assignments'

Subject:

RE: PRI FOR SKW 4194X; YOUR INSURED SKH 9388A (CLAIM REF:

SNM19D202001C02/8)

Attachments:

SAS REPORT - SKW4194X.pdf

#### WITHOUT PREJUDICE

Dear Royce,

We refer to your email of 08.05.19.

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please refer email below and proceed to survey the third party vehicle.

Thank you.

Regards,

**Elaine Cheong** 

Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909 Co. Reg. No. 200208384E

DID: 6389 6530

Fax: 6224 7478 / 6224 7175

Email: elaine.cheong@sq.cntaiping.com

Website: www.sg.cntaiping.com

From: claims@96motorsports.com [mailto:claims@96motorsports.com]

Sent: Wednesday, 8 May, 2019 3:55 PM

To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>

Cc: Alfred Toh <alfred.toh@sg.cntaiping.com>; Angie Foo <angie.foo@sg.cntaiping.com>; Chee So Chow

<sochow.chee@sg.cntaiping.com>

Subject: RE: PRI FOR SKW 4194X; YOUR INSURED SKH 9388A (CLAIM REF: SNM19D202001C02/8)

Dear China,

Please expedite on the matter.

Thank you.



62/64 Kaki Bukit Avenue 6 Ark @ KB Singapore 417893

Tel Fax

6702 6996 6384 6996

Email : Operation@96motorsports.com

Website: www.96motorsports.com

From: claims@96motorsports.com <claims@96motorsports.com>

Sent: Wednesday, 8 May, 2019 1:32 AM

To: 'Elaine Cheong' <elaine.cheong@sg.cntaiping.com>

Subject: RE: PRI FOR SKW 4194X; YOUR INSURED SKH 9388A (CLAIM REF: SNM19D202001C02/8)

Dear Elaine,

We would like Adrian ling to conduct the survey.

Thank you

Royce Phua

# MOTOR SPORTS

62/64 Kaki Bukit Avenue 6 Ark @ KB Singapore 417893

Tel

: 6702 6996 6384 6996

Fax

Email : Operation@96motorsports.com

Website: www.96motorsports.com

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>

Sent: Tuesday, 7 May, 2019 6:30 PM To: claims@96motorsports.com

Subject: RE: PRI FOR SKW 4194X; YOUR INSURED SKH 9388A (CLAIM REF: SNM19D202001C02/8)

#### WITHOUT PREJUDICE

Dear Royce,

We refer to your email of 06.05.19.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

| ADRIAN LING             |
|-------------------------|
| Kelvin Ang              |
| SEE CHEW SENG           |
| MOHD FADHILAH BIN OSMAN |
| XING QUO QIANG          |
| KENNETH KONG            |
| SIMON HO                |
| CHUA WEIJIE             |

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

#### Elaine Cheong

Executive (Motor Claims)
Claims Department

### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909 Co. Reg. No. 200208384E

DID: 6389 6530

Fax: 6224 7478 / 6224 7175

Email: elaine cheong@sg cntaiping.com

Website: www.sg.cntaiping.com

From: Claims Dept of CTI

Sent: Monday, 6 May, 2019 4:25 PM

To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; claims@96motorsports.com

Cc: Alfred Toh <alfred.toh@sg.cntaiping.com>; Angie Foo <angie.foo@sg.cntaiping.com>; Chee So Chow

<sochow.chee@sg.cntaiping.com>

Subject: FW: PRI FOR SKW 4194X; YOUR INSURED SKH 9388A

Dear Elaine,

Please conduct PRS - TP: SKW4194X (SNM19D202001) soonest possible

File with OIC - Elaine - 63896530

From: claims@96motorsports.com [mailto:claims@96motorsports.com]

Sent: Monday, 6 May 2019 4:01 PM

To: Claims Dept of CTI < claimsdept@sg.cntaiping.com > Subject: PRI FOR SKW 4194X; YOUR INSURED SKH 9388A

#### WITHOUT PREJUDICE

Dear China Taiping,

## ACCIDENT INVOLVING SKW 4194X and SKH 9388A on 06.05.2019 AT / ALONG TOH TUCK FLYOVER

We act for HOO WEI KUN, whose vehicle registration number SKW 4194X was damaged in the above accident.

Kindly let us have your list of surveyors within 2 working days of your receipt of this notice should you like to conduct a prerepair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Thank you



62/64 Kaki Bukit Avenue 6 Ark @ KB Singapore 417893

Tel : 6702 6996 Fax : 6384 6996

Email : Operation@96motorsports.com

Website: www.96motorsports.com

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit <a href="http://www.symanteccloud.com">http://www.symanteccloud.com</a>

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit <a href="http://www.symanteccloud.com">http://www.symanteccloud.com</a>

New Cars

**Used Cars** 

Sell My Car

Directory

Products

Insurance

Articles

Forum


Resources





Classic Promot Best Deall Fast Selling! Hurry Down Now! Flexible Loan, Trade In Are Welcome, 100% Deposit Refund For Unapproved Loan.







Volkswagen Sportsvan 1.4A TSI Comfortline

\$72,000 \$8,740 /yr 27-301-2016

1.395 cc

Hatchback

Available

Fully Maintained And Serviced By Agent, Loan Available, Comes With Free Servicing And Warranty With Volkswagen Center Singapore, Trade In Available, Consignment Unit, Viewing By Appointment Only,

Pestile: 25-aur-2019 Tatte: 2016 Volkswagen Sportwan, 2016 Volkswagen sportsvan, Volkswagen Sportsvan, Volkswagen Sportsvan, United Volkswagen

PERMITTER



Volkswagen Sportsvan 1.4A Highline

\$88,000

\$8,980 /vr

27-Sep-2017

1.395 cc

20,300 km Hatchback

Available

Single Owner, Carefully Driven And Accident-free. Only Selling To Upgrade To A 7-seater, Still Under 5-year VW Warranty. Great Condition. Test Drives Welcome With No Obligation. Posted: 26-Apr-2019 Tegs: 2017 Volksverger Sportwers, 2017 volksvagen sportwers, Volksvagen Sportwers, unknowners approximate, Volksvagen Sportwers, Sportwers, Unic Volksvagen





Volkswagen Sportsvan 1.4A

\$87,800

16,081 km

Available

\$8,700 /уг

26-Dec-2017

1,395 cc

Historiback

# > Back to One Motoring

Enquire PARF/COE Rebate for Registered Vehicle

| Owner ID Type:                | Singapore NRIC                       |
|-------------------------------|--------------------------------------|
| Owner ID:                     | 9140A                                |
| Yeingle Details               |                                      |
| Vehicle No.:                  | SKW4194X                             |
| Vehicle to be Exported:       | Yes                                  |
| Intended Deregistration Date: | 13 May 2019                          |
| Vehicle Make:                 | VOLKSWAGEN                           |
| Vehicle Model:                | SPORTSVAN 1.4 AT AM13HZ CL           |
| Primary Colour:               | White                                |
| Manufacturing Year:           | 2015                                 |
| Engine No.:                   | CZC267327                            |
| Chassis No.:                  | WVWZZZAUZGW502055                    |
| Maximum Power Output:         | 92.0 kW (123 bhp)                    |
| Open Market Value:            | \$22,081.00                          |
| Original Registration Date:   | 29 Oct 2015                          |
| First Registration Date:      | 29 Oct 2015                          |
| Transfer Count:               | 0                                    |
| Actual ARF Paid:              | \$17,914.00                          |
| Intended PARE Behate Details  |                                      |
| PARF Eligibility:             | Yes                                  |
| PARF Eligibility Expiry Date: | 28 Oct 2025                          |
| PARF Rebate Amount:           | \$13,435.00                          |
| Interses CGE Repart Darries   |                                      |
| COE Expiry Date:              | 28 Oct 2025                          |
| COE Category:                 | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):            | 10                                   |
| QP Paid:                      | \$57,301.00                          |
| COE Rebate Amount:            | \$36,999.00                          |
| Total Rebate Amount:          | \$50,434.00                          |

The information contained herein is correct as at 13 May 2019

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available.

|   | ACCIDENT STATEMENT                   |
|---|--------------------------------------|
| Date Of Report  | 06/05/2019 08:07                     |
| Date Of Accident  | 06/05/2019 07:10                     |
| Exact Location Of Accident  | TOH TUCK FLYOVER                     |
| Country/State of Loss   | SINGAPORE                            |
|   | DETAILS OF OWN VEHICLE               |
| Vehicle Registration Number   | SKW4194X                             |
| Insured/Policyholder  |                                      |
| Name Of Registered Owner  | HOO WEI KUN                          |
| NRIC No   | S8309140A                            |
| Email Address   | WEIKUNHOO@GMAIL.COM                  |
| Mobile Phone No   | (LOCAL) +65-81899379                 |
| Alternative Phone No  | OFFICE-81899379                      |
| Vehicle Particulars   |                                      |
| Manufacturer  | VOLKSWAGEN                           |
| Model   | SPORTSVAN 1.4CLBMT 92 TSI D7F        |
| Exact Purpose for which vehicle was being used at<br>time of accident           |                                      |
| Are you claiming under your own insurance policy<br>for repair to your vehicle? | NO                                   |
| If No, Please state action to be taken  | THIRD PARTY                          |
| Vehicle Category  | PRIVATE CAR                          |
| Insurance Company   |                                      |
| Name of Insurance Company   | MSIG INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage  | COMPREHENSIVE                        |
| Fleet Policy  | NO                                   |
|   |                                      |

Policy Number Cover Note Number

#### Driver

Name of Driver HOO WEI KUN NRIC No S8309140A Date Of Birth 18/03/1983 Occupation INDOOR Date Of Driving Pass 07/08/2003

Driving Experience 15 YEARS AND 8 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-81899379

Fax Number

Contact Number OFFICE-81899379

EMail Address WEIKUNHOO@GMAIL.COM Address 703 BEDOK RESERVOIR ROAD

#08-3502

Postcode 470703

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

.

Insurance Company of Driver's Own Vehicle

•

#### General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR
Road Surface DRY

#### Other Information

ambulance?

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident

4

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

#### **Details of Police Action**

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

#### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SKH9388A

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category PRIVATE CAR

Name of Driver ZHANG QIN NRIC/Passport Number S2703545J

Contact Number 9225 5558

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### **DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number

SJG9712P

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

PRIVATE CAR

JUMAHAT BIN ZAINAL NGABIDIN

S8002994B

90081443

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the Seneral Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"], the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me:
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my ciaims. (collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud. regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Driver's Sign


(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No.:

#### Sketch Plan Pg. 2



I noticed the vehicle (SJG9712P) did an emergency etop, and which I immediately applied my brakes and managed to stop in time. From my rear mirror, I also noticed that the vehicle behind me, sk493884, managed to stop in time too. Hotel Barely seconds, I tett a strong impact from behind. It was a callision from behind which led my car to collide with the near of the flost vehicle (SJG9712P). Hotel There were a total of 4 vehicles involved in this accident. The last volvicle (SJR30238) is likely to have caused this chain collision as both my an and vehicle St49388A managed to stop (stay trationary) in time. There was no injury in recounted in this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyhaider wyname

(If driver is not the adjicyholder)
Date 8. Time:

Reporting Centre Personnel's Signature Name

NAIC/FIN No.:

# 96 MOTORSPORTS

## 96 MOTORSPORTS PTE LTD

64 Kaki Bıkit Ave 6 Singapore (417893) Email: estimator@96motorsports.com

Tel: 67026996/83118211

TP Chin

WVWZ22AUZGWSOZUSS

VEHICLE NUM:

MAKE & MODEL:

MILEAGE:

TYRE: FRONT

TYRE: REAR

CHASSIS NUM:

SKW 4194X GOLF TST

|             |                                    | Ì                    |     | CHASSIS | NUM:   |                |
|-------------|------------------------------------|----------------------|-----|---------|--|----------------|
| TTN:        |                                    |                      |     | QTY     | PRICE  | ADJUSTED PRICE |
| NO.         | U CATE                             | DESCRIPTION - PARTS  |     | 1       | \$ 1,945.00  | *              |
| -           | IL GATE<br>IL GATE BADGE WITH OPEN | ER SWITCH AND CAMERA | /   | 1       | \$ 698.00  | 7              |
|             | IL GATE EMBLEM ( TSI )             | ER SWITCH AND CAMERA | 7   | 1       | \$ 126.00  | 2              |
| _           | IL GATE ENBLEM ( BLUE MC           | OTION )              |     | 1       | \$ 165.00  | *              |
| -           | IL GATE LAMP L+R                   | 7110117              |     | 2       | \$ 1,476.00  | *              |
|             | IL GATE LAMP INNER SEAL            | I A D                |     | 2       | \$ 120.00  | +              |
|             | IL GATE LAMP CLIP                  | LYN                  |     | 1SET    | \$ 40.00   | +              |
| 2 20        | IL GATE INNER LOCK                 |                      |     | 1       | \$ 590.00  | 4              |
| 20 20       | IL GATE LOCK CATCH                 |                      |     | 1       | \$ 156.00  | +              |
|             | IL GATE WEATHERSTRIP               |                      | XV. | 1       | \$ 365.00  | +              |
|             | AL GATE INNER TRIM                 |                      | n   | 1       | \$ 379.00  | L              |
|             | AL GATE INNER TRIM CLIP            |                      |     | 1SET    | \$ 30.00   | 4              |
|             | AL GATE HINGE L+R                  |                      |     | 2       | 7,000  | +              |
|             | ALL GATE ABSORBER L+R              |                      |     | 2       |  | +              |
| **          | AIL GATE WIPER MOTOR               |                      |     | 1       |  | *              |
|             | AIL GATE WIPER ARM                 |                      |     | 1       |  | +              |
| March Lines | EAR WINDSCREEN INNER SE            | AL W/WINDSCREEN _    |     | 1       |  | *              |
|             | AIL LAMP L+R                       | 7                    |     | 2       | \$ 1,492.00  | £              |
|             | AIL LAMP INNER SEAL L+R            | 7                    |     | 2       | \$ 120.00  | ±              |
|             | AIL LAMP CLIP                      | H                    |     | ISET    | \$ 30.00   | +              |
|             | AIL LAMP PANEL L+R                 |                      |     | 2       |  | 4              |
|             | EAR BUMPER De                      | 1_1                  |     | 1       | \$ 1,368,00  | 1150.          |
|             | EAR BUMPER SIDE RETAINE            |                      |     | 2       | \$ 420.00  | 210.           |
| 33.0        |                                    | u                    |     | 1SET    | THE SHOW OF THE PARTY OF THE PA | 30             |
|             | EAR BUMPER CENTER RETA             | INER Zouled          |     | 2       | \$ 574.00  | 2/0.           |
| 2000        | EAR BUMPER REINFORCEM              | 5. 5                 |     | 1       | \$ 698.00  | X              |
| 10000000    | EAR BUMPER NUMBER PLA              |                      |     | 2       | \$ 246.00  | <b>+</b> .     |
|             | EAR BUMPER REFLECTOR L             |                      |     | 2       | \$ 312.00  | +              |
|             | EAR BUMPER TOWING COV              | 6 . 12               |     | 1       | \$ 85.60   | х.             |
| -           | EAR BUMPER REVERSE SEN             |                      |     | 2PC     | \$ 486,60  | 243.30         |
|             | EAR FENDER L+R ( REPAIR )          | 2                    |     | 2       |  | *              |
|             | REAR FENDER INNER TRIM L           | VSAU                 |     | 2       |  | +              |

| PARE WHEEL PANEL ( REPAIR )                             | 1       |     |           | *         |
|---|---------|-----|-----------|-----------|
| PARE WHEEL PANEL TOP BOARD                              | 1       |     |           | 4         |
| END PANEL ( REPAIR )                                    | 1       |     |           | £         |
| END PANEL TOP GARNISH                                   | 1       | \$  | 287.00    | ×         |
| END PANEL TOP GARNISH CLIP                              | 1SET    | \$  | 40.00     | ×         |
| REAR KEY ANTERNER SENSOR 7.11 AL                        | 1       |     |           | 4         |
| REAR EXHAUST SILENSER 2                                 | 1       |     |           | 4         |
| REAR EXHAUST MOUNTING                                   | 1       |     |           | ž.        |
| REAR EXHAUST GASKET                                     | 1       |     |           | 4         |
| HEAD LAMP L+R ZH Cruckel                                | 2       | \$  | 3,182.40  | ¥ 1591.50 |
| HEAD LAMP CLIP 744 W                                    | 1SET    | \$  | 30.00     | *         |
| FRONT BUMPER TEL  | 1       | \$  | 1,205.30  | -         |
| FRONT BUMPER SIDE RETAINER L+R /                        | 2       | \$  | 400.00    | 210.      |
| FRONT BUMPER CLIP                                       | 1SET    | \$  | 40.00     |           |
| FRONT BUMPER REINFORCEMENT                              | 1       | \$  | 898.70    | 5. t.     |
| FRONT BUMPER FOG LAMP L+R MEL CL                        | 2       | \$  | 868.90    | +         |
| FRONT BUMPER LOWER GRILLE                               | 1       | \$  | 418.30    | 5 238     |
| FRONT BUMPER UNDER COVER X4 4                           | 1       | \$  | 363.20    | +         |
| FRONT BUMPER UNDER COVER CLIP                           | 1SET    | \$  | 30.00     | +         |
| FRONT GRILLE CHROME ZALLE AGE O                         | 1       | \$  | 781.60    | *         |
| FRONT GRILLE BADGE 704 6078                             | 1       | \$  | 108.60    | ~         |
| FRONT GRILLE CLIP M 5488-20                             | 1SET    | \$  | 40.00     | 10.       |
| SUBTOTA   | L       | \$  | 11,992.20 | \$ -      |
|   |         | \$  |           | \$ -      |
| PARTS TOTAL   | L       | \$  | 11,992.20 | \$ -      |
| SPECIAL NETT  | QTY     |     | PRICE     | PRICE     |
| REAR WINDSCREEN SEALANT                                 | 1       | \$  | 100.00    | +         |
| REAR NUMBER PLATE WITH COVER BEST 00                    | 1       | \$  | 80.00     | _         |
| BODY PANEL JOINT SEALANT Ne n                           | 1       | \$  | 150.00    | *         |
| Specia  | AL NETT | 115 | 330.00    | \$        |
| LABOUR  | QTY     | -   | PRICE     | PRICE     |
| TO KNOCK, STRAINHTEN AND REALIGN ACCIDENT AFFECTED AREA | 1       | s   | 2,800.00  |           |
| TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA             | 1       | 5   | 1,600.00  |           |
| TO RUST PROOF ACCIDENT AFFECTED ARAE                    | 1       | 5   | 120.00    | 1 .       |
|   | 1       | 5   | 150.00    | 1         |
| TO R & R REAR WINDSCREEN                                | 1       | 5   | 120.00    | 1-        |
| TO R & R TAIL GATE PARTS                                | 1       | \$  | 150.00    |           |
| TO R & R REVERSE SENSOR                                 | -       | +   | 120.00    | 1         |
| TO R & R REAR EXHAUST                                   | 1       | 2   | 5.576.00  | 1 114     |
| TO CHECH AND REFIX ACCIDENT AFFECTED AREA WATER LIKING  | 1       | S   | 120,00    | - 60.     |

 $1_{\lambda_{\epsilon}}$ 

.

| 910              |                 |             |  |
|------------------|-----------------|-------------|--|
|                  |                 |             |  |
| LABOUR TOTAL     | \$<br>4,300.00  | 5           |  |
| GRAND TOTAL COST | \$<br>16,622.20 | \$ 25316.20 |  |

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after sprity painting
- To display damaged partitly during resurvey.
- . Parts prices are suffert to confirmation.
- . Third party survey is on a "Wilhout Pilipudice" basis.
- . No Regar modification(s) is allowed.
- Supplementary (terms) in stible meyed and is subject to final approval from Laru ce Company.

Acknowledged by Repairer

Signature:

Date:

Adrian Ling-4/5 10/05/19. 048mp total: 6478.20 4/2: 5150

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI19008322/AVD3N2

Date:

15/07/2019

REFERENCE

Handling Insurer:

China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMPCSN1335321805

Claimant Vehicle No:

SKW4194X

Insured Vehicle No:

SKH9388A

Date of Loss:

06/05/2019

Nature of Claim:

TP

Claim No:

SNM19D202001C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKW4194X

Make & Model:

VOLKSWAGEN SPORTSVAN, 1.4 TSI

Comfortline (AM13HZ) (A)

Engine No:

CZC267327

Reg. Date: Colour:

29/10/2015 (Man. Year: 2015)

Chassis No: Odometer:

WVWZZZAUZGW502055 81163 km

Engine Capacity:

White

1395 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

74.41

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size: Front Left Side:

225/45R17 Michelin 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 225/45R17 Michelin 6 mm

Michelin 6 mm

18,838.00

Front Right Side: Michelin 6 mm The above values represent the remaining tyre treads depth

| COST OF CLAIMS      | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------|------------|------------|--------|
| Parts               | 21,016.20  | 5,568.20   | 15,448.00  | 73.51  |
| Miscellaneous Items | 0.00       | 0.00       | 0.00       |        |
| Labour              | 4,300.00   | 910.00     | 3,390.00   | 78.84  |
| Paintwork Labour    | 0.00       | 0.00       | 0.00       |        |
| Towing              | 0.00       | 0.00       | 0.00       |        |

| (S\$)                  | 25,316.20 | 5,150.00 | 20,166.20 | 79.66 |
|------------------------|-----------|----------|-----------|-------|
| + GST 7.00/7.00% (S\$) | 1,772.13  | 360.50   | 1,411.63  | 79.66 |
| Nett Amount (SS)       | 27.088.33 | 5.510.50 | 21.577.83 | 79.66 |

25,316.20

INSPECTION

Date of Assignment:

10/05/2019

Calculated Gross Total (S\$)

Approved Total (Overridden) (S\$)

Date Inspected:

10/05/2019 Inspected At:

96 Motorsports Pte Ltd (HQ)

62 Kaki Bukit Avenue 6, The Ark@KB

Singapore 417893

6,478.20

5,150,00

Estimated Period of Repair:

4.0 days

Manager: VERON CHEN Adjuster: ADRIAN LING

Adjuster Report Page 2 of 5

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

# REPAIR DETAILS

| Referen       | ce   |   |  |
|---------------|--|---|--|
| Part Source:  | MRM-SG   | Version: 1.0 (Last Synchronised: 15 Jul 2019)   |  |
| Parts:        | 144  | VOLKSWAGEN SPORTSVAN 1.4 TSI Comfortline (AM13HZ) (A) (Catalogue:Merimen Singapore 1.0) |  |
| Labour:       | Repairer's   | (Price-denominated Standard List)   |  |
| Print Code:   | (Unsubmitted, no print-code for SKW4194X)  |   |  |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |   |  |
| Further Info: | Items/values   | s not in reference catalogue are prefixed with an asterisk *.                           |  |

# Recommended Parts

| No. | Qty  | Part<br>No. | Particulars                                       | Condition  | Repairer's | Amount       |
|-----|------|-------------|---|--|------------|--------------|
| 1   | 1    |             | *TAIL GATE  | Not Necessary  | 1,945.00 F | *-FI         |
| 2   | 1    |             | *TAIL GATE BADGE WITH OPENER SWITCH AND CAMERA    | Not Necessary  | 698.00 F   | *-FI         |
| 3   | 1    |             | *TAIL GATE EMBLEM (TSI)                           | Not Necessary  | 126.00 F   | *-FL         |
| 4   | 1    |             | *TAIL GATE EMBLEM (BLUE MOTION)                   | Not Necessary  | 165.00 F   | *-FL         |
| 5   | 2    |             | *TAIL GATE LAMP L+R                               | Not Necessary  | 1,476.00 F | *-FL         |
| 6   | 2    |             | *TAIL GATE LAMP INNER SEAL L+R                    | Not Necessary  | 120.00 F   | *-FL         |
| 7   | 1    |             | *SET TAIL GATE LAMP CLIP                          | Not Necessary  | 40.00 F    | *-FL         |
| 8   | 1    |             | *TAIL GATE INNER LOCK                             | Not Necessary  | 590.00 F   | *- FL        |
| 9   | 1    |             | *TAIL GATE LOCK CATCH                             | Not Necessary  | 156.00 F   | *-FL         |
| 10  | 1    |             | *TAIL GATE WEATHERSTRIP                           | Not Necessary  | 365.00 F   | *-FL         |
| 11  | 1    |             | *TAIL GATE INNER TRIM                             | Not Necessary  | 379.00 F   | *-FI         |
| 12  | 1    |             | *SET TAIL GATE INNER TRIM CLIP                    | Not Necessary  | 30.00 F    | *-FL         |
| 13  | 2    |             | *TAIL GATE HINGE L+R (NPA)                        | Not Necessary  | 0.00 F     | *-FL         |
| 14  | 2    |             | *TAIL GATE ABSORBER L+R (NPA)                     | Not Necessary  | 0.00 F     | *-FL         |
| 15  | 1    |             | *TAIL GATE WIPER MOTOR (NPA)                      | Not Necessary  | 0.00 F     | *-FL         |
| 16  | 1    |             | *TAIL GATE WIPER ARM (NPA)                        | Not Necessary  | 0.00 F     | *-FL         |
| 17  | 1    |             | *REAR WINDSCREEN INNER SEAL<br>W/WINDSCREEN (NPA) | Not Necessary  | 0.00 F     | *-FL         |
| 18  | 2    |             | *TAIL LAMP L+R                                    | Not Necessary  | 1,492.00 F | *-FL         |
| 19  | 2    |             | *TAIL LAMP INNER SEAL L+R                         | Not Necessary  | 120.00 F   | *-FL         |
| 20  | 1    |             | *SET TAIL LAMP CLIP                               | Not Necessary  | 30.00 F    | *-FL         |
| 21  | 2    |             | *TAIL LAMP PANEL L+R (NPA)                        | Not Necessary  | 0.00 F     | *-FL         |
| 22  | 1    |             | *REAR BUMPER                                      | Deformed   | 1,368.00 F | *1,150.00 FL |
| 23  | 2    |             | *REAR BUMPER SIDE RETAINER L+R                    | Necessary  | 420.00 F   | *210.00 FL   |
| 24  | 1    |             | *SET REAR BUMPER CLIP                             | Necessary  | 70.00 F    | *30.00 FL    |
| 25  | 2    |             | *REAR BUMPER CENTER RETAINER                      | Cracked  | 574.00 F   | *210.00 FL   |
| 26  | 1    |             | *REAR BUMPER REINFORCEMENT                        | Not Necessary  | 698.00 F   | *-FL         |
| 27  | 2    |             | *REAR BUMPER NUMBER PLATE LAMP L+R                | Not Necessary  | 246.00 F   | *-FL         |
| 28  | 2    |             | *REAR BUMPER REFLECTOR L+R                        | Not Necessary  | 312.00 F   | *-FL         |
| 29  | 1    |             | *REAR BUMPER TOWING COVER                         | Not Necessary  | 85.60 F    | *-FL         |
| 30  | 1    |             | *REAR BUMPER REVERSE SENSOR<br>(2 Pcs)            | Damaged (1 Pc<br>only)   | 486.60 F   |              |
| 31  | 2    |             | *REAR FENDER L+R (NPA)                            | Not Necessary  | 0.00 F     | *-FL         |
| 32  | 2    |             | *REAR FENDER INNER TRIM L+R (NPA)                 | Not Necessary  | 0.00 F     | *-FL         |
| 33  | 1    |             | *SPARE WHEEL PANEL (NPA)                          | Not Necessary  | 0.00 F     | *-FL         |
| 34  | 1    |             | *SPARE WHEEL PANEL TOP BOARD (NPA)                | Not Necessary  | 0.00 F     | *-FL         |
| 35  | 1    |             | *END PANEL (NPA)                                  | Not Necessary  | 0.00 F     | *-FL         |
| 36  | 1    |             | *END PANEL TOP GARNISH                            | Not Necessary  | 287.00 F   | *-FL         |
| 37  | 1    |             | *SET END PANEL TOP GARNISH CLIP                   | Not Necessary  | 40.00 F    | *-FL         |
| 38  | 1    |             | *REAR KEY ANTERNER SENSOR (NPA)                   | Not Necessary  | 0.00 F     | *-FL         |
| 39  | 1    |             | *REAR EXHAUST SILENSER (NPA)                      | Not Necessary  | 0.00 F     | *-FL         |
| 40  | 4    |             | *REAR EXHAUST MOUNTING (NPA)                      | Not Necessary  | 0.00 F     | *-FL         |
| 10  | - 10 |             | Report was unsubmitted during this                | The second secon | 4,441      |              |

Adjuster Report Page 4 of 5

| No.         | Qty          | Part<br>No. | Particulars  | Condition              | Repairer's | Amount       |  |
|-------------|--------------|-------------|--|------------------------|------------|--------------|--|
| 41          | 1            |             | *REAR EXHAUST GASKET (NPA)                           | Not Necessary          | 0.00 F     | *-FL         |  |
| 42          | 1            |             | *HEAD LAMP L+R                                       | O/s Cracked            | 3,182.40 F | *1,591.20 FL |  |
| 43          | 1            |             | *SET HEAD LAMP CLIP                                  | Not Necessary          | 30.00 F    | *-FL         |  |
| 44          | 1            |             | *FRONT BUMPER  | Deformed               | 1,205.30 F | *1,205.30 FL |  |
| 45          | 2            |             | *FRONT BUMPER SIDE RETAINER L+R                      | Necessary              | 400.00 F   | *210.00 FL   |  |
| 46          | 1            |             | *SET FRONT BUMPER CLIP                               | Necessary              | 40.00 F    | *40.00 FL    |  |
| 47          | 1            |             | *FRONT BUMPER REINFORCEMENT                          | Repair                 | 898.70 F   | *-FL         |  |
| 48          | 2            |             | *FRONT BUMPER FOG LAMP L+R                           | Not Necessary          | 868.90 F   | *-FL         |  |
| 49          | 1            |             | *FRONT BUMPER LOWER GRILLE                           | Cracked                | 418.30 F   | *298.00 FL   |  |
| 50          | 1            |             | *FRONT BUMPER UNDER COVER                            | Not Necessary          | 363.20 F   | *-FL         |  |
| 51          | 1            |             | *SET FRONT BUMPER UNDER COVER CLIP                   | Not Necessary          | 30.00 F    | *-FL         |  |
| 52          | 1            |             | *FRONT GRILLE CHROME                                 | Cracked                | 781.60 F   | *781.60 FL   |  |
| 53          | 1            |             | *FRONT GRILLE BADGE                                  | Necessary              | 108.60 F   | *108.60 FL   |  |
| 54          | 1            |             | *SET FRONT GRILLE CLIP                               | Necessary              | 40.00 F    | *20.00 FL    |  |
| 55          | 1            |             | *REAR WINDSCREEN SEALANT                             | Not Necessary          | 100.00 FS  | *-FS         |  |
| 56          | 1            |             | *FRONT NUMBER PLATE WITH COVER                       | Bent                   | 80.00 FS   | *80.00 FS    |  |
| 57<br>F=Fta | 1<br>inchise | part. S=S   | *BODY PANEL JOINT SEALANT<br>pcNett. L=ListItemDisc. | Not Necessary          | 150.00 FS  | *-FS         |  |
|             |              |             |  | Sub Total (S\$)        | 21,016.20  | 6,178.00     |  |
|             |              |             | - List Item Discount on L I                          | tems 0.00/10.00% (S\$) | 0.00       | 609.80       |  |
|             |              |             |  | Total Parts (S\$)      | 21,016.20  | 5,568.20     |  |
|             |              |             | Report was unsubmitted during t                      | this print-out.        |            |              |  |

Adjuster Report Page 5 of 5

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

| No   | Particulars   | Lab.Type           | Repairer's | Amount |
|------|---|--------------------|------------|--------|
| Labo | our Items   |                    |            |        |
| 1    | TO KNOCK, STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA | New                | 1,800.00   | 400.00 |
| 2    | TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA             | New                | 1,600.00   | 400.00 |
| 3    | TO RUST PROOF ACCIDENT AFFECTED AREA                    | New                | 120.00     | 0.00   |
| 4    | TO R&R REAR WINDSCREEN                                  | New                | 150.00     | 0.00   |
| 5    | TO R&R TAIL GATE PARTS                                  | New                | 120.00     | 0.00   |
| 6    | TO R&R REVERSE SENSOR                                   | New                | 150.00     | 50.00  |
| 7    | TO R&R REAR EXHAUST                                     | New                | 120.00     | 0.00   |
| 8    | TO CHECK AND REFIX ACCIDENT AFFECTED AREA WATER LIKING  | New                | 120.00     | 60.00  |
| 9    | TO REPROGRAM AND REDIANOS FAULT CODE                    | New                | 120.00     | 0.00   |
|      | Gross Labou   | r Cost (S\$)       | 4,300.00   | 910.00 |
|      | Report was unsubmitted during                           | ng this print-out. |            |        |

< END OF ESTIMATES >