

TO :

FAX NO:

ESTIMATE REPORT

1ST Quotation

10/05/2019 8:48

JOB-NO: 50111642

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
 ADDRESS: 383 SIN MING DRIVE
 SINGAPORE 575717 0

CONTACT: 65533880
 64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHB2304E
 MAKE / MODEL: HYUNDAI / i40

TRANS: AUTO

CHASSIS: KMHLB41UMHU097850

ENGINE: D4FDGU701160

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	800.00	0.00	800.00		Y	500400
2 CONDUCT 4 WHEEL ALIGNMENT	1.00	120.00	0.00	120.00		Y	80.
3 REMOVE & REFIT WHEEL CAP & CHECK UNDERCARRIAGE NECESSARY ADJUSTMENT	1.00	120.00	0.00	120.00		Y	30.
4 RESPRAY REAR BUMPER	1.00	230.00	0.00	230.00		Y	200
5 RESPRAY REAR FENDER LHS	1.00	230.00	0.00	230.00		Y	200
6 RUST PROOFING	1.00	0.00	0.00	0.00		Y	-
TOTAL:		1,500.00	0.00	1,500.00			
MATERIALS							
1 WHEEL CAP LHS	1.00	265.20	53.04	212.16	L	Y	inf
2 WHEEL RIM LHS	1.00	325.30	65.06	260.24	L	Y	Rv
3 WHEEL BEARING LHS	1.00	151.00	30.20	120.80	L	Y	?
4 REAR BUMPER	1.00	698.33	139.67	558.66	L	Y	de
5 REAR BUMPER RETAINER LHS	1.00	49.14	9.83	39.31	L	Y	ne
6 REAR FENDER INNER SHIELD LHS	1.00	179.31	35.86	143.45	L	Y	?
7 REAR FENDER AIR VENT LHS	1.00	67.80	13.56	54.24	L	Y	?
8 REPAIR REAR FENDER LHS	1.00	0.00	0.00	0.00	S	Y	
9 WHEEL TYRE LHS	1.00	250.00	0.00	250.00	S	Y	x
10 REAR BUMPER CLIP SET	1.00	35.00	0.00	35.00	S	Y	ne
11 REAR FENDER CLIP SET LHS	1.00	35.00	0.00	35.00	S	Y	x
TOTAL:		2,056.08	347.22	1,708.86			
TOTAL PARTS & LABOUR :		3,556.08	347.22	3,208.86			

EXCESS/LOADING:\$S 0.00

No. Of Day:

4 days

RE-SURVEY: BEFORE/AFTER PAINTING
 PART-BY-PART OR LUMP SUM: \$S

DATE OF SURVEY:

10 / 5 / 19 - WP

SURVEYED BY:

Taufik

CONTACT NO:

97495749

FAX NO:

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: