From: Date:	Vah No. SHB 306 M Yr Regn: 20 Aug/2014
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Tax / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Toyota Prins c.c 1798.
at Workshop m/s	Colour Marson A/C: Insured / Std / NI / NA
of	Sp.Reading 6(3407 T/Radio: Insured / Std / NI / NA
Insured: , SMA 42018	Eng/No:
Policy No. 5087771209-03	C/No: JTOKN36UX05747663
Claims No. MT/1043566 - 004	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 195/65 R15
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S V	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of Inspection.	TOYO/YOKO OF Falken
Bal, or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 8/5/19 D.O.I. 9/5/19
Lum Sum: % 3 Val.; Yes or No	Survey held at Survey
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
SHB 306M - CE4 A3M 18017741/	Nh639,2 DUA: 05/9/18
19 61550, 3 days (feel \$ 6	710.30, 817)
07 4.0301 7 6.04 7 6.00 4.0	10.27, 01/2)
REC	CEIVED 1 7 JUN 2019
Onto/Timo, File Pass to? : Preli. Report	Days Of Repair:
ale haves	Resurvey No. of Trip:   Survey Fee:
Date/Time. File Return to?	Transportation:
2) Add Fee	
	: Interview (\$ ) Photos
Report Format:	Tech Invs (\$ ) Others
Lump Sum / I.B.f. (3 1550 )	Weekend (\$ )
	TOTAL

TP Claims against NTUC Income: Follow-Through Survey

Date: 14/06/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident		Estimate
1	MT/1043566-004	SMRT TAXIS PTELTD	SHB 306M	SMA 42018	08/05/2019	10:40	s	8,260.30
2	MT/1049036-001	COMFORT TRANSPORTATION PTE LTD	SHD 3604Y	PC 3697P	30/05/2019	18:30	s	1,502.40
3	MT/1047126-002	COMFORT TRANSPORTATION PTE LTD	SHD 7286E	SLS 8336L	31/05/2019	14:45	s	1,896.12
4	MT/1048935-002	COMFORT TRANSPORTATION PTE LTD	SHA 2456E	PC 6649J	11/06/2019	16:05	s	2,316.65
5	MT/1047949-002	CITYCAB PTE LTD	SHC 7964L	SGM 2112X	02/06/2019	22:30	s	1,520.00
9	MT/1048179-002	COMFORT TRANSPORTATION PTE LTD	SHD 6523C	GT 5718S	07/06/2019	13:00	s	2,099.08

· Log Out

### Hello, NAC\_PAYA\_UBI\_800601

My Desktop Notice of Loss **Policy Query** 

Policy No.

0

Vehicle No.(For Motor)

SMA4201B

Date of Accident

Certificate Number

· Change Language

08/05/2019 14:52

· Change Password

Search

Select Policy No.

5087272209-

03

Certificate Number

Policyholder Name HUA HONG PTE. LTD.

Policyholder NRIC 200900309M

Product Cover Type drivo PREMIUM **GFT** 

Insured Object Vehicle No.

Commence Date Expiry Date

SMA4201B SMA4201B 04/03/2019

Continue

# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCID			ALC: NO
ACCID	1 21/	( I El	TIEN I

08/05/2019 13:16 Date Of Report Date Of Accident 08/05/2019 10:40

HAVELOCK ROAD TOWARDS NEW BRIDGE ROAD **Exact Location Of Accident** 

Country/State of Loss SINGAPORE

**DETAILS OF OWN VEHICLE** 

Vehicle Registration Number SHB306M

Insured/Policyholder

SMRT TAXIS PTE LTD Name Of Registered Owner

Co Reg No 198905369K **Email Address** NOEMAIL

Mobile Phone No

Alternative Phone No OFFICE-80000000

Vehicle Particulars

Manufacturer TOYOTA

Model PRIUS TAXI-1.8 (A)

Exact Purpose for which vehicle was being used at HIRE AND REWARD

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD Type Of Coverage THIRD PARTY FIRE AND/OR THEFT

Fleet Policy YES

D-19093197MFSH Policy Number

Cover Note Number

Driver

Name of Driver GOH SHEW PENG

NRIC No S6920885A Date Of Birth 16/06/1969 Occupation OUTDOOR Date Of Driving Pass 25/07/2000

Driving Experience 18 YEARS AND 9 MONTHS

Gender

Mobile Number (LOCAL) +65-80000000

Fax Number Contact Number

EMail Address NOEMAIL 'Address

Postcode

Was driver an employee of the Insured's Company NO

OTHER - HIRER If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

303

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident SIDE SWIPE Weather Conditions RAINING

Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) 2

involved in the accident

NO Was any body injured in the Accident?

Was any injured conveyed to hospital by NO

ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) Passenger 1

NAME:

: UNKNOWN

GENDER:

: FEMALE

**Details of Police Action** 

Was the accident reported to the police?

NO

NO

2

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

### Circumstances of Accident

I WAS TRAVELLING ALONG HAVELOCK ROAD TURNING RIGHT TOWARDS NEW BRIDGE ROAD/CHINATOWN POINT WITH ONE PASSENGER (FEMALE CHINESE) ON BOARD, WHILST I WAS TURNING RIGHT, I FELT AN IMPACT AT THE RIGHT PORTION OF MY TAXI. A VEHICLE SMA4201B WHICH WAS TRAVELLING ON MY RIGHT HAD ENCROACHED INTO MY LANE AND COLLIDED ONTO THE RIGHT PORTION OF MY TAXI.

### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

Remarks/ Reasons:

FILE TOO BIG

Was there any audio recorded?

## **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

SMA4201B

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category

PRIVATE CAR

Name of Driver

UNKNOWN

NRIC/Passport Number

Contact Number

Address

Postcode

·Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

# Sketch Plan Pg. 1

SKETCH PLAN	Havelock Rd toward	ds New Bridge Kd
A constitution of the		
		D
Volume Alexander (Control of Control of Cont	tan da da a da a da a da a da a da a da	TAI =>
freger morting are extended		1 7
4		1 A- 5HB 306M P1 7 B- 5MA4201B
1 1 1 10 10	714171	171 (13- SMA4201B
DESCRIBE CIRCUMSTANCE	S OF THE ACCIDENT	
		A CONTRACTOR OF THE STATE OF TH
	· · · · · · · · · · · · · · · · · · ·	
DECLARATION  /We declare the forceoing part	ticulars are true in every respect.	
(6)	1	Mar 1 mg
000	(Bril)	/2 3/2/so.
Policyholder's Signature	Driver's Signature	Reporting Centre Personnel's Signature
Date & Time:	(If driver is not the policyholder) Date & Time:	Name: NRIC/FIN No.:

### Sketch Plan Pg. 2

#### SKETCH PLAN

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy hability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of .
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed.
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

# > Back to OneMotoring

# Enquire PARF/COE Rebate for Registered Vehicle

**Vehicle Owner Particulars** 

Owner ID Type: Company
Owner ID: 5369K

Vehicle Details

Vehicle No.: SHB306M

Vehicle to be Exported: No

Intended Deregistration Date: 09 May 2019
Vehicle Make: TOYOTA

Vehicle Model: PRIUS TAXI (SMRT)

Primary Colour: Maroon
Manufacturing Year: 2014

Engine No.: 2ZR6107521

Chassis No.: JTDKN36UX05747663 Maximum Power Output: 100.0 kW (134 bhp)

Open Market Value: \$32,920.00
Original Registration Date: 20 Aug 2014
First Registration Date: 20 Aug 2014

Transfer Count:

Actual ARF Paid: \$8,088.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 19 Aug 2022
PARF Rebate Amount: \$6,066.00

Intended COE Rebate Details

COE Expiry Date: 19 Aug 2022

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$50,088.00
COE Rebate Amount: \$20,516.00
Total Rebate Amount: \$26,582.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 09 May 2019

OK



# Case Details

Case Reference Number :

TAX/05/19/2037

Type of Repair : Accident Repair

Vehicle Registration Number ; SHB306M

Company Type: SMRT Taxis Pte Ltd

Estimation ID: EST-6814-ID

Assigned By: Taxi Claims Manager

Insurance Company Name: NTUC Income Insurance Co-operative

Accident Date and Time: 08/05/2019 02:42 AM

Vehicle Age(In Months): 57

# Documents / Photographs

View Documents / Photographs

Total Documents: 1

# **Estimation Details**

### Spare Part's Cost Detail

				SMRT Re	ecomm	nendation							Surveyor Approval	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(S)	List Price(S)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	1	0	Repair +	R
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92 38.92	Replace *	nlc
One Time Key In	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give *	m
One Time Key In	Main			FENDER LINER PAD, FR WHEEL. RH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give •	hn
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair •	R
One Time Key In	Main			DOOR FRT/RH	1	894,40	894.40	25.00	670.80	Replace	1	670.80	Replace •	DEP
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace •	nec
One Time Key In	Main			MIRROR ASSY, RH	1	1,307.10	1,307.10	25.00	980.32	Replace	0	0	Not Give ▼	wu
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	107,40	107.40	25,00	80,55	Replace	1	80.55	Replace v	mls
One Time Key In	Main			MIRROR LAMP RH	1	65.30	65.30	10.00	58.77	Replace	1	58.77	Replace *	SCR

Total Spare Part Cost 4,216.00 Lump Sum Discount (%) 20.00

Surveyor Total 909.04

Lump Sum Dis (%)

Final Spare Part Cost 3,372.80

Final Sur Total 727.23

				SMRT Re	comme	endation						s	urveyor Approval	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(S)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MOULDING BODY, RH	1	673.60	673.60	25.00	505.20	Replace	0	0	Not Give *	Xnn
						т	otal Spare F	Part Cost	4,216.00			Surveyor Total	909.04	
						Lum	p Sum Disc	count (%)	20.00		Lum	np Sum Dis (%)	20	
						F	inal Spare F	Part Cost	3 372 80			Final Sur Total	797 93	

### Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
18	Main	TO REPAIR RH PORTION	676.00	400	
Total:			676.00	400.00	

### Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(S)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
2	Main	TO RESPRAY RIM	180.00	50	
3	Main	TO RESPRAY FRONT DOOR RH	378.00	200	
4	Main	RESPRAY MIRROR COVER RH	180.00	40	
5	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	0	
Total:			1,296.00	490.00	

# Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO TRANSFER DOOR MECHANISM	120.00	50	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
5	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	20	
6	Main	TO WASH AND VACUUM	60.00	0	

110.00

700.00

5/9/2019			https://vacsweb.s				
S.No.	Costing Type	Job Scope	SMRT Recommendation(S)	Surveyor Adjustment(\$)	Remarks		
*7	Main	TO REPLACE SUNDRY PARTS	100.00	0			

110.00

8260.30

# Summary

Total:

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,372.80	727.23
Total Labour Cost	676.00	400.00
Total Spray Painting	1,296.00	490.00
Other	700.00	110.00
Overall Total	6,044.80	1,727.23
Lump Sum Repair Option	2	•
Lump Sum Total	6,050.00	1,750.00
Surveyor Approved Amount		1,750.00
No of Repair Days*	5	3
Remarks	8	L/S REPAIR, PHOTO AFTER PAINT.
Surveyor Name		Hwee jie
Signature		~ \ 1L.
		O Jungant 18
		PHZIOI
		Save Clear
Survey Date	09/05/2019	

the Repairer of the following:
To resurvey betoreratter spray painting
To display damaged part(s) during resurvey
Parts prices are subject to confirmation.
Third party survey is on a "Without Prejudice" basis
No illegal modification(s) is allowed
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:

Date:



### SMRT Accident Vehicle Repair Estimates


SMRT Automotive Services Pte Lid 50 Weedlands Industrial Park E4, Singapore 757705 FAX Number 02083592 Estimator Telephone Number 08652923 Accident Reporting Number 08502072


Date Generated : 18/06/2019 : PahSuan

Shinn chan

	Section A - Accident Details
Registration Number	SHB306M
Case Reference Number	TAX/05/19/2037
Registration Date	20/8/2014
Company Type	SMRT Taxis Pte Ltd
Make	тоуота
Model	PRIUS
Name of Driver	GOH SHEW PENG
Type of Accident	Head To Side
Accident Date and Time	8/5/2019 10:42 AM
Accident Reported Date and Time	8/5/2019 12:55 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101429
Special Instruction to ARC, if any	TP
Prepared Date and Time	9/5/2019 8:50 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Summary of Repair Estimate	15	
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$400.00
Total Spray Cost	\$1,296.00	\$490.00
Total Spare Part Cost	\$3,372.80	\$909.05
Total Other Cost	\$700.00	(\$249.05)
TOTAL COST	\$6,044.80	\$1,550.00 (L/S)
Lump Sum Total	\$6,050.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Kim Ming Chin	Hwee Jie (LKK) / NTUC
ARC / Surveyor Sign Off Date	09/05/2019 3:29 PM	09/05/2019 1:09 PM
Signature	Ø	•
Remarks		L/S REPAIR, PHOTO AFTER PAINT





healta

L/5 \$1550/- 3days.



### SMRT Accident Vehicle Repair Estimates

SHRT Automotive Services Pta Ltd
00 Woodbards Industrial Park E4, Singapore 757705
FAX Number - 63563592
Estimator Teraphone Number - 68562629
Accident Reporting Number - 68661612

Date Generated : 12,660019 User ID : PohSuan

	Section C - Quota	tion and Accident Invoice Details	
Quotation Number	QN-1905-0446	Invoice Number	PERSONAL PL
Quotation Date	24.05.2019	Invoice Date	
Invoice Amount		Prepared Date	-

	Section D - Details of Repair Estimates	
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if
TO REPAIR RH PORTION	\$676.00	applicable \$400,00
Total Labour	\$676.00	\$400.00

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
RESPRAY MIRROR COVER RH	\$180.00	\$40.00
O RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,296.00	\$490.00

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$50.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20,00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
ump Sum Adjustment by Surveyor	\$0.00	(\$359.04)
Total Other Costs	\$700.00	(\$249.04)

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor	
		53801- 47050	FENDER FRT/RH	1,00	\$723.40	100.00	\$0.00	Replace	Repair	V
		75374- 47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	_
		53875- 47030	FENDER LINER FRT/RH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given	)
	Junier -	53851- 47040	FENDER LINER PAD, FR WHEEL, RH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	y
		42611 47140(Frt)	WHEEL DISC, FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair	1
less de l'inter		67001- 47070	DOOR FRT/RH	1.00	\$894.40	25.00	\$670.80	Replace	Replace	-
7.000			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	7
		87910- 47330	MIRROR ASSY, RH	0.00	\$1,307.10	0.00	\$0.00	Replace	Not Given	X
		879157- 4010	COVER, OUTER MIRROR, RH	1.00	\$107.40	25.00	\$80.55	Replace	Replace	1



#### SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Lnd 69 Woodlands Industrial Park E4, Singapore 757705 PAX Number 19369502 Estimato: Telephone Number 186502623 Accident Reparting Number 188602672

Date Generaled : 10/06/2019 User ID : PohSuan

	81730- 52090	MIRROR LAMP RH	1.00	\$65,30	10.00	\$58.77	Replace	Replace	
	75851- 47900	MOULDING BODY, RH	0.00	\$673.60	0.00	\$0.00	Replace	Not Given X	nn
Total				\$5,588.30		\$909.05			

Added Spare Parts / Material Usage After Surveyor Signed off									
Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price	ARC Check	Surveyor
Total								The second second	OHOUR ISSUE

909.05 + 400.00 + 800.00 + 800.00 - 1909.05 - 20% - 1527.24 - 1527.24



# **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315



Reg. No: 52983356E GST Reg. No. 20-0405911-H

NTU	C INCOME INSUR	ANCE CO-OPERATIVE LTD	Ref:	NS/INC1900832	27/Jqd3s2
73 B #05- 1895		D UNION HOUSESINGAPORE	Date:	01-07-2019 INC4	
1.		Policy Particulars			
	Insured Veh.	SMA 4201B	_	nspected	SHB 306M
	Policy No.	5087272209-03	_	age (\$)	0.00
	Claim No.	MT/1043566-004	Exces	-	0.00
	Assign From	\$100.00 To \$59.00 \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$	0.0000000000000000000000000000000000000	n Date	09/05/2019
2.		Vehicle Parti		01707413506	
	Make & Model	TOYOTA PRIUS	c.c		1798
	Engine No.	HIDDEN	Year	of Reg.	2014
	Chassis No.	JTDKN36UX05747663	Colou		MAROON
	Odometer	613407	Steeri	ng	IN ORDER
	Brakes	IN ORDER		ication	SPORTS RIM
	General	GOOD			
3.		Condit	ions of	Tyres	
		Size	Make		Balance
	R/H Front Tyre	195/65R15	FALKE	N	6 mm
	L/H Front Tyre	195/65R15	FALKE	N	6 mm
	R/H Rear Tyre	195/65R15	FALKE	N	6 mm
	L/H Rear Tyre	195/65R15	FALKE	N	6 mm
4.		Descripti	NAME OF TAXABLE PARTY.	amages	See Side all
	THE VEHICLE SU	STAINED DAMAGES AT THE O/S	BODY.		
	DAMAGES SEE D	ETAILS.			
5.	Safet Miles	Genera	l Inform	nation	
	<b>Accident Date</b>	08/05/2019		ction Date	09/05/2019
	Survey held at	SMRT AUTOMOTIVE SERVICE	S PTE L	.TD	
		60 WOODLANDS INDUSTRIAL	PARK E	4 SINGAPORE 757	7705
5a.			emarks	The second secon	
	A)THE INSPECTION	ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W	THOUT P	REJUDICE" BASIS NOT AUTHORISE	C REPAIRS.
5b.	E ATT TO CONDAIN	Estimate			
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:		3 Working Days	



# **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





# ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 306M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
	DOOR FRT/RH (DISC 25%)	DEFORMED	894.40	670.80
	COVER, OUTER MIRROR, RH (DISC 25%)	MISSING	107.40	80.55
100	MIRROR LAMP RH (DISC 10%)	SCRATCHED	65.30	58.77
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
	FENDER LINER FRT/RH	NOT NECESSARY	171.70	
1	FENDER LINER PAD, FR WHEEL, RH	NOT NECESSARY	49.30	
1	MIRROR ASSY, RH	NOT NECESSARY	1,307.10	E 2
1	MOULDING BODY, RH	NOT NECESSARY	673.60	
1	FENDER FRT/RH	TO REPAIR SEE	723.40	
1	WHEEL DISC, FRONT	TO REPAIR SEE LABOUR	1,484.20	
			5,588.30	909.05
	LABOUR			
	PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF FENDER FRT/RH AND WHEEL DISC, FRONT.		676.00	400.00
	SPRAY PAINT.		1,296.00	490.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO TRANSFER DOOR MECHANISM.		120.00	50.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	20.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)		120.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	25
			2,672.00	1,000.00
	GRAND TOTAL		8,260.30	1,909.05
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,550.00

Report Ref No. NS/INC19008327/Jqd3s2





Report Ref No. NS/INC19008327/Jqd3s2

ONG HWEE JIE

**Automotive Assessor** 

M.

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.