

ASS. REC. BY:

REF: CS/FJ 19008342/T19d3n2 Special Instruction:

(CWS)

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person): Sorani of FCI Date/Time: 10.5.19 3.07pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGX 6642Z Insured: SHC 8509L

at Workshop m/s 3A Automobile Tel: 67387777

of 120 Lower Delta RD #02-15

Policy No: Claim No: D19003093MFSH

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 6.5.2019

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 10.5.19 3.13pm Person Contacted: Enjo Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SGX 6642Z-X
	SHC 8509L - MS/INC 18022202/Kloba2 DOA-07/12/2018
14/5/19 @ 3.45pm	revised to Sorani lev by email.
07/8/19 @ 6.23pm	Confirmed with Enjo vs \$650, 2 days. Cled \$786.08, 55%
	* MV: \$151000; LTA: \$14938; NV: 63062


Signature *Tanfer*

REF: FC/

ASSIGNMENT

2022 Aug  
2007 Aug

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop no/s: \_\_\_\_\_  
 of: \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bat. or Market Value: \$18K  
 IDAC Accident Rpt: Consistent? : Yes or No  
 GIA / PR Seen: Consistent? : Yes or No  
 Est. Repairs: 2 days Res.: Yes or No  
 Lump Sum: % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT



Veh No: 59X66422 V Regn: \_\_\_\_\_  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Honda Jazz cc 1339  
 Colour: Blue A/C: Insured / Std / Nil / NA  
 Sp. Reading: 249857 T/Radio: Insured / Std / Nil / NA  
 Eng/No: 249857  
 C/No: JHM90185075225353  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / SRim / STD AIRim or  
 Tyre Size: F: 195/55R15  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Westlake  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: 6 mm R/Bal: 6 mm  
 L/Bal: 6 mm L/Bal: 6 mm  
 D.O.A: \_\_\_\_\_ D.O.I: 10/5/19C1715  
 Survey held at 34 Auto.  
 Des. of Damages: Fnt / Rear / O/S / MS / U/C / Rooftop or  
 Rear n/s  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 13 AUG 2019

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: 2  
 Resurvey No. of Trip: 1

Report Format: TP  
 Lump Sum / I.B. (\$) 650

Add Fee:  Site Insp (\$)  Interview (\$)  Tech Insp (\$)  Weekend (\$)

Survey Fee:	100
Transportation:	50
Site Insp. (\$)	50
Photo:	23
Other:	
TOTAL	223



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003093MFSH

Date: 14 May 2019

Our Ref: CS/FC119008348/T1qd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SGX 6642Z**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 10/05/2019 at the premises of M/s 3A AUTOMOBILE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,436.08</u>
Revised Estimate Amount	: S\$ <u>814.88</u>
“Check” Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Yours faithfully

Taufikh  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	10-05-2019	<b>Our Ref No.</b> D19003093MFSH
<b>Accident Date</b>	06-05-2019	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHC8509L	<b>Third Party Vehicle.</b> SGX6642Z
<b>Survey Location</b>	120 LOWER DELTA ROAD #02-15 CENDEX CENTRE	
<b>Contact Person.</b>	ENJO HO	
<b>Contact No.</b>	62231122/ 0	<b>Fax No.</b> 67386666
<b>Survey Type</b>	WITHOUT PREJUDICE:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	3A AUTOMOBILE PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	SERENE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Shiau Chan (LKKAuto)

---

**From:** Enjo Ho <enjo.ho@bkw.sg>  
**Sent:** Wednesday, 7 August 2019 6:23 PM  
**To:** Shiau Chan (LKKAuto); SUR  
**Cc:** Kenneth Tan; Winnie Fan; Bowie Teng  
**Subject:** RE: After repair - SGX6642Z  
**Attachments:** LOD.pdf

Dear Ms Chan,

We agreed COR at lump sum cost of repair is at \$ 650.00 and 02 repair days.  
Please find attached LOD FYNA.

Warmest regards,  
ENJO HO

---

**From:** Shiau Chan (LKKAuto) <siewsc@lkkauto.com>  
**Sent:** Monday, 17 June, 2019 2:31 PM  
**To:** Enjo Ho <enjo.ho@bkw.sg>; SUR <sur@lkkauto.com>  
**Cc:** Kenneth Tan <kenneth.tan@bkw.sg>; Winnie Fan <winnie.fan@bkw.sg>; Bowie Teng <bowie.teng@bkw.sg>  
**Subject:** RE: After repair - SGX6642Z

Dear Enjo,

WITHOUT PREJUDICE

Offer Lump Sum \$650.00 and 2 repair days.

Kindly check and confirm.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Enjo Ho <enjo.ho@bkw.sg>  
**Sent:** Wednesday, 15 May 2019 10:40 AM  
**To:** CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>  
**Cc:** Kenneth Tan <kenneth.tan@bkw.sg>; Winnie Fan <winnie.fan@bkw.sg>; Bowie Teng <bowie.teng@bkw.sg>  
**Subject:** After repair - SGX6642Z

Dear Sir/Mdm,

We have attached after repair photos for vehicle SGX6642Z.

Please let us have the finalised amount asap.

Thank you and Have a nice day :) Cheers

Warmest regards,

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Tuesday, 14 May 2019 3:45 PM  
**To:** 'CWS Motor Claims'; assignments; SUR  
**Cc:** 'Serene Ler'  
**Subject:** RE: SURVEY ASSESSMENT - D19003093MFSH/1  
**Attachments:** CSFC19008348T1qd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SGX 6642Z.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Friday, 10 May 2019 3:43 PM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** 'Serene Ler' <[Sereneler@msfirstcapital.com.sg](mailto:Sereneler@msfirstcapital.com.sg)>  
**Subject:** RE: SURVEY ASSESSMENT - D19003093MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Best Regards,

**Summer Lee** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Friday, 10 May, 2019 3:07 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Serene Ler <[Sereneler@msfirstcapital.com.sg](mailto:Sereneler@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D19003093MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	6276D
<b>Vehicle Details</b>	
Vehicle No.:	SGX6642Z
Vehicle to be Exported:	No
Intended Deregistration Date:	14 May 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.4A
Primary Colour:	Blue
Manufacturing Year:	2007
Engine No.:	L13A54002499
Chassis No.:	JHMGD18507S225383
Maximum Power Output:	60.0 kW (80 bhp)
Open Market Value:	\$13,611.00
Original Registration Date:	30 Aug 2007
First Registration Date:	30 Aug 2007
Transfer Count:	2
Actual ARF Paid:	\$14,973.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Aug 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$22,700.00
COE Rebate Amount:	\$14,938.00
<b>Total Rebate Amount:</b>	<b>\$14,938.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 14 May 2019

OK

Text size + -

**Enquire Vehicle Registration Details****Owner Particulars**

NRIC/Passport/Company Cert No.: 200106276D  
 Owner ID Type: Company  
 Owner Name: B K W RENT A CAR PTE LTD  
 Registered Address: 120 LOWER DELTA ROAD #02-15 CENDEX CENTRE SINGAPORE 169208  
 Mailing Address: -  
 Birth Date: -

**Vehicle Particulars**

Vehicle No.: SGX6642Z  
 Previous Vehicle No.: -  
 Effective Date of Ownership: 15 Aug 2017  
 Original Regn Date: 30 Aug 2007  
 Registration Date: 30 Aug 2007  
 Year of Manufacture: 2007  
 Vehicle Type: Private Hire (Self-Drive) Motor Car  
 Vehicle Scheme: -  
 Vehicle Attachment 1: No Attachment  
 Vehicle Attachment 2: -  
 Vehicle Attachment 3: -  
 Vehicle Make: HONDA  
 Vehicle Model: JAZZ 1.4A  
 Primary Colour: Blue  
 Secondary Colour: -  
 Passenger Capacity: 4  
 Chassis No.: JHMGD18507S225383  
 Engine No.: L13A54002499  
 Engine Capacity/Power Rating: 1339 cc / -  
 Maximum Power Output: 60.0 kW (80 bhp)  
 Propellant: Petrol  
 Max Unladen Weight: 1040 kg  
 Maximum Laden Weight: 1490 kg  
 Open Market Value: \$13,611.00  
 PARF Eligibility: Yes  
 PARF Eligibility Expiry Date: 29 Aug 2017  
 Minimum PARF Benefit: \$7,486.00  
 No. of Transfers: 2  
 IU Label No.: 1121575790  
 COE No.: 2007090101000186D  
 COE Expiry Date: 29 Aug 2022  
 COE Category: A - Car (1600cc & below)  
 COE Registration Category: A - Car (1600cc & below)

# 3A Automobile Pte Ltd

No 120 Lower Delta Road #02-15 Cendex Centre Singapore 169208 Tel: 6223 1122 Fax: 6738 6666

## Estimate Report

Date: 10-May-2019

MS First Capital Insurance Ltd

36 Robinson Road

#16-01

Singapore 068877

Email: MotorClaims@msfirstcapital.com.sg

Attn: Claims Officer

Dept: Motor Claim Department

Vehicles Number: SGX 6642 Z

Make and Model: Honda Jazz 1.4A

Date Of Accident: 6-May-2019

Tel: 65073848

Fax: 65073849

Unit	List Items	Units Price	Prices
1	pc	Rear Bumper	\$ 490.60
1	pc	Bumper Retainer	\$ 26.50
8	pcs	Bumper Clips	\$ 3.50
<b>S/Total</b>			\$ 545.10
<b>Less 20%</b>			(\$109.02)
			<b>\$ 436.08</b>

de ✓  
kan  
all ✓

1	pc	Reverse Sensor	\$ 200.00
			\$ 636.08

xm

### Labour Charges

To Remove & Replace the Damaged Parts as Listed Above, including Reinstatements of necessary Attachments & Fittings to Facilitate Repairs; Jack, Panel Beat & Reshape the Affected Parts & Components, Correct & Realign the Necessary Parts.	\$ 450.00
To Provide Skill Labour & Material to do Surface Treatment / Epoxy Treatment and to Respray with 2K Paint On All Affected Areas with Oven Spray Booth Facilities.	\$ 350.00
<b>Total</b>	<b>\$ 1,436.08</b>

200

200

*[Handwritten signature]*  
14/5/19

Yours faithfully,

3A Automobile Pte Ltd

Person to contact: Alwin / Enjo

Mobilephone : 9786 8677 / 6223 1122

Tanpin 9749 5749  
-wp-

6/5/19 @ 5:15 pm

02 days

Inspsun.  
Resurvey after repair

Sur @ lkkauto.com

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19008348/T1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 13-08-2019	
		Code : FC12	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8509L	Veh. Inspected	SGX 6642Z
Policy No.		Coverage (\$)	0.00
Claim No.	D19003093MFSH	Excess (\$)	0.00
Assign From	SERENE LER	Assign Date	10/05/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA JAZZ	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JHMGD18507S225383	Colour	BLUE
Odometer	249857	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/55 R15	WEST LAKE	6 mm
L/H Front Tyre	195/55 R15	WEST LAKE	6 mm
R/H Rear Tyre	195/55 R15	WEST LAKE	6 mm
L/H Rear Tyre	195/55 R15	WEST LAKE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	06/05/2019	Inspection Date	10/05/2019
Survey held at	3A AUTOMOBILE PTE LTD BLK 120 LOWER DELTA ROAD #02-15 SINGAPORE 169208		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGX 6642Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	DEFORMED	490.60	490.60
1	BUMPER RETAINER	NOT NECESSARY	26.50	-
8	BUMPER CLIPS @\$3.50 LESS 20% DISCOUNT	NECESSARY	28.00 -109.02	28.00 -103.72
			436.08	414.88
<b>SPECIAL NETT ITEMS</b>				
1	REVERSE SENSOR (SN)	NOT NECESSARY	200.00	-
			200.00	-
<b>LABOUR</b>				
	TO REMOVE & REPLACE THE DAMAGED PARTS AS LISTED ABOVE,INCLUDING REINSTATEMENTS OF NECESSARY ATTACHMENTS & FITTINGS TO FACILITATE REPAIRS;JACK,PANEL BEAT & RESHAPE THE AFFECTED PARTS & COMPONENTS,CORRECT & REALIGN THE NECESSARY PARTS.		450.00	200.00
	TO PROVIDE SKILL LABOUR & MATERIAL TO DO SURFACE TREATMENT/EPOXY TREATMENT AND TO RESPRAY WITH 2K PAINT ON ALL AFFECTED AREAS WITH OVER SPRAY BOOTH FACILITIES.		350.00	200.00
			800.00	400.00
<b>GRAND TOTAL</b>			<b>1,436.08</b>	<b>814.88</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>650.00</b>

Report Ref No. CS/FCI19008348/T1qd3n2

MARKET VALUE: \$18,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,938.00=NETT VALUE: \$3,062.00

MOHAMAD TAUFIKH  
M.MATAI, AMSAE-A  
Automotive Assessor

ADRIAN LING WAI PING  
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI  
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.