

ASS. REC. BY:

REF: (S/CT1 1900 8383) E+d302

Special Instruction:

Survivor: Steve

ASSIGNMENT (Office)

From (Person): Chong Bun Sen

of CT1

Date/Time: 10.5.19 17.09p.m.

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SMG 2971 T

Insured:

at Workshop m/s cycle or carriage  
of 188 Pandan Loop

Tel: 91865113

Policy No: DMPCSN 19035919000

Claim No: SVM19D 2020 91 C01

Sum Insured:

Excess:

500/-

Make of Veh:

(Client's Record)

D.O.A. 9.5. 2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 13.5.2019 9.35am

Person Contacted:

Kerlyn

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMG 2971 T-X
14/5-	Revert via menmen
15/5-9:15	mandate approved by Irene Tan Hui Ping
15/5@9:26am	- email proceed to repair excess \$500 to Kerlyn
	Part by part \$4314.63; (Red: 2522.27, 36%)

ASSIGNMENT

From \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop in/s: \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured \_\_\_\_\_  
 Policy No \_\_\_\_\_  
 Claims No \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No SMG 2971T Vi Regn. 28/09/15  
 Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Mercedes benz CLA 180 cc 1595  
 Colour White A/C Insured / Std / NI / N/  
 Sp.Reading 41855 T/Rndr: Insured / Std / NI / N.

Eng/No: \_\_\_\_\_  
 CiNo: W 00 1173422N 257672  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 225/40R18  
 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 7 mm R/Bal. 7 mm  
 L/Bal. 7 mm L/Bal. 7 mm  
 D.O.A. 9/5/19 D.O.I. 13/5/19

Survey held at C & C

Des. of Damages Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time : \_\_\_\_\_ Action / Instruction

Mr - 99K

RECEIVED 22 MAY 2019

Date/Time, File Pass to:

22/5 Typst

Date/Time, File Return to:

21

Report Format:

Lump Sum / I.B. 4314.63

☐ : Prel. Report

☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation

☐ : S + R + G

☐ : Photos

☐ : Labels

☐ : ...

220

220

220

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 May 2019		10 May 2019 17:09 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <div style="float: right;">[Created by insurer]</div>									
Insured:	LIM SHEAU CHIA (LIN QIAOJIA), ID: S7977388C, Tel: +6596441455, Email: NOEMAIL								
Vehicle Reg. No.:	SMG2971T	Date of Loss:	09/05/2019 16:00 - :59						
Claim Type:	OD / SNM19D202091C01	Policy/Cover Note No.:	DMPCSN19035919000 (Comprehensive)						
		Excess:	S\$500.00						
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/05/2019]								
Driver/Custodian:	LIM SHEAU CHIA (LIN QIAOJIA) (39 / Male), NRIC: S7977388C, Tel: +6596441455 Email: NOEMAIL								
<b>ASSOCIATED MAIL RECEIVED</b> <div style="float: right;"> <a href="#">View All</a> <a href="#">Compose Case Mail</a> </div>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <div style="float: right;"> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </div>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Wednesday, 15 May 2019 9:26 AM  
**To:** kerlyn.ong@cyclecarriage.com.sg  
**Cc:** vincent.seah@cyclecarriage.com.sg  
**Subject:** SMG 2971T CHINA TAI PING

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SMG 2971T (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Wednesday, 22 May 2019 9:38 AM  
**To:** Mei Kwan (LKKAuto); Kerlyn Ong; Steve Chen (LKK Auto)  
**Cc:** Admin A; Admin-D (LKKAuto)  
**Subject:** RE: SMG2971T \*\*\* LKK REF: ref: CS/CTI19008383/Etd3  
**Attachments:** CHINA TAIPING (DV)\_0001.pdf

Dear Kerlyn,

Confirm final figure at \$4,314.63 before GST and excess

Working days 3

Attached China Taiping Discharge voucher.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Mei Kwan (LKKAuto)  
**Sent:** Tuesday, 21 May 2019 8:59 AM  
**To:** Kerlyn Ong <[kerlyn.ong@cyclecarriage.com.sg](mailto:kerlyn.ong@cyclecarriage.com.sg)>; Steve Chen (LKK Auto) <[SteveChen@lkkauto.com](mailto:SteveChen@lkkauto.com)>  
**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Subject:** RE: SMG2971T \*\*\* LKK REF: ref: CS/CTI19008383/Etd3

'WITHOUT PREJUDICE'  
SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Hi Steve,

FYNA please. Our ref: CS/CTI19008383/Etd3.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## View Received Message

This mail is associated with :

**\*SMG2971T (SNM19D202091C01)**

OD

May 9 2019 4:00PM

[LIM SHEAU CHIA (LIN QIAOJIA)]  
Cycle & Carriage Industries Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on 15/05/2019 09:15 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$5385.19) - SMG2971T - Claim Handler: Chong Boon Sen

Approved:5385.19.

### DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chong Boon Sen

Date: 14 May 2019

**Preliminary Advice**

Vehicle No	: SMG2971T	Accident Date	: 09/05/2019
Make	: MERCEDES-BENZ CLA180	Policy No.	: DMPCSN19035919000
Assignment Date	: 10/05/2019	Excess	: S\$500.00
Date of Inspection	: 13/05/2019	Est. Duration of Repair	: 3.00
Inspection At	: CYCLE & CARRIAGE INDUSTRIES PTE LTD (PANDAN LOOP) 188 PANDAN LOOP SINGAPORE 128378		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,836.90
Revised Amount	:S\$	5,134.86
Check Items (Estimated)	:S\$	250.33
Total	:S\$	5,385.19
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	99,000.00
COE / PARF Rebate	:S\$	55,237.00
Salvage Value	:S\$	
Margin for Repair	:S\$	43,763.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	7388C
<b>Vehicle Details</b>	
Vehicle No.:	SMG2971T
Vehicle to be Exported:	No
Intended Deregistration Date:	13 May 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CLA180 (R18 BI)
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	27091030737872
Chassis No.:	WDD1173422N257672
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$27,247.00
Original Registration Date:	28 Sep 2015
First Registration Date:	28 Sep 2015
Transfer Count:	1
Actual ARF Paid:	\$25,146.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Sep 2025
PARF Rebate Amount:	\$18,859.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	27 Sep 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,089.00
COE Rebate Amount:	\$36,378.00
<b>Total Rebate Amount:</b>	<b>\$55,237.00</b>

The information contained herein is correct as at 13 May 2019

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/05/2019 14:32
Date Of Accident	09/05/2019 16:45
Exact Location Of Accident	SHAW TOWER CARPARK EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMG2971T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM SHEAU CHIA (LIN QIAOJIA)
NRIC No	S7977388C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96441455
Alternative Phone No	OFFICE-96441455
<b>Vehicle Particulars</b>	
Manufacturer	MERCEDES-BENZ
Model	CLA180
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	
<b>Driver</b>	
Name of Driver	LIM SHEAU CHIA (LIN QIAOJIA)
NRIC No	S7977388C
Date Of Birth	19/10/1979
Occupation	INDOOR
Date Of Driving Pass	14/05/1999
Driving Experience	19 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96441455
Fax Number	
Contact Number	OFFICE-96441455
Email Address	NOEMAIL

Address	BLK 7 CLAYMORE ROAD #15-04
Postcode	229538
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS DRIVING MY CAR ALONG SHAW TOWER CARPARK EXIT TOWARD THE MAIN ROAD. THE FLOOR WAS WET WHILE I WAS DRIVING DOWNSLOPE AND IT WAS A BEND. AS I WAS MOVING ALONG THE BEND, SOMEHOW MY CAR SKIDDED AND COLLIDED ONTO RIGHT FRONT PORTION.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time 10/05/2019 1339

Driver's Signature

(If driver is not the policyholder)

Date & Time

**Kerlyn Ong Kai Li**  
DID : 6771 4420 HP : 9186 5113  
Email : kerlyn.ong@cyclecarriage.com.sg  
Cycle & Carriage Industries Pte Ltd  
Customer Service Centre - Pandan Loop


Reporting Centre Personnel's

Name: KERLYN

NRIC/FIN No.:

SKETCH PLAN

A : SMG2971T



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING MY CAR (SMG2971T) ALONG SHAW TOWER CARPARK EXIT TOWARD THE MAIN ROAD. THE FLOOR WAS WET WHILE I WAS DRIVING DOWNSLOPE AND IT WAS A BEND. AS I WAS MOVING ALONG THE BEND, SOMEHOW MY CAR SKIDDED AND COLLIDED ONTO RIGHT FRONT PORTION.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

**Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.**

(Please contact your insurance company for any further details)

Policyholder's Signature

Date & Time 10/05/2019 1339

Driver's Signature

(If driver is not the policyholder)

Date & Time

**Kerlyn Ong Kai Li**

DID : 6771 4420 HP : 9186 5113

Email : kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop  
Reporting Centre Personnel's

Name: KERLYN

NRIC/FIN No.:

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S7977388C**

Name:

**LIM SHEAU CHIA**  
(LIN QIAOJIA)

Birth Date: **19 Oct 1979**

Issue Date: **29 Sep 2003**



FOR C&C USE ONLY

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. **S7977388C**



Name

**SHAWN LIM SHEAU CHIA**  
(LIN QIAOJIA)

林 俏 伽

Race

**CHINESE**

Date of birth

**19-10-1979**

Country/Place of birth

**MALAYSIA**

Sex

**M**

**S7977388C**



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

**14 May 1999**

NP 428A



Licence No: **S7977388C**

FOR C&C USE ONLY

**5568377**



NRIC No: **S7977388C**



Date of issue

**01-03-2016**

**7 CLAYMORE ROAD #15-04**  
**SINGAPORE 229538**

NRIC No: **S7977388C**

Date: **13/09/2017**

Steve (LKK) OD - Not Authorised (Revert)  
83228813 13/5/19 11:30am  
EXCESS - \$500.00



Mercedes-Benz

PIP, Resurvey before spray  
3 days

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

ESTIMATE FOR SMG2971T\*RA

CHINA TAIPING INSURANCE (S) PTE LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

Vehicle & Document Information  
WIP No 33251  
Reg No/Reg Date SMG2971T\*RA / 28/09/2015  
Date In/Mileage / 0  
Chassis No WDD1173422N257672  
Engine No 27091030737872  
Make/Model MB/CLA 180 (C117) "URBAN"  
Colour/Trim 026 650 Calcit Whit/ 041 151-Leather Twi

Account No	Terms	Date/Time Printed	CSE	Operator				
WC000668	Credit	10/05/2019/ 14:00	K0	301 / Kerlyn Ong				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : // 09/05/2019								
TOWED IN/EXCESS : 09/05/2019 //								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
A BPILAB								
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH. 960								960 1920.00
A BPIRES								
RESpray FRONT BUMPER 600								600 960.00
A BPILAB							0.10	380.00 /
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT								
A BPILAB								540.00 /
TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT								
S BPNSUB								60.00 /
TRANSFER RIM AND BALANCING TYRE. NETT								
PURCHASE ORDER NO:								
S BPNSUB								266 380.00
SUPPLY RH/ FRONT TYRE x 1 - 1M (70%)								
PURCHASE ORDER NO:								
M FRONT BUMPER 9 X NAI					1.00	1353.79	00.00	1353.79
M RH/ FRONT WHEEL HOUSE COVERING - 11/5					1.00	188.53	00.00	188.53
M RH/ FRONT FENDER INTERMEDIATE LAYER - 11/5 X NAI					1.00	17.71	00.00	17.71
M FRONT BUMPER UNDER COVER - 11/5 X NAI					1.00	326.11	00.00	326.11
M FRONT BUMPER COMPANY SIGN - 11/5 X NAI					1.00	61.80	00.00	61.80
M RH/ FRONT DISK WHEEL - 11/5					1.00	648.96	00.00	648.96

K Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Confirmed & accepted by

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

Kerlyn Ong Kai Li  
DID: 6771 4420 HP: 9186 5113  
Email: kerlyn.ong@cyclecarriage.com.sg  
Cycle & Carriage Industries Pte Ltd  
Customer Service Centre - Pandan Loop

Nett 6,836.90  
7% GST on 6836.90 478.58  
Total Payable 7,315.48

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SMG2971T\*RA

CHINA TAIPING INSURANCE (S) PTE  
LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

### Vehicle & Document Information

WIP No 33251  
Reg No/Reg Date SMG2971T\*RA / 28/09/2015  
Date In/Mileage 15/05/2019 / 41855  
Chassis No WDD1173422N257672  
Engine No 27091030737872  
Make/Model MB/CLA 180 (C117) "URBAN"  
Colour/Trim 026 650 Calcit Whit/ 041 151-Leather Twi

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	17/05/2019/ 14:38	K0	301 / Kerlyn Ong
Description of Goods / Services				
Qty	Unit Price	Disc%	Amount	

<b>THIS IS NOT AN OFFICIAL TAX INVOICE</b>				
<b>ESTIMATE</b>				
Z REQUEST				
Customer Request				
M BPNSUB				
POLICY NO/ACC DATE : // 09/05/2019				
TOWED IN/EXCESS : 09/05/2019 // \$500				
DATE IN/DATE SURVEY: 13/05/2019 1130 // LKK - STEVE				
BY/AUTHORIZED ON : 15/05/2019 0926 // LKK - DENISE				
A BPILAB				960.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				600.00
A BPIRES				
RESpray FRONT BUMPER				380.00
		0.10		
A BPILAB				
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				540.00
A BPILAB				
TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT				60.00
S BPNSUB				
TRANSFER RIM AND BALANCING TYRE. NETT				
PURCHASE ORDER NO:				266.00
S BPNSUB				
SUPPLY & INSTALL RH/ FRONT TYRE x 1 PC				140.00
S BPNTOW				
ACCIDENT TOWING FROM MIDDLE RD TO PLSC USING KING DOLLEY				
WO: 164227				-500.00
X BPNEXC				
INSURANCE EXCESS				
	1.00	188.53	00.00	188.53
X RH/ FRONT WHEEL HOUSE COVERING	1.00	326.11	00.00	326.11
X FRONT BUMPER UNDER COVER	1.00	648.96	00.00	648.96
X RH/ FRONT DISK WHEEL	5.00	5.21	00.00	26.05
X RIVET	3.00	1.75	00.00	5.25
X PLASTIC NUT	1.00	142.47	00.00	142.47
X RH/ BASIC MOUNTING FOR BUMPER				

Confirmed & accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg





Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SMG2971T\*RA

CHINA TAIPING INSURANCE (S) PTE  
LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

### Vehicle & Document Information

WIP No **33251**  
Reg No/Reg Date **SMG2971T\*RA / 28/09/2015**  
Date In/Mileage **15/05/2019 / 41855**  
Chassis No **WDD1173422N257672**  
Engine No **27091030737872**  
Make/Model **MB/CLA 180 (C117) "URBAN"**  
Colour/Trim **026 650 Calcit Whit/ 041 151-Leather Twi**

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	17/05/2019/ 14:38	K0	301 / Kerlyn Ong
Description of Goods / Services				
	Qty	Unit Price	Disc%	Amount

X RIVET

6.00 5.21 00.00 31.26

**THIS IS NOT AN OFFICIAL TAX INVOICE**

**ESTIMATE**

Confirmed & accepted by

**Finalization**

7% GST on **3,814.63** **267.02**

**Total Payable 4,081.65**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg





Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SMG2971T\*RA

CHINA TAIPING INSURANCE (S) PTE  
LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

### Vehicle & Document Information

WIP No 33251  
Reg No/Reg Date SMG2971T\*RA / 28/09/2015  
Date In/Mileage 15/05/2019/ 41855  
Chassis No WDD1173422N257672  
Engine No 27091030737872  
Make/Model MB/CLA 180 (C117) "URBAN"  
Colour/Trim 026 650 Calcit Whit/ 041 151-Leather Twi

Account No	Terms	Date/Time Printed	CSE	Operator			
WC000668	Credit	17/05/2019/ 14:37		301 / Kerlyn Ong			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

S BPNTOW

ACCIDENT TOWING FROM MIDDLE RD TO PLSC  
USING KING DOLLEY  
WO: 164227

- X RIVET / NEC
- X PLASTIC NUT / NEC
- \* X RH/ BASIC MOUNTING FOR BUMPER / SR
- X RIVET / NEC

5.00 5.21 00.00  
3.00 1.75 00.00  
1.00 142.47 00.00  
6.00 5.21 00.00

26.05  
5.25  
142.47  
31.26

140.00

**THIS IS NOT AN OFFICIAL TAX INVOICE**

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

7% GST on **Nett 345.03**  
**24.15**  
**Total Payable 369.18**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 May 2019		10 May 2019 17:09 <a href="#">Edit Adj Rpt</a>	<b>S\$4,314.63</b> <a href="#">Edit Estimates</a>	<b>S\$4,314.63</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>





















  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>LIM SHEAU CHIA (LIN QIAOJIA)</b> , ID: S7977388C, Tel: +6596441455, Email: NOEMAIL									
Vehicle Reg. No.: <b>SMG2971T</b>		Date of Loss: 09/05/2019 16:00 - :59	[43 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type: <b>OD / SNM19D202091C01</b>		Policy/Cover Note No.: DMPCSN19035919000 (Comprehensive)							
		Excess: S\$500.00							
Repairer: <b>Cycle &amp; Carriage Industries Pte Ltd (Pandan Loop)</b> 188 Pandan Loop, 128378 West Coast - Tel: 91865300									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... [Final Rpt due 22/05/2019]									
Driver/Custodian: LIM SHEAU CHIA (LIN QIAOJIA) (39 / Male) , NRIC: S7977388C, Tel: +6596441455 Email: NOEMAIL									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>CHINA_TAIPING (15/05/2019): Alert - Adj Mandate Approved (S\$5385.19) - SMG2971T - Claim Handler: Chong Boon ...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									














## Claim Documents

\*SMG2971T (SNM19D202091C01)  
OD  
May 9 2019 4:00PM  
[LIM SHEAU CHIA (LIN QIAOJIA)]  
Cycle & Carriage Industries Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)							Thumbnail	Print		
1	10/05/19 14:37	Accident Statement							Load HTM			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print		
1	14/05/19 14:51	Adjuster Immediate Advice							Load HTM			
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)							Thumbnail	Print		
1	10/05/19 14:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>		
2	10/05/19 14:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>		
3	10/05/19 14:37	Driving License [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>		
4	10/05/19 14:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>		
5	10/05/19 14:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>		
6	10/05/19 14:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>		
7	10/05/19 14:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>		
8	10/05/19 14:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>		
9	10/05/19 14:37	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print		
1	13/05/19 19:56	Chassis Number							Load JPG	<input checked="" type="checkbox"/>		
2	13/05/19 19:56	General View							Load JPG	<input checked="" type="checkbox"/>		
3	13/05/19 19:56	General View							Load JPG	<input checked="" type="checkbox"/>		
4	13/05/19 19:56	General View							Load JPG	<input checked="" type="checkbox"/>		
5	13/05/19 19:56	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>		
6	13/05/19 19:56	General View							Load JPG	<input checked="" type="checkbox"/>		
7	13/05/19 19:56	General View							Load JPG	<input checked="" type="checkbox"/>		
8	13/05/19 19:56	General View							Load JPG	<input checked="" type="checkbox"/>		
9	13/05/19 19:56	General View							Load JPG	<input checked="" type="checkbox"/>		
10	13/05/19 19:56	General View							Load JPG	<input checked="" type="checkbox"/>		
11	13/05/19 19:56	General View							Load JPG	<input checked="" type="checkbox"/>		
12	13/05/19 19:56	General View							Load JPG	<input checked="" type="checkbox"/>		
13	13/05/19 19:56	General View							Load JPG	<input checked="" type="checkbox"/>		
14	13/05/19 19:56	General View							Load JPG	<input checked="" type="checkbox"/>		
15	13/05/19 19:56	General View							Load JPG	<input checked="" type="checkbox"/>		
16	13/05/19 19:56	General View							Load JPG	<input checked="" type="checkbox"/>		
17	13/05/19 19:56	General View							Load JPG	<input checked="" type="checkbox"/>		
18	13/05/19 19:56	General View							Load JPG	<input checked="" type="checkbox"/>		
19	13/05/19 19:56	General View							Load JPG	<input checked="" type="checkbox"/>		
20	13/05/19 19:56	General View							Load JPG	<input checked="" type="checkbox"/>		
21	13/05/19 19:56	General View							Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
				<input checked="" type="checkbox"/>
22	13/05/19 19:56	General View	 Load JPG	<input checked="" type="checkbox"/>
23	13/05/19 19:56	General View	 Load JPG	<input checked="" type="checkbox"/>
24	13/05/19 19:56	General View	 Load JPG	<input checked="" type="checkbox"/>
25	13/05/19 19:56	General View	 Load JPG	<input checked="" type="checkbox"/>
26	13/05/19 19:56	General View	 Load JPG	<input checked="" type="checkbox"/>
27	13/05/19 19:56	General View	 Load JPG	<input checked="" type="checkbox"/>
28	13/05/19 19:56	General View	 Load JPG	<input checked="" type="checkbox"/>
29	13/05/19 19:56	General View	 Load JPG	<input checked="" type="checkbox"/>
30	13/05/19 19:56	General View	 Load JPG	<input checked="" type="checkbox"/>
31	13/05/19 19:56	General View	 Load JPG	<input checked="" type="checkbox"/>
32	22/05/19 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	22/05/19 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	22/05/19 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	22/05/19 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	22/05/19 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/05/19 17:10	od estimate	 Load PDF	
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	10/05/19 14:36	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	10/05/19 14:36	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	10/05/19 14:36	Sketch Plan #3 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/06/19 09:47	Supplementary	 Load PDF	

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	10/05/19 14:37	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	10/05/19 14:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	10/05/19 14:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	10/05/19 14:37	Driving License	 Load JPG	<input checked="" type="checkbox"/>
4	10/05/19 14:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	10/05/19 14:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	10/05/19 14:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	10/05/19 14:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	10/05/19 14:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	10/05/19 14:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	10/05/19 14:36	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	10/05/19 14:36	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	10/05/19 14:36	Sketch Plan #3	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI19008383/ETD3E2

**Date:** 11/06/2019

### REFERENCE

Insured/Claimant: LIM SHEAU CHIA (LIN QIAOJIA) Policy No: DMPCSN19035919000

Date of Loss: 09/05/2019

Nature of Claim: OD

Claim No: SNM19D202091C01

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMG2971T</b>	Engine No:	27091030737872
Make & Model:	MERCEDES-BENZ CLA180, 1.6 (A)	Chassis No:	WDD1173422N257672
Reg. Date:	28/09/2015 (Man. Year: 2015)	Odometer:	41855 km
Colour:	White		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	S\$99,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,181.93	1,634.63	1,547.30	48.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,000.00	2,680.00	1,320.00	33.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,181.93</b>	<b>4,314.63</b>	<b>2,867.30</b>	<b>39.92</b>
<b>- Excess (S\$)</b>	<b>500.00</b>	<b>500.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>6,681.93</b>	<b>3,814.63</b>	<b>2,867.30</b>	<b>42.91</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>467.74</b>	<b>267.02</b>	<b>200.72</b>	<b>42.91</b>
<b>Nett Amount (S\$)</b>	<b>7,149.67</b>	<b>4,081.65</b>	<b>3,068.02</b>	<b>42.91</b>

### INSPECTION

Date of Assignment: 10/05/2019

Date Inspected: 13/05/2019 Inspected At:

Cycle & Carriage Industries Pte Ltd  
(Pandan Loop)  
188 Pandan Loop  
Singapore 128378

Estimated Period of Repair: 3.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 11 Jun 2019)
<b>Parts:</b> 143	MERCEDES-BENZ CLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMG2971T)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH / FRONT TYRE (70%)	Torn	380.00 FS	*266.00 FS
2	1		*FRONT BUMPER	Not Necessary	1,353.79 FS	*- FS
3	1		*RH / FRONT WHEEL HOUSE COVERING	Missing	188.53 FS	*188.53 FS
4	1		*RH / FRONT FENDER INTERMEDIATE LAYER	Not Necessary	17.71 FS	*- FS
5	1		*FRONT BUMPER UNDER COVER	Broken	326.11 FS	*326.11 FS
6	1		*FRONT BUMPER COMPANY SIGN	Not Necessary	61.80 FS	*- FS
7	1		*RH / FRONT DISK WHEEL	Cut	648.96 FS	*648.96 FS
8	5		*RIVET	Necessary	26.05 FS	*26.05 FS
9	3		*PLASTIC NUT	Necessary	5.25 FS	*5.25 FS
10	1		*RH / BASIC MOUNTING FOR BUMPER	Broken	142.47 FS	*142.47 FS
11	6		*RIVET	Necessary	31.26 FS	*31.26 FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (S\$)</b>					<b>3,181.93</b>	<b>1,634.63</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	New	1,920.00	960.00
2	RESPRAY FRONT BUMPER	New	960.00	600.00
3	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	380.00	380.00
4	TO INSPECT & CONDUCT WHEEL ALIGNMENT	New	540.00	540.00
5	TRANSFER RIM AND BALANCING TYRE	New	60.00	60.00
6	ACCIDENT TOWING FROM MIDDLE RD TO PLSC USING KING DOLLEY	New	140.00	140.00
Gross Labour Cost (\$\$)			4,000.00	2,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >