



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SMG2971T\*RA

CHINA TAIPING INSURANCE (S) PTE  
LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

### Vehicle & Document Information

WIP No 33251  
Reg No/Reg Date SMG2971T\*RA / 28/09/2015  
Date In/Mileage 15/05/2019/ 41855  
Chassis No WDD173422N257672  
Engine No 27091030737872  
Make/Model MB/CLA 180 (C117) "URBAN"  
Colour/Trim 026 650 Calcit Whit/ 041 151-Leather Twi

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	17/05/2019/ 14:37		301 / Kerlyn Ong
Description of Goods / Services				
Qty	Unit Price	Disc%	Amount	

S BPNTOW

ACCIDENT TOWING FROM MIDDLE RD TO PLSC  
USING KING DOLLEY  
WO: 164227

- X RIVET / NLC
- X PLASTIC NUT / NLC
- \* X RH/ BASIC MOUNTING FOR BUMPER / BR
- X RIVET / NLC

5.00 5.21 00.00  
3.00 1.75 00.00  
1.00 142.47 00.00  
6.00 5.21 00.00

140.00  
26.05  
5.25  
142.47  
31.26

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

Nett 345.03  
7% GST on 345.03 24.15  
Total Payable 369.18

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg