

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR II	NSPECTION REPORT	
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS3/FCI19008399	9/Jcd3s2
			Date: 10-06-2019	
			Code: FCI2	
1.			ars :- (THIRD PARTY CLAIN	
	Insured Veh.	SHB 3263H	Veh. Inspected	JSM 8536
	Policy No.		Coverage (\$)	0.00
	Claim No.	D19003102MFSH	Excess (\$)	0.00
	Assign From	SITHARA	Assign Date	13/05/2019
2.		Vehicle F	Particulars & Condition	
	Make & Model	YAMAHA	c.c	150
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	PMYRG3410G0005967	Colour	WHITE
	Odometer	32154 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Co	nditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	90/80 R17	MAXXIS	6 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	120/70 R17	MAXXIS	6 mm
	L/H Rear Tyre			mm
4.		Desc	ription of Damages	
	THE VEHICLE SU	ISTAINED DAMAGES AT THE O/S BODY.		
5.		Ge	neral Information	
	Accident Date	08/05/2019	Inspect Date / Time	13/05/2019 (01:46 PM)
	Survey held at	SINCERE LEAD AUTOMOT	IVE	1.
	72:41	280 WOODLANDS INDUSTRIAL PARK E5 #02-10 SINGAPORE 757322		
5a.		Remarks		
	B) THE REPAIR E THE REPAIRER V	STIMATE WAS NOT PRESEN VAS TOLD TO PREPARE THE EASE FIND DAMAGED VEHI		

Report Ref No. CS3/FCI19008399/Jcd3s2

Inspected By

M.

ONG HWEE JIE

Automotive Assessor

2

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.