

1- AIG / LK
22/5 @ 11am

Kh



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLN 156 T

Parts	(a) Cost / List Price Items	Finalised \$ 642.17	7,782.91
	Plus/Less 25%	\$ 160.54	1,945.73
	Total of Cost / List	\$ 421.63	5,837.18
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	350.00
Total Parts Cost		\$	6,187.18
Labour		\$ 760.00	1,870.00
Total		\$ 1241.63	8,057.18

Not Authorized
Resurvey Required

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is ☒ authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

(c) Resurvey : Required / ☒ Not Required

(d) Excess : \$

(e) Signature of surveyor

Kennerth

LKIC

4/6/19

at

Le

Date:

4/6/19



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLN 156 T

TOYOTA PRIUS
JTDKB3FU103556203

Submit By :
Year Manufacture :
Engine No. :
Cost / List

SERENGE

2017

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp RH	1	\$2,531.60		X
2	Fog lamp RH	1	\$910.70		X
3	Front bumper	1	\$450.80		X
4	Front bumper clip	10	\$40.00		X
5	Front bumper reinforcement - upper	1	\$711.50		X
6	Front bumper reinforcement - lower	1	\$245.30		X
7	Front bumper side retainer RH	1	\$107.20		X
8	Front bumper side retainer LH	1	\$107.20		X
9	RH front fender	1	\$868.70		X
10	RH front fender undershield	1	\$185.64		X
11	RH front fender undershield clip	10	\$25.00		X
12	RHF fender wording "HYBRID"	1	\$44.17		X
13	RH front rim	1	\$1,555.10		X
14	RH front tyre	1	\$350.00	S.N	X
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

64.17



Blok 5033 Ang Mo Kio, Inrd Park 2 #01-251/ 259, 569535.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempart.com.sg

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.osteoperf.com.sg

Vehicle No. : SLN 156 T Submit By : SERENCE
Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.