

Quotation

DATE: 09/05/19
VEHICLE NO: PA32M
DRIVER: Lim Tian Sze
ATTENTION TO:
PREPARED BY: Chan Soo Lye

LOCATION: Gul Workshop
Q REF No: Q19/05/1017
DEPARTMENT: WTS Bus Department
ACCIDENT DATE: 08/05/19
REF No: JW-0519-320

S/N	Description	Qty	Cost per Unit	Amount S\$
Spare Parts				
1	FRONT RHS VIEW MIRROR ASSY / DR	1	546	546.00
2	DRIVER SIDE GLASS / DR	1	1069.2	1,069.20
3	FRONT RHS NO1 SIDE GLASS - DR	1	1325.4	1,325.40
4	FRONT RHS COVER / DD	1	850	850.00
5	COVER LOCK / DR	1	25	25.00
6	RHS SIDE SIDE LAMP / DR	1	130	130.00
7	SEALANT SIKA 600ML / NEC	12	42.7	512.40
8	LUGGAGE COVER / DD	1	850	850.00
9	WTS STICKER / NEC	1	150	150.00
Labour Costs				
1	TO DISMANTLE THE CRACKED DRIVER SIDE GLASS AND NO1 SIDE PANEL GLASS, CLEAN AND GRIND THE GLASS FRAME AND INSTALL NEW DRIVER SIDE GLASS AND NO1 SIDE PANEL GLASS.	1	1000	1,000.00 800
2	TO REMOVE AND REPLACE DAMAGED PARTS RHS COVER WITH LOCK AND LUGGAGE COVER TO KNOCK REPAIR RHS SIDE PANEL STRUCTURE TO ORIGINAL POSITION. TO KNOCK AND PANEL BEAT RHS SIDE PANEL.	1	1000	1,000.00 700
Spray Paint				
1	Spray Painting TO PUTTY AND SPRAY PAINTING FRONT RHS COVER, WTS COLOUR TO PUTTY AND SPRAY PAINTING RHS LUGGAGE COVER AND SIDE PANEL AND PATCH STICKER.	1	1200	1,200.00 1000
			TOTAL:	8,658.00
			Total Amount	SGD 8,658.00

Remarks:

Signature of Workshop Dpt

Signature of Department Head

Signature of Claim Department

Surveyor Sign: 
Surveyor Name: Steve
Date: 13/5/19

LKK Auto Components hereby certifies that the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: