

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 41883

ROP No: 53291793J. Tel: 6741-1730 / 731. Fax: 6744-5746. Email: liusbrog@gmail.com

Invoice/Ref No: YP4100M19031

Estimate

Customer

Name: AXA Insurance Singapore Pte Ltd

Date: 13-05-19

Address: Motor Claims Department

Vehicle No: YP4100M

8 Shenton Way #27-01

Model/Make: Mitsubishi

AXA Tower

Singapore 068811

Fuso FM65FM2RDEB

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Lh Safety Bar <i>9.5</i>	\$ 350.00	<i>S.N. ✓</i>
2	Safety Bar Bracket <i>1 Belf</i>	\$ 180.00	<i>S.N. ✓</i>
3	Safety Bar "Centre" Bracket <i>5uf</i>	\$ 400.00	<i>S.N. ✓</i>
4	Safety Bar "Centre" Bracket <i>side n 7</i>	\$ 180.00	<i>X</i>
5	Tail Lamp <i>Che</i>	\$ 325.00	<i>✓</i>
6	Powergate Pump Inner <i>su</i>	\$ 1,650.00	<i>X</i>
7	Powergate Pump Inner Cover <i>su</i>	\$ 320.00	<i>SN X</i>
8	Powergate Pump Outer <i>su</i>	\$ 1,650.00	<i>IX</i>
9	Powergate Pump Outer Cover <i>su</i>	\$ 320.00	<i>SN X</i>
10	Power gate Wire Cover <i>To n</i>	\$ 250.00	<i>SN ✓</i>
11	Power gate Side Panel <i>n</i>	\$ 850.00	<i>SN X</i>
12	Pillar <i>20</i>	\$ 400.00	<i>SN ✓</i>
13	Powergate Oil <i>11</i>	\$ 200.00	<i>SN X</i>
To check all wiring & electrical component for proper function		\$ 50.00	<i>20</i>
Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc		\$ 800.00	<i>600</i>
To putty & spray painting & including touch up paint on accident affected a		\$ 400.00	<i>280</i>
To apply Rust Proofing, reseal tuff-coating treatment on accident area		\$ 60.00	<i>11 X</i>

Total Parts & Labour of estimate for damaged vehicle

\$8,385.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

not Authorised
2/5 #2600
4 days
13/5/19
the pre Approval

7-325
502
7-162.50
S.V-1580.00
162-900.00
2642.50

