

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

09 MAY 2019

E S T I M A T E

Estimate No. : b1 51136	Page No. : 1 of 5
Date Estimated : 09/05/2019	
Prepared By : Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR - Khojama Kalimuddin 35 Toh Drive Singapore 507808	- ACCOUNT - 158 Lonpac Insurance Bhd 300 Beach Road #17-04/07 The Concourse Singapore 199555
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGX4763X	LE85988	02/10/2018	X3 M40i SAV	0

DESCRIPTION	VALUE
To replace rear bumper, tailgate and attachments.	1700 2,550.00
Painting rear bumper and tailgate.	1805 2,006.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To remove and install rear windscreen glass to facilitate the repair job.	574.00
To conduct water leak tests.	75.00
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.	451 531.00
To carry out body cavity preservation. (Per panel).	100 118.00
Sundries.	? 150.00
Total Labour 1:	6,181.00

DESCRIPTION	QTY	PRIC	VALUE
TRUNK LID	1	1,963.55	1,963.55
REAR BUMPER CARRIER	1	739.80	739.80
RH SIDE GUIDE FOR BUMPER	1	61.50	61.50
RH BUMPER GUIDE	1	70.30	70.30
REAR BUMPER BOTTOM REINFORCEMENT	1	70.90	70.90
REAR BUMPER PANEL PRIMED (M/PMA)	1	1,531.70	1,531.70
SET MOUNTING PDC/PMA SENSOR REAR(M)	1	126.60	126.60
REAR BUMPER TRIM PANEL BOTTOM M DAR	1	364.70	364.70
PLAQUE 82MM	1	71.25	71.25
LETTERING X3 CERIUM GREY	1	99.75	99.75
LETTERING M40i	1	64.10	64.10

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 51136**
Date Estimated : **09/05/2019**
Prepared By : **Inthiran A/L Thurasamy**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGX4763X	LE85988	02/10/2018	X3 M40i SAV	0

DESCRIPTION	QTY	PRIC	VALUE
BUMP STOP <i>new</i>	10	3.50	35.00
RH REFLECTOR <i>CRA</i>	1	37.90	37.90
REAR RH LIGHT IN THE SIDE PANEL <i>CRA</i>	1	568.05	568.05
REAR RH LIGHT IN THE TRUNK LID <i>CRA</i>	1	397.65	397.65
(DG) CLEANER R1 (100ML) <i>new</i>	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>new</i>	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206) <i>new</i>	1	27.85	27.85

Total Parts : **6,519.85**

Claims OD (3rd Party) / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 21/05/19 @ 1300 Excess S\$ _____

Surveyor's Name Ramul Sign _____

Surveyor's Tel 900 10068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	6,181.00
Parts	:	6,519.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	889.06
Grand Total	:	13,589.91

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY ****

**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****