



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AXA Insured's Veh No : SHF633Y

Date of Accident : 06 May 2019

Messrs Hi Power Pte Ltd

Date : 13 May 2019

Estimate To Repair SKG3500L - Toyota COROLLA ALTIS 1.6 AUTO

Chassis No : MR053REE104144369

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper	\$ 2 465.75 X
02	8 pc	rear bumper clips @ \$4.30	\$ 11 34.40 X
03	1 pc	rear door outer garnish with moulding	\$ 11 125.80 X
			\$ 625.95
		Less 25 %	\$ 156.49
			\$ 469.46
		<u>LABOUR & MISC. CHARGES</u>	
01		To reinstall of rear bumper parking sensor.	\$ 11 80.00 X
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 750.00 200
03		Putty and spray painting of the affected portion.	\$ 900.00 600
			\$ 1,730.00
		Total	\$ 2,199.46

not allocated
here

Take photo After repair -
17/5/19

2 by.

7/7 \$800

KK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: