



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AXA Insured's Veh No : SHF633Y

Date of Accident : 06 May 2019

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs Hi Power Pte Ltd

Date : 13 May 2019

Estimate To Repair SKG3500L - Toyota COROLLA ALTIS 1.6 AUTO

Chassis No : MR053REE104144369

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper	\$ 465.75
02	8 pc	rear bumper clips @ \$4.30	\$ 34.40
03	1 pc	rear door outer garnish with moulding	\$ 125.80
			\$ 625.95
		Less 25 %	\$ 156.49
			\$ 469.46
		<u>LABOUR & MISC. CHARGES</u>	
01		To reinstall of rear bumper parking sensor.	\$ 80.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 750.00
03		Putty and spray painting of the affected portion.	\$ 900.00
			\$ 1,730.00
		Total	\$ 2,199.46