

REC. BY:

REF: CS/ASM (900844/Excl 304) Special Instruction:

Survey: SteveASSIGNMENT (Office)From (Person): KITTY TED of ASM Date/Time: 13/05/19

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMA 838R Insured: _____at Workshop m/s EURO SPORTS Tel: Richard 65655995of 24 LENG KEEPolicy No: _____ Claim No: 59M01N40Sum Insured: _____ Excess: 18000Make of Veh: _____ D.O.A. 04/5/19
(Client's Record)

CA (REV) REP. / REV 24 HRS

Date/Time: _____ Person Contacted: _____ Vehicle IN/OUT

Date/Time	Action/Instruction
	<u>Exh1011 ()</u>
	<u>SMA 838R x</u>
<u>14/5/19</u>	<u>Revert via SMART claim</u>
<u>15/5/19</u>	<u>Rec approved from Kitty by SMART claim</u>
<u>16/5/19</u>	<u>Informed Richard c/A ex \$18000 by email</u>
<u>19/6/19</u>	<u>Vehicle waiting for parts from factory</u>

Steve

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
QD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop no: _____
at: _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Vch: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Vch No: **SMA838R** Vi Regn: **27/4/18**
Type: **M/Car** M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: **Lamborghini Huracan** CC: **S204**
Colour: **Blue Silver** A/C: Insured / Std / NI / N.
Sp. Reading: **7940** T/Rvlin: Insured / Std / NI / N
Eng/No: _____
C/No: **ZHWE C22F16LA 04/SS**
Gen. Cond: **Good** / Fair / Poor / Burnt
Steering: **Inorder** / Jammed / Leaked / Burnt or
Brake: **Inorder** / Jammed / Leaked / Burnt or
Modl: **Nil** / S/Rlm / STD A/Rlm or
Tyre Size: F: **245/35 ZR19**
R: **305/35 ZR19**
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or **Pirelli**
Front: _____ Rear: _____
R/Bal. **7** mm R/Bal. **7** mm
L/Bal. **7** mm L/Bal. **7** mm
D.O.A. _____ D.O.I. **13/5/19**
Survey held at **Eurosports**
Des. of Damages: **Frt** / Rear / O/S / N/S / UIC / Rooftop or
Interior
The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MV - 950K

16/1/19 @ 3:41pm Richard said vehicle pending for spare parts.
20/9/19 Recd Supplementary approval from Kian Chuan by SMART claim
4/10/19 Final fig \$ 128,676.55 confirmed by email (Ref 14,860-90, 10%)

RECEIVED 07 OCT 2019

Date/Time. File Pass to?

☐
☐

: Prel. Report

: Final Report

1)

Date/Time. File Return to?

2) 7/10 - typist

Report Format:

SMART claim

Lump Sum / L.B. : 128,676.55

Days Of Repair: 12

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation

1) S + RT. 0

2) Station

3) Index

10/1/19

200

200

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 20 September 2019 2:12 PM
To: Richard Harjanto; Steve Chen (LKK Auto)
Cc: SF Eyu; Khan Wei Loh; SUR
Subject: RE: Supplementary Part Quotation for SMA838R

Dear Richard,

Please proceed repairs not exceeding \$119,254.88 AFT EXCESS \$18,000.00.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Richard Harjanto <richardharjanto@eurosportsauto.com.sg>
Sent: Monday, 16 September 2019 5:38 PM
To: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Cc: SF Eyu <Sfeyu@eurosportsauto.com.sg>; Khan Wei Loh <khanwei@eurosportsauto.com.sg>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: Supplementary Part Quotation for SMA838R

Hello Steve,

There was a delay on the notification of supplementary parts as the car was left un-touched for many weeks, while we wait, to get approval from factory to repair and order crucial parts, like the whole front chassis frame.

The whole process of ordering the parts from the factory in Italy also has some delay, most parts don't have corresponding part numbers and pricings.

And the car was sent to outside body repair shop to do the cutting and welding.

During that time we are unable to confirm what additional parts needed to replace, until we started to fit back the car.

We waited until all parts are compiled and prices available, then we passed the list to you to recheck and re survey.

The supplementary parts submitted are necessary for the repair.

If you have more enquiries or need to take physical inspection of the parts, please do let me know.

Thank you and,

Best regards,
Richard Harjanto

Lamborghini Singapore
EuroSports Auto Pte Ltd
Richard Harjanto

Service Advisor

24 Leng Kee Road #01-03

Singapore 159096

Phone: +65 6882 0865

Mobile: +65 9799 9593

Email: richardharjanto@eurosportsauto.com.sg

Web: www.lamborghini-singapore.com

Web: www.eurosportsglobal.com

The contents of this e-mail, and any attachments, are confidential and intended only for the person(s) to whom they are addressed. If you have received the email by mistake please notify the sender immediately and delete it from your computer system. Do not copy or distribute it or disclose its contents to any person. Any improper use of the contents of this email will be prosecuted by law in compliance with the laws in the matter of data protection as well as in order to protect the right of confidentiality of correspondence.

From: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>

Sent: Friday, September 13, 2019 5:38 PM

To: Richard Harjanto <richardharjanto@eurosportsauto.com.sg>

Cc: SF Eyu <Sfeyu@eurosportsauto.com.sg>; Khan Wei Loh <khanwei@eurosportsauto.com.sg>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: Supplementary Part Quotation for SMA838R

Dear Richard,

Kindly explain for the vehicle delay to inform us the supplementary parts and the vehicle repair was done.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Richard Harjanto [<mailto:richardharjanto@eurosportsauto.com.sg>]

Sent: Thursday, September 12, 2019 4:14 PM

To: Steve Chen (LKK Auto)

Cc: SF Eyu; Khan Wei Loh

Subject: Supplementary Part Quotation for SMA838R

Hello Steve,

Here is the supplementary parts quotation, as attached.

For the Lamborghini Huracan SMA838R.

Also attached are the parts catalog, for your reference, so that you know where the parts are located.

You may use the corresponding numbers at the side of the part number in the catalog to match the specific parts in the quotation.

I have all the parts here at workshop if you need to take photos.

Thank you and,

Best regards,
Richard Harjanto

Lamborghini Singapore
EuroSports Auto Pte Ltd
Richard Harjanto
Service Advisor

24 Leng Kee Road #01-03
Singapore 159096
Phone: +65 6882 0865
Mobile: +65 9799 9593
Email: richardharjanto@eurosportsauto.com.sg
Web: www.lamborghini-singapore.com
Web: www.eurosportsglobal.com

The contents of this e-mail, and any attachments, are confidential and intended only for the person(s) to whom they are addressed. If you have received the email by mistake please notify the sender immediately and delete it from your computer system. Do not copy or distribute it or disclose its contents to any person. Any improper use of the contents of this email will be prosecuted by law in compliance with the laws in the matter of data protection as well as in order to protect the right of confidentiality of correspondence.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



RE: Re:SMA 838R-SUPPLEMENTARY

Type

🔔 Question

Message

PLS PROCEED TO AUTHORIZED REPAIRS NOT EXCEEDING \$119,254.88 AFT EXCESS \$18,000.00.

Reply

New Message

Type *

☒ Message

Subject *

SMA 838R-SUPPLEMENTARY

Message *

Dear Kitty,
Please have received supplementary from repairer. Kindly let us have your approval please.
Best Regard, Veron Chen



Auto
Consultants
Pte Ltd

51 UBI AVE, L-001-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408033 TEL : (065) 62963561 FAX : (065) 62564335

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 17/9/2019

Survey details

Date of loss	4/5/2019
Date of appointment	13/5/2019
Date of survey	13/5/2019
Location of survey	EUROSPORTS AUTO PTE LTD

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SMA 838R
Make and Model	LAMBORGHINI HURACAN LP580-2
Date of registration	27/4/2018
Excess	\$18,000
Market Value	\$950,000.00
Parf Rebate	\$284,472.00
Nett Loss	\$665,528.00

Repair details

Initial Estimate	\$143,221.38 (incl. supplementary \$39,582.38)
------------------	--

Proposed/Revised repair cost:

Revised Estimate Amount	\$122,354.88
"Check items (Estimated)	
Labour	\$14,900.00
Total Repair (Estimated)	\$137,254.88 (incl.supplementary \$39,582.38)
Lump Sum (Estimated)	

Number of days of repair	12 DAYS (est)
--------------------------	---------------

Remarks:

The vehicle sustained damages at the front portion and interior.

Damages Consistent
Repair Cost Economical

Repairer is aware that late submitted of supplementary due to parts and prices from the factory in Italy.

Veron Chen (LKKAuto)

From: Richard Harjanto <richardharjanto@eurosportsauto.com.sg>
Sent: Monday, 16 September 2019 5:38 PM
To: Steve Chen (LKK Auto)
Cc: SF Eyu; Khan Wei Loh; Veron Chen (LKKAuto)
Subject: RE: Supplementary Part Quotation for SMA838R

Hello Steve,

There was a delay on the notification of supplementary parts as the car was left un-touched for many weeks, while we wait, to get approval from factory to repair and order crucial parts, like the whole front chassis frame.

The whole process of ordering the parts from the factory in Italy also has some delay, most parts don't have corresponding part numbers and pricings.

And the car was sent to outside body repair shop to do the cutting and welding.

During that time we are unable to confirm what additional parts needed to replace, until we started to fit back the car.

We waited until all parts are compiled and prices available, then we passed the list to you to recheck and re survey.

The supplementary parts submitted are necessary for the repair.

If you have more enquiries or need to take physical inspection of the parts, please do let me know.

Thank you and,

Best regards,
Richard Harjanto

Lamborghini Singapore
EuroSports Auto Pte Ltd
Richard Harjanto
Service Advisor

24 Leng Kee Road #01-03
Singapore 159096
Phone: +65 6882 0865
Mobile: +65 9799 9593
Email: richardharjanto@eurosportsauto.com.sg
Web: www.lamborghini-singapore.com
Web: www.eurosportsglobal.com

The contents of this e-mail, and any attachments, are confidential and intended only for the person(s) to whom they are addressed. If you have received the email by mistake please notify the sender immediately and delete it from your computer system. Do not copy or distribute it or disclose its contents to any person. Any improper use of the contents of this email will be prosecuted by law in compliance with the laws in the matter of data protection as well as in order to protect the right of confidentiality of correspondence.

From: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Sent: Friday, September 13, 2019 5:38 PM
To: Richard Harjanto <richardharjanto@eurosportsauto.com.sg>
Cc: SF Eyu <Sfeyu@eurosportsauto.com.sg>; Khan Wei Loh <khanwei@eurosportsauto.com.sg>; Veron Chen

(LKKAuto) <veronchen@lkkauto.com>

Subject: Supplementary Part Quotation for SMA838R

Dear Richard,

Kindly explain for the vehicle delay to inform us the supplementary parts and the vehicle repair was done.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Richard Harjanto [<mailto:richardharjanto@eurosportsauto.com.sg>]

Sent: Thursday, September 12, 2019 4:14 PM

To: Steve Chen (LKK Auto)

Cc: SF Eyu; Khan Wei Loh

Subject: Supplementary Part Quotation for SMA838R

Hello Steve,

Here is the supplementary parts quotation, as attached.

For the Lamborghini Huracan SMA838R.

Also attached are the parts catalog, for your reference, so that you know where the parts are located.

You may use the corresponding numbers at the side of the part number in the catalog to match the specific parts in the quotation.

I have all the parts here at workshop if you need to take photos.

Thank you and,

Best regards,

Richard Harjanto

Lamborghini Singapore

EuroSports Auto Pte Ltd

Richard Harjanto

Service Advisor

24 Leng Kee Road #01-03

Singapore 159096

Phone: +65 6882 0865

Mobile: +65 9799 9593

Email: richardharjanto@eurosportsauto.com.sg

Web: www.lamborghini-singapore.com

Web: www.eurosportsglobal.com

The contents of this e-mail, and any attachments, are confidential and intended only for the person(s) to whom they are addressed. If you have received the email by mistake please notify the sender immediately and delete it from your computer system. Do not copy or distribute it or disclose its contents to any person. Any improper use of the contents of this email will be prosecuted by law in compliance with the laws in the matter of data protection as well as in order to protect the right of confidentiality of correspondence.

Veron Chen (LKKAuto)

From: Richard Harjanto <richardharjanto@eurosportsauto.com.sg>
Sent: Wednesday, 14 August 2019 5:42 PM
To: Veron Chen (LKKAuto); SUR
Cc: SF Eyu; Khan Wei Loh
Subject: RE: SMA 838R-DOA: 4/5/2019 (AXA OD)

Hello Veron,

The vehicle is still being repaired.
As some of the parts are not available or pending back order and being shipped from the factory in Italy,
It is taking more time than expected.
But we should be finishing up the repair in 4 weeks time, or middle of September 2019.

Thank you and,

Best regards,
Richard Harjanto

Lamborghini Singapore
EuroSports Auto Pte Ltd
Richard Harjanto
Service Advisor

24 Leng Kee Road #01-03
Singapore 159096
Phone: +65 6882 0865
Mobile: +65 9799 9593
Email: richardharjanto@eurosportsauto.com.sg
Web: www.lamborghini-singapore.com
Web: www.eurosportsglobal.com

The contents of this e-mail, and any attachments, are confidential and intended only for the person(s) to whom they are addressed. If you have received the email by mistake please notify the sender immediately and delete it from your computer system. Do not copy or distribute it or disclose its contents to any person. Any improper use of the contents of this email will be prosecuted by law in compliance with the laws in the matter of data protection as well as in order to protect the right of confidentiality of correspondence.

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Wednesday, August 14, 2019 5:12 PM
To: Richard Harjanto <richardharjanto@eurosportsauto.com.sg>; SUR <sur@lkkauto.com>
Cc: SF Eyu <Sfeyu@eurosportsauto.com.sg>; Khan Wei Loh <khanwei@eurosportsauto.com.sg>
Subject: RE: SMA 838R-DOA: 4/5/2019 (AXA OD)

Dear Richard,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Tuesday, 6 August 2019 3:34 PM

To: Richard Harjanto <richardharjanto@eurosportsauto.com.sg>; SUR <sur@lkkauto.com>

Cc: SF Eyu <Sfeyu@eurosportsauto.com.sg>; Khan Wei Loh <khanwei@eurosportsauto.com.sg>

Subject: RE: SMA 838R-DOA: 4/5/2019 (AXA OD)

Dear Richard,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Richard Harjanto <richardharjanto@eurosportsauto.com.sg>

Sent: Wednesday, 19 June 2019 11:24 AM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: SF Eyu <Sfeyu@eurosportsauto.com.sg>; Khan Wei Loh <khanwei@eurosportsauto.com.sg>

Subject: RE: SMA 838R-DOA: 4/5/2019 (AXA OD)

Hello Veron,

Vehicle is still not repaired yet.
We are waiting for parts from factory.

Thank you and,

Best regards,
Richard Harjanto

Lamborghini Singapore
EuroSports Auto Pte Ltd
Richard Harjanto
Service Advisor

24 Leng Kee Road #01-03
Singapore 159096
Phone: +65 6882 0865
Mobile: +65 9799 9593
Email: richardharjanto@eurosportsauto.com.sg

Web: www.lamborghini-singapore.com

Web: www.eurosportsglobal.com

The contents of this e-mail, and any attachments, are confidential and intended only for the person(s) to whom they are addressed. If you have received the email by mistake please notify the sender immediately and delete it from your computer system. Do not copy or distribute it or disclose its contents to any person. Any improper use of the contents of this email will be prosecuted by law in compliance with the laws in the matter of data protection as well as in order to protect the right of confidentiality of correspondence.

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Tuesday, June 18, 2019 5:32 PM
To: Richard Harjanto <richardharjanto@eurosportsauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SMA 838R-DOA: 4/5/2019 (AXA OD)

Dear Richard,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Thursday, 16 May 2019 10:50 AM
To: Richard Harjanto <richardharjanto@eurosportsauto.com.sg>; SUR <sur@lkkauto.com>
Subject: SMA 838R-DOA: 4/5/2019 (AXA OD)

Dear Richard,

As instructed by our client , please proceed to repair the **insured vehicle SMA 838R (Excess \$18,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

***Our client reserve their right not to pay if there is no valid approval obtained before repair.**

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Veron Chen (LKKAuto)

From: Richard Harjanto <richardharjanto@eurosportsauto.com.sg>
Sent: Wednesday, 19 June 2019 11:24 AM
To: Veron Chen (LKKAuto); SUR
Cc: SF Eyu; Khan Wei Loh
Subject: RE: SMA 838R-DOA: 4/5/2019 (AXA OD)

Hello Veron,

Vehicle is still not repaired yet.
We are waiting for parts from factory.

Thank you and,

Best regards,
Richard Harjanto

Lamborghini Singapore
EuroSports Auto Pte Ltd
Richard Harjanto
Service Advisor

24 Leng Kee Road #01-03
Singapore 159096
Phone: +65 6882 0865
Mobile: +65 9799 9593
Email: richardharjanto@eurosportsauto.com.sg
Web: www.lamborghini-singapore.com
Web: www.eurosportsglobal.com

The contents of this e-mail, and any attachments, are confidential and intended only for the person(s) to whom they are addressed. If you have received the email by mistake please notify the sender immediately and delete it from your computer system. Do not copy or distribute it or disclose its contents to any person. Any improper use of the contents of this email will be prosecuted by law in compliance with the laws in the matter of data protection as well as in order to protect the right of confidentiality of correspondence.

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Tuesday, June 18, 2019 5:32 PM
To: Richard Harjanto <richardharjanto@eurosportsauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SMA 838R-DOA: 4/5/2019 (AXA OD)

Dear Richard,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

From: Veron Chen (LKKAuto)

Sent: Thursday, 16 May 2019 10:50 AM

To: Richard Harjanto <richardharjanto@eurosportsauto.com.sg>; SUR <sur@lkkauto.com>

Subject: SMA 838R-DOA: 4/5/2019 (AXA OD)

Dear Richard,

As instructed by our client , please proceed to repair the **insured vehicle SMA 838R (Excess \$18,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 16 May 2019 10:50 AM
To: Richard Harjanto; SUR
Subject: SMA 838R-DOA: 4/5/2019 (AXA OD)

Dear Richard,

As instructed by our client , please proceed to repair the **insured vehicle SMA 838R (Excess \$18,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Re:RE: Please advise

Type

🔔 Question

Message

Hi Veron, Noted and please proceed at \$98,711 before excess of \$18,000.

Reply



RE: Please advise

Type

🔗 Question

Message

Hi Kitty, Basing on police report, insured vehicle was making a right turn when he lost control. Initially it was stationary at a traffic light and moved off on green light. In our opinion, it could be that insured stepped on the accelerator pedal excessively which caused the rear wheels to lose traction whilst turning. Regards
Denise on behalf of Veron.

Reply

<< Please advise

Type

🔔 Question

Message

Hi Veron, Since the vehicle has no malfunction and everything in good condition, then please let us have your surveyor advise the reason why the vehicle rear wheel suddenly swerved outwards mid turn as reported by our insured in his claim report. Thanks.

Dr Kitty.

Reply

~~Insured did not mention that was not said by~~
Being a Police report, involved vehicle ^{was} making a
right turn when he lost control. Initially it was
~~stationary~~ stationary at a traffic light and
moved off on green light. In our opinion,
it could be that Insured stepped on the
accelerator pedal excessively which ~~caused~~ caused the
rear wheels to lose traction whilst turning.

SURVEY STATUS

Type

🔍 Question

Message

Hi, Please let us have your surveyor's advise on my query.

Reply *

Dear Kitty,

According to surveyor, at time of assesement there were no signs of mechanical failure.Brakes are working, tyres are in working conditions.There is no oil patch on the car tyre. Best Regards,Veron Chen

Cancel Reply

Reply Now

New Message

Type *



Message

Subject *

IA SUBMITTED FOR SMA 838R

Message *

Dear Kitty,
Please be informed that IA submitted. We have Not Authorize repair. Kindly let us have your approval please.Thanks
Veron Chen

CancelSend



Auto
Consultants
Pte Ltd

31, KITE AVENUE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408931 TEL : (665) 62563561 FAX : (665) 62563518

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 14/5/2019

Survey details

Date of loss	4/5/2019
Date of appointment	13/5/2019
Date of survey	13/5/2019
Location of survey	EUROSPORTS AUTO PTE LTD

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SMA 838R
Make and Model	LAMBORGHINI HURACAN LP580-2
Date of registration	27/4/2018
Excess	\$18,000
Market Value	\$950,000.00
Part Rebate	\$284,472.00
Nett Loss	\$665,528.00

Repair details

Initial Estimate	\$103,639.00
------------------	--------------

Proposed/Revised repair cost:

Revised Estimate Amount	\$69,541.00
"Check Items (Estimated)	\$14,770.00
Labour	\$14,400.00
Total Repair (Estimated)	\$98,711.00
Lump Sum (Estimated)	

Number of days of repair	12 DAYS
--------------------------	---------

Remarks:

The vehicle sustained damages at the front portion and interior.

Damages Consistent
Repair Cost Economical

We have Not Authorise repair

<< Please advise - SMA 838R

Type

🔗 Question

Message

Hi Please refer to insured's police report. Our insured reported he might have driven over a oily wet patch and caused the car to lost control. Please advise if there is any malfunction of the car or is there any traces of oil patch on the car tyre. No accident scene photos. Thanks.

[Reply](#)

Based on our survey, no oily on the tyre



Service Request Details

Claim

S9M01N40

Reference

None

Loss Date

May 4, 2019

Report Date

May 10, 2019 12:00:00 AM

Request Date

May 13, 2019

Due Date

May 21, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

*34 long Lee Rd #8
Pichand
Steve*

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SMA838R

(H00001)
XXXXXX

Service Address

...

Primary Contact/Insured

TAY HIN NGAN (ZHENG XINYAN)
23 MARIGOLD DRIVE, 576425, Singapore
97999593

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

Additional Instructions
W/S - EUROSPTS XS - \$18,000

Messages Invoices History Documents Assessment Metrics Notes

New Message

TYPE



SENT

5/13/19 10:48 AM

FROM

TEO Kitty

SUBJECT

Please advise

BODY

Hi Please refer to insured's police report. Our ...



[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8383D
Vehicle Details	
Vehicle No.:	5MA838R
Vehicle to be Exported:	No
Intended Deregistration Date:	14 May 2019
Vehicle Make:	LAMBORGHINI
Vehicle Model:	HURACAN LP580-2
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	CSJ005887
Chassis No.:	ZHWEC2ZF1GLA04755
Maximum Power Output:	426.0 kW (571 bhp)
Open Market Value:	\$201,740.00
Original Registration Date:	27 Apr 2018
First Registration Date:	27 Apr 2018
Transfer Count:	0
Actual ARF Paid:	\$335,132.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Apr 2028
PARF Rebate Amount:	\$251,349.00
Intended COE Rebate Details	
COE Expiry Date:	26 Apr 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$38,000.00
COE Rebate Amount:	\$33,123.00
Total Rebate Amount:	\$284,472.00

The information contained herein is correct as at 14 May 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8383D
Vehicle Details	
Vehicle No:	SMA838R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 May 2019
Vehicle Make:	LAMBORGHINI
Vehicle Model:	HURACAN LP580-2
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No:	CSJ005887
Chassis No:	ZHWEC2ZF1GLA04755
Maximum Power Output:	426.0 kW (571 bhp)
Open Market Value:	\$201,740.00
Original Registration Date:	27 Apr 2018
First Registration Date:	27 Apr 2018
Transfer Count:	0
Actual ARF Paid:	\$335,132.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Apr 2028
PARF Rebate Amount:	\$251,349.00
Intended COE Rebate Details	
COE Expiry Date:	26 Apr 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$38,000.00
COE Rebate Amount:	\$29,608.00
Total Rebate Amount:	\$280,957.00

The information contained herein is correct as at 13 May 2019

OK

Das WeltAuto.
Used cars you can trust. Guaranteed.

Low on mileage. High on savings.



Post an Advertisement
Sell it yourself. Advertise it at just
\$58 until it's SOLD!

Now 5 Year Removal Car Toyota ARIA 1.8i

1.800L & 10.000 Miles
Prestige 2 Year Warranty
Hurry! Only 1 left
Call Credit Pte Ltd

* Free VCOM evaluation
* Free grooming and 8 months maintenance
* In-house workshop ensures quality service
* Member of SFTA and hire purchase association
* 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Post an Ad Advertiser Login Ways of Selling

Browse by Category

Sort by Date Posted 20 results/page

8 vehicles

Lamborghini Huracan

Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Lamborghini Huracan	Any	Any	Any	Any	Any	Any	Available

Search Selection

Lamborghini Huracan



Lamborghini Huracan LP610-4 \$638,800 \$72,880 /yr 03-Dec-2014 5,204 cc 15,000 km Sports Available

Pristine Condition, 1 Owner, Exterior Paint In Bianco Marzotto With Yellow Interior In Black Leather With White Stitching, Call To Inquire More Information And Arrange For Viewing.

Tags: 2014 Lamborghini Huracan, 2014 Lamborghini Huracan, Lamborghini Huracan, Lamborghini Huracan, Lamborghini Huracan, Huracan, Huracan, Used Lamborghini

Posted: 19-Apr-2019



Lamborghini Huracan LP610-4 \$688,828 \$79,520 /yr 01-Feb-2015 5,204 cc 14,000 km Sports Available

Comes With IPL Titanium Exotic Every Man's Dream Car! Its Time To Own One! Meticulously Maintained By Pervert Owner At Eurosports With Warranty Till 2020! Coating Done Very Frequently! Non Abused, Non ...

Tags: 2015 Lamborghini Huracan, 2015 Lamborghini Huracan, Lamborghini Huracan, Lamborghini Huracan, Lamborghini Huracan, Huracan, Huracan, Used Lamborghini

Posted: 13-Apr-2019



Lamborghini Huracan LP580-2 \$668,000 \$72,500 /yr 25-Mar-2016 5,204 cc 15,080 km Sports Available

Sporty Blue Lamborghini Huracan LP580-2 Exterior With Matching Black/Yellow Interior. Full Serviced And Maintained From Euro Sports. Low Mileage At 15,080km Only! Don't Miss! Trade-In Welcome! Easy ...

Tags: 2016 Lamborghini Huracan, 2016 Lamborghini Huracan, Lamborghini Huracan, Lamborghini Huracan, Lamborghini Huracan, Huracan, Huracan, Used Lamborghini

Posted: 16-Apr-2019



Lamborghini Huracan LP580-2 \$608,000 \$62,830 /yr 19-Apr-2016 5,204 cc 31,799 km Sports Available

Pristine Condition, 1 Owner, Exterior Paint In Bianco Marzotto With Yellow Interior In Black Leather With White Stitching, Call To Inquire More Information And Arrange For Viewing.

Tags: 2016 Lamborghini Huracan, 2016 Lamborghini Huracan, Lamborghini Huracan, Lamborghini Huracan, Lamborghini Huracan, Huracan, Huracan, Used Lamborghini

Posted: 25-Mar-2019



Toyota Camry takes on Volkswagen's Passat

The Toyota Camry offers more legroom for rear passengers, is sportier around corners and has more safety systems but the Volkswagen Passat is more affordable and feels more premium overall.

Find out more!



Lamborghini Huracan LP610-4 \$730,000 \$69,870 /yr 20-Sep-2016 5,204 cc 6,300 km Sports Available

Beautiful Red One, Fully Serviced And Maintained By Agent With 5 Years Agent Warranty! Very Low Mileage At 6300km.

Tags: 2016 Lamborghini Huracan, 2016 Lamborghini Huracan, Lamborghini Huracan, Lamborghini Huracan, Lamborghini Huracan, Huracan, Huracan, Used Lamborghini

Posted: 20-Mar-2019



Lamborghini Huracan LP610-4 \$798,000 \$71,990 /yr 10-Feb-2017 5,204 cc 15,132 km Sports Available

Pristine Condition, 1 Owner, Fitted With Factory Aero Kit, Exterior Paint In Bianco Marzotto With Yellow Interior In Alcantara With Orange Stitching. Factory Warranty Till July 2019, Call To Inquire M...

Tags: 2017 Lamborghini Huracan, 2017 Lamborghini Huracan, Lamborghini Huracan, Lamborghini Huracan, Lamborghini Huracan, Huracan, Huracan, Used Lamborghini

Posted: 23-Mar-2019



Lamborghini Huracan Spyder LP580-2 \$777,600 \$73,220 /yr 04-May-2017 5,204 cc 2,880 km Sports Available

Almost New Condition, 2nd Owner, Exterior Paint In Giallo Ino, Sports Boost Interior In Black Leather With Yellow Contrast, A Pillars In Alcantara, Soft Top In Black, Factory Warranty Till May 20...

Tags: 2017 Lamborghini Huracan, 2017 Lamborghini Huracan, Lamborghini Huracan, Lamborghini Huracan, Lamborghini Huracan, Huracan, Huracan, Used Lamborghini

Posted: 10-Apr-2019



Lamborghini Huracan LP640-4 Performante \$998,000 \$81,520 /yr 23-Jan-2018 5,204 cc 1,300 km Sports Available

THE Highest Spec Performante In Singapore. Immaculate Condition

Tags: 2018 Lamborghini Huracan, 2018 Lamborghini Huracan, Lamborghini Huracan, Lamborghini Huracan, Lamborghini Huracan, Huracan, Huracan, Used Lamborghini

Posted: 20-Mar-2019

Save this search criteria, to get email alerts whenever a match is found.

Compare Price Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/05/2019 17:11
Date Of Accident	04/05/2019 23:15
Exact Location Of Accident	THOMPSON ROAD TOWARDS UPPER THOMPSON RD / LORNIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA838R
Insured/Policyholder	
Name Of Registered Owner	TAY HIN NGAN
NRIC No	S7238383D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97999593
Alternative Phone No	OFFICE-97999593
Vehicle Particulars	
Manufacturer	LAMBORGHINI
Model	HURACAN-5.2 LP610-4 (M)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPX/P2115122
Cover Note Number	-

Driver

Name of Driver	TAY HIN NGAN
NRIC No	S7238383D
Date Of Birth	19/10/1972
Occupation	INDOOR
Date Of Driving Pass	20/08/1992
Driving Experience	26 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97999593
Fax Number	
Contact Number	OFFICE-97999593
Email Address	NOEMAIL

Address 23 MARIGOLD DRIVE
Postcode 576425
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLIDED INTO PROPERTY
Weather Conditions CLEAR
Road Surface PATCHY WET / WATER OR OIL

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 1
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name TRAFFIC POLICE DIVISION HQ
Police Station Address ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY: SINGAPORE
Police Station Contact TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

Please refer to police report

Attachment(s)


Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: TP TOOK MEM CARD
Was there any audio recorded? NO

Sketch Plan

SKETCH PLAN

MacRitchie Reservoir

A) SMA 838 R



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Police Officer's Signature

Date & Time: 9/5/19

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Roshan Maharaj
RECEIPT No: P0546577W

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind and/or revoke the policy.
4. The acceptance and completion of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the General Insurance Association of Singapore (GIAS) for archiving and that copies of this report will for a further made available upon application of interested parties.
7. By the completion of this report on the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIAS") may be permitted to collect, use, disclose and/or process my personal data (personal information) as set out in this form and any other personal information provided by me or generated by my insurer collectively the "Personal Information" and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (if reported) who may be involved vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the statutory authority of Singapore and any relevant government agency/authorities (such as the police, for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my data (including the making of correspondence, statements, incidents, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external server at email/physical messages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurers who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/ can be disclosed by any of the Insurers and/or GIAS to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulatory, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 9/5/19

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: RICHARD WARGATE
N/CTN No: F0546599W

AXA INSURANCE PTE LTD
8 Shenton Way, #24-01
AXA Tower, Singapore 068811
Customer Centre #01-21
Tel: 1800 8804888 Fax:
Website: www.axa.com.sg
GST Registration Number: 199903512M
customer.care@axa.com.sg



CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO. : VPX/P2115122 Account No. : 01948
Coverage : Comprehensive
Sum Insured : Market Value At The Time Of Loss
Name of Policy Holder : TAY HIN NGAN (EHENG XINYAN)
Vehicle Registration No. : SMA638R
Period of Insurance : From 27/04/2019 To 26/04/2020 (Both Dates Inclusive)

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*

- (a) The Policyholder
The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employer or his partner
(b) Any Named Driver as stated in the Policy
(c) 1. TAY HIN NGAN (EHENG XINYAN)
2. LOW BEE LAN AUDREY

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes. (01)

EXCESS :

Sect I - Used In S'pore Only : SGD 18,000.00
Sect I - Used Outside S'pore : SGD 36,000.00
Fire&Theft - Outside Singapore : SGD 36,000.00
Windscreen Excess : SGD 1,000.00

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD


Authorized Signature

Issued by - SGOGOWT on 18/04/2019

IMPORTANT :

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

Driving License



YOU ARE LICENSED TO DRIVE VEHICLES OF THE FOLLOWING CLASSIFICATION

Class 1 Motor Cars and Motor Tractors the weight of which, including driver and passengers, does not exceed 3000 kilograms

NP 428



police report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000



T201905057005

2 of 3

Report No. T201905057005

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TAY HIN NGAN	ID No.	57238383D
Related Vehicle	5MA838R (Car)	Contact No.	97377584
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	05/05/2019	Date Discharge	05/05/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details

I was turning right from Thomson Road in the direction of Braddell Road after stopping at the red light. The accident happened just beyond the dual bus stop under the Lorie flyover and pedestrian overhead bridge after the light turned green and I was accelerating off. The rear of my car suddenly swerved outwards mid turn and I corrected the direction and the car swerved the other way and hit the guardrail after the bus stop underneath the pillar of the over head pedestrian bridge. There was a wet patch on the road just under the flyover, which I saw after I exited the car, which was different from the trickle of liquid from my car but the rest of the road was dry. I did not touch the road, so not sure if it was water or oil. There was a dent on the railing but no other damage to public structures. No other vehicle was hit and no other persons were involved. The ambulance was activated by a member of the public who thought I was unconscious but I was just looking for my glasses which had fallen off after which I exited the car. I sustained minor contusions to my left hand and abrasions from my watch hitting my wrist and one foot hitting the other. This was checked in Mount Alvernia Hospital, which I walked to after the police officer cleared me to leave. The paramedic had thought that my ECG was abnormal and required me to sign the refusal of conveyance to hospital, but it was probably due to high adrenaline level and heart rate after the accident and this was confirmed later in MAH A&E where my ECG and blood pressure had returned to normal.

police report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408855
Tel No: 65470000



T20190504/005

1 of 3

Report No. T20190504/005

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/05/2019 15:05 Vide Report No.: E/20190504/0214 Station Diary No.

Informant's Particulars

Name of Informant: TAY HIN NGAN		Address: 23 MARIGOLD DRIVE SINGAPORE 576425	
ID Type / ID No.: NRIC NO / S7238383D		Contact No.: Home/Office: Mobile: 97377584	
Nationality: SINGAPORE CITIZEN		Email: tay.hin.ngan@gmail.com	
Sex: Male	Age: 46	Date of Birth: 19/10/1972	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Otorhinolaryngologist/Ear, nose, throat (ENT) surgeon		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 04/05/2019 23:15	Type of Location: Road
Location: THOMSON ROAD				
Weather: Clear	Road Surface: Wet	Road Speed Limit: 60 Km/h		
Traffic Flow: Two Way	Traffic Control: Not Controlled	Traffic Volume: Light		
Type of Collision: Moving Vehicle Against - Road Divider/Kerb/Railings				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Name	Model	Color	Condition: Seriously Damaged	No of Passenger
SMA836R	Car	LAMBORGHINI	HURACAN+ LP580-2	Silver		0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SMA836R	AXA INSURANCE SINGAPORE PTE LTD	P2115122	27/04/2019	26/04/2020

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, SINGAPORE 159096

TEL : (65) 6565 5995 FAX : (65) 6567 5515

Vehicle / Model :

SMA838R

Lamborghini Huracan

CI:

AXA Insurance

Policy:

VPX/P2115122

Accident Date:

May 4th.-2019

Own Damage Claim

			Qty	List Price	Total
1	4T0807109C	STORAGE FRAME FRNT / BT	1	\$ 1,604.00	\$ 1,604.00
2	4T0821021D	WING LF / BT	1	\$ 6,552.00	\$ 6,552.00
3	4T0821022D	WING RH / BT	1	\$ 6,552.00	\$ 6,552.00
4	4T0941004G	HEADLIGHT RH / BT	1	\$ 10,000.00	\$ 10,000.00
5	4T0941003G	HEADLIGHT LF / BT	1	\$ 10,000.00	\$ 10,000.00
6	4T0805028K	FRONT END / BT	1	\$ 12,248.00	\$ 12,248.00
7	4T0807103G	BUMPER WITH PARKING SENSOR / BT	1	\$ 10,416.00	\$ 10,416.00
8	4T0807253	FRONT SPOILER / MISC	1	\$ 592.00	\$ 592.00
9	4T0807254	FRONT SPOILER RIGHT / ?	1	\$ 592.00	\$ 592.00
10	4T0853745	LAMBORGHINI EMBLEM / BT	1	\$ 728.00	\$ 728.00
11	4T0823021C	BONNET FRNT / BT	1	\$ 10,296.00	\$ 10,296.00
12	4T0823301B	HINGE LF / BT	1	\$ 336.00	\$ 336.00
13	4T0823302B	HINGE RH / BT	1	\$ 336.00	\$ 336.00
14	4T0823351B	ARM / ?	1	\$ 75.00	\$ 75.00
15	4T0823359	GAS FILLED STRUT / ?	1	\$ 61.00	\$ 61.00
16	4T0805669C	ATTACHMENT BARS LF / ?	1	\$ 97.00	\$ 97.00
17	4T0805670C	ATTACHMENT BARS RH / ?	1	\$ 95.00	\$ 95.00
18	4T0819967	ARM LF / ?	1	\$ 85.00	\$ 85.00
19	4T0819968	ARM RH / ?	1	\$ 85.00	\$ 85.00
20	1K1823509E	BONNET LOCK LOWER PART / BT	1	\$ 147.00	\$ 147.00
21	1Q0823480	CATCH HOOK FRNT / BT	1	\$ 52.00	\$ 52.00
22	WHT001308	CAP NUT, SELF LOCKING / NEC	1	\$ 55.00	\$ 55.00
23	4T2819426D	COVER (candle) / BT	1	\$ 399.00	\$ 399.00
24	4T0821170D	COVER RH / BT	1	\$ 503.00	\$ 503.00
25	4T0821169D	COVER LH / BT	1	\$ 503.00	\$ 503.00
26	4T0821171C	WHEEL HOUSING LINER LH / ?	1	\$ 497.00	\$ 497.00
27	4T0821172C	WHEEL HOUSING LINER RH / ?	1	\$ 497.00	\$ 497.00
28	4T0853745	LAMBORGHINI EMBLEM FRONT / Repet	1	\$ 728.00	\$ 728.00
29	4T0863405D	LUGGAGE COMPARTMENT TRIM SEAL / BT	1	\$ 4,060.00	\$ 4,060.00
30	4T0823727B	SEAL (Rubber) / BT	1	\$ 207.00	\$ 207.00
31	4T0880201A6PS	AIRBAG FOR STEERING / BT	1	\$ 900.00	\$ 900.00
32	4G8880204D	AIRBAG UNIT / BT	1	\$ 2,565.00	\$ 2,565.00
33	4S0121252B	ADDITIONAL COOLER FOR COOLANT / BT	2	\$ 647.00	\$ 1,294.00

(All candle) LH, RH BT

10/4/19

Richard

14/5/19



00 - Not Amhar

12 days

10-04-19

EXTRA - \$18,909

P/P

Ry bel sy

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, SINGAPORE 159096

TEL : (65) 6565 5995 FAX : (65) 6567 5515



Vehicle / Model : **SMA838R**
 Lamborghini Huracan
 CI: AXA Insurance
 Policy: VPX/P2115122
 Accident Date: May 4th.-2019

10-04-19**Own Damage Claim**

34	4T0807157C	AIR GUIDE LH ?	1	\$ 130.00	\$ 130.00
35	4T0807158C	AIR GUIDE RH ?	1	\$ 120.00	\$ 120.00
36	4S0121254B	COOLER FOR COOLANT (center) ? ON	1	\$ 716.00	\$ 716.00
37	4T0121334B	AIR GUIDE CENTER - RR	1	\$ 128.00	\$ 128.00
38	4T0121334C	AIR GUIDE REAR CENTER ?	1	\$ 188.00	\$ 188.00
39		Rivets and fasteners, Glue and Sealers supply	1	\$ 700.00	\$ 700.00

PARTS TOTAL**40****\$ 85,139.00****Labor Charges**

Dismantle, Re Fitting and Repair/knocking (10 Days) ^{1200X1} 9690 \$ 12,000.00
 Respray front bumper and fender and spoiler ^{1200X1} 4800 \$ 6,500.00

Subtotal for Labor**103,639****\$ 18,500.00****GST Total****\$ 7,254.73****Total****\$ 110,893.73**

- 1 This is only an estimate, should any additional job be found necessary in the course of work, extra material and labour, cost will be charged accordingly for which you will be informed prior to action taken.
- 2 All materials prices quoted are subject to change without notification
- 3 All repairs are subject to spare parts availability
- 4 Quotation valid for one month from date of issue.

Lamborghini Singapore**Workshop Contact:**

Richard Harjanto
 Service Advisor
 97999593

[Signature] 10/4/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, SINGAPORE 159096

TEL : (65) 6565 5995 FAX : (65) 6567 5515

Vehicle / Model :

SMA838R

Lamborghini Huracan

CI:

AXA Insurance

Policy:

VPX/P2115122

Accident Date:

May 4th.-2019

Own Damage Claim

Steve Chen @ KKant.com



00 - Not Author

12 days

10-04-19

Excess - \$18,000

P/P

Ry bel spj

Steve (LKK)

8322 8817

Steve 13/9/19

Steve 22/5/19, 300pm

			Qty	List Price	Total
1	4T0807109C	STORAGE FRAME FRNT / BT 1440.14	1	\$ 1,604.00	\$ 1,604.00
2	4T0821021D	WING LF / DD 5816.80	1	\$ 6,552.00	\$ 6,552.00
3	4T0821022D	WING RH / DD 5978.70	1	\$ 6,552.00	\$ 6,552.00
4	4T0941004G	HEADLIGHT RH / BR 9970.93	1	\$ 10,000.00	\$ 10,000.00
5	4T0941003G	HEADLIGHT LF / CR 9970.93	1	\$ 10,000.00	\$ 10,000.00
6	4T0805028K	FRONT END CR ? / DD 11,036.40	1	\$ 12,248.00	\$ 12,248.00
7	4T0807103G	BUMPER WITH PARKING SENSOR / BR 9374.40	1	\$ 10,416.00	\$ 10,416.00
8	4T0807253	FRONT SPOILER / MIS 532.15	1	\$ 592.00	\$ 592.00
9	4T0807254	FRONT SPOILER RIGHT 532.15 / PR CR	1	\$ 592.00	\$ 592.00
10	4T0853745	LAMBORGHINI EMBLEM / CR 655.30	1	\$ 728.00	\$ 728.00
11	4T0823021C	BONNET FRNT / DD 9266.40	1	\$ 10,296.00	\$ 10,296.00
12	4T0823301B	HINGE LF / BT 303.32	1	\$ 336.00	\$ 336.00
13	4T0823302B	HINGE RH / BT 303.32	1	\$ 336.00	\$ 336.00
14	4T0823351B	ARM ? / BT 66.98	1	\$ 75.00	\$ 75.00
15	4T0823359	GAS FILLED STRUT ? X 100046 ✓ BT	1	\$ 61.00	\$ 61.00
16	4T0805669C	ATTACHMENT BARS LF ? X 86.70 ✓ DD	1	\$ 97.00	\$ 97.00
17	4T0805670C	ATTACHMENT BARS RH ? X 85.30 ✓ DD	1	\$ 95.00	\$ 95.00
18	4T0819967	ARM LF ? X NA	1	\$ 85.00	\$ 35.00
19	4T0819968	ARM RH ? X NA	1	\$ 85.00	\$ 35.00
20	1K1823509E	BONNET LOCK LOWER PART / BT 121.49	1	\$ 147.00	\$ 147.00
21	1Q0823480	CATCH HOOK FRNT / BT 46.32	1	\$ 52.00	\$ 52.00
22	WHT001308	CAP NUT, SELF LOCKING X 1167.66 NN	1	\$ 55.00	\$ 55.00
23	4T2819426D	COVER (center) BR X X PR NN	1	\$ 399.00	\$ 399.00
24	4T0821170D	COVER RH BR 452	1	\$ 503.00	\$ 503.00
25	4T0821169D	COVER LH BR 452	1	\$ 503.00	\$ 503.00
26	4T0821171C	WHEEL HOUSING LINER LH ? 35.30 / CR	1	\$ 497.00	\$ 497.00
27	4T0821172C	WHEEL HOUSING LINER RH ? 35.34 / CR	1	\$ 497.00	\$ 497.00
28	4T0853745	LAMBORGHINI EMBLEM FRONT X Reported	1	\$ 728.00	\$ 728.00
29	4T0863405D	LUGGAGE COMPARTMENT TRIM SEAL / CR	1	\$ 4,060.00	\$ 4,060.00
30	4T0823727B	SEAL (Rubber) CR 186.03 365.92	1	\$ 207.00	\$ 207.00
31	4T0880201A6PS	AIRBAG FOR STEERING MIS 810	1	\$ 900.00	\$ 900.00
32	4G8880204D	AIRBAG UNIT (LH) 2308.50 BR	1	\$ 2,565.00	\$ 2,565.00
33	4S0121252B	ADDITIONAL COOLER FOR COOLANT - NE	2	\$ 647.00	\$ 1,294.00

1167.66 (4H Carole) LH, RH BT
 10/4/19

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, SINGAPORE 159096

TEL : (65) 6565 5995 FAX : (65) 6567 5515



Vehicle / Model : **SMA838R**
 Lamborghini Huracan
 CI: AXA Insurance
 Policy: VPX/P2115122
 Accident Date: May 4th.-2019

10-04-19**Own Damage Claim**

34	4T0807157C	AIR GUIDE LH ? - <i>RR 116.78</i>	1	\$	130.00	\$	130.00
35	4T0807158C	AIR GUIDE RH ? - <i>RR 1106.10</i>	1	\$	120.00	\$	120.00
36	4S0121254B	COOLER FOR COOLANT <i>(center) 8 01 644.14</i>	1	\$	716.00	\$	716.00
37	4T0121334B	AIR GUIDE CENTER - <i>RR 112.34</i>	1	\$	128.00	\$	128.00
38	4T0121334C	AIR GUIDE REAR CENTER ? - <i>RR 167.35</i>	1	\$	188.00	\$	188.00
39		Rivets and fasteners, Glue and Sealers supply <i>RR</i>	1	\$	700.00	\$	720.00

PARTS TOTAL**40****\$ 85,139.00****Labor Charges**

1200X1 8 444x1
 Dismantle, Re Fitting and Repair/knocking *(10 Days)* ✓ *9600* \$ 12,000.00
 Respray front bumper and fender and spoiler *1600x1* ✓ *4800* \$ 6,500.00
1200X1

Subtotal for Labor**103,639****\$ 18,500.00****GST Total****143,537.45****\$ 7,254.73****Total****\$ 110,893.73**

- 1 This is only an estimate, should any additional job be found necessary in the course of work, extra material and labour, cost will be charged accordingly for which you will be informed prior to action taken.
- 2 All materials prices quoted are subject to change without notification
- 3 All repairs are subject to spare parts availability
- 4 Quotation valid for one month from date of issue.

Lamborghini Singapore**Workshop Contact:**

Richard Harjanto

Service Advisor

97999593


10/4/19

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, SINGAPORE 159096

TEL : (65) 6565 5995 FAX : (65) 6567 5515



Vehicle / Model :

SMA838R

12-Sep-19

CI:

Lamborghini Huracan

Policy:

AXA Insurance

Accident Date:

VPX/P2115122

May 4th.-2019

Steve (LKK) 13/9/19, 11.22 am

Supplementary Parts

No	Parts	Description	Qty	Unit Price	Amount
1	4T0805178A	Mounting Bar (Right) for bumper protection / <i>DR</i>	1	\$ 123.08	\$ 123.08 <i>116.77</i>
2	4T0807130A	Front bumper bracket (CENTER RIGHT) / <i>DR</i>	1	\$ 70.00	\$ 70.00 <i>63</i>
3	4T0807167	Air Guide (Left) for Radiator / <i>DR</i>	1	\$ 64.00	\$ 64.00 <i>57.60</i>
4	* 4T0805255D	Reinforcement - Bracket (LEFT) / <i>MIS</i>	1	\$ 132.00	\$ 132.00 <i>118.80</i>
5	4T0807945	Air Guide for radiator (Left) / <i>DR</i>	1	\$ 47.73	\$ 47.73 <i>42.95</i>
6	4T0807946	Air Guide for radiator (Right) / <i>DR</i>	1	\$ 47.73	\$ 47.73 <i>42.95</i>
7	4T0809963	Air Guide for radiator (Left) / <i>DR</i>	1	\$ 78.80	\$ 78.80 <i>70.92</i>
8	N10738101	SCREW / <i>DR</i>	20	\$ 1.25	\$ 25.00 <i>22.60</i>
9	N90926601	CLAMP / <i>DR</i>	10	\$ 2.03	\$ 20.30 <i>18.20</i>
10	4T0819968	BRACKET Arm for front Bonnet (Right) / <i>DR</i>	1	\$ 84.40	\$ 84.40 <i>75.96</i>
11	8E0806193	CLIP / <i>DR</i>	2	\$ 21.00	\$ 21.00 <i>37.80</i>
12	G013A8JM1	COOLANT Liquid for Radiator 1.5L (AUDI) / <i>MIS</i>	5	\$ 38.00	\$ 38.00 <i>190</i>
13	N10173402	NUT / <i>DR</i>	20	\$ 0.58	\$ 11.60 <i>10.40</i>
14	N10405702	SCREW / <i>DR</i>	10	\$ 1.68	\$ 16.80 <i>15.10</i>
15	N10415903	SCREW / <i>DR</i>	20	\$ 0.40	\$ 8.00 <i>7.20</i>
16	N10424102	SCREW / <i>DR</i>	4	\$ 12.35	\$ 49.40 <i>44.48</i>
17	N10442204	BOLT / <i>DR</i>	10	\$ 2.50	\$ 25.00 <i>22.50</i>
18	4T0805177A	Mounting Bar (LEFT) for bumper protection / <i>DR</i>	1	\$ 123.08	\$ 123.08 <i>110.77</i>
19	* 4T0805256D	Reinforcement - Bracket (RIGHT) / <i>MIS</i>	1	\$ 72.28	\$ 72.28 <i>65.05</i>
20	4T0805532B	Centre Mounting Bracket / <i>DR</i>	1	\$ 99.55	\$ 99.55 <i>89.60</i>
21	WHT001308	CLAMPING CAP NUT M6 / <i>DR</i>	20	\$ 1.10	\$ 22.00 <i>19.80</i>
22	WHT004750	EXPANSION RIVET 8.1X13.0 / <i>DR</i>	10	\$ 2.50	\$ 25.00 <i>22.50</i>
23	WHT007052	BOLT / <i>DR</i>	20	\$ 0.85	\$ 17.00 <i>15.40</i>
24	4H0959651A	FRONT AIRBAG SENSOR LP610 / <i>Shut / MIS</i>	2	\$ 203.98	\$ 407.96 <i>361.16</i>
25	4S0121059D	COOLANT HOSE for radiator (LEFT) / <i>MIS</i>	1	\$ 34.00	\$ 34.00 <i>30.60</i>
26	4S0805137D	Car Battery Bracket / <i>DR</i>	2	\$ 70.60	\$ 70.60 <i>127.08</i>
27	4S0816411A	Aircon CONDENSER / <i>DR</i>	2	\$ 829.40	\$ 1,658.80 <i>1492.92</i>
28	* 4S0816726G	REFRIGERANT LINE, Aircon piping / <i>DR</i>	2	\$ 320.00	\$ 640.00 <i>576</i>
29	4S0816750D	REFRIGERANT LINE, Aircon piping / <i>DR</i>	1	\$ 320.00	\$ 320.00 <i>288</i>
30	4T0805063C	Cover Plate SIDE PANEL (RIGHT) / <i>DR</i>	1	\$ 172.88	\$ 172.88 <i>155.59</i>
31	4T0805064C	Cover Plate SIDE PANEL (LEFT) / <i>DR</i>	1	\$ 172.88	\$ 172.88 <i>155.59</i>
32	4T0805157C	UPPER SIDE MEMBER (Left Bar) / <i>DR</i>	1	\$ 173.68	\$ 173.68 <i>156.81</i>
33	4T0805158B	UPPER SIDE MEMBER (Right Bar) / <i>DR</i>	1	\$ 188.75	\$ 188.75 <i>169.85</i>
34	4T2857706DV04	SEAT BELT (Driver) / <i>Shut</i>	1	\$ 2,655.00	\$ 2,655.00 <i>✓</i>

35	4T0805303C	Connecting Part (Lower member plate Panel) / <i>AK</i> <i>DD</i>	1	\$	208.53	\$	208.53	167.6
36	4T0819967	BRACKET Arm for front Bonnet (Left) / <i>MIS</i>	1	\$	84.40	\$	84.40	75.96
37	4T0809964	Air Guide (Right) / <i>BR</i>	1	\$	78.80	\$	78.80	70.92
38	4T0805585E	COVER PLATE Front (for front chassis) X <i>NN</i>	1	\$	69.95	\$	69.95	
39	4T0805667C	Reinforcement bar LEFT / <i>MIS</i>	1	\$	132.00	\$	132.00	118.80
40	4T0807168	Air Guide (RIGHT) for Radiator / <i>CUT</i>	1	\$	64.00	\$	64.00	57.60
41	N91042302	BOLT / <i>AK</i>	20	\$	2.50	\$	50.00	45
42	4T0805668C	BRACKET RIGHT / <i>MIS</i>	1	\$	170.53	\$	170.53	153.47
43	4T0805669C	Attachement Bar for bonnet damper / <i>jeann</i> <i>(1)</i>	2	\$	96.35	\$	192.70	86.72
44	T0805670C	Head Lamp Brackets / <i>MIS</i> <i>(1)</i>	2	\$	94.75	\$	189.50	85.28
45	T0805845B	STOP BAR for head lamp mount (LEFT) / <i>BT</i>	1	\$	45.00	\$	45.00	40.50
46	4T0805846B	STOP BAR for head lamp mount (RIGHT) X <i>NN</i>	1	\$	45.55	\$	45.55	
47	4T0807129A	Front bumper bracket (CENTER LEFT) / <i>OR</i>	1	\$	70.00	\$	70.00	63
48	4S0915181	Control Unit for Battery Cut Off sensor / <i>SPM</i>	1	\$	390.00	\$	390.00	351
49	4T0807551E	ARM / Bracket for Bumper Protection LEFT / <i>DD</i>	1	\$	363.53	\$	363.53	327.17
50	4T0807552E	ARM / Bracket for Bumper Protection RIGHT / <i>DD</i>	1	\$	310.25	\$	310.25	279.3
51	4T0825101D	Under Body trim panel (FRONT) / <i>OR</i>	1	\$	1,051.20	\$	1,051.20	✓
52	4T0825208A	Under Body trim panel (Center) / <i>OR</i>	1	\$	884.75	\$	884.75	796.21
53	4T0863635E	PARTITION TRIM for bonnet compartment / <i>OR</i>	1	\$	378.13	\$	378.13	340.31
54	4T0867393C	COVER (center console) / <i>OR</i> <i>2</i>	2	\$	213.43	\$	213.43	384.16
55	4T0951206A	HORN WITH BRACKET / <i>BT</i>	1	\$	175.20	\$	175.20	157.68
56	4T0971095F	Wire set Harness for front sensors / <i>CRU</i>	1	\$	256.35	\$	256.35	230.7
57	4T2819426E	Front under bonnet Trim / <i>OR</i>	1	\$	398.55	\$	398.55	358.70
58	4T2858451D	DASHBOARD UPPER LP610 / <i>OR</i>	1	\$	11,008.40	\$	11,008.40	✓
59	7P0915105C	Car BATTERY 95AH LP580/LP610 / <i>OR</i>	1	\$	651.45	\$	651.45	✓
60	4S0937548BA	MAIN FUSE BOX LP610 / <i>Shd</i>	1	\$	319.80	\$	319.80	287.82
61	4T0803593Y9B	TOWING HOOK COVER (LEFT) / <i>MIS</i>	1	\$	208.48	\$	208.48	187.63
62	4T2857705CV04	SEAT BELT (Passenger) / <i>Shd</i>	1	\$	2,655.00	\$	2,655.00	2389.5
63	53912032	HOSE CLAMP / <i>AK</i>	1	\$	3.00	\$	3.00	✓
64	5Q0919275CGRU	FRT PARKING SENSOR LP580 / <i>Shd</i>	4	\$	217.88	\$	871.52	✓
65	N10680601	HEX SOCKET / <i>AK</i>	20	\$	0.88	\$	17.60	15.80
66	4T0803594Y9B	TOWING HOOK COVER (RIGHT) / <i>AK</i> X <i>NN</i>	1	\$	208.48	\$	208.48	
67	4T0845099G	Front Windscreen Glass / <i>Wid too</i>	1	\$	8,900.00	\$	8,900.00	✓
68		Winscreen Glass Sealant and gasket / <i>AK</i> X <i>NN</i>	1	\$	200.00	\$	200.00	
					Sub-Total	\$	38,582.38	
Supplementary Labour for Windscreen / <i>AK</i>						\$	1,000.00	500 ✓
					Sub Total	\$	39,582.38	
					gst	\$	2,770.77	
					TOTAL	\$	42,353.15	



12/09/2019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 4 October 2019 5:41 PM
To: Steve Chen (LKK Auto); Richard Harjanto
Cc: SF Eyu; Khan Wei Loh; SUR
Subject: RE: SMA838R OD Claim - finalization

Dear Richard,

Confirmed amount \$128,676.55 before excess \$18,000 and GST
No of days: 12 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Sent: Friday, 4 October 2019 5:34 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: SMA838R OD Claim - finalization

Dear Veron,

FYI

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Richard Harjanto [<mailto:richardharjanto@eurosportsauto.com.sg>]
Sent: Thursday, October 03, 2019 11:57 AM
To: Steve Chen (LKK Auto)
Cc: Sf Eyu; Loh Khan Wei
Subject: SMA838R OD Claim - finalization

Hello Steve,

I have amended the invoice as requested.
Please proceed to finalize the claim.

Thank you and,

Best regards,
Richard Harjanto

Lamborghini Singapore
EuroSports Auto Pte Ltd
Richard Harjanto
Service Advisor

24 Leng Kee Road #01-03
Singapore 159096
Phone: +65 6882 0865
Mobile: +65 9799 9593
Email: richardharjanto@eurosportsauto.com.sg
Web: www.lamborghini-singapore.com
Web: www.eurosportsglobal.com

The contents of this e-mail, and any attachments, are confidential and intended only for the person(s) to whom they are addressed. If you have received the email by mistake please notify the sender immediately and delete it from your computer system. Do not copy or distribute it or disclose its contents to any person. Any improper use of the contents of this email will be prosecuted by law in compliance with the laws in the matter of data protection as well as in order to protect the right of confidentiality of correspondence

This email has been scanned by the NEX Managed Cloud Messaging service powered by Barracuda Networks

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: M90368995L



TAX INVOICE

GST Reg No.: M90368995L

Deliver To: Dr.
Tay Hin Ngan
23 Marigold Drive
Singapore 576425

AXA Insurance (S) Pte Ltd
8 Shenton way #27-01 AXA Tower
Singapore 068811
Invoice to: 3

Document No.:
Document Date: 03-Oct-19
REGN No.: SMA838R
Odometer:
Model: 2016 Huracan
Variant: LP580-2
Vehicle ID No.: ZHWEC2ZF1GLA04755
Repair Order No.: 17236
Delivery Date: 27/04/2018
Page: 1 of 5
Advisor: Richard Harjanto

Accident Reporting DOA 04/05/2019

Accident Reporting DOA 04/05/2019

OD Claim

AXA Insurance (Surveyor LKK Auto)

VPX/P2115122

Part Number	Part Description	List Price	Nett Price	Quantity	Total Cost
4T0821171C	WHEEL HOUSING LP610	392.00	352.80	1.00	352.80
4T0823727B	SEAL ENGINE	206.70	186.03	1.00	186.03
4T0807109C	BUMPER BAR, FRONT PARALYT. OSSAT. ANT	1,600.15	1,440.14	1.00	1440.14
4T0863405D	LINING KOFFERRAUM OBEN	4,058.80	3,652.92	1.00	3652.92
4T0823301B	LEFT FRONT HOOD HINGE	335.80	302.22	1.00	302.22
4T0121334B	AIR DUCT ELEMENT	124.88	112.39	1.00	112.39
4T0821170D	COVER	502.23	452.00	1.00	452.00
4T0821169D	COVER	502.23	452.00	1.00	452.00
4T0807254	FRONT BUMPER FIN, RH STD	591.28	532.15	1.00	532.15
4S0805137D	BRACKET BATTERIE <i>(front and rear) NPC</i>	70.60	63.54	2.00	127.08
WHT001308	CLAMPING CAP NUT M6 <i>NPC</i>	1.10	0.99	20.00	19.80
4T0807253	FRONT BUMPER FIN, LH STD	591.28	532.15	1.00	532.15
4T0807157C	AIR DUCT ELEMENT LH	129.75	116.78	1.00	116.78
4T0805670C	BRACKET SCHEINWERFER OBEN	94.75	85.28	1.00	85.28
4T0941004G	FRT HEADLAMP RH LP580/LP610	9,970.93	9,970.93	1.00	9970.93
4T0805028K	FRONT FRAME ASSEMBLY LP610	12,246.00	11,021.40	1.00	11021.40
4T0121334C	AIR DUCT ELEMENT	186.20	167.58	1.00	167.58
4T0823351B	BEARING	74.43	66.98	1.00	66.98
4T0823359	FRT BONNET DAMPER LP610	112.18	100.96	1.00	100.96
4S0121254B	RADIATOR CENTER LP610	716.00	644.40	1.00	644.40
4T0821022D	FRT FENDER RH LP580/LP610	6,643.00	5,978.70	1.00	5978.70
4S0121252B	RADIATOR LINKS/RECHTS	648.70	583.83	2.00	1167.66
4T0807997A	LICENCE PLATE BRACKET LP580 <i>/ MIS (A)</i>	75.10	67.59	1.00	67.59
1K1823509E	HOOD LATCH LP610	146.10	131.49	1.00	131.49
G013A8JM1	COOLANT 1.5L (AUDI) <i>* NPC</i>	38.00	38.00	5.00	190.00



Continued Next Page ...

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: M90368995L



TAX INVOICE

GST Reg No.: M90368995L

Deliver To: Dr.
Tay Hin Ngan
23 Marigold Drive
Singapore 576425

AXA Insurance (S) Pte Ltd
8 Shenton way #27-01 AXA Tower
Singapore 068811
Invoice to: 3

Document No.:
Document Date: 03-Oct-19
REGN No.: SMA838R
Odometer:
Model: 2016 Huracan
Variant: LP580-2
Vehicle ID No.: ZHWEC2ZF1GLA04755
Repair Order No.: 17236
Delivery Date: 27/04/2018
Page: 2 of 5
Advisor: Richard Harjanto

Accident Reporting DOA 04/05/2019

4G8880204D	AIRBAG PASSENGER SIDE	2,565.00	2,308.50	1.00	2308.50
4T0821172A	WHEEL HOUSING LP610	382.15	352.94	1.00	352.94
4T0823021C	HOOD PERFORMANTE	10,296.00	9,266.40	1.00	9266.40
4T0807158C	AIR DUCT ELEMENT	118.55	106.70	1.00	106.70
4T0823302B	RIGHT FRONT HOOD HINGE	335.80	302.22	1.00	302.22
4T0853745	FRT LOGO LP700LP750	728.00	655.20	1.00	655.20
1Q0823480	BONNET HOOK	51.35	46.22	1.00	46.22
4T0807103G	FRT BUMPER W/SENSOR LP560	10,626.00	9,374.40	1.00	9374.40
4T0941003G	FRT HEADLAMP LH LP580/LP610	9,970.93	9,970.93	1.00	9970.93
4T0880201C6PS	AIRBAG STEERING WHEEL	900.00	810.00	1.00	810.00
4T0805669C	ATTACHMENT BARS	96.35	86.72	1.00	86.72
4T0821021D	FRT FENDER LH LP580/LP610	6,552.00	5,896.80	1.00	5896.80
					\$77,048.46

Supplementary parts

Part Number	Part Description	List Price	Nett Price	Quantity	Total Cost
N10415903	SCREW	0.40	0.36	20.00	7.20
N10405702	SCREW	1.68	1.51	10.00	15.10
N10173402	NUT	0.58	0.52	20.00	10.40
4T0819968	BRACKET	84.40	75.96	1.00	75.96
4T0819967	BRACKET	84.40	75.96	1.00	75.96
4T0809964	AIR DUCT ELEMENT	78.80	70.92	1.00	70.92
4T0807946	AIR DUCT PART	47.73	42.95	1.00	42.95
4T0807945	AIR DUCT PART	47.73	42.95	1.00	42.95
4S00375488A	MAIN FUSE BOX LP610	319.80	287.82	1.00	287.82
7P0915105C	BATTERY 95AH LP580/LP610 & PERFORMANTE	651.45	651.45	1.00	651.45
4T2857706DV04	SEAT BELT	2,655.00	2,655.00	1.00	2655.00
4T0809963	AIR DUCT ELEMENT	78.80	70.92	1.00	70.92
4T0807168	PROTECTIVE CAP SPOTEL RADIAT ANT	64.00	57.60	1.00	57.60
4T0807167	PROTECTIVE CAP SPOTEL RADIAT ANT	64.00	57.60	1.00	57.60



Continued Next Page ...

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: M90368995L



TAX INVOICE

GST Reg No.: M90368995L

Deliver To: Dr.
Tay Hin Ngan
23 Marigold Drive
Singapore 576425

AXA Insurance (S) Pte Ltd
8 Shenton way #27-01 AXA Tower
Singapore 068811
Invoice to: 3

Document No.:

Document Date:

REGN No.:

Odometer:

Model:

Variant:

Vehicle ID No.:

Repair Order No.:

Delivery Date:

Page:

Advisor:

03-Oct-19

SMA838R

2016 Huracan

LP580-2

ZHWEC2ZF1GLA04755

17238


27/04/2018

3 of 5

Richard Harjanto

Supplementary parts

4T0551206A	HORN WITH BRACKET	175.20	157.68	1.00	157.68
8E0806193	CLIP <i>AKC</i>	21.00	18.90	2.00	37.80
4S0915181	BATTERY MANAGEMENT/DIAG	390.00	351.00	1.00	351.00
4T0867393C	COVER	213.43	192.08	2.00	384.16
4T0863635E	PARTITION TRIM	378.13	340.31	1.00	340.31
N10424102	SCREW	12.35	11.12	4.00	44.48
053912032	HOSE CLAMP 20-32	3.00	3.00	1.00	3.00
4T0825208A	CD ENHANCING VORNE HINTEN	884.75	796.28	1.00	796.28
4T0825101D	CD ENHANCING	1,051.20	1,051.20	1.00	1051.20
4T0807551E	ARM LP610	363.53	327.17	1.00	327.17
4T0807130A	BRACKET (CENTER RIGHT)	70.00	63.00	1.00	63.00
4T0807129A	BRACKET SUPPORT FIX BUMPER	70.00	63.00	1.00	63.00
4T0805670C	BRACKET SCHEINWERFER OBEN	94.75	85.28	1.00	85.28
4T0805669C	ATTACHMENT BARS	96.35	86.72	1.00	86.72
4T0805668C	BRACKET RIGHT	170.53	153.47	1.00	153.47
5Q0919275CGRU	FRT PARKING SENSOR LP580	217.88	217.88	4.00	871.52
4T0805532B	MOUNTING SCHLOSS	99.55	89.60	1.00	89.60
4T0805303C	CONNECTING PART BODEN KOFFERRAUM	208.53	187.67	1.00	187.67
4T0805256D	REINF.PART	72.28	65.05	1.00	65.05
4T0805178A	CLIP ANGLE TELAIO ANTERIORE	123.08	110.77	1.00	110.77
4T0805177A	CLIP ANGLE TELAIO ANTERIORE	123.08	110.77	1.00	110.77
4T0805158B	UPPER SIDE MEMBER	188.75	169.88	1.00	169.88
4T2857705CV04	SEAT BELT	2,855.00	2,389.50	1.00	2389.50
4T0803593Y9B	TOWING HOOK COVER	208.48	187.63	1.00	187.63
4T0805157C	UPPER SIDE MEMBER	173.68	156.31	1.00	156.31
4T0805255D	REINF.PART	132.00	118.80	1.00	118.80
4T0805064C	SIDE PANEL	172.88	155.59	1.00	155.59
4T0805063C	SIDE PANEL	172.88	155.59	1.00	155.59
4S0816750D	REFRIGERANT LINE HEISSGAS KOND-KOND	320.00	288.00	1.00	288.00
4T0805667C	BRACKET LEFT	132.00	118.80	1.00	118.80
4S0816726G	REFRIGERANT LINE, HEISSGASLTG.KOND.	320.00	288.00	2.00	576.00



Continued Next Page ...

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: M90368995L



TAX INVOICE

GST Reg No.: M90368995L

Deliver To: Dr.
Tay Hin Ngan
23 Marigold Drive
Singapore 576425

AXA Insurance (S) Pte Ltd
8 Shenton way #27-01 AXA Tower
Singapore 068811
Invoice to: 3

Document No.:

Document Date: 03-Oct-19

REGN No.: SMA838R

Odometer:

Model: 2016 Huracan

Variant: LP580-2

Vehicle ID No.: ZHWEC2ZF1GLA04755

Repair Order No.: 17236

Delivery Date: 27/04/2018

Page: 4 of 5

Advisor: Richard Harjanto

Supplementary parts

4S0816411A	CONDENSER	829.40	745.46	2.00	1492.92
4S0121059D	COOLANT HOSE	34.00	30.80	1.00	30.60
4T0805845B	STOP BAR (LEFT)	45.00	40.50	1.00	40.50
4H0959651A	FRONT AIRBAG SENSOR LP610	203.98	183.58	2.00	367.16
4T0845099A	FRT WINDSCREEN LP580/LP610	8,900.00	8,900.00	1.00	8900.00
WHT007052	BOLT	0.85	0.77	20.00	15.40
4T0807552E	DEFORMATION	310.25	279.23	1.00	279.23
WHT004750	EXPANSION RIVET 8.1X13.0	2.50	2.25	10.00	22.50
N91042302	BOLT	2.50	2.25	20.00	45.00
N90926601	CLAMP	2.03	1.82	10.00	18.20
N10738101	SCREW	1.25	1.13	20.00	22.60
N10680601	HEX SOCKET	0.88	0.79	20.00	15.80
4T0971095F	HARNESS, BUMPER FRONT	256.35	230.72	1.00	230.72
4T2819426E	PLENUM PANEL COVER	358.55	358.70	1.00	358.70
4T2858451D	DASHBOARD UPPER LP610	11,008.40	11,008.40	1.00	11008.40
N10442204	BOLT	2.50	2.25	10.00	22.50
					\$36,688.09

TO supply new number plate

new plate SMA838R

03 / DR

\$40.00

To Repair, knocking, and respray body panels

\$4,800.00

To Repair, knocking, and respray body panels

To perform repair, knocking and welding on car front chassis and frame

Repair, knocking and welding on car front chassis

\$9,600.00



Continued Next Page ...

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: M90368995L



TAX INVOICE

GST Reg No.: M90368995L

Deliver To: Dr.
Tay Hin Ngan
23 Marigold Drive
Singapore 578425

AXA Insurance (S) Pte Ltd
8 Shenton way #27-01 AXA Tower
Singapore 068811
Invoice to: 3

Document No.:

Document Date: 03-Oct-19

REGN No.: SMA838R

Odometer:

Model: 2016 Huracan

Variant: LP580-2

Vehicle ID No.: ZHWEC2ZF1GLA04755

Repair Order No.: 17236

Delivery Date: 27/04/2018

Page: 5 of 5

Advisor: Richard Harjanto

To perform repair, knocking and welding on car front chassis and frame
Labor to dismantle and re fitting parts and panels, do adjustment on panels

Customer paid Excess

(\$18,000.00)

Labor to replace new windscreen

\$500.00

128,676.55

EuroSports Auto Pte Ltd



Signature

Date

3/10/19

Sub Total for All: \$110,676.55

Rounding: \$0.00

GST: \$7,747.36

Total: \$118,423.91

Terms:


Any objections to the validity of the charges must be made within seven (7) days from the date of this invoice otherwise it is assumed this Bill is accepted as correct.

GOODS SOLD ARE NOT RETURNABLE OR REFUNDABLE

Model : HURACAN LP580-2 COUPE Market: AUSTRALIA MY 2016

Group : 823-FRONT HOOD

Table : 823.01.00-BONNET



Ref.	Code	Q.ty	Description
1	4T0823021C	1	BONNET (CONTACT YOUR AREA MANAGER)
2	4T0823301B	1	HINGE (LEFT)
2	4T0823302B	1	HINGE (RIGHT)
3	4T0823351B	1	ARM
4	4T0823359	1	GAS FILLED STRUT
5	4T0805669C	2	ATTACHMENT BARS (LEFT)
5	4T0805670C	1	ATTACHMENT BARS (RIGHT)
6	4T0819549	1	BRACKET
7	4T0823531B	1	BOWDEN CABLE
8	420959782	1	SERVOMOTOR
9	4T0819967	1	ARM (LEFT)
9	4T0819968	1	ARM (RIGHT)
10	1K1823509E	1	BONNET LOCK-LOWER PART (WITH WIRING HARNESS)
11	1Q0823480	1	CATCH HOOK (FRONT)
12	N91205301	3	HEXAGON FLANGE NUT, SELF-LOCKING (M6)
13	WHT001308	3	CAP NUT, SELF-LOCKING
14	4E0823481	2	STOP BUFFER (LEFT A. RIGHT)
15	3D0971497D	4	CABLE TIE WITH TERMINAL SOCKET (1-3MM VERTICAL OUTER)
16	N90863802	4	HEXAGON HEAD BOLT (COMBI) (M8X25)
17	N10553804	2	HEXAGON HEAD BOLT (COMBI) (M6X45)
18	895827439D	4	BALL STUD
19	N90798805	2	HEXAGON COLLAR NUT (M8)
20	N90900401	2	HEX SOCKET OVAL HEAD COLLARED (M6X20)
21	N90739704	2	PANEL SCREW (5X22)
22	N91042302	4	OVAL HEXAGON SOCKET HEAD BOLT (M6X16)
23			MOUNTING BAR (ONLY FOR USA AND CANADA MARKET)

#43


#36
#10

07



Model : HURACAN LP580-2 COUPE Market: AUSTRALIA MY 2016

Group : 941-FRONT LIGHTS

Table : 941.01.00-LED HEADLIGHT



Ref.	Code	Q.ty	Description
1	4T0941003G	1	LED HEADLIGHT (LEFT FRONT)
1	4T0941004G	1	LED HEADLIGHT (RIGHT FRONT)
2			BUMPER (SEE ILLUSTRATION : 807.05-FRONT)
3	4T0945119B	1	TURN SIGNAL INDICATOR (SIDE, LEFT)
3	4T0945120B	1	TURN SIGNAL INDICATOR (SIDE, RIGHT)
4	N90965702	2	HEXAGON SOCKET HEAD BOLT (COMBI) (M6X35)
5	8E0806193	2	COMPENSATING PIECE (3,4MM)
6	N10442204	4	HEXAGON SOCKET OVAL HEAD BOLT (COMBI) (M5X40-M6X40)
7	N91136801	4	HEXAGON SOCKET HEAD PANEL BOLT (ST4.2X9.5-4,2X11)
#45 #46	8 4T0805845B	1	STOP BAR (LEFT)
	8 4T0805846B	1	STOP BAR (RIGHT)
	9 N10017304	4	HEXAGON COLLAR NUT (M5-M5)
	10 N91042302	5	OVAL HEXAGON SOCKET HEAD BOLT (M6X16-M6X16)
#44	11 4T0805669C	1	ATTACHMENT BARS (LEFT)
	11 4T0805670C	1	ATTACHMENT BARS (RIGHT)



ITEMS

CART 0

SEARCH

Ref	PN	Q.ty	Description	Notes	Q.ty Ord.	Model	Type	MY	MKT	CT
1	4T2819426D	1	COVER	RHD <i>Broken</i>		HURACAN	LP580-2 COUPE'	2016	AUSTRALIA	SP
2	4T0821170D	1	COVER	RIGHT		HURACAN	LP580-2 COUPE'	2016	AUSTRALIA	SP
3	4T0821169D	1	COVER	LEFT		HURACAN	LP580-2 COUPE'	2016	AUSTRALIA	SP
4	4T0815715E	1	COVER FOR BRAKE FLUID CONTAINER			HURACAN	LP580-2 COUPE'	2016	AUSTRALIA	SP
5	N10738101	20	HEX SOCKET HEAD BOLT (COMBI)	M5X16		HURACAN	LP580-2 COUPE'	2016	AUSTRALIA	SP
6	N0200241	4	BUNGS	10X1X12		HURACAN	LP580-2 COUPE'	2016	AUSTRALIA	SP

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: M90368995L



TAX INVOICE

GST Reg No.: M90368995L

Deliver To: Dr.
Tay Hin Ngan
23 Marigold Drive
Singapore 576425

AXA Insurance (S) Pte Ltd
8 Shenton way #27-01 AXA Tower
Singapore 068811
Invoice to: 3

Document No.:

Document Date: 03-Oct-19
REGN No.: SMA838R
Odometer:
Model: 2016 Huracan
Variant: LP580-2
Vehicle ID No.: ZHWEC2ZF1GLA04755
Repair Order No.: 17236
Delivery Date: 27/04/2018
Page: 1 of 5
Advisor: Richard Harjanto

Accident Reporting DOA 04/05/2019


Accident Reporting DOA 04/05/2019

OD Claim

AXA Insurance (Surveyor LKK Auto)

VPX/P2115122

Part Number	Part Description	List Price	Nett Price	Quantity	Total Cost
4T0821171C	WHEEL HOUSING LP610	392.00	352.80	1.00	352.80
4T0823727B	SEAL,ENGINE	206.70	186.03	1.00	186.03
4T0807109C	BUMPER BAR,FRONT PARAURT.OSSAT,ANT	1,600.15	1,440.14	1.00	1440.14
4T0863405D	LINING KOFFERRAUM OBEN	4,058.80	3,652.92	1.00	3652.92
4T0823301B	LEFT FRONT HOOD HINGE	335.80	302.22	1.00	302.22
4T0121334B	AIR DUCT ELEMENT	124.88	112.39	1.00	112.39
4T0821170D	COVER	502.23	452.00	1.00	452.00
4T0821169D	COVER	502.23	452.00	1.00	452.00
4T0807254	FRONT BUMBER FIN, RH STD	591.28	532.15	1.00	532.15
4S0805137D	BRACKET BATTERIE	70.60	63.54	2.00	127.08
WHT001308	CLAMPING CAP NUT M6	1.10	0.99	20.00	19.80
4T0807253	FRONT BUMBER FIN, LH STD	591.28	532.15	1.00	532.15
4T0807157C	AIR DUCT ELEMENT LH	129.75	116.78	1.00	116.78
4T0805670C	BRACKET SCHEINWERFER OBEN	94.75	85.28	1.00	85.28
4T0941004G	FRT HEADLAMP RH LP580/LP610	9,970.93	9,970.93	1.00	9970.93
4T0805028K	FRONT FRAME ASSEMBLY LP610	12,246.00	11,021.40	1.00	11021.40
4T0121334C	AIR DUCT ELEMENT	166.20	167.58	1.00	167.58
4T0823351B	BEARING	74.43	66.98	1.00	66.98
4T0823359	FRT BONNET DAMPER LP610	112.18	100.96	1.00	100.96
4S0121254B	RADIATOR CENTER LP610	716.00	644.40	1.00	644.40
4T0821022D	FRT FENDER RH LP580/LP610	6,643.00	5,978.70	1.00	5978.70
4S0121252B	RADIATOR LINKS/RECHTS	646.70	583.63	2.00	1167.66
4T0807997A	LICENCE PLATE BRACKET LP580	75.10	67.59	1.00	67.59
1K1823509E	HOOD LATCH LP610	146.10	131.49	1.00	131.49
G013A8JM1	COOLANT 1.5L (AUDI)	38.00	38.00	5.00	190.00



Continued Next Page ...

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: M90368995L



TAX INVOICE

GST Reg No.: M90368995L

Deliver To: Dr.
Tay Hin Ngan
23 Marigold Drive
Singapore 576425

AXA Insurance (S) Pte Ltd
8 Shenton way #27-01 AXA Tower
Singapore 068811
Invoice to: 3

Document No.:

Document Date: 03-Oct-19
REGN No.: SMA838R
Odometer:
Model: 2016 Huracan
Variant: LP580-2
Vehicle ID No.: ZHWEC2ZF1GLA04755
Repair Order No.: 17238
Delivery Date: 27/04/2018
Page: 2 of 5
Advisor: Richard Harjanto

Accident Reporting DOA 04/05/2019

4G8880204D	AIRBAG PASSENGER SIDE	2,585.00	2,308.50	1.00	2308.50
4T0821172A	WHEEL HOUSING LP610	392.15	352.94	1.00	352.94
4T0823021C	HOOD PERFORMANTE	10,296.00	9,266.40	1.00	9266.40
4T0807158C	AIR DUCT ELEMENT	118.55	106.70	1.00	106.70
4T0823302B	RIGHT FRONT HOOD HINGE	335.80	302.22	1.00	302.22
4T0853745	FRT LOGO LP700/LP750	728.00	655.20	1.00	655.20
1Q0823480	BONNET HOOK	51.35	46.22	1.00	46.22
4T0807103G	FRT BUMPER W/SENSOR LP580	10,525.00	9,374.40	1.00	9374.40
4T0941003G	FRT HEADLAMP LH LP580/LP610	9,970.93	9,970.93	1.00	9970.93
4T0880201C6PS	AIRBAG STEERING WHEEL	900.00	810.00	1.00	810.00
4T0805669C	ATTACHMENT BARS	96.35	86.72	1.00	86.72
4T0821021D	FRT FENDER L I LP580/LP610	6,552.00	5,896.80	1.00	5896.80
					\$77,048.46

Supplementary parts

Part Number	Part Description	List Price	Nett Price	Quantity	Total Cost
N10415903	SCREW	0.40	0.36	20.00	7.20
N10405702	SCREW	1.68	1.51	10.00	15.10
N10173402	NUT	0.58	0.52	20.00	10.40
4T0819968	BRACKET	84.40	75.96	1.00	75.96
4T0819967	BRACKET	84.40	75.96	1.00	75.96
4T0809964	AIR DUCT ELEMENT	78.80	70.92	1.00	70.92
4T0807946	AIR DUCT PART	47.73	42.95	1.00	42.95
4T0807945	AIR DUCT PART	47.73	42.95	1.00	42.95
4S0937548BA	MAIN FUSE BOX LP610	319.80	287.82	1.00	287.82
7P0915105C	BATTERY 95AH LP580/LP610 & PERFORMANTE	651.45	651.45	1.00	651.45
4T2857700DV04	SEAT BELT	2,655.00	2,655.00	1.00	2655.00
4T0809963	AIR DUCT ELEMENT	78.80	70.92	1.00	70.92
4T0807168	PROTECTIVE CAP SPORTEL RADIAT ANT	64.00	57.60	1.00	57.60
4T0807167	PROTECTIVE CAP SPORTEL RADIAT ANT	64.00	57.60	1.00	57.60



Continued Next Page ...

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: M90368995L



TAX INVOICE

GST Reg No.: M90368995L

Deliver To: Dr.
Tay Hin Ngan
23 Marigold Drive
Singapore 576425

AXA Insurance (S) Pte Ltd
8 Shenton way #27-01 AXA Tower
Singapore 068811
Invoice to: 3

Document No.:

Document Date: 03-Oct-19

REGN No.: SMA838R

Odometer:

Model: 2016 Huracan

Variant: LP580-2

Vehicle ID No.: ZHWEC2ZF1GLA04755

Repair Order No.: 17236


Delivery Date: 27/04/2018

Page: 3 of 5

Advisor: Richard Harjanto

Supplementary parts

4T0851208A	HORN WITH BRACKET	175.20	157.68	1.00	157.68
8E0806193	CLIP	21.00	18.90	2.00	37.80
4S0815181	BATTERY MANAGEMENTDIAG	390.00	351.00	1.00	351.00
4T0867393C	COVER	213.43	192.08	2.00	384.16
4T0863635E	PARTITION TRIM	378.13	340.31	1.00	340.31
N10424102	SCREW	12.35	11.12	4.00	44.48
053912032	HOSE CLAMP 20-32	3.00	3.00	1.00	3.00
4T0825208A	CD ENHANCING VORNE HINTEN	884.75	796.28	1.00	796.28
4T0825101D	CD ENHANCING	1,051.20	1,051.20	1.00	1051.20
4T0807551E	ARM LP610	363.53	327.17	1.00	327.17
4T0807130A	BRACKET (CENTER RIGHT)	70.00	63.00	1.00	63.00
4T0807129A	BRACKET SUPPORT FIX BUMPER	70.00	63.00	1.00	63.00
4T0806670C	BRACKET SCHEINWERFER OBEN	94.75	85.28	1.00	85.28
4T0805669C	ATTACHMENT BARS	96.35	86.72	1.00	86.72
4T0805668C	BRACKET RIGHT	170.53	153.47	1.00	153.47
5Q0919275CGRU	FRT PARKING SENSOR LP580	217.88	217.88	4.00	871.52
4T0805532B	MOUNTING SCHLOSS	99.55	89.60	1.00	89.60
4T0805303C	CONNECTING PART BODEN KOFFERRAUM	208.53	187.67	1.00	187.67
4T0805258D	REINF.PART	72.28	65.05	1.00	65.05
4T0805178A	CLIP ANGLE TELAIO ANTERIORE	123.08	110.77	1.00	110.77
4T0805177A	CLIP ANGLE TELAIO ANTERIORE	123.08	110.77	1.00	110.77
4T0805158B	UPPER SIDE MEMBER	188.75	169.88	1.00	169.88
4T2857705CV04	SEAT BELT	2,655.00	2,389.50	1.00	2389.50
4T0803593Y9B	TOWING HOOK COVER	208.48	187.63	1.00	187.63
4T0805157C	UPPER SIDE MEMBER	173.68	156.31	1.00	156.31
4T0805255D	REINF.PART	132.00	118.80	1.00	118.80
4T0805054C	SIDE PANEL	172.88	155.59	1.00	155.59
4T0805083C	SIDE PANEL	172.88	155.59	1.00	155.59
4S0816750D	REFRIGERANT LINE HEISSGAS KOND-KOND	320.00	288.00	1.00	288.00
4T0805667C	BRACKET LEFT	132.00	118.80	1.00	118.80
4S0816726G	REFRIGERANT LINE, HEISSGASLTG.KOND.	320.00	288.00	2.00	576.00



Continued Next Page ...

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: M90368995L



TAX INVOICE

GST Reg No.: M90368995L

Deliver To: Dr.
Tay Hin Ngan
23 Marigold Drive
Singapore 576425

AXA Insurance (S) Pte Ltd
8 Shenton way #27-01 AXA Tower
Singapore 068811
Invoice to: 3

Document No.:
Document Date: 03-Oct-19
REGN No.: SMA838R
Odometer:
Model: 2016 Huracan
Variant: LP580-2
Vehicle ID No.: ZHWEC2ZF1GLA04755
Repair Order No.: 17236
Delivery Date: 27/04/2018
Page: 4 of 5
Advisor: Richard Harjanto

Supplementary parts

4S0816411A	CONDENSER	629.40	746.46	2.00	1492.92
4S0121059D	COOLANT HOSE	34.00	30.60	1.00	30.60
4T0805345B	STOP BAR (LEFT)	45.00	40.50	1.00	40.50
4H0959651A	FRONT AIRBAG SENSOR LP610	203.98	183.58	2.00	367.16
4T0845099A	FRT WINDSCREEN LP580/LP610	8,900.00	8,900.00	1.00	8900.00
WHT007052	BOLT	0.85	0.77	20.00	15.40
4T0807552E	DEFORMATION	310.25	279.23	1.00	279.23
WHT004750	EXPANSION RIVET 8.1X13.0	2.50	2.25	10.00	22.50
N91042302	BOLT	2.50	2.25	20.00	45.00
N90926601	CLAMP	2.03	1.82	10.00	18.20
N10738101	SCREW	1.25	1.13	20.00	22.60
N10600001	HEX SOCKET	0.88	0.79	20.00	15.80
4T0971085F	HARNESS, BUMPER FRONT	256.35	230.72	1.00	230.72
4T2819426E	PLENUM PANEL COVER	396.55	358.70	1.00	358.70
4T2858451D	DASHBOARD UPPER LP610	11,008.40	11,008.40	1.00	11008.40
N10442204	BOLT	2.50	2.25	10.00	22.50
					\$36,688.09

To supply new number plate

\$40.00

new plate SMA838R

To Repair, knocking, and respray body panels

\$4,800.00

To Repair, knocking, and respray body panels

To perform repair, knocking and welding on car front chassis and frame

Repair, knocking and welding on car front chassis

\$9,600.00



Continued Next Page ...

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: M90368995L



TAX INVOICE

GST Reg No.: M90368995L

Deliver To: Dr.
Tay Hin Ngan
23 Marigold Drive
Singapore 576425

AXA Insurance (S) Pte Ltd
8 Shenton way #27-01 AXA Tower
Singapore 068811
Invoice to: 3

Document No.:

Document Date: 03-Oct-19
REGN No.: SMA838R
Odometer:
Model: 2016 Huracan
Variant: LP580-2
Vehicle ID No.: ZHWEC2ZF1GLA04755
Repair Order No.: 17238
Delivery Date: 27/04/2018
Page: 5 of 5
Advisor: Richard Harjanto

To perform repair, knocking and welding on car front chassis and frame

Labor to dismantle and re fitting parts and panels, do adjustment on panels

Customer paid Excess

(\$18,000.00)

Labor to replace new windscreen

\$500.00

EuroSports Auto Pte Ltd



Signature

Date

3/10/19

Sub Total for All: \$110,676.55

Rounding: \$0.00

GST: \$7,747.36

Total: \$118,423.91

Terms:

Any objections to the validity of the charges must be made within seven (7) days from the date of this invoice otherwise it is assumed this Bill is accepted as correct.

GOODS SOLD ARE NOT RETURNABLE OR REFUNDABLE

SATISFACTION DISCHARGE VOUCHER

I hereby certify that my motor vehicle, as per particulars stated here under has been repaired to my complete satisfaction. To pay Own Damage claim Excess \$18,000 + GST.

Own Damage Claim (AXA Insurance)

Name of insured: Dr Tay Hin Ngan
Vehicle number: SMA838R
Model of vehicle: Lamborghini Huracan LP580-2
Policy number: AXA VPX/P2115122
Date of accident: 04/05/2019
Date of collection: 18/09/2019


SIGNATURE OF INSURED

Tay Hin Ngan
NAME

57238383D
NRIC NO.