

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: M90368995L



TAX INVOICE

GST Reg No.: M90368995L

Deliver To: Dr.
Tay Hin Ngan
23 Marigold Drive
Singapore 576425

AXA Insurance (S) Pte Ltd
8 Shenton way #27-01 AXA Tower
Singapore 068811
Invoice to: 3

Document No.:

Document Date: 01-Oct-19
REGN No.: SMA838R
Odometer:
Model: 2016 Huracan
Variant: LP580-2
Vehicle ID No.: ZHWEC2ZF1GLA04755
Repair Order No.: 17236
Delivery Date: 27/04/2018
Page: 1 of 5
Advisor: Richard Harjanto

Accident Reporting DOA 04/05/2019

Accident Reporting DOA 04/05/2019

OD Claim

AXA Insurance (Surveyor LKK Auto)

VPX/P2115122

Part Number	Part Description	List Price	Nett Price	Quantity	Total Cost
4S0121254B	RADIATOR CENTER LP610	716.00	644.40	1.00	644.40
4T0823301B	LEFT FRONT HOOD HINGE	335.80	302.22	1.00	302.22
G013A8JM1	COOLANT 1.5L (AUDI)	38.00	38.00	4.00	152.00
4T0805028K	FRONT FRAME ASSEMBLY LP610	12,246.00	11,021.40	1.00	11021.40
4T0823302B	RIGHT FRONT HOOD HINGE	335.80	302.22	1.00	302.22
4T0807158C	AIR DUCT ELEMENT	118.55	106.70	1.00	106.70
4T0821171C	WHEEL HOUSING LP610	392.00	352.80	1.00	352.80
4T0821170D	COVER	502.23	452.00	1.00	452.00
4S0805137D	BRACKET BATTERIE	70.60	63.54	1.00	63.54
4T0121334C	AIR DUCT ELEMENT	186.20	167.58	1.00	167.58
4T0853745	FRT LOGO LP700/LP750	728.00	655.20	1.00	655.20
4T0807109C	BUMPER BAR,FRONT PARAURT.OSSAT.ANT	1,600.15	1,440.14	1.00	1440.14
4T0807157C	AIR DUCT ELEMENT LH	129.75	116.78	1.00	116.78
1Q0823480	BONNET HOOK	51.35	46.22	1.00	46.22
4T0805669C	ATTACHMENT BARS	96.35	86.72	1.00	86.72
4T0941003G	FRT HEADLAMP LH LP580/LP610	9,970.93	9,970.93	1.00	9970.93
4T0807253	FRONT BUMBER FIN, LH STD	591.28	532.15	1.00	532.15
4T0823727B	SEAL,ENGINE	206.70	186.03	1.00	186.03
4T0821169D	COVER	502.23	452.00	1.00	452.00
4T0821172A	WHEEL HOUSING LP610	392.15	352.94	1.00	352.94
4S0121252B	RADIATOR LINKS/RECHTS	648.70	583.83	2.00	1167.66
4T0807254	FRONT BUMBER FIN, RH STD	591.28	532.15	1.00	532.15
4T0823359	FRT BONNET DAMPER LP610	112.18	100.96	1.00	100.96
4T0823021C	HOOD PERFORMANTE	10,296.00	9,266.40	1.00	9266.40
4G8880204D	AIRBAG PASSENGER SIDE	2,565.00	2,308.50	1.00	2308.50

Continued Next Page ...

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: M90368995L



TAX INVOICE

GST Reg No.: M90368995L

Deliver To: Dr.
Tay Hin Ngan
23 Marigold Drive
Singapore 576425

AXA Insurance (S) Pte Ltd
8 Shenton way #27-01 AXA Tower
Singapore 068811
Invoice to: 3

Document No.:

Document Date: 01-Oct-19
REGN No.: SMA838R
Odometer:
Model: 2016 Huracan
Variant: LP580-2
Vehicle ID No.: ZHWEC2ZF1GLA04755
Repair Order No.: 17236
Delivery Date: 27/04/2018
Page: 2 of 5
Advisor: Richard Harjanto

Accident Reporting DOA 04/05/2019

4T0805670C	BRACKET SCHEINWERFER OBEN	94.75	85.28	1.00	85.28
4T0121334B	AIR DUCT ELEMENT	124.88	112.39	1.00	112.39
4T0821021D	FRT FENDER LH LP580/LP610	6,552.00	5,896.80	1.00	5896.80
4T0807997A	LICENCE PLATE BRACKET LP580	75.10	67.59	1.00	67.59
4T0821022D	FRT FENDER RH LP580/LP610	6,643.00	5,978.70	1.00	5978.70
4T0823351B	BEARING	74.43	66.98	1.00	66.98
1K1823509E	HOOD LATCH LP610	146.10	131.49	1.00	131.49
4T0863405D	LINING KOFFERRAUM OBEN	4,058.80	3,652.92	1.00	3652.92
4T0807103G	FRT BUMPER W/SENSOR LP580	10,626.00	9,374.40	1.00	9374.40
8E0806193	CLIP	21.00	18.90	2.00	37.80
4T0880201C6PS	AIRBAG STEERING WHEEL	900.00	810.00	1.00	810.00
4T0941004G	FRT HEADLAMP RH LP580/LP610	9,970.93	9,970.93	1.00	9970.93
					\$76,964.92

Supplementary parts

Part Number	Part Description	List Price	Nett Price	Quantity	Total Cost
G013A8JM1	COOLANT 1.5L (AUDI)	38.00	38.00	1.00	38.00
8E0806193	CLIP	21.00	18.90	2.00	37.80
4T0819968	BRACKET	84.40	75.96	1.00	75.96
4T0809964	AIR DUCT ELEMENT	78.80	70.92	1.00	70.92
4T2857706DV04	SEAT BELT	2,655.00	2,655.00	1.00	2655.00
4T2857705CV04	SEAT BELT	2,655.00	2,389.50	1.00	2389.50
4T0807946	AIR DUCT PART	47.73	42.95	1.00	42.95
4T2858451D	DASHBOARD UPPER LP610	11,008.40	11,008.40	1.00	11008.40
4T0807168	PROTECTIVE CAP SPORTEL RADIAT ANT	64.00	57.60	1.00	57.60
4T0807167	PROTECTIVE CAP SPORTEL RADIAT ANT	64.00	57.60	1.00	57.60
4T0951206A	HORN WITH BRACKET	175.20	157.68	1.00	157.68
4T0807945	AIR DUCT PART	47.73	42.95	1.00	42.95
4T0867393C	COVER	213.43	192.08	2.00	384.16
5Q0919275CGRU	FRT PARKING SENSOR LP580	217.88	217.88	4.00	871.52

Continued Next Page ...

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: M90368995L



TAX INVOICE

GST Reg No.: M90368995L

Deliver To: Dr.
Tay Hin Ngan
23 Marigold Drive
Singapore 576425

AXA Insurance (S) Pte Ltd
8 Shenton way #27-01 AXA Tower
Singapore 068811
Invoice to: 3

Document No.:

Document Date: 01-Oct-19
REGN No.: SMA838R
Odometer:
Model: 2016 Huracan
Variant: LP580-2
Vehicle ID No.: ZHWEC2ZF1GLA04755
Repair Order No.: 17236
Delivery Date: 27/04/2018
Page: 3 of 5
Advisor: Richard Harjanto

Supplementary parts

4S0915181	BATTERY MANAGEMENTDIAG	390.00	351.00	1.00	351.00
4T0819967	BRACKET	84.40	75.96	1.00	75.96
053912032	HOSE CLAMP 20-32	3.00	3.00	1.00	3.00
4T0825101D	CD ENHANCING	1,051.20	1,051.20	1.00	1051.20
4T0807552E	DEFORMATION	310.25	279.23	1.00	279.23
N10173402	NUT	0.58	0.52	20.00	10.40
4T0807551E	ARM LP610	363.53	327.17	1.00	327.17
4T0807130A	BRACKET (CENTER RIGHT)	70.00	63.00	1.00	63.00
4T0807129A	BRACKET SUPPORT FIX BUMPER	70.00	63.00	1.00	63.00
4T0805845B	STOP BAR (LEFT)	45.00	40.50	1.00	40.50
4T0809963	AIR DUCT ELEMENT	78.80	70.92	1.00	70.92
4T0805669C	ATTACHMENT BARS	96.35	86.72	1.00	86.72
4T0805668C	BRACKET RIGHT	170.53	153.47	1.00	153.47
4T0805667C	BRACKET LEFT	132.00	118.80	1.00	118.80
4T0805303C	CONNECTING PART BODEN KOFFERRAUM	208.53	187.67	1.00	187.67
4T0805256D	REINF.PART	72.28	65.05	1.00	65.05
4T0805255D	REINF.PART	132.00	118.80	1.00	118.80
4T0805177A	CLIP ANGLE TELAIO ANTERIORE	123.08	110.77	1.00	110.77
4T0805157C	UPPER SIDE MEMBER	173.68	156.31	1.00	156.31
4T0803593Y9B	TOWING HOOK COVER	208.48	187.63	1.00	187.63
4T0805063C	SIDE PANEL	172.88	155.59	1.00	155.59
4S0816750D	REFRIGERANT LINE HEISSGAS KOND-KOND	320.00	288.00	1.00	288.00
4S0816726G	REFRIGERANT LINE, HEISSGASLTG.KOND.	320.00	288.00	2.00	576.00
4S0937548BA	MAIN FUSE BOX LP610	319.80	287.82	1.00	287.82
7P0915105C	BATTERY 95AH LP580/LP610 & PERFORMANTE	651.45	651.45	1.00	651.45
4T0805064C	SIDE PANEL	172.88	155.59	1.00	155.59
4S0816411A	CONDENSER	829.40	746.46	2.00	1492.92
4T0805158B	UPPER SIDE MEMBER	188.75	169.88	1.00	169.88
4S0805137D	BRACKET BATTERIE	70.60	63.54	1.00	63.54
4T0805178A	CLIP ANGLE TELAIO ANTERIORE	123.08	110.77	1.00	110.77
4S0121059D	COOLANT HOSE	34.00	30.60	1.00	30.60

Continued Next Page ...

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: M90368995L



TAX INVOICE

GST Reg No.: M90368995L

Deliver To: Dr.
Tay Hin Ngan
23 Marigold Drive
Singapore 576425

AXA Insurance (S) Pte Ltd
8 Shenton way #27-01 AXA Tower
Singapore 068811
Invoice to: 3

Document No.:

Document Date: 01-Oct-19
REGN No.: SMA838R
Odometer:
Model: 2016 Huracan
Variant: LP580-2
Vehicle ID No.: ZHWEC2ZF1GLA04755
Repair Order No.: 17236
Delivery Date: 27/04/2018
Page: 4 of 5
Advisor: Richard Harjanto

Supplementary parts

4H0959651A	FRONT AIRBAG SENSOR LP610	203.98	183.58	2.00	367.16
470845099A	FRT WINDSCREEN LP580/LP610	8,900.00	8,900.00	1.00	8900.00
4T0805532B	MOUNTING SCHLOSS	99.55	89.60	1.00	89.60
WHT007052	BOLT	0.85	0.77	20.00	15.40
WHT004750	EXPANSION RIVET 8.1X13.0	2.50	2.25	10.00	22.50
WHT001308	CLAMPING CAP NUT M6	1.10	0.99	20.00	19.80
4T0805670C	BRACKET SCHEINWERFER OBEN	94.75	85.28	1.00	85.28
N91042302	BOLT	2.50	2.25	20.00	45.00
N90926601	CLAMP	2.03	1.82	10.00	18.20
N10738101	SCREW	1.25	1.13	20.00	22.60
N10680601	HEX SOCKET	0.88	0.79	20.00	15.80
N10442204	BOLT	2.50	2.25	10.00	22.50
N10424102	SCREW	12.35	11.12	4.00	44.48
4T0825208A	CD ENHANCING VORNE HINTEN	884.75	796.28	1.00	796.28
4T0863635E	PARTITION TRIM	378.13	340.31	1.00	340.31
N10415903	SCREW	0.40	0.36	20.00	7.20
N10405702	SCREW	1.68	1.51	10.00	15.10
4T0971095F	HARNESS, BUMPER FRONT	256.35	230.72	1.00	230.72
4T2819426E	PLENUM PANEL COVER	398.55	358.70	1.00	358.70
					\$36,809.43

TO supply new number plate

new plate SMA838R

\$40.00

To Repair, knocking, and respray body panels

To Repair, knocking, and respray body panels

\$4,800.00

Continued Next Page ...

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: M90368995L



TAX INVOICE

GST Reg No.: M90368995L

Deliver To: Dr.
Tay Hin Ngan
23 Marigold Drive
Singapore 576425

AXA Insurance (S) Pte Ltd
8 Shenton way #27-01 AXA Tower
Singapore 068811
Invoice to: 3

Document No.:

Document Date: 01-Oct-19
REGN No.: SMA838R
Odometer:
Model: 2016 Huracan
Variant: LP580-2
Vehicle ID No.: ZHWEC2ZF1GLA04755
Repair Order No.: 17236
Delivery Date: 27/04/2018
Page: 5 of 5
Advisor: Richard Harjanto

To remove and reinstall front windscreen to facilitate chassis welding

\$600.00

Remove and reinstall front glass

To perform repair, knocking and welding on car front chassis and frame

Repair, knocking and welding on car front chassis

\$9,600.00

Labor to dismantle and re fitting parts and panels, do adjustment on panels

Customer paid Excess

(\$18,000.00)

Labor to replace new windscreen

\$500.00

EuroSports Auto Pte Ltd

Sub Total for All: \$111,314.35

Rounding: \$0.00

GST: \$7,792.00

Total: \$119,106.35

Signature

Date

Terms:

Any objections to the validity of the charges must be made within seven (7) days from the date of this Invoice otherwise it is assumed this Bill is accepted as correct.

GOODS SOLD ARE NOT RETURNABLE OR REFUNDABLE