

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, SINGAPORE 159096

TEL : (65) 6565 5995 FAX : (65) 6567 5515



Vehicle / Model : **SMA838R**
 Lamborghini Huracan

12-Sep-19

CI: AXA Insurance

Policy: VPX/P2115122


Accident Date: May 4th.-2019

Steve (LKK) 13/9/19, 11.30 am

Supplementary Parts

No	Parts	Description	Qty	Unit Price	Amount
1	4T0805178A	Mounting Bar (Right) for bumper protection / <i>DD</i>	1	\$ 123.08	\$ 123.08
2	4T0807130A	Front bumper bracket (CENTER RIGHT) / <i>BR</i>	1	\$ 70.00	\$ 70.00
3	4T0807167	Air Guide (Left) for Radiator / <i>CT</i>	1	\$ 64.00	\$ 64.00
4	* 4T0805255D	Reinforcement - Bracket (LEFT) / <i>MIS</i>	1	\$ 132.00	\$ 132.00
5	4T0807945	Air Guide for radiator (Left) / <i>BR</i>	1	\$ 47.73	\$ 47.73
6	4T0807946	Air Guide for radiator (Right) / <i>BR</i>	1	\$ 47.73	\$ 47.73
7	4T0809963	Air Guide for radiator (Left) / <i>BR</i>	1	\$ 78.80	\$ 78.80
8	N10738101	SCREW / <i>NR</i>	20	\$ 1.25	\$ 25.00
9	N90926601	CLAMP / <i>NR</i>	10	\$ 2.03	\$ 20.30
10	4T0819968	BRACKET Arm for front Bonnet (Right) / <i>BT</i>	1	\$ 84.40	\$ 84.40
11	8E0806193	CLIP / <i>NR</i>	1	\$ 21.00	\$ 21.00
12	G013A8JM1	COOLANT Liquid for Radiator 1.5L (AUDI) / <i>NR ALL 1 AS MIS</i>	1	\$ 38.00	\$ 38.00
13	N10173402	NUT / <i>NR</i>	20	\$ 0.58	\$ 11.60
14	N10405702	SCREW / <i>NR</i>	10	\$ 1.68	\$ 16.80
15	N10415903	SCREW / <i>NR</i>	20	\$ 0.40	\$ 8.00
16	N10424102	SCREW / <i>NR</i>	4	\$ 12.35	\$ 49.40
17	N10442204	BOLT / <i>NR</i>	10	\$ 2.50	\$ 25.00
18	4T0805177A	Mounting Bar (LEFT) for bumper protection / <i>DD</i>	1	\$ 123.08	\$ 123.08
19	* 4T0805256D	Reinforcement - Bracket (RIGHT) / <i>MIS</i>	1	\$ 72.28	\$ 72.28
20	4T0805532B	Centre Mounting Bracket / <i>BT</i>	1	\$ 99.55	\$ 99.55
21	WHT001308	CLAMPING CAP NUT M6 / <i>NR</i>	20	\$ 1.10	\$ 22.00
22	WHT004750	EXPANSION RIVET 8.1X13.0 / <i>NR</i>	10	\$ 2.50	\$ 25.00
23	WHT007052	BOLT / <i>NR</i>	20	\$ 0.85	\$ 17.00
24	4H0959651A	FRONT AIRBAG SENSOR LP610 / <i>Shd / MIS</i>	2	\$ 203.98	\$ 407.96
25	4S0121059D	COOLANT HOSE for radiator (LEFT) / <i>MIS</i>	1	\$ 34.00	\$ 34.00
26	4S0805137D	Car Battery Bracket / <i>BT</i>	1	\$ 70.60	\$ 70.60
27	4S0816411A	Aircon CONDENSER / <i>DD</i>	2	\$ 829.40	\$ 1,658.80
28	* 4S0816726G	REFRIGERANT LINE, Aircon piping / <i>BT</i>	2	\$ 320.00	\$ 640.00
29	4S0816750D	REFRIGERANT LINE, Aircon piping / <i>BT</i>	1	\$ 320.00	\$ 320.00
30	4T0805063C	Cover Plate SIDE PANEL (RIGHT) / <i>NR</i>	1	\$ 172.88	\$ 172.88
31	4T0805064C	Cover Plate SIDE PANEL (LEFT) / <i>NR</i>	1	\$ 172.88	\$ 172.88
32	4T0805157C	UPPER SIDE MEMBER (Left Bar) / <i>NR</i>	1	\$ 173.68	\$ 173.68
33	4T0805158B	UPPER SIDE MEMBER (Right Bar) / <i>NR</i>	1	\$ 188.75	\$ 188.75
34	4T2857706DV04	SEAT BELT (Driver) / <i>Shd</i>	1	\$ 2,655.00	\$ 2,655.00

35	4T0805303C	Connecting Part (Lower member plate Panel) / <i>AK</i>	1	\$	208.53	\$	208.53
36	4T0819967	BRACKET Arm for front Bonnet (Left) / <i>MIS</i>	1	\$	84.40	\$	84.40
37	4T0809964	Air Guide (Right) / <i>BR</i>	1	\$	78.80	\$	78.80
38	4T0805585E	COVER PLATE Front (for front chassis) X	1	\$	69.95	\$	69.95
39	4T0805667C	Reinforcement bar LEFT / <i>MIS</i>	1	\$	132.00	\$	132.00
40	4T0807168	Air Guide (RIGHT) for Radiator / <i>CUT</i>	1	\$	64.00	\$	64.00
41	N91042302	BOLT / <i>AK</i>	20	\$	2.50	\$	50.00
42	4T0805668C	BRACKET RIGHT / <i>MIS</i>	1	\$	170.53	\$	170.53
43	4T0805669C	Attachement Bar for bonnet damper / <i>jeanne</i>	2	\$	96.35	\$	192.70
44	T0805670C	Head Lamp Brackets / <i>MIS</i>	2	\$	94.75	\$	189.50
45	T0805845B	STOP BAR for head lamp mount (LEFT) / <i>BT</i>	1	\$	45.00	\$	45.00
46	4T0805846B	STOP BAR for head lamp mount (RIGHT) X	1	\$	45.55	\$	45.55
47	4T0807129A	Front bumper bracket (CENTER LEFT) / <i>BR</i>	1	\$	70.00	\$	70.00
48	4S0915181	Control Unit for Battery Cut Off sensor / <i>SMI</i>	1	\$	390.00	\$	390.00
49	4T0807551E	ARM / Bracket for Bumper Protection LEFT / <i>BR</i>	1	\$	363.53	\$	363.53
50	4T0807552E	ARM / Bracket for Bumper Protection RIGHT / <i>BR</i>	1	\$	310.25	\$	310.25
51	4T0825101D	Under Body trim panel (FRONT) / <i>BR</i>	1	\$	1,051.20	\$	1,051.20
52	4T0825208A	Under Body trim panel (Center) / <i>BR</i>	1	\$	884.75	\$	884.75
53	4T0863635E	PARTITION TRIM for bonnet compartment / <i>BR</i>	1	\$	378.13	\$	378.13
54	4T0867393C	COVER (center console) / <i>BR</i>	1	\$	213.43	\$	213.43
55	4T0951206A	HORN WITH BRACKET / <i>BT</i>	1	\$	175.20	\$	175.20
56	4T0971095F	Wire set Harness for front sensors / <i>CRU</i>	1	\$	256.35	\$	256.35
57	4T2819426E	Front under bonnet Trim / <i>BR</i>	1	\$	398.55	\$	398.55
58	4T2858451D	DASHBOARD UPPER LP610 / <i>BR</i>	1	\$	11,008.40	\$	11,008.40
59	7P0915105C	Car BATTERY 95AH LP580/LP610 / <i>BR</i>	1	\$	651.45	\$	651.45
60	4S0937548BA	MAIN FUSE BOX LP610 / <i>SMI</i>	1	\$	319.80	\$	319.80
61	4T0803593Y9B	TOWING HOOK COVER (LEFT) / <i>MIS</i>	1	\$	208.48	\$	208.48
62	4T2857705CV04	SEAT BELT (Passenger) / <i>SMI</i>	1	\$	2,655.00	\$	2,655.00
63	53912032	HOSE CLAMP / <i>AK</i>	1	\$	3.00	\$	3.00
64	5Q0919275CGRU	FRT PARKING SENSOR LP580 / <i>SMI</i>	4	\$	217.88	\$	871.52
65	N10680601	HEX SOCKET / <i>AK</i>	20	\$	0.88	\$	17.60
66	4T0803594Y9B	TOWING HOOK COVER (RIGHT) / <i>MIS</i>	1	\$	208.48	\$	208.48
67	4T0845099G	Front Windscreen Glass / <i>Wine form</i>	1	\$	8,900.00	\$	8,900.00
68		Winscreen Glass Sealant and gasket / <i>AK</i>	1	\$	200.00	\$	200.00
					Sub-Total	\$	38,582.38
Supplementary Labour for Windscreen / <i>AK</i>						\$	1,000.00 <i>500</i>
Sub Total					\$	39,582.38	
gst					\$	2,770.77	
TOTAL					\$	42,353.15	



12/09/2019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____