


MSG18012604/GSD3-1
ASSIGNMENT (Office)
Guo Dong
Monica Chung
MSIG
Date/Time: 14/05/2019

Estimated Cost: Bill to:
OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS
To Inspect Vehicle No: SLM 3405K Insured: FBB 6288M
at Workshop in: Global Auto Specialist Tel: 9639 1629
of: 176 Sin Ming Drive # 05-14
Policy No: MSD/VMT/17-985915-WTT Claim No: MSC/V/18-000925
Sum Insured: Excess:
Make of Veh: D.O.A. 01/07/2018
(C Bent's Record)

CA / REV / REP. / REV 24 HRS / up
Date/Time: 9.41am 01/7/18 Person Contacted: Jenny Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLM 3405K - X
	FBB 6288M - CS/FCI/16008825/Kvh3c2 D.O.A: 11/5/2016
28/05/19	Confirmed L/S \$650/- @ 2days with XHQ (\$1,706.72 Red - 72%)


28/5/19

Shirley Hiew (LKK Auto)

From: Global Auto Specialist - Sin Ming <sm@globalautospecialist.com>
Sent: Friday, 31 May 2019 9:54 AM
To: 'Shirley Hiew (LKK Auto)'
Subject: RE: SLM3405K - After repair photos

Dear Shirley,

We confirm LS \$650 @ 2 days of repairs before GST.

Warmest Regards,
Jenny Png
Global Auto Specialist Pte Ltd
HP: 9639 1626
Sin Ming Branch: 6481 7675
Toh Guan Branch: 6464 9291

New Toh Guan address(from 1 Oct 2018):

48 Toh Guan Road East
#06-99 Enterprise Hub
Singapore 608586

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 29 May, 2019 8:52 AM
To: 'Global Auto Specialist - Sin Ming' <sm@globalautospecialist.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SLM3405K - After repair photos

Dear Jenny,

Please Confirm final fig \$ 650.00 (lump sum) @ 2 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Global Auto Specialist - Sin Ming [<mailto:sm@globalautospecialist.com>]
Sent: Tuesday, 28 May 2019 3:43 PM
To: sur@lkkauto.com
Subject: SLM3405K - After repair photos

Hi,

As requested. Kindly let us know the COR & DOR soon.

Warmest Regards,
Jenny Png

Global Auto Specialist Pte Ltd
HP: 9639 1626
Sin Ming Branch: 6481 7675
Toh Guan Branch: 6464 9291

New Toh Guan address(from 1 Oct 2018):

48 Toh Guan Road East
#06-99 Enterprise Hub
Singapore 608586

GLOBAL AUTO SPECIALIST PTE LTD

19/7/18

48 TOH GUAN ROAD EAST #06-142 ENTERPRISE HUB SINGAPORE 608586 TEL/FAX: 6464 9291 H/P: 9147 7675
BRANCH: 176 SIN MING DRIVE #05-14 SIN MING AUTOCARE SINGAPORE 575721 TEL/FAX: 6481 7675 H/P: 9639 1626
MAILING ADDRESS: 177 ANG MO KIO AVE 4 #04-911 SINGAPORE 560177
CO / GST REG NO.: 201018026D

LKK Auto Consultants hence notify the Repairs of the following:

- To resurvey before/after spray
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ESTIMATE

Mr. Ang Thian Siong

Blk 653 Senja Link

#17-26

Singapore 670653

TEL : 96231197

c/o 176 Sin Ming Dr #05-14 Sin Ming Autocare Singapore 575721

Acknowledged by Repairer

Signature FAX :

Date:

No. : GSQ-SM-1808001

Date : 01/08/2018

Vehicle No. : SLM3405K

Make : HONDA

Model : MOBILIO SV

Accident Date : 01/07/2018

Page : 1 of 1

Item	Description	Qty	U/ Price S\$	Total S\$
1.	Front bumper / 22	1.0	879.90	879.90
2.	RH Front bumper side retainer X	1.0	50.50	50.50
3.	RH Front bumper side moulding X	1.0	98.00	98.00
4.	RH Fog lamp X	1.0	318.90	318.90
5.	RH Fog lamp garnish X	1.0	163.30	163.30
6.	Front lower dust cover X	1.0	59.50	59.50
7.	RH Front fender inner shield (front) X	1.0	150.40	150.40
8.	RH Front fender inner shield (rear) X	1.0	150.40	150.40
	Discount 20 %			-374.18
9.	Front number plate w/frame X NN	1.0	60.00	60.00
10.	Labour charge for panel beating & replacement of parts	1.0	400.00	400.00
11.	Spray painting on affected areas	1.0	350.00	350.00
12.	Labour charge to check wiring and lightings	1.0	50.00	50.00

SINGAPORE DOLLAR TWO THOUSAND FIVE HUNDRED TWENTY ONE AND CENTS
SIXTY NINE ONLY

Sub Total 2,356.72

Add GST 7% 164.97

Net Total 2,521.69

Validity :

Delivery Term :

For and on behalf of
GLOBAL AUTO SPECIALIST PTE LTD



Authorised Signature & Company Stamp

809.84
20%: 650
2 Days.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jul 2018		10 Jul 2018 16:01 Edit Adj Rpt	\$650.00 Edit Estimates	\$650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LIM SHAN XIANG RUSSELL, ID: S9347929G		
Main Claimant:	ANG THIAN SIONG, ID: S1485090B		
Vehicle Reg. No.:	SLM3405K	Date of Loss:	01/07/2018 13:00 - :59 [15 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-000925	Policy/Cover Note No.:	MSD/VMT/17-985915-WTT (Third Party Only) Coverage: 13/09/2017 - 12/09/2018
Vehicle Reg. No. (Insured):	FBB6288M	Policy No. (Claimant):	
		Excess:	
Repairer:	Global Auto Specialist Pte Ltd(sing Ming) (HQ) 176 Sin Ming Drive #05-14, 575721 Sin Ming - Tel: 96391626		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 04/06/2019]		
Driver/Custodian (Insured):	LIM SHAN XIANG RUSSELL (24 / Male) , NRIC: S9347929G Email:		
Adj Asg. Remarks:	SJE Agree Please appoint kenneth Kong from LKK and contact Jenny @ 9639 1626 to conduct the survey. Liability (100%)		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- MSIG_SG (31/05/2019): Report Send Back Alerts - SLM3405K (TP)

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLM3405K (MSC/V/18-000925)**
[FBB6288M]
TP
ANG THIAN SIONG
Jul 1 2018 1:00PM
[LIM SHAN XIANG RUSSELL]
Global Auto Specialist Pte Ltd(sing Ming)

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	09/07/18 10:12	Accident Statement From:SC - Reg. No: FBB6288M, Claimant: LIM SHAN XIANG RUSSELL	 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/07/18 11:42	General View	 Load JPG	☒
2	23/07/18 11:42	General View	 Load JPG	☒
3	23/07/18 11:42	General View	 Load JPG	☒
4	23/07/18 11:42	General View	 Load JPG	☒
5	23/07/18 11:42	General View	 Load JPG	☒
6	23/07/18 11:42	General View	 Load JPG	☒
7	23/07/18 11:42	General View	 Load JPG	☒
8	23/07/18 11:42	General View	 Load JPG	☒
9	23/07/18 11:42	General View	 Load JPG	☒
10	23/07/18 11:42	General View	 Load JPG	☒
11	23/07/18 11:42	General View	 Load JPG	☒
12	23/07/18 11:42	General View	 Load JPG	☒
13	31/05/19 10:18	Reinspection Photo	 Load JPG	☒
14	31/05/19 10:18	Reinspection Photo	 Load JPG	☒
15	31/05/19 10:18	Reinspection Photo	 Load JPG	☒
16	31/05/19 10:18	Reinspection Photo	 Load JPG	☒
17	31/05/19 10:18	Reinspection Photo	 Load JPG	☒
18	31/05/19 10:18	Reinspection Photo	 Load JPG	☒
19	31/05/19 10:18	Reinspection Photo	 Load JPG	☒
20	31/05/19 10:18	Reinspection Photo	 Load JPG	☒
21	31/05/19 10:18	Reinspection Photo	 Load JPG	☒
22	31/05/19 10:18	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	09/07/18 10:12	Third Party Accident Report From:SC - Reg. No: FBB6288M, Claimant: LIM SHAN XIANG RUSSELL	 Load PDF	
2	09/07/18 10:38	Email to Workshop	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/05/19 15:14	PRS INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18012604/GSD3S2-1

Date: 31/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMT/17-985915-WTT
 Claimant Vehicle No: SLM3405K Insured Vehicle No: FBB6288M
 Date of Loss: 01/07/2018 Nature of Claim: TP Claim No: MSC/V/18-000925

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM3405K
 Make & Model: HONDA MOBILIO, 1.5 V CVT (A) Engine No: L15Z12874864
 Reg. Date: 28/03/2017 (Man. Year: 2016) Chassis No: MRHDD4870GP000472
 Colour: Black Odometer: 21866 km
 Engine Capacity: 1497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15 Rear Tyre Size: 185/65R15
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,556.72	409.84	1,146.88	73.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	400.00	400.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,356.72	809.84	1,546.88	65.64
Approved Total (Overridden) (S\$)		650.00		
(S\$)	2,356.72	650.00	1,706.72	72.42
+ GST 7.00/7.00% (S\$)	164.97	45.50	119.47	72.42
Nett Amount (S\$)	2,521.69	695.50	1,826.19	72.42

INSPECTION

Date of Assignment: 10/07/2018
 Date Inspected: 19/07/2018 Inspected At: Global Auto Specialist Pte Ltd(sing Ming) (HQ)
 176 Sin Ming Drive #05-14
 Singapore 575721
 Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=723255&extid=277136&CFID=53683112&C... 1/4

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 May 2019)
Parts:	M1-MPV	HONDA MOBILIO 1.5 V CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM3405K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	879.90 FL	*512.30 FL
2	1		*RH FRONT BUMPER SIDE RETAINER	Not Necessary	50.50 FL	*- FL
3	1		*RH FRONT BUMPER SIDE MOULDING	Not Necessary	98.00 FL	*- FL
4	1		*RH FOG LAMP	Not Necessary	318.90 FL	*- FL
5	1		*RH FOG LAMP GARNISH	Not Necessary	163.30 FL	*- FL
6	1		*FRONT LOWER DUST COVER	Not Necessary	59.50 FL	*- FL
7	1		*RH FRONT FENDER INNER SHIELD (FRONT)	Not Necessary	150.40 FL	*- FL
8	1		*RH FRONT FENDER INNER SHIELD (REAR)	Not Necessary	150.40 FL	*- FL
9	1		*FRONT NUMBER PLATE W/FRAME	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,930.90	512.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	374.18	102.46
Total Parts (\$\$)	1,556.72	409.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE FOR PANEL BEATING & REPLACING OF PARTS.	New	400.00	200.00
2	SPRAY PAINTING ON AFFECTED AREAS.	New	350.00	200.00
3	LABOUR CHARGE TO CHECK WIRING AND LIGHTINGS.	New	50.00	0.00
Gross Labour Cost (S\$)			800.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >