

REF: NTUC NS/INC19008479/Jtd1302

REF: NTUC NS/INC19008479/Jtd1302

REF: NTUC NS/INC19008479/Jtd1302

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: SJX5579U

Policy No. 500561928-01 (10/07/2013-)

Claims No. MT/1043950-002


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No. SHL4401P Yr Regn: 6 Jan 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798

Colour: maroon A/C: Insured / Std / NI / NA

Sp. Reading: 533376 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKN36U60S720864

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SR / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or chilles

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 10/5/19 D.O.I. 13/5/19

Survey held at Sumit

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|--|
| | SHL 440.1 P - C03/ AICU015115 / ZH D.O.A - 13/07/2009 05/19/2046 |
| | SJX 5579U - X SJX5579U |
| | lump sum \$4900, 9 days (Red: 25009.10: 83%) |
| | RECEIVED 14 JUN 2019 |

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 9

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: 1

2)

Add Fee: ☐ : Site Insp (\$

Survey Fee: 160

Transportation: _____

) \$ + PS. \$ SI

) Photos

) Others

Report Format :

Lump Sum / L.B.E: \$ 4900/-

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

TOTAL

160

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No.(For Motor) Certificate Number

| Select | Policy No. | Certificate Number | Policyholder Name | Policyholder NRIC | Product | Cover Type | Vehicle No. | Insured Object | Commence Date | Expiry Date |
|-----------------------|---------------|--------------------|-------------------------|-------------------|---------|---------------|-------------|----------------|---------------|-------------|
| <input type="radio"/> | 5092561928-01 | | A. C. LEASING PTE. LTD. | 201717305Z | GFT | drivo CLASSIC | SJX5579U | SJX5579U | 10/07/2018 | |

TP Claims against NTUC Income: Follow-Through Survey

Date 13/6/2019

| S/No | Income Reference | Claimant (Owner / Taxi Company) | Claimant Vehicle No. | Income Vehicle No. |
|------|------------------|---------------------------------|----------------------|--------------------|
| 1 | MT/1048491-002 | COMFORT TRANSPORTATON PTE LTD | SHA 7031P | SGR 2886U |
| 2 | MT/1048204-002 | COMFORT TRANSPORTATON PTE LTD | SHB 3550D | SKM 3574S |
| 3 | MT/1043950-002 | SMRT TAXIS PTE LTD | SHC 4401P | SIX 5579U |

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|---|--------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Company |
| Owner ID: | 5369K |
| Vehicle Details | |
| Vehicle No.: | SHC4401P |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 14 May 2019 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | PRIUS TAXI (SMRT) |
| Primary Colour: | Maroon |
| Manufacturing Year: | 2013 |
| Engine No.: | 2ZR1325580 |
| Chassis No.: | JTDKN36U605720864 |
| Maximum Power Output: | 100.0 kW (134 bhp) |
| Open Market Value: | \$33,120.00 |
| Original Registration Date: | 06 Jan 2014 |
| First Registration Date: | 06 Jan 2014 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$8,368.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 05 Jan 2022 |
| PARF Rebate Amount: | \$5,857.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 05 Jan 2022 |
| COE Category: | A - Car (1600cc & below) |
| COE Period(Years): | 8 |
| PQP Paid: | \$60,888.00 |
| COE Rebate Amount: | \$20,111.00 |
| Total Rebate Amount: | \$25,968.00 |
| Message | |
| Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. | |

The information contained herein is correct as at 14 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|---|
| Date Of Report | 10/05/2019 12:28 |
| Date Of Accident | 10/05/2019 10:15 |
| Exact Location Of Accident | TAMPINES AVE 10 TOWARDS BARTLEY FLYOVER |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|--------------------|
| Vehicle Registration Number | SHC4401P |
| Insured/Policyholder | |
| Name Of Registered Owner | SMRT TAXIS PTE LTD |
| Co Reg No | 198905369K |
| Email Address | NOEMAIL |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-80000000 |

Vehicle Particulars

| | |
|--|--------------------|
| Manufacturer | TOYOTA |
| Model | PRIUS TAXI-1.8 (A) |
| Exact Purpose for which vehicle was being used at time of accident | HIRE AND REWARD |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | TAXI |

Insurance Company

| | |
|---------------------------|--------------------------------|
| Name of Insurance Company | MS FIRST CAPITAL INSURANCE LTD |
| Type Of Coverage | THIRD PARTY FIRE AND/OR THEFT |
| Fleet Policy | YES |
| Policy Number | D-19093197MFSH |
| Cover Note Number | |

Driver

| | |
|----------------------|----------------------|
| Name of Driver | YEO SOO THIAM |
| NRIC No | S1379766H |
| Date Of Birth | 01/11/1959 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 02/10/2009 |
| Driving Experience | 9 YEARS AND 7 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-80000000 |
| Fax Number | |
| Contact Number | |
| EEmail Address | NOEMAIL |

| | |
|---|---------------|
| Address | 11 |
| Postcode | |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OTHER - HIRER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

I WAS TRAVELLING ALONG TAMPINES AVE 10 TOWARDS BARTLEY FLYOVER. SUDDENLY A VEHICLE IN FRONT OF MY TAXI JAMMED BRAKE. I APPLIED MY BRAKE TO STOP AS WELL AFTER WHICH I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SJX5579U HAD COLLIDED ONTO THE REAR OF MY TAXI.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|-------------|
| Vehicle Registration Number | SJX5579U |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | LEE DE YUAN |
| NRIC/Passport Number | S9642032C |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

A- SHC4401P
B- SJX5579U

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Date & Time: 10/5/2019

Reporting Centre Personnel's Signature

Name _____

NRIC/FIN No. _____

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Denise

Section A - Accident Details

| | |
|------------------------------------|--------------------|
| Registration Number | SHC4401P |
| Case Reference Number | TAX/05/19/2046 |
| Registration Date | 6/1/2014 |
| Company Type | SMRT Taxis Pte Ltd |
| Make | TOYOTA |
| Model | PRIUS |
| Name of Driver | YEO SOO THIAM |
| Type of Accident | Head to Rear |
| Accident Date and Time | 10/5/2019 10:20 AM |
| Accident Reported Date and Time | 10/5/2019 12:13 PM |
| Is Surveyor Required? | Yes |
| Survey by | |
| Vehicle is Towed Back? | No |
| Towed Back Date and Time | |
| Replacement Vehicle issued? | No |
| Job Card Number | 24101451 |
| Special Instruction to ARC, if any | TOWED \$40/TP |
| Prepared Date and Time | 10/5/2019 2:17 PM |
| Chassis Number | |
| Mileage | |
| Work Shop | |
| Repair Completion Date and Time | |



Toyota Prius

L/S \$4900/ 9 days

Section B - Summary of Repair Estimates

| Summary of Repair Estimates | | |
|------------------------------|--------------------|-------------------------------------|
| | Quotation from ARC | Adjusted by Surveyor, if applicable |
| Total Labour Cost | \$2,366.00 | \$1,100.00 |
| Total Spray Cost | \$3,870.00 | \$800.00 |
| Total Spare Part Cost | \$17,101.79 | \$4,113.41 |
| Total Other Cost | \$2,406.00 | (\$1,113.41) |
| TOTAL COST | \$25,743.79 | \$4,900.00 (L/S) |
| Lump Sum Total | \$0.00 | \$0.00 |
| Number of Repair Days | 10.0 | 9.0 |
| Prepared / Adjusted By | Zhi Yang Phua | Hwee Jie (LKK) / NTUC |
| ARC / Surveyor Sign Off Date | | 13/05/2019 2:59 PM |
| Signature | | |
| Remarks | SUP = 4 DAYS | L/S REPAIR, PHOTO AFTER PAINT. |

Section C - Quotation and Accident Invoice Details

| | | | |
|------------------|--------------|----------------|--|
| Quotation Number | QN-1905-0583 | Invoice Number | |
| Quotation Date | 31.05.2019 | Invoice Date | |
| Invoice Amount | | Prepared Date | |

Section D - Details of Repair Estimates

Part 1 - Labour Works

| Job Scope | Quotation from AR | Adjusted by Surveyor, if applicable |
|------------------------|-------------------|-------------------------------------|
| TO REPAIR REAR PORTION | \$676.00 | \$500.00 |
| TO REPAIR REAR PORTION | \$1,690.00 | \$600.00 |
| Total Labour | \$2,366.00 | \$1,100.00 |

Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|--------------------------------------|--------------------|-------------------------------------|
| TO RESPRAY REAR BUMPER | \$378.00 | \$200.00 |
| TO RESPRAY REAR PANEL | \$180.00 | \$100.00 |
| TO RESPRAY REAR SPARE TYRE PANEL | \$180.00 | \$0.00 |
| TO RESPRAY TAIL GATE | \$378.00 | \$200.00 |
| TO RESPRAY TAILGATE OUTSIDE GARNISH | \$180.00 | \$0.00 |
| TO RESPRAY REAR FENDER RH | \$378.00 | \$0.00 |
| TO RESPRAY REAR FENDER LH | \$378.00 | \$0.00 |
| TO RESPRAY TROUGH BACK DOOR LH | \$180.00 | \$0.00 |
| TO RESPRAY TROUGH BACK DOOR RH | \$180.00 | \$0.00 |
| TO RESPRAY REAR MEMBER, LH | \$180.00 | \$0.00 |
| TO RESPRAY REAR MEMBER, RH | \$180.00 | \$0.00 |
| TO RESPRAY REAR FLOOR SIDE PANEL LH | \$180.00 | \$0.00 |
| TO RESPRAY REAR FLOOR SIDE PANEL RH | \$180.00 | \$0.00 |
| TO RESPRAY SPOILER | \$180.00 | \$0.00 |
| TO RESPRAY REAR FENDER RH | \$378.00 | \$200.00 |
| TO RESPRAY REAR SPARE TYRE PANEL | \$180.00 | \$100.00 |
| Total Spray Painting & Panel Beating | \$3,870.00 | \$800.00 |

Part 3 - Other Costs - Accident and Accident Repair Related Expense

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|--|--------------------|-------------------------------------|
| Lump Sum Adjustment by Surveyor | \$0.00 | (\$1,253.41) |
| TO CHECK & RESET SYSTEM FUNCTION | \$350.00 | \$0.00 |
| TOWING CHARGE | \$56.00 | \$0.00 |
| TO CHECK WIRING AND SYSTEM FUNCTION | \$80.00 | \$30.00 |
| TO APPLY RUST-PROOFING ON AFFECTED AREA | \$200.00 | \$0.00 |
| TO ALIGN CHASSIS | \$350.00 | \$0.00 |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM | \$120.00 | \$30.00 |
| TO TRANSFER REAR TAILGATE MECHANISM | \$120.00 | \$50.00 |
| TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR. | \$120.00 | \$30.00 |

| | | | | | | | | | |
|-------|-------------|-------------------------|------|-------------|------|------------|---------|-----------|---|
| | | STICKER SMRT LOGO | 0.00 | \$7.80 | 0.00 | \$0.00 | Replace | Not Given | X |
| | | STICKER DECAL 6555 8888 | 0.00 | \$21.60 | 0.00 | \$0.00 | Replace | Not Given | X |
| | 62710-47130 | QUARTER GLASS RR/RH | 0.00 | \$846.50 | 0.00 | \$0.00 | Replace | Not Given | X |
| | | SEALANT W/SCREEN | 0.00 | \$37.00 | 0.00 | \$0.00 | Replace | Not Given | X |
| | 65637-47021 | FENDER LINER RR/RH | 0.00 | \$141.30 | 0.00 | \$0.00 | Replace | Not Given | X |
| | 52591-47021 | BUMPER SEAL, RR RH | 0.00 | \$65.70 | 0.00 | \$0.00 | Replace | Check | X |
| | 65631-47041 | SILL MEMBER PLATE RR/RH | 0.00 | \$57.50 | 0.00 | \$0.00 | Replace | Check | X |
| | 61621-47030 | TROUGH, BACK DOOR | 0.00 | \$110.90 | 0.00 | \$0.00 | Replace | Not Given | X |
| | 52562-47010 | TAIL LAMP BRACKET, RH | 0.00 | \$30.70 | 0.00 | \$0.00 | Replace | Check | X |
| | 81551-47180 | TAIL LAMP RH | 0.00 | \$557.80 | 0.00 | \$0.00 | Replace | Check | X |
| Total | | | | \$19,100.50 | | \$2,154.38 | | | |

hu

1376.30

Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Stock Number | Part Name | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|-------------|---------|--------------|--------------------------------|----------|---------------|--------------|------------------|-----------|----------------|
| | | 69350-47030 | TAILGATE DOOR LOCK | 1.00 | \$444.10 | 25.00 | \$333.08 | Replace | Replace |
| | | 67881-47022 | TAILGATE DOOR WEATHER STRIP | 1.00 | \$353.40 | 25.00 | \$265.05 | Replace | Replace |
| | | 52563-47010 | TAIL LAMP BRACKET, LH | 1.00 | \$30.70 | 25.00 | \$23.03 | Replace | Replace |
| | | 52576-47020 | BUMPER SIDE RETAINER RR/LH | 1.00 | \$94.80 | 25.00 | \$71.10 | Replace | Replace |
| | | 52575-47020 | BUMPER SIDE RETAINER RR/RH | 1.00 | \$94.80 | 25.00 | \$71.10 | Replace | Replace |
| | | 58308-47011 | UNDER COVER SUB-ASSY, RR FLOOR | 1.00 | \$514.50 | 25.00 | \$385.88 | Replace | Replace |
| | | 58307-47060 | END PANEL | 1.00 | \$602.10 | 25.00 | \$451.58 | Replace | Replace |
| | | 52562-47010 | TAIL LAMP BRACKET, RH | 1.00 | \$30.70 | 25.00 | \$23.03 | Replace | Replace |
| | | | SEALANT SIKAFLEX | 3.00 | \$37.00 | 0.00 | \$111.00 | Replace | Replace |
| | | 51931-47020 | CARRIER, SPARE | 1.00 | \$19.70 | 25.00 | \$14.78 | Replace | Replace |
| | | 52016-47030 | ARM SUB-ASSY, RR BUMPER LH | 1.00 | \$139.60 | 25.00 | \$104.70 | Replace | Replace |
| | | 52015-47050 | ARM SUB-ASSY, RR BUMPER RH | 1.00 | \$139.60 | 25.00 | \$104.70 | Replace | Replace |
| Total | | | | | 2,501.00 | | 1,959.03 | | |

Jam
cut
cra
cra
cra
def
Buc
cra
neu
cra
BT
BT

$$\begin{array}{r}
 4113.41 \\
 + 1100.00 \\
 + 940.00 \\
 \hline
 6153.41 \\
 - 20\% \\
 \hline
 4922.72
 \end{array}$$

4/5 \$4900/-

30291.50

REQUEST FOR SUPPLYMENT PARTS

| | | | |
|----------------------|----------------|-----------------------------------|------------|
| Contractor: | | | |
| Accident Case Number | TAK/05/19/2046 | Date of Collection | 1 / 1 |
| Vehicle No | SHC 4401 P | Date of Request | 16/05/2019 |
| Vehicle Model | TOYOTA PRIUS | Number of Days to Extend (If any) | 6 4 |

| S/N | Part Number | Part Description | Quantity | Unit Price |
|-----|-------------|------------------------------|----------|------------|
| | | TAILGATE DOOR LOCK | 1 pc | / Jam |
| | | TAILGATE DOOR WEATHERSTRIP | 1 pc | / LUT |
| | | TAILLAMP BRACKET LH | 1 pc | / CRI |
| | | BUMPER SIDE RETAINER REAR LH | 1 pc | / CRA |
| | | BUMPER SIDE RETAINER REAR RH | 1 pc | / CRA |
| | | UNDER COVER SUB ASSY, REAR | 1 pc | / DEF |

<<<Please submit photographs for damaged parts>>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

| | | |
|-----------------|--|---|
| Acknowledge By | ARC Executive / Supervisor / SA | |
| Approval By | Surveyor / In-house Staff | |
| Parts Ordering | SMRT Store / Contractor Supply / Form 22 / WOC | Form 22 / PO / WOC / Reservation / Number |
| Photo Submitted | YES / NO | Date of submission |

REF 1/3

REQUEST FOR SUPPLYMENT PARTS

| | | | |
|----------------------|----------------|-----------------------------------|------------|
| Contractor: | | | |
| Accident Case Number | TAR/05/19/2046 | Date of Collection : | 1 1 |
| Vehicle No | SHC 4401 P | Date of Request | 16/05/2019 |
| Vehicle Model | TOYOTA PRIUS | Number of Days to Extend (If any) | 6 4 |

| S/N | Part Number | Part Description | Quantity | Unit Price |
|-----|-------------|---------------------------------|----------|------------------------|
| | | END PANEL | 1pc | ✓ BUC |
| | | TAIL LAMP BRACKET RH | 1pc | ✓ CRA |
| | Labour | to cut & replace REAR END PANEL | | \$350 \$200 |
| | Labour | to REPAIR SPARE TYRE PANEL | | \$300 \$200 |
| | Labour | to SPRAY SPARE TYRE PANEL | | \$200 \$100 |
| | | SPARE TYRE INSULATION COAT | 3pcs | ✓ nec |

<<<Please submit photographs for damaged parts>>>

I, (Name)

(Position)

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

| | | |
|-----------------|--|--|
| Acknowledge By | ARC Executive / Supervisor / SA | |
| Approval By | Surveyor / In-house Staff | |
| Parts Ordering | SMRT Store / Contractor Supply / Form 22 / WOC | Form22 / PO / WOC / Reservation / Number |
| Photo Submitted | YES / NO | Date of submission |

RF 2/3

REQUEST FOR SUPPLEMENT PARTS

| | | | |
|----------------------|----------------|-----------------------------------|------------|
| Contractor: | | | |
| Accident Case Number | TAX/05/19/2046 | Date of Collection | 1 / 1 |
| Vehicle No | SHC 4401 P | Date of Request | 16.10.2019 |
| Vehicle Model | TOYOTA PRIUS | Number of Days to Extend (If any) | 84 |

| S/N | Part Number | Part Description | Quantity | Unit Price |
|-----|-------------|-----------------------------------|----------|------------------------|
| | labour | to REPAIR REAR FENDER RH | 1 | \$200 \$100 |
| | labour | to SPRAY REAR FENDER RH | 1 | \$398 \$200 |
| | | SPARE TYRE FOAM | 1pc. | CRA |
| | | ARM SUB ASSY, REAR BUMPER RH | 1pc. | BT |
| | | ARM SUB ASSY, REAR BUMPER LH | 1pc. | BT |
| | | TO REQUEST ADDITIONAL REPAIR DAYS | | |

<<<Please submit photographs for damaged parts>>>

I, (Name)

(Position)

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

| | | |
|-----------------|--|---|
| Acknowledge By | ARC Executive / Supervisor / SA | |
| Approval By | Surveyor / In-house Staff | |
| Parts Ordering | SMRT Store / Contractor Supply / Form 22 / WOC | Form 22 / PO / WOC / Reservation / Number |
| Photo Submitted | YES / NO | Date of submission |

9/13



Case Details

Case Reference Number :

TAX/05/19/2046

Type of Repair : Accident Repair

Vehicle Registration Number : SHC4401P

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-6833-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 10/05/2019 02:20 AM

Vehicle Age(In Months) : 64

Documents / Photographs

[View Documents / Photographs](#)










Total Documents: 1

Estimation Details

Spare Part's Cost Detail

| SMRT Recommendation | | | | | | | | | | Surveyor Approval | | | | |
|-----------------------|--------------|---------|-----------------|-----------------------------------|-----|-------------------------|----------------|--------|-----------------|-------------------|-------------------|--------------------------|----------------|---------|
| BOM Type | Costing Type | Portion | Material Number | Part Name | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In | Main | | | TAIL GATE DOOR GLASS MOULDING, LH | 1 | 29.40 | 29.40 | 25.00 | 22.05 | Replace | 1 | 22.05 | Replace ▾ | hll |
| One Time Key In | Main | | | TAIL GATE DOOR GLASS MOULDING, RH | 1 | 29.40 | 29.40 | 25.00 | 22.05 | Replace | 1 | 22.05 | Replace ▾ | nll |
| One Time Key In | Main | | | MOULDING BACK WINDOW, LOWER NO.1 | 1 | 29.40 | 29.40 | 25.00 | 22.05 | Replace | 1 | 22.05 | Replace ▾ | nll |
| One Time Key In | Main | | | SEALANT W/SCREEN | 3 | 37.00 | 111.00 | 0.00 | 111.00 | Replace | 3 | 111.00 | Replace ▾ | nec |
| One Time Key In | Main | | | SPOILER REAR | 1 | 953.70 | 953.70 | 25.00 | 715.28 | Replace | 0 | 0 | Not Give ▾ | nn |
| One Time Key In | Main | | | 3RD BRAKE LAMP | 1 | 231.30 | 231.30 | 10.00 | 208.17 | Replace | 0 | 0 | Not Give ▾ | hy |
| One Time Key In | Main | | | LICENSE PLATE LAMP | 1 | 35.70 | 35.70 | 10.00 | 32.13 | Replace | 0 | 0 | Not Give ▾ | hy |
| One Time Key In | Main | | | NUMBER PLATE | 1 | 15.00 | 15.00 | 0.00 | 15.00 | Replace | 1 | 15.00 | Replace ▾ | SCR |
| One Time Key In | Main | | | NUMBER PLATE FRAME | 1 | 12.00 | 12.00 | 0.00 | 12.00 | Replace | 1 | 12.00 | Replace ▾ | SCR |
| One Time Key In | Main | | | END PANEL COVER, DECK TRIM HOLE | 1 | 46.10 | 46.10 | 25.00 | 34.58 | Replace | 0 | 0 | Check ▾ | |
| Total Spare Part Cost | | | | | | | | | 15,142.77 | Surveyor Total | | 2,154.35 | | |
| Lump Sum Discount (%) | | | | | | | | | 0.00 | Lump Sum Dis (%) | | 20 | | |
| Final Spare Part Cost | | | | | | | | | 12,114.22 | Final Sur Total | | 1,723.48 | | |

| BOM Type | Costing Type | Portion | Material Number | SMRT Recommendation | | | | | | | Surveyor Approval | | | | |
|-----------------------|--------------|---------|-----------------|--------------------------------|-----|-------------------------|----------------|--------|-----------------|------------------|-------------------|--------------------------|----------------|---------|-----|
| | | | | Part Name | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks | |
| One Time Key In | Main | | | END PANEL COVER, DECK TRIM, RR | 1 | 121.10 | 121.10 | 25.00 | 90.82 | Replace | 0 | 0 | Check | ▼ | |
| One Time Key In | Main | | | CAMERA ASSY, TELEVISION, RR | 1 | 1,436.60 | 1,436.60 | 10.00 | 1,292.94 | Replace | 0 | 0 | Not Give | ▼ | mm |
| One Time Key In | Main | | | ANTENNA, ELECTRICAL LOWER REAR | 1 | 157.40 | 157.40 | 10.00 | 141.66 | Replace | 1 | 141.66 | Replace | ▼ | CRA |
| One Time Key In | Main | | | TAILGATE DOOR LOCK | 1 | 444.10 | 444.10 | 10.00 | 399.69 | Replace | 0 | 0 | Check | ▼ | |
| One Time Key In | Main | | | TAILGATE DOOR WEATHER STRIP | 1 | 353.40 | 353.40 | 25.00 | 265.05 | Replace | 0 | 0 | Check | ▼ | |
| One Time Key In | Main | | | PANEL ASSY, DECK LH | 1 | 307.00 | 307.00 | 25.00 | 230.25 | Replace | 0 | 0 | Check | ▼ | |
| One Time Key In | Main | | | PANEL ASSY, DECK RH | 1 | 307.00 | 307.00 | 25.00 | 230.25 | Replace | 0 | 0 | Check | ▼ | |
| One Time Key In | Main | | | BOX, DECK FLOOR, COVER LH | 1 | 230.10 | 230.10 | 25.00 | 172.57 | Replace | 0 | 0 | Check | ▼ | |
| One Time Key In | Main | | | BOX, DECK FLOOR, LH | 1 | 196.80 | 196.80 | 25.00 | 147.60 | Replace | 0 | 0 | Check | ▼ | |
| One Time Key In | Main | | | BOX RR FLOOR, BOARD | 1 | 679.60 | 679.60 | 25.00 | 509.70 | Replace | 0 | 0 | Check | ▼ | |
| One Time Key In | Main | | | BOX, DECK FLOOR, RR | 1 | 649.70 | 649.70 | 25.00 | 487.28 | Replace | 0 | 0 | Check | ▼ | |
| One Time Key In | Main | | | BOARD ASSY, RR RH | 1 | 379.20 | 379.20 | 25.00 | 284.40 | Replace | 0 | 0 | Check | ▼ | |
| One Time Key In | Main | | | BATTERY | 1 | 278.00 | 278.00 | 0.00 | 278.00 | Replace | 0 | 0 | Not Give | ▼ | mm |
| One Time Key In | Main | | | BATTERY CLAMP | 1 | 16.10 | 16.10 | 25.00 | 12.08 | Replace | 0 | 0 | Check | ▼ | |
| One Time Key In | Main | | | TAILGATE TRIM, LH | 1 | 85.90 | 85.90 | 25.00 | 64.43 | Replace | 0 | 0 | Check | ▼ | |
| One Time Key In | Main | | | TAILGATE TRIM, LOWER | 1 | 180.70 | 180.70 | 25.00 | 135.52 | Replace | 0 | 0 | Check | ▼ | |
| Total Spare Part Cost | | | | | | | | | 15,142.77 | Surveyor Total | | 2,154.35 | | | |
| Lump Sum Discount (%) | | | | | | | | | 0.00 | Lump Sum Dis (%) | | 20 | | | |
| Final Spare Part Cost | | | | | | | | | 12,114.22 | Final Sur Total | | 1,723.48 | | | |

| BOM Type | Costing Type | Portion | Material Number | SMRT Recommendation | | | | | | | Surveyor Approval | | | |
|-----------------------|--------------|---------|-----------------|-------------------------|-----|-------------------------|----------------|--------|-----------------|--------------------------|-------------------|--------------------------|----------------|---|
| | | | | Part Name | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In | Main | | | TAILGATE TRIM, RH | 1 | 88.30 | 88.30 | 25.00 | 66.22 | Replace | 0 | 0 | Check | ▼ |
| One Time Key In | Main | | | TAILGATE TRIM, UPPER | 1 | 49.60 | 49.60 | 25.00 | 37.20 | Replace | 0 | 0 | Check | ▼ |
| One Time Key In | Main | | | TAILGATE, BOARD ASSY | 1 | 246.90 | 246.90 | 25.00 | 185.18 | Replace | 0 | 0 | Check | ▼ |
| One Time Key In | Main | | | MEMBER SUB-ASSY, RR LH | 1 | 174.10 | 174.10 | 25.00 | 130.57 | Replace | 0 | 0 | Not Give | ▼  |
| One Time Key In | Main | | | MEMBER SUB-ASSY, RR RH | 1 | 174.10 | 174.10 | 25.00 | 130.57 | Replace | 0 | 0 | Not Give | ▼  |
| One Time Key In | Main | | | FLOOR PANEL RR/LH | 1 | 102.00 | 102.00 | 25.00 | 76.50 | Replace | 0 | 0 | Check | ▼ |
| One Time Key In | Main | | | FLOOR PANEL RR/RH | 1 | 209.90 | 209.90 | 25.00 | 157.43 | Replace | 0 | 0 | Check | ▼ |
| One Time Key In | Main | | | FENDER RR/LH | 1 | 766.80 | 766.80 | 25.00 | 575.10 | Replace | 0 | 0 | Not Give | ▼  |
| One Time Key In | Main | | | STICKER SMRT LOGO | 1 | 7.80 | 7.80 | 0.00 | 7.80 | Replace | 0 | 0 | Not Give | ▼  |
| One Time Key In | Main | | | STICKER DECAL 6555 8888 | 1 | 21.60 | 21.60 | 0.00 | 21.60 | Replace | 0 | 0 | Not Give | ▼  |
| One Time Key In | Main | | | QUARTER GLASS RR/LH | 1 | 168.10 | 168.10 | 25.00 | 126.07 | Replace | 0 | 0 | Not Give | ▼  |
| One Time Key In | Main | | | SEALANT W/SCREEN | 1 | 37.00 | 37.00 | 0.00 | 37.00 | Replace | 0 | 0 | Not Give | ▼  |
| One Time Key In | Main | | | SILL MEMBER PLATE RR/LH | 1 | 57.50 | 57.50 | 25.00 | 43.13 | Replace | 0 | 0 | Check | ▼ |
| One Time Key In | Main | | | BUMPER SEAL, RR LH | 1 | 88.90 | 88.90 | 25.00 | 66.68 | Replace | 0 | 0 | Not Give | ▼  |
| One Time Key In | Main | | | TROUGH, BACK DOOR LH | 1 | 110.90 | 110.90 | 25.00 | 83.18 | Replace | 0 | 0 | Not Give | ▼  |
| One Time Key In | Main | | | TAIL LAMP BRACKET, LH | 1 | 30.70 | 30.70 | 25.00 | 23.02 | Replace | 0 | 0 | Check | ▼ |
| Total Spare Part Cost | | | | | | | | | 15,142.77 | Surveyor Total 2,154.35 | | | | |
| Lump Sum Discount (%) | | | | | | | | | 0.00 | Lump Sum Dis (%) 20 | | | | |
| Final Spare Part Cost | | | | | | | | | 12,114.22 | Final Sur Total 1,723.48 | | | | |

| BOM Type | Costing Type | Portion | Material Number | SMRT Recommendation | | | | | | | Surveyor Approval | | | |
|-----------------------|--------------|---------|-----------------|--------------------------------|-----|-------------------------|----------------|--------|-----------------|--------------------------|-------------------|--------------------------|----------------|---------|
| | | | | Part Name | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In | Main | | | TAIL LAMP LH | 1 | 548.40 | 548.40 | 10.00 | 493.56 | Replace | 0 | 0 | Check | |
| One Time Key In | Main | | | TAILGATE DOOR HINGE LH/RH | 2 | 58.30 | 116.60 | 25.00 | 87.45 | Replace | 0 | 0 | Not Give | nn |
| One Time Key In | Main | | | TAILGATE DOOR STAY LH | 1 | 241.50 | 241.50 | 25.00 | 181.13 | Replace | 0 | 0 | Not Give | nn |
| One Time Key In | Main | | | TAILGATE DOOR STAY RH | 1 | 241.50 | 241.50 | 25.00 | 181.13 | Replace | 0 | 0 | Not Give | nn |
| One Time Key In | Main | | | BUMPER REAR | 1 | 458.60 | 458.60 | 25.00 | 343.95 | Replace | 1 | 343.95 | Replace | DEF |
| One Time Key In | Main | | | BUMPER SIDE RETAINER RR/LH | 1 | 94.80 | 94.80 | 25.00 | 71.10 | Replace | 0 | 0 | Check | |
| One Time Key In | Main | | | BUMPER SIDE RETAINER RR/RH | 1 | 94.80 | 94.80 | 25.00 | 71.10 | Replace | 0 | 0 | Check | |
| One Time Key In | Main | | | BUMPER REINFORCEMENT REAR | 1 | 205.70 | 205.70 | 25.00 | 154.27 | Replace | 1 | 154.27 | Replace | DD |
| One Time Key In | Main | | | BUMPER LIP COVER RR/LH | 1 | 72.20 | 72.20 | 25.00 | 54.15 | Replace | 1 | 54.15 | Replace | SCR |
| One Time Key In | Main | | | BUMPER LIP COVER RR/RH | 1 | 118.10 | 118.10 | 25.00 | 88.57 | Replace | 1 | 88.57 | Replace | SCR |
| One Time Key In | Main | | | BUMPER LIP REAR | 1 | 228.90 | 228.90 | 25.00 | 171.68 | Replace | 1 | 171.68 | Replace | SCR |
| One Time Key In | Main | | | SENSOR REVERSE | 1 | 180.00 | 180.00 | 0.00 | 180.00 | Replace | 1 | 180.00 | Replace | Shorted |
| One Time Key In | Main | | | PIXEL STICKER | 1 | 60.00 | 60.00 | 0.00 | 60.00 | Replace | 1 | 60.00 | Replace | nn |
| One Time Key In | Main | | | UNDER COVER SUB-ASSY, RR FLOOR | 1 | 514.50 | 514.50 | 25.00 | 385.88 | Replace | 0 | 0 | Check | |
| One Time Key In | Main | | | EXHAUST TAIL PIPE | 1 | 656.20 | 656.20 | 25.00 | 492.15 | Replace | 0 | 0 | Not Give | nn |
| One Time Key In | Main | | | SUPPORT, EXHAUST REAR | 1 | 33.60 | 33.60 | 25.00 | 25.20 | Replace | 0 | 0 | Not Give | nn |
| Total Spare Part Cost | | | | | | | | | 15,142.77 | Surveyor Total 2,154.35 | | | | |
| Lump Sum Discount (%) | | | | | | | | | 0.00 | Lump Sum Dis (%) 20 | | | | |
| Final Spare Part Cost | | | | | | | | | 12,114.22 | Final Sur Total 1,723.48 | | | | |

| BOM Type | Costing Type | Portion | Material Number | SMRT Recommendation | | | | | | | Surveyor Approval | | | |
|-----------------|--------------|---------|-----------------|--------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|----------|
| | | | | Part Name | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In | Main | | | END PANEL | 1 | 602.10 | 602.10 | 25.00 | 451.58 | Replace | 1 | 0 | Repair | ▼ |
| One Time Key In | Main | | | SEALANT SIKAFLEX | 1 | 37.00 | 37.00 | 0.00 | 37.00 | Replace | 0 | 0 | Not Give | ▼ nn |
| One Time Key In | Main | | | SPARE TYRE PANEL | 1 | 667.70 | 667.70 | 25.00 | 500.78 | Replace | 0 | 0 | Check | ▼ |
| One Time Key In | Main | | | TAILGATE ASY | 1 | 1,007.90 | 1,007.90 | 25.00 | 755.92 | Replace | 1 | 755.92 | Replace | ▼ Buc |
| One Time Key In | Main | | | TAILGATE OUTSIDE GARNISH | 1 | 504.90 | 504.90 | 25.00 | 378.67 | Replace | 0 | 0 | Not Give | ▼ nn |
| One Time Key In | Main | | | EMBLEM REAR | 1 | 60.30 | 60.30 | 25.00 | 45.22 | Replace | 0 | 0 | Not Give | ▼ nn |
| One Time Key In | Main | | | NAME PLATE (HYBRID) | 1 | 51.90 | 51.90 | 25.00 | 38.92 | Replace | 0 | 0 | Not Give | ▼ nn |
| One Time Key In | Main | | | NAME PLATE (PRIUS) | 1 | 60.80 | 60.80 | 25.00 | 45.60 | Replace | 0 | 0 | Not Give | ▼ |
| One Time Key In | Main | | | NAME PLATE (TOYOTA) | 1 | 51.90 | 51.90 | 25.00 | 38.92 | Replace | 0 | 0 | Not Give | ▼ |
| One Time Key In | Main | | | STICKER DECAL 6555 8888 | 1 | 21.60 | 21.60 | 0.00 | 21.60 | Replace | 0 | 0 | Not Give | ▼ |
| One Time Key In | Main | | | STICKER DECAL SMRT | 1 | 7.80 | 7.80 | 0.00 | 7.80 | Replace | 0 | 0 | Not Give | ▼ |
| One Time Key In | Main | | | FENDER RR/RH | 1 | 766.80 | 766.80 | 25.00 | 575.10 | Replace | 0 | 0 | Not Give | ▼ |
| One Time Key In | Main | | | STICKER SMRT LOGO | 1 | 7.80 | 7.80 | 25.00 | 5.85 | Replace | 0 | 0 | Not Give | ▼ nn |
| One Time Key In | Main | | | STICKER DECAL 6555 8888 | 1 | 21.60 | 21.60 | 25.00 | 16.20 | Replace | 0 | 0 | Not Give | ▼ |
| One Time Key In | Main | | | QUARTER GLASS RR/RH | 1 | 846.50 | 846.50 | 25.00 | 634.88 | Replace | 0 | 0 | Not Give | ▼ |
| One Time Key In | Main | | | SEALANT W/SCREEN | 1 | 37.00 | 37.00 | 0.00 | 37.00 | Replace | 0 | 0 | Not Give | ▼ |

Total Spare Part Cost 15,142.77

Surveyor Total 2,154.35

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 20

Final Spare Part Cost 12,114.22

Final Sur Total 1,723.48

| SMRT Recommendation | | | | | | | | | | | Surveyor Approval | | | |
|-----------------------|--------------|---------|-----------------|-------------------------|-----|-------------------------|----------------|--------|-----------------|--------------------------|-------------------|--------------------------|----------------|---------|
| BOM Type | Costing Type | Portion | Material Number | Part Name | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In | Main | | | FENDER LINER RR/RH | 1 | 141.30 | 141.30 | 25.00 | 105.98 | Replace | 0 | 0 | Not Give | h n |
| One Time Key In | Main | | | BUMPER SEAL, RR RH | 1 | 65.70 | 65.70 | 25.00 | 49.28 | Replace | 0 | 0 | Check | |
| One Time Key In | Main | | | SILL MEMBER PLATE RR/RH | 1 | 57.50 | 57.50 | 25.00 | 43.13 | Replace | 0 | 0 | Check | |
| One Time Key In | Main | | | TROUGH, BACK DOOR | 1 | 110.90 | 110.90 | 25.00 | 83.18 | Replace | 0 | 0 | Not Give | h n |
| One Time Key In | Main | | | TAIL LAMP BRACKET, RH | 1 | 30.70 | 30.70 | 25.00 | 23.02 | Replace | 0 | 0 | Check | |
| One Time Key In | Main | | | TAIL LAMP RH | 1 | 557.80 | 557.80 | 10.00 | 502.02 | Replace | 0 | 0 | Check | |
| Total Spare Part Cost | | | | | | | | | 15,142.77 | Surveyor Total 2,154.35 | | | | |
| Lump Sum Discount (%) | | | | | | | | | 0.00 | Lump Sum Dis (%) 20 | | | | |
| Final Spare Part Cost | | | | | | | | | 12,114.22 | Final Sur Total 1,723.48 | | | | |

Labour's Cost Detail

| S.No. | Costing Type | Job Scope | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|------------------------|-------------------------|-------------------------|---------|
| 1 | Main | TO REPAIR REAR PORTION | 1,690.00 | 600 | |
| Total: | | | 1,690.00 | 600.00 | |

Spray Cost Detail

| S.No. | Costing Type | Job Scope | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|-------------------------------------|-------------------------|-------------------------|---------|
| 1 | Main | TO RESPRAY REAR BUMPER | 378.00 | 200 | |
| 2 | Main | TO RESPRAY REAR PANEL | 180.00 | 100 | |
| 3 | Main | TO RESPRAY REAR SPARE TYRE PANEL | 180.00 | 0 | |
| 4 | Main | TO RESPRAY TAIL GATE | 378.00 | 200 | |
| 5 | Main | TO RESPRAY TAILGATE OUTSIDE GARNISH | 180.00 | 0 | |
| 6 | Main | TO RESPRAY REAR FENDER RH | 378.00 | 0 | |
| 7 | Main | TO RESPRAY REAR FENDER LH | 378.00 | 0 | |
| Total: | | | 3,312.00 | 500.00 | |

| S.No. | Costing Type | Job Scope | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|--------------|--|----------------------------|----------------------------|---------|
| 8 | Main | TO RESPRAY TROUGH BACK DOOR LH | 180.00 | 0 | |
| 9 | Main | TO RESPRAY TROUGH BACK DOOR RH | 180.00 | 0 | |
| 10 | Main | TO RESPRAY REAR MEMBER,LH | 180.00 | 0 | |
| 11 | Main | TO RESPRAY REAR MEMBER,RH | 180.00 | 0 | |
| 12 | Main | TO RESPRAY REAR FLOOR SIDE PANEL LH | 180.00 | 0 | |
| 13 | Main | TO RESPRAY REAR FLOOR SIDE PANEL RH | 180.00 | 0 | |
| 14 | Main | TO RESPRAY SPOILER | 180.00 | 0 | |
| Total: | | | 3,312.00 | 500.00 | |

Other Cost Detail

| S.No. | Costing Type | Job Scope | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|--------------|---|----------------------------|----------------------------|---------|
| 1 | Main | TO CHECK & RESET SYSTEM FUNCTION | 350.00 | 0 | |
| 2 | Main | TOWING CHARGE | 56.00 | 0 | |
| 3 | Main | TO CHECK WIRING AND SYSTEM FUNCTION | 80.00 | 30 | |
| 4 | Main | TO APPLY RUST-PROOFING ON AFFECTED AREA | 200.00 | 0 | |
| 5 | Main | TO ALIGN CHASSIS | 350.00 | 0 | |
| 6 | Main | TO TEST AND REFIX REVERSE SENSOR SYSTEM | 120.00 | 30 | |
| 7 | Main | TO TRANSFER REAR TAILGATE MECHANISM | 120.00 | 50 | |
| 8 | Main | TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR. | 120.00 | 30 | |
| 9 | Main | TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE | 120.00 | 0 | |
| 10 | Main | TO DO WHEEL ALIGNMENT / TYRE BALANCING | 120.00 | 0 | |
| 11 | Main | TO REMOVE & REFIT REAR QUARTER GLASS LH | 120.00 | 0 | |
| 12 | Main | TO REMOVE & REFIT REAR QUARTER GLASS RH | 120.00 | 0 | |
| 13 | Main | TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET) | 250.00 | 0 | |
| 14 | Main | TO REMOVE / REFIT SEAT | 120.00 | 0 | |
| Total: | | | 2,406.00 | 140.00 | |

| S.No. | Costing Type | Job Scope | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|--------------|-------------------------|----------------------------|----------------------------|---------|
| 15 | Main | TO WASH AND VACUUM | 60.00 | 0 | |
| 16 | Main | TO REPLACE SUNDRY PARTS | 100.00 | 0 | |
| Total: | | | 2,406.00 | 140.00 | |

Summary

| | Estimator Assesment(\$) | Surveyor Assesment(\$) |
|--------------------------|---|--|
| Total Spare Part Detail | 12,114.22 | 1,723.48 |
| Total Labour Cost | 1,690.00 | 600.00 |
| Total Spray Painting | 3,312.00 | 500.00 |
| Other | 2,406.00 | 140.00 |
| Overall Total | 19,522.22 | 2,963.48 |
| Lump Sum Repair Option | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| Lump Sum Total | 19,500.00 | 2,950.00 |
| Surveyor Approved Amount | | 2,950.00 |
| No of Repair Days* | 10 | 5 |
| Remarks | - | L/S REPAIR, PHOTO AFTER PAINT. |
| Surveyor Name | | Hwee jie |
| Signature |  |  14/5/19 |
| Survey Date | 13/05/2019 | |

Save

Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: -



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



| | | | | |
|--|--|-----------------|------------------|---|
| NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19008479/Jtd3e2 | | | | |
| 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 | | | Date: 01-07-2019 |  |
| Code: INC4 | | | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SJX 5579U | Veh. Inspected | SHC 4401P | |
| Policy No. | 5092561928-01 | Coverage (\$) | 0.00 | |
| Claim No. | MT/1043950-002 | Excess (\$) | 0.00 | |
| Assign From | | Assign Date | 13/05/2019 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | TOYOTA PRIUS | c.c | 1798 | |
| Engine No. | HIDDEN | Year of Reg. | 2014 | |
| Chassis No. | JTDKN36U605720864 | Colour | MAROON | |
| Odometer | 533376 | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 195/65 R15 | CHILLES | 6 mm | |
| L/H Front Tyre | 195/65 R15 | CHILLES | 6 mm | |
| R/H Rear Tyre | 195/65 R15 | CHILLES | 6 mm | |
| L/H Rear Tyre | 195/65 R15 | CHILLES | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 10/05/2019 | Inspection Date | 13/05/2019 | |
| Survey held at | SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 9 Working Days | | |

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4401P

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|--|---------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | TAIL GATE DOOR GLASS MOULDING, LH (DISC 25%) | NECESSARY | 29.40 | 22.05 |
| 1 | TAIL GATE DOOR GLASS MOULDING, RH (DISC 25%) | NECESSARY | 29.40 | 22.05 |
| 1 | MOULDING BACK WINDOW, LOWER NO.1 (DISC 25%) | NECESSARY | 29.40 | 22.05 |
| 1 | BUMPER REAR (DISC 25%) | DEFORMED | 458.60 | 343.95 |
| 1 | BUMPER REINFORCEMENT REAR (DISC 25%) | DENTED | 205.70 | 154.28 |
| 1 | BUMPER LIP COVER RR/LH (DISC 25%) | SCRATCHED | 72.20 | 54.15 |
| 1 | BUMPER LIP COVER RR/RH (DISC 25%) | SCRATCHED | 118.10 | 88.58 |
| 1 | BUMPER LIP REAR (DISC 25%) | SCRATCHED | 228.90 | 171.68 |
| 1 | TAILGATE ASY (DISC 25%) | BUCKLED | 1,007.90 | 755.93 |
| 1 | TAILGATE DOOR LOCK (DISC 25%) | JAMMED | 444.10 | 333.08 |
| 1 | TAILGATE DOOR WEATHER STRIP (DISC 25%) | CUT | 353.40 | 265.05 |
| 1 | TAIL LAMP BRACKET, LH (DISC 25%) | CRACKED | 30.70 | 23.03 |
| 1 | BUMPER SIDE RETAINER RR/LH (DISC 25%) | CRACKED | 94.80 | 71.10 |
| 1 | BUMPER SIDE RETAINER RR/RH (DISC 25%) | CRACKED | 94.80 | 71.10 |
| 1 | UNDER COVER SUB-ASSY, RR FLOOR (DISC 25%) | DEFORMED | 514.50 | 385.88 |
| 1 | END PANEL (DISC 25%) | BUCKLED | 602.10 | 451.58 |
| 1 | TAIL LAMP BRACKET, RH (DISC 25%) | CRACKED | 30.70 | 23.03 |
| 1 | CARRIER, SPARE (DISC 25%) | CRACKED | 19.70 | 14.78 |
| 1 | ARM SUB-ASSY, RR BUMPER LH (DISC 25%) | BENT | 139.60 | 104.70 |
| 1 | ARM SUB-ASSY, RR BUMPER RH (DISC 25%) | BENT | 139.60 | 104.70 |
| 1 | ANTENNA, ELECTRICAL LOWER REAR (DISC 10%) | CRACKED | 157.40 | 141.66 |
| 3 | SEALANT W/SCREEN @\$37.00 (SN) | NECESSARY | 111.00 | 111.00 |
| 1 | SENSOR REVERSE (SN) | SHORTED | 180.00 | 180.00 |
| 1 | PIXEL STICKER (SN) | NECESSARY | 60.00 | 60.00 |
| 3 | SEALANT SIKAFLEX @\$37.00 (SN) | NECESSARY | 111.00 | 111.00 |
| 1 | NUMBER PLATE (SN) | SCRATCHED | 15.00 | 15.00 |
| 1 | NUMBER PLATE FRAME (SN) | SCRATCHED | 12.00 | 12.00 |
| 1 | SPOILER REAR | NOT NECESSARY | 953.70 | - |
| 1 | 3RD BRAKE LAMP | NOT NECESSARY | 231.30 | - |
| 1 | LICENSE PLATE LAMP | NOT NECESSARY | 35.70 | - |

Report Ref No. NS/INC19008479/Jtd3e2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 4

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---------------------------------|---------------|---------------------------|-------------------|
| 1 | END PANEL COVER, DECK TRIM HOLE | NOT NECESSARY | 46.10 | - |
| 1 | END PANEL COVER, DECK TRIM, RR | NOT NECESSARY | 121.10 | - |
| 1 | CAMERA ASSY, TELEVISION, RR | NOT NECESSARY | 1,436.60 | - |
| 1 | TAILGATE DOOR LOCK | NOT NECESSARY | 444.10 | - |
| 1 | TAILGATE DOOR WEATHERSTRIP | NOT NECESSARY | 353.40 | - |
| 1 | PANEL ASSY, DECK LH | NOT NECESSARY | 307.00 | - |
| 1 | PANEL ASSY, DECK RH | NOT NECESSARY | 307.00 | - |
| 1 | BOX, DECK FLOOR, COVER LH | NOT NECESSARY | 230.10 | - |
| 1 | BOX, DECK FLOOR, LH | NOT NECESSARY | 196.80 | - |
| 1 | BOX RR FLOOR, BOARD | NOT NECESSARY | 679.60 | - |
| 1 | BOX, DECK FLOOR, RR | NOT NECESSARY | 649.70 | - |
| 1 | BOARD ASSY, RR RH | NOT NECESSARY | 379.20 | - |
| 1 | BATTERY | NOT NECESSARY | 278.00 | - |
| 1 | BATTERY CLAMP | NOT NECESSARY | 16.10 | - |
| 1 | TAILGATE TRIM, LH | NOT NECESSARY | 85.90 | - |
| 1 | TAILGATE TRIM, LOWER | NOT NECESSARY | 180.70 | - |
| 1 | TAILGATE TRIM, RH | NOT NECESSARY | 88.30 | - |
| 1 | TAILGATE TRIM, UPPER | NOT NECESSARY | 49.60 | - |
| 1 | TAILGATE, BOARD ASSY | NOT NECESSARY | 246.90 | - |
| 1 | MEMBER SUB-ASSY, RR LH | NOT NECESSARY | 174.10 | - |
| 1 | MEMBER SUB-ASSY, RR RH | NOT NECESSARY | 174.10 | - |
| 1 | FLOOR PANEL RR/LH | NOT NECESSARY | 102.00 | - |
| 1 | FLOOR PANEL RR/RH | NOT NECESSARY | 209.90 | - |
| 1 | FENDER RR/LH | NOT NECESSARY | 766.80 | - |
| 1 | STICKER SMRT LOGO | NOT NECESSARY | 7.80 | - |
| 1 | STICKER DECAL 6555 8888 | NOT NECESSARY | 21.60 | - |
| 1 | QUARTER GLASS RR/LH | NOT NECESSARY | 168.10 | - |
| 1 | SEALANT W/SCREEN | NOT NECESSARY | 37.00 | - |
| 1 | SILL MEMBER PLATE RR/LH | NOT NECESSARY | 57.50 | - |
| 1 | BUMPER SEAL, RR LH | NOT NECESSARY | 88.90 | - |
| 1 | TROUGH, BACK DOOR LH | NOT NECESSARY | 110.90 | - |
| 1 | TAIL LAMP BRACKET, LH | NOT NECESSARY | 30.70 | - |
| 1 | TAIL LAMP LH | NOT NECESSARY | 548.40 | - |

Report Ref No. NS/INC19008479/Jtd3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:3 of 4

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------|----------------------|---------------------------|-------------------|
| 2 | TAILGATE DOOR HINGE LH / RH | NOT NECESSARY | 58.30 | - |
| 1 | TAILGATE DOOR STAY LH | NOT NECESSARY | 241.50 | - |
| 1 | TAILGATE DOOR STAY RH | NOT NECESSARY | 241.50 | - |
| 1 | BUMPER SIDE RETAINER RR/LH | NOT NECESSARY | 94.80 | - |
| 1 | BUMPER SIDE RETAINER RR/RH | NOT NECESSARY | 94.80 | - |
| 1 | UNDER COVER SUB-ASSY, RR FLOOR | NOT NECESSARY | 514.50 | - |
| 1 | EXHAUST TAIL PIPE | NOT NECESSARY | 656.20 | - |
| 1 | SUPPORT, EXHAUST REAR | NOT NECESSARY | 33.60 | - |
| 1 | SEALANT SIKAFLEX | NOT NECESSARY | 37.00 | - |
| 1 | SPARE TYRE PANEL | NOT NECESSARY | 667.70 | - |
| 1 | TAILGATE OUTSIDE GARNISH | NOT NECESSARY | 504.90 | - |
| 1 | EMBLEM REAR | NOT NECESSARY | 60.30 | - |
| 1 | NAME PLATE (HYBRID) | NOT NECESSARY | 51.90 | - |
| 1 | NAME PLATE (PRIUS) | NOT NECESSARY | 60.80 | - |
| 1 | NAME PLATE (TOYOTA) | NOT NECESSARY | 51.90 | - |
| 1 | STICKER DECAL 6555 8888 | NOT NECESSARY | 21.60 | - |
| 1 | STICKER DECAL SMRT | NOT NECESSARY | 7.80 | - |
| 1 | FENDER RR/RH | NOT NECESSARY | 766.80 | - |
| 1 | STICKER SMRT LOGO | NOT NECESSARY | 7.80 | - |
| 1 | STICKER DECAL 6555 8888 | NOT NECESSARY | 21.60 | - |
| 1 | QUARTER GLASS RR/RH | NOT NECESSARY | 846.50 | - |
| 1 | SEALANT W/SCREEN | NOT NECESSARY | 37.00 | - |
| 1 | FENDER LINER RR/RH | NOT NECESSARY | 141.30 | - |
| 1 | BUMPER SEAL, RR RH | NOT NECESSARY | 65.70 | - |
| 1 | SILL MEMBER PLATE RR/RH | NOT NECESSARY | 57.50 | - |
| 1 | TROUGH, BACK DOOR | NOT NECESSARY | 110.90 | - |
| 1 | TAIL LAMP BRACKET, RH | NOT NECESSARY | 30.70 | - |
| 1 | TAIL LAMP RH | NOT NECESSARY | 557.80 | - |
| 1 | END PANEL | TO REPAIR SEE LABOUR | 602.10 | - |
| | | | 21,749.50 | 4,113.41 |

Report Ref No. NS/INC19008479/Jtd3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:4 of 4

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|---------------|---------------------------|-------------------|
| | LABOUR | | | |
| | PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF END PANEL. | | 2,366.00 | 1,100.00 |
| | SPRAY PAINT. | | 3,870.00 | 800.00 |
| | TO CHECK & RESET SYSTEM FUNCTION. | NOT NECESSARY | 350.00 | - |
| | TOWING CHARGE. | | 56.00 | - |
| | TO CHECK WIRING AND SYSTEM FUNCTION. | | 80.00 | 30.00 |
| | TO APPLY RUST-PROOFING ON AFFECTED AREA. | NOT NECESSARY | 200.00 | - |
| | TO ALIGN CHASSIS. | NOT NECESSARY | 350.00 | - |
| | TO TEST AND REFIX REVERSE SENSOR SYSTEM. | | 120.00 | 30.00 |
| | TO TRANSFER REAR TAILGATE MECHANISM. | | 120.00 | 50.00 |
| | TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR. | | 120.00 | 30.00 |
| | TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE. | NOT NECESSARY | 120.00 | - |
| | TO DO WHEEL ALIGNMENT / TYRE BALANCING. | NOT NECESSARY | 120.00 | - |
| | TO REMOVE & REFIT REAR QUARTER GLASS LH. | NOT NECESSARY | 120.00 | - |
| | TO REMOVE & REFIT REAR QUARTER GLASS RH. | NOT NECESSARY | 120.00 | - |
| | TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM. | NOT NECESSARY | 250.00 | - |
| | TO REMOVE / REFIT SEAT. | NOT NECESSARY | 120.00 | - |
| | TO WASH AND VACUUM. | NOT NECESSARY | 60.00 | - |
| | TO REPLACE SUNDRY PARTS. | NOT NECESSARY | 100.00 | - |
| | | | 8,642.00 | 2,040.00 |
| | GRAND TOTAL | | 30,391.50 | 6,153.41 |

| | | | | |
|---|--|--|--|-----------------|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) | | | | 4,900.00 |
|---|--|--|--|-----------------|

Report Ref No. NS/INC19008479/Jtd3e2

ONG HWEE JIE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.