

not allowed
here
4/5 @ 7800
4 day.
14/5/19

14/5/19

(57)

$$\begin{array}{r} 6024 \\ \times 52 \\ \hline 12048 \\ 30120 \\ \hline 98028 \end{array}$$

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 1104Z

Vehicle Details

Vehicle No.: SLX6802U

Vehicle to be Exported: No

Intended Deregistration Date: 14 May 2019

Vehicle Make: B.M.W.

Vehicle Model: M3 4.0 SMT ABS D/AB 2WD 4DR GAS/D

Primary Colour: Grey

Manufacturing Year: 2010

Engine No.: 20994730S65B40A

Chassis No.: WBSPM92030E198220

Maximum Power Output: 308.0 kW (413 bhp)

Open Market Value: \$82,408.00

Original Registration Date: 27 Oct 2010

First Registration Date: 27 Oct 2010

Transfer Count: 2

Actual ARF Paid: \$82,408.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 26 Oct 2020

PARF Rebate Amount: \$45,324.00

Intended COE Rebate Details

COE Expiry Date: 26 Oct 2020

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$44,600.00

COE Rebate Amount: \$6,462.00

Total Rebate Amount: \$51,786.00

The information contained herein is correct as at 14 May 2019

OK

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Classic Promo! Best Deal! Fast Selling! Hurry Down Now!

Flexible Loan. Trade In Are

Welcome. 100% Deposit Refund

For Unapproved Loan.

Classic Credit StarAd

VALUE FOR MONEY

VALUE FOR TIME

A PEACE OF MIND

HOTLINE: 6741 9997

view our cars

Browse by Category

Sort by Date Posted

20 results/page

8 vehicles

bmw m3

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	bmw m3		Any	Any	2010	Any	Any	Any	Available
	BMW M Series M3 Coupe (New 10-yr COE)		\$158,888	\$15,880 /yr	15-Jan-2010	3,999 cc	68,888 km	Sports	Available
	Rare Manual V8 M3. Low Mileage. Regularly Maintained At Reputable Workshop. Number Plate To Be Retained. Direct Owner								
Posted: 14-May-2019 Tags: 2010 BMW M3, 2010 bmw m3, BMW M3, bmw m3, BMW, M3, m3, Used BMW									
	BMW M Series M3 Convertible (New 10-yr COE)		\$119,888	\$11,980 /yr	11-Mar-2010	3,999 cc	95,000 km	Sports	Available
	Perfect Condition. Fully Maintained From Day 1 With Munich Motors. New 10-yr COE. Intake Mods, Exhaust Mods Fully Certified. Viewing By Appointment Only!								
Posted: 12-May-2019 Tags: 2010 BMW M3, 2010 bmw m3, BMW M3, bmw m3, BMW, M3, m3, Used BMW									
	BMW M Series M3 Coupe (New 10-yr COE)		\$129,800	\$12,970 /yr	02-Feb-2010	3,999 cc	54,000 km	Sports	Available
	Low Mileage Done Of 54K Km, Ehicle In Showroom Condition. Grooming Done By Professional Groomer, Fast And Hassle Free Transaction. Immediate Delivery! Buy With A Peace Of Mind. View To Believe. Come V...								
Shuang Hup Credit Posted: 11-May-2019 Tags: 2010 BMW M3, 2010 bmw m3, BMW M3, bmw m3, BMW, M3, m3, Used BMW									
	BMW M Series M3 Convertible (New 10-yr COE)		\$121,500	\$12,140 /yr	26-Oct-2010	3,999 cc	63,000 km	Sports	Available
	New Road Tax! Low Mileage, Agent Unit, Full Service Records At Munich Automobile (Agent) Over The Years! View Now At Showroom!								
Posted: 03-May-2019 Tags: 2010 BMW M3, 2010 bmw m3, BMW M3, bmw m3, BMW, M3, m3, Used BMW									
GET YOUR COE RENEWAL LOAN Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.									
	BMW M Series M3 Convertible (New 10-yr COE)		\$128,888	\$12,880 /yr	30-Apr-2010	3,999 cc	109,000 km	Sports	Available
	High Revving 4.0 Litre V8 Engine Producing 420hp At 8300rpm. 7 Speed Double Clutch Transmission For Lightning Quick Shifts. 0-100 In 5.1secs. Very Well Maintained, Wear And Tear Parts Replaced, Recent...								
Posted: 21-Apr-2019 Tags: 2010 BMW M3, 2010 bmw m3, BMW M3, bmw m3, BMW, M3, m3, Used BMW									
	BMW M Series M3 Coupe		\$83,000	\$46,660 /yr	26-May-2010	3,999 cc	-	Sports	Available
	Coupe Edition! Owner Reluctant Sale, Changing To 4 Doors Ride. Accident Free. Well Maintained. Coe Renewal Can Be Arranged. Owner Consigned, Please Call For Viewing Appointment.								
Posted: 18-Apr-2019 Tags: 2010 BMW M3, 2010 bmw m3, BMW M3, bmw m3, BMW, M3, m3, Used BMW									
Compare									

sgCARMART.COM

Home

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Log in

Sign up

• 2014 Honda 3

• New Electricity Service providers

• 10th Generation Honda Civic (2016)

bmw m3

Price Range

Depreciation

2010

Vehicle Type

Submit

Advanced Search

Home > Used Cars > Ole Supercars > BMW M Series M3 Coupe

BMW M Series M3 Coupe

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price

\$83,000

Depreciation

\$48,660 /yr

View models with similar depre

Mileage

N.A.

Road Tax

\$3,948 /yr

Dereg Value

\$38,292 as of today (change)

COE

N.A.

Engine Cap

3,999 cc

Curb Weight

1,675 kg

Type of Vehicle

Sports Car

Reg Date

26-May-2010

(1yr 11days COE left)

Manufactured

2010

Transmission

Auto

OMV

\$89,621

ARF

\$89,621

Power

309.0 kW (414 bhp)

No. of Owners

4

Location Map

Shortlist

Compare

Add note

Report Error

More Actions

Features

View specs of the BMW M3

Accessories

Aicon Superkit, Akrapovic Exhaust, Street Legal Carbon Interior, Bootlip And Front Lip, Etc

Description

Coupe Edition! Owner Reluctant Sale, Changing To 4 Doors Ride. Accident Free. Well Maintained. Coe Renewal Can Be Arranged. Owner Consigned, Please Call For Viewing Appointment.

Category

Exotic Car

Status

Available

Resources

Car Valuation - Free

Find out the market value of your existing car for free. Get started

Vehicle Evaluation

Alfred of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 28-Apr-2019

Last updated on: 11-May-2019

Upfront Payment

Transfer Fee

Down Payment

1st Instalment

More Financial Info

Products and Services

View All

For Handling & Excellent Braking

Compare

BMW E92

Roboton Design Carbon Fibre Spoiler

Roboton Design Carbon Fibre Spoiler

Compare

https://www.sgcarmart.com/used_cars/info.php?ID=801932&DL=2051

14-May-19

COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

Sys
INV 6330

FASTTECH AUTO PTE LTD
SLX 6802 U
14.5.19 14:18



SLX 6802 U

BMW : 3 Series - E90/E91 (2005 - 2012) : M3 : with AFS (Active Front Steering) : 19" Wheel

Front : Left

Actual	Before	Specified Range
-0°17'	-0°17'	-1°35' -0°45'
6°51'	6°51'	
0°16'	0°16'	0°03' 0°07'
14°16'	14°16'	
13°59'	13°59'	
		-2°44' -1°44'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°29'	-0°30'	-1°35' -0°45'
6°54'	6°54'	
0°18'	0°18'	0°03' 0°07'
13°02'	13°03'	
12°33'	12°33'	
		-2°44' -1°44'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°12'	0°13'	-0°30' 0°30'
-0°04'	-0°04'	-0°30' 0°30'
1°14'	1°13'	
0°34'	0°34'	0°02' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°52'	-1°52'	-2°00' -1°30'
0°05'	0°05'	0°03' 0°07'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°38'	-1°38'	-2°00' -1°30'
0°03'	0°03'	0°03' 0°07'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°14'	-0°14'	-0°30' 0°30'
0°08'	0°08'	0°02' 0°18'
0°01'	0°01'	-0°04' 0°04'

Print Received Message

This mail is associated with :

***SLX6802U (MCT19050360)**
[SHC8361U]

TP
HAN CHING LIN LUKE

May 14 2019 12:00AM

[-]
Choo Motor Spray Painter

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 26/08/2019 12:52 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8340.00) - SLX6802U - Claim Handler: Zuhaidah Bte Samsuri

Approved:8340.00:Request TP WS to Issue Tax Invoice for Repairs in III's favour

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 May 2019 Edit Reg		14 May 2019 00:00 Edit Adj Rpt	\$57,800.00 Edit Estimates	\$57,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS			[Created by adjuster]
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	HAN CHING LIN LUKE, ID: S7911104Z		
Vehicle Reg. No.:	SLX6802U	Date of Loss:	14/05/2019 00:00 - :59 [102 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT19050360	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHCB361U	Policy No. (Claimant):	MA001991
		Excess:	
Repairer:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 67453897		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]		
Claimant's Insurer:	Etiga Insurance Pte Ltd (HQ) - Tel: 63360477		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 24/05/2019]		

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
- III_SG (26/08/2019): Alert - Adj Mandate Approved (\$58340.00) - SLX6802U - Claim Handler: Zuhaidah Bt... - III_SG (01/07/2019): Alert - Adj Mandate Maintained - SLX6802U - Claim Handler: Zuhaidah Bte Samsuri - III_SG (20/06/2019): Alert - Adj Mandate Approved (\$50.00) - SLX6802U - Claim Handler: Zuhaidah Bte S...			

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SLX6802U (MCT19050360)
[SHC8361U]
TP
HAN CHING LIN LUKE
May 14 2019 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Choo Motor Spray Painter

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/07/19 12:08	General View	 Load JPG	☒
2	01/07/19 12:08	General View	 Load JPG	☒
3	01/07/19 12:08	General View	 Load JPG	☒
4	01/07/19 12:08	General View	 Load JPG	☒
5	01/07/19 12:08	General View	 Load JPG	☒
6	01/07/19 12:08	General View	 Load JPG	☒
7	01/07/19 12:08	General View	 Load JPG	☒
8	01/07/19 12:08	General View	 Load JPG	☒
9	01/07/19 12:08	General View	 Load JPG	☒
10	01/07/19 12:08	General View	 Load JPG	☒
11	01/07/19 12:08	General View	 Load JPG	☒
12	01/07/19 12:08	General View	 Load JPG	☒
13	01/07/19 12:08	General View	 Load JPG	☒
14	01/07/19 12:08	General View	 Load JPG	☒
15	01/07/19 12:08	General View	 Load JPG	☒
16	01/07/19 12:08	General View	 Load JPG	☒
17	01/07/19 12:08	General View	 Load JPG	☒
18	01/07/19 12:08	General View	 Load JPG	☒
19	01/07/19 12:08	General View	 Load JPG	☒
20	01/07/19 12:08	General View	 Load JPG	☒
21	01/07/19 12:08	General View	 Load JPG	☒
22	01/07/19 12:08	General View	 Load JPG	☒
23	01/07/19 12:08	General View	 Load JPG	☒
24	01/07/19 12:08	General View	 Load JPG	☒
25	01/07/19 12:08	General View	 Load JPG	☒
26	01/07/19 12:08	General View	 Load JPG	☒
27	01/07/19 12:08	General View	 Load JPG	☒
28	01/07/19 12:08	General View	 Load JPG	☒
29	01/07/19 12:08	General View	 Load JPG	☒
30	01/07/19 12:08	General View	 Load JPG	☒
31	01/07/19 12:08	General View	 Load JPG	☒
32	01/07/19 12:08	General View	 Load JPG	☒
33	01/07/19 12:08	General View	 Load JPG	☒
34	01/07/19 12:08	General View	 Load JPG	☒
35	01/07/19 12:08	General View	 Load JPG	☒
36	01/07/19 12:08	General View	 Load JPG	☒
37	01/07/19 12:08	General View	 Load JPG	☒
38	01/07/19 12:08	General View	 Load JPG	☒
39	01/07/19 12:08	General View	 Load JPG	☒
40	01/07/19 12:08	General View	 Load JPG	☒
41	01/07/19 12:08	General View	 Load JPG	☒
42	01/07/19 12:08	General View	 Load JPG	☒
43	01/07/19 12:08	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	01/07/19 12:08	General View	 Load JPG	☒
45	01/07/19 12:08	General View	 Load JPG	☒
46	01/07/19 12:08	General View	 Load JPG	☒
47	01/07/19 12:08	General View	 Load JPG	☒
48	01/07/19 12:08	General View	 Load JPG	☒
49	01/07/19 12:08	General View	 Load JPG	☒
50	01/07/19 12:08	General View	 Load JPG	☒
51	01/07/19 12:08	General View	 Load JPG	☒
52	01/07/19 12:08	General View	 Load JPG	☒
53	01/07/19 12:08	General View	 Load JPG	☒
54	01/07/19 12:08	General View	 Load JPG	☒
55	01/07/19 12:08	General View	 Load JPG	☒
56	01/07/19 12:08	General View	 Load JPG	☒
57	01/07/19 12:08	General View	 Load JPG	☒
58	01/07/19 12:09	General View	 Load JPG	☒
59	01/07/19 12:09	General View	 Load JPG	☒
60	01/07/19 12:09	General View	 Load JPG	☒
61	01/07/19 12:09	General View	 Load JPG	☒
62	01/07/19 12:09	General View	 Load JPG	☒
63	01/07/19 12:09	General View	 Load JPG	☒
64	01/07/19 12:09	General View	 Load JPG	☒
65	01/07/19 12:09	General View	 Load JPG	☒
66	01/07/19 12:09	General View	 Load JPG	☒
67	01/07/19 12:09	General View	 Load JPG	☒
68	01/07/19 12:09	General View	 Load JPG	☒
69	01/07/19 12:09	General View	 Load JPG	☒
70	01/07/19 12:09	General View	 Load JPG	☒
71	01/07/19 12:09	General View	 Load JPG	☒
72	01/07/19 12:09	General View	 Load JPG	☒
73	01/07/19 12:09	General View	 Load JPG	☒
74	01/07/19 12:09	General View	 Load JPG	☒
75	01/07/19 12:09	General View	 Load JPG	☒
76	01/07/19 12:09	General View	 Load JPG	☒
77	01/07/19 12:09	General View	 Load JPG	☒
78	01/07/19 12:09	General View	 Load JPG	☒
79	01/07/19 12:09	General View	 Load JPG	☒
80	01/07/19 12:09	General View	 Load JPG	☒
81	01/07/19 12:09	General View	 Load JPG	☒
82	01/07/19 12:09	General View	 Load JPG	☒
83	01/07/19 12:09	General View	 Load JPG	☒
84	01/07/19 12:09	General View	 Load JPG	☒
85	01/07/19 12:09	General View	 Load JPG	☒
86	01/07/19 12:09	General View	 Load JPG	☒
87	01/07/19 12:09	General View	 Load JPG	☒
88	01/07/19 12:09	General View	 Load JPG	☒
89	01/07/19 12:09	General View	 Load JPG	☒
90	01/07/19 12:09	General View	Load JPG	☒
91	01/07/19 12:09	General View	Load JPG	☒
92	01/07/19 12:09	General View	Load JPG	☒
93	01/07/19 12:09	General View	Load JPG	☒
94	01/07/19 12:09	General View	Load JPG	☒
95	01/07/19 12:09	General View	Load JPG	☒
96	01/07/19 12:09	General View	Load JPG	☒
97	01/07/19 12:09	General View	Load JPG	☒
98	01/07/19 12:09	General View	Load JPG	☒
99	01/07/19 12:09	General View	Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	01/07/19 12:09	General View	 Load JPG	☒
101	01/07/19 12:09	General View	 Load JPG	☒
102	01/07/19 12:09	General View	 Load JPG	☒
103	01/07/19 12:09	General View	 Load JPG	☒
104	01/07/19 12:09	General View	 Load JPG	☒
105	01/07/19 12:09	General View	 Load JPG	☒
106	01/07/19 12:09	General View	 Load JPG	☒
107	01/07/19 12:09	General View	 Load JPG	☒
108	01/07/19 12:09	General View	 Load JPG	☒
109	01/07/19 12:09	General View	 Load JPG	☒
110	01/07/19 12:09	General View	 Load JPG	☒
111	01/07/19 12:09	General View	 Load JPG	☒
112	01/07/19 12:09	General View	 Load JPG	☒
113	01/07/19 12:09	General View	 Load JPG	☒
114	01/07/19 12:09	General View	 Load JPG	☒
115	01/07/19 12:09	General View	 Load JPG	☒
116	01/07/19 12:09	General View	 Load JPG	☒
117	01/07/19 12:09	General View	 Load JPG	☒
118	01/07/19 12:09	General View	 Load JPG	☒
119	01/07/19 12:09	General View	 Load JPG	☒
120	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
121	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
122	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
123	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
124	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
125	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
126	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
127	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
128	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
129	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
130	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
131	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
132	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
133	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
134	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
135	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
136	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
137	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
138	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
139	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
140	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
141	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
142	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
143	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
144	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
145	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
146	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
147	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
148	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
149	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
150	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
151	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
152	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
153	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
154	06/07/19 10:13	Reinspection Photo	 Load JPG	☒
155	06/07/19 10:13	Reinspection Photo	 Load JPG	☒

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
156	06/07/19 10:13	Reinspection Photo		Load JPG	☒
157	06/07/19 10:13	Reinspection Photo		Load JPG	☒
158	06/07/19 10:13	Reinspection Photo		Load JPG	☒
159	06/07/19 10:13	Reinspection Photo		Load JPG	☒
160	06/07/19 10:13	Reinspection Photo		Load JPG	☒
161	06/07/19 10:13	Reinspection Photo		Load JPG	☒
162	06/07/19 10:13	Reinspection Photo		Load JPG	☒
163	06/07/19 10:13	Reinspection Photo		Load JPG	☒
164	06/07/19 10:13	Reinspection Photo		Load JPG	☒
165	06/07/19 10:13	Reinspection Photo		Load JPG	☒
166	06/07/19 10:13	Reinspection Photo		Load JPG	☒
167	06/07/19 10:13	Reinspection Photo		Load JPG	☒
168	06/07/19 10:13	Reinspection Photo		Load JPG	☒
169	06/07/19 10:13	Reinspection Photo		Load JPG	☒
170	06/07/19 10:13	Reinspection Photo		Load JPG	☒
171	06/07/19 10:13	Reinspection Photo		Load JPG	☒
172	06/07/19 10:13	Reinspection Photo		Load JPG	☒
173	06/07/19 10:13	Reinspection Photo		Load JPG	☒
174	06/07/19 10:13	Reinspection Photo		Load JPG	☒
175	06/07/19 10:13	Reinspection Photo		Load JPG	☒
176	06/07/19 10:13	Reinspection Photo		Load JPG	☒
177	06/07/19 10:13	Reinspection Photo		Load JPG	☒
178	06/07/19 10:13	Reinspection Photo		Load JPG	☒
179	06/07/19 10:13	Reinspection Photo		Load JPG	☒
180	06/07/19 10:13	Reinspection Photo		Load JPG	☒
181	06/07/19 10:13	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/05/19 20:43	TP GIA REPORT		Load PDF	
2	17/05/19 14:48	TP SAS REPORT		Load PDF	
3	28/06/19 12:20	WORKSHOP INVOICE		Load PDF	
4	28/06/19 12:20	RENTAL RECEIPT		Load PDF	
5	28/06/19 12:20	LOD		Load PDF	
6	09/03/20 10:41	AUTHORISATION TO ACT FORM		Load PDF	
7	09/03/20 10:41	DISCHARGE VOUCHER		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	15/05/19 08:51	Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19008494/UGA3Q2

Date: 09/03/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No: SLX6802U Insured Vehicle No: SHC8361U
 Date of Loss: 14/05/2019 Nature of Claim: TP Claim No: MCT19050360

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX6802U
 Make & Model: BMW M3, 4.0 (A) Engine No: 20994730S65B40A
 Reg. Date: 27/10/2010 (Man. Year: 2010) Chassis No: WBSPM92030E198220
 Colour: Grey Odometer: 93587 km
 Engine Capacity: 3999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35Z R19 Rear Tyre Size: 265/35Z R19
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,096.32	8,422.80	13,673.52	61.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,580.00	1,380.00	1,200.00	46.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,676.32	9,802.80	14,873.52	60.27
Approved Total (Overridden) (S\$)		7,800.00		
Nett Amount (S\$)	24,676.32	7,800.00	16,876.32	68.39
+ Car Rental (3.0 x S\$120.00/day) (S\$)		360.00		
Nett Liability (S\$)		8,160.00		

INSPECTION

Date of Assignment: 14/05/2019
 Date Inspected: 14/05/2019 Inspected At: Choo Motor Spray Painter (HQ)
 1 Kaki Bukit Avenue 6, #01-39
 AutoBay @ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2019)
Parts:	143	BMW M3 4.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX6802U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,566.32 F	*- FL
2	1		*SET FRONT BUMPER CLIPS	Not Necessary	50.00 F	*- FL
3	1		*HEADLAMP N/S	Cracked	3,200.00 F	*2,450.00 FL
4	1		*FRONT FENDER O/S	Repair	988.00 F	*- FL
5	2		*FRONT SHOCK ABSORBER	Serviceable	1,798.00 F	*- FL
6	2		*FRONT WHEEL HUBS	Bent	1,370.00 F	*1,370.00 FL
7	2		*FRONT WHEEL HUB BEARINGS	Damaged	850.00 F	*630.00 FL
8	2		*FRONT KNUCKLE ARMS	Serviceable	2,250.00 F	*- FL
9	2		*FRONT LOWER ARMS	Bent	798.00 F	*798.00 FL
10	2		*FRONT TORSION ARMS	Bent	776.00 F	*776.00 FL
11	1		*FRONT STEERING ASSY	Serviceable	2,650.00 F	*- FL
12	1		*FRONT DOOR VIEW MIRROR SPORT N/S	Cracked / Damaged	1,200.00 FS	*900.00 FS
13	2		*FRONT SPORT RIMS	Dented / Bent	3,600.00 FS	*1,800.00 FS
14	2		*FRONT TYRES	Serviceable	1,000.00 FS	*- FS

F=Franchise part S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,096.32	8,724.00
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	301.20
Total Parts (\$\$)	22,096.32	8,422.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	20.00
2	TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE	New	500.00	240.00
3	TO CONDUCT WHEEL ALIGNMENT	New	150.00	120.00
4	TO SPRAY RUST PROOFING	New	50.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	800.00	400.00
6	TO PUTTY & SPRAY PAINTING	New	1,000.00	600.00
Gross Labour Cost (\$\$)			2,580.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >