

Surveyor:

ASSIGNMENT (Office)

From (Person): Thelma choo

of

SMD

Date/Time: 14.5.19 14.15 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: CB 79014

Insured:

SGX 52375

at Workshop m/s New Hock Teck motor

Tel:

67479241

of 1 Kaki Bukit Ave 6, Bldg C #01-43

Policy No: DIBMTPO01010337

Claim No: CMTD1902224

Sum Insured:

Excess:

Make of Veh:

D.O.A.

8.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time: 14.5.17 2.47pm

Person Contacted:

Sukyi

Vehicle IN / OUT

Date/Time Action/Instruction (✓) Estimate

CB79014-X

SGX 52375-NA/TM112014668/52

D.O.A - 28/03/2012

1615-0930 Sent via merimen pending estimate.

lump sum \$9500 (Red: 30240.70; 76%)

GIA / PR Seen:

Consistent?: Yes or No

L/Bal.

96

mm

L/Bal.

00

mm

Est. Repairs:

10

days

Res.:

Yes or No

D.O.A.

D.O.I.

15/05/15

Lum Sum:

%

3 Val.:

Yes or No

Survey held at

NITT

CA / REV / REP. / 24 HRS

Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Sampo.

RECEIVED 19 JUN 2019

MV:

PV:

Nett:

Date/Time, File Pass to?

1) 1916 Tupi 1st

Date/Time, File Return to?

2)

3)

4)

5)

6)

Preli. Report:

Final Report:

Part Prices Check:

IN

OUT

10 days

Survey Fee:

Date:

Basic & Add.

450

S + RS, SI

11

Photos

Others

TOTAL

461