

ASS. REC. BY:

REF: CS/SM019008496/At d3

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Thelma choo

of

SMD

Date/Time: 14.5.14 14.15 pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: CB 7901H

Insured:

SGX 5237S

at Workshop m/s New Hock Teck motor

Tel:

67479241

of 1 Kaki Bukit Ave 6, BIK C #01-43

Policy No: DIBMTPO1010337

Claim No: CMTD1902224

Sum Insured:

Excess:

Make of Veh:

D.O.A. 8.5.2014

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time: 14.5.14 2.47 pm

Person Contacted: Suky

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	CB7901H - X
	SGX 5237S - NA/TMI12014668152 D.O.A - 28/01/2012
16/5-0938	Sent via merimen pending estimate.
	lump sum \$9500 (Red: 30240.70; 76%)

ASS. REC BY:

REF:

ASSIGNMENT

Adrian

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Pottery Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: CB7901H Yr Regn: 2017 / April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Mini Bus

Make: Toyota Regius Ace c.c 2982

Colour Silver A/C: Insured / Std / NI / NA

Sp.Reading 46862 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KDH201205776

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/80R15

R: 195/80R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 15/05/15

Survey held at NHT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Sampo.

RECEIVED 19 JUN 2019

MV:

PV:

Nett:

Date/Time, File Pass to?

1) 19/6 TUP1ST

3) _____

5) _____

Prel. Report:

Final Report:

Date/Time, File Return to?

2) _____

4) _____

6) _____

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add. _____ S + RS. _____ SI

Photos

Others

TOTAL

Date:

450

11

461

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 May 2019		14 May 2019 14:15 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ONG YEW TIAN, ID: S6940831A, Tel: +6597511609, Email: oyt1969@gmail.com								
Main Claimant:	LIONG HWEE KEE, ID: S7103807F								
Vehicle Reg. No.:	CB7901H	Date of Loss:	08/05/2019 07:00 - :59						
Claim Type:	TP / CMTD1902224	Policy/Cover Note No.:	D18MTPV01010337 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGX5237S	Policy No. (Claimant):							
		Excess:							
Repairer:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/05/2019]								
Driver/Custodian (Insured):	ONG YEW TIAN (49 / Male), NRIC: S6940831A, Tel: +6597511609 Email: oyt1969@gmail.com								
Adj Asg. Remarks:	WS: REENE/ Sukyi 67479241								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***CB7901H (CMTD1902224)**
[SGX52375]

TP
LIONG HWEE KEE
May 8 2019 7:00AM
[ONG YEW TIAN]
New Hock Teck Motor Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 16/05/2019 09:38 AM.
To thelma.choo@sompo.com.sg
Subject

Dear Sir/Madam,

Please be informed that we have inspected the vehicle CB 7901H on 15/05/2019.
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 08/05/2019 10:52
 Date Of Accident 08/05/2019 07:15
 Exact Location Of Accident BARTLEY ROAD OUTSIDE MARIS STELLA HIGH SCHOOL
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number CB7901H
Insured/Policyholder
 Name Of Registered Owner LIONG HWEE KEE
 NRIC No S7103807F
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-96860649
 Alternative Phone No OTHERS-96860649

Vehicle Particulars

Manufacturer TOYOTA
 Model REGIUS-3.0 D LXH43 (A)
 Exact Purpose for which vehicle was being used at time of accident COMMERCIAL USE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category BUS

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 5089666996-02
 Cover Note Number COMPREHENSIVE

Driver

Name of Driver LIONG HWEE KEE
 NRIC No S7103807F
 Date Of Birth 13/02/1971
 Occupation INDOOR
 Date Of Driving Pass 28/07/1994
 Driving Experience 24 YEARS AND 9 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-96860649
 Fax Number
 Contact Number
 EMail Address NOEMAIL

Address	BLK 144 RIVERVALE DRIVE #12-547
Postcode	540144
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I STOPPED MY VEHICLE DUE TO HEAVY TRAFFIC WHEN VEHICLE B HIT INTO THE REAR PORTION OF MY VEHICLE AND PROPELLED MY VEHICLE TO HIT INTO THE REAR PORTION OF VEHICLE C.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGX5237S
Vehicle Make/Model/Colour	SILVER MERCEDES
Details Of Properties	FRONT PORTION
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKR5380U
-----------------------------	----------

Vehicle Make/Model/Colour

BLACK HONDA FREED

Details Of Properties

REAR PORTION

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

References 511

12464

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"; the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurers who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonable required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, law or court orders



8/5/2019 11:14

Policyholder's Signature
Date & Time:

6/25/2019 11:14


Driver's Signature (if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: Eric Woo Jun Kiat
NRIC/ Fin No: S992753

Sketch Plan Pg. 2

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I STOPPED MY VEHICLE DUE TO HEAVY TRAFFIC WHEN VEHICLE B HIT INTO THE REAR PORTION OF MY VEHICLE AND PROPELLED MY VEHICLE TO HIT INTO THE REAR PORTION OF VEHICLE C.

DECLARATION

I/We declare the foregoing particulars are true in every respect


 Policyholder's Signature
 Date & Time: 8/5/2019 11:14


 Driver's Signature (if driver is not the policyholder)
 Date & Time: 8/5/2019 11:14


 Reporting Centre Personnel's Signature
 Name: Eric Woo Jun Kiat
 NRIC/ Fin No: S992753

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 3807F

Vehicle Details

Vehicle No.: CB7901H
Vehicle to be Exported: No
Intended Deregistration Date: 14 May 2019
Vehicle Make: TOYOTA
Vehicle Model: REGIUS ACE DX 3.0 AUTO
Primary Colour: Silver
Manufacturing Year: 2016
Engine No.: 1KD2650069
Chassis No.: KDH2010205776
Maximum Power Output: -
Open Market Value: \$37,517.00
Original Registration Date: 07 Apr 2017
First Registration Date: 07 Apr 2017
Transfer Count: 0
Actual ARF Paid: \$1,876.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Rebate Amount: \$0.00
Total Rebate Amount: \$0.00

The information contained herein is correct as at 14 May 2019

OK



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

LIONG HWEE KEE

16/05/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Somp
Denise

Accident date: 08/05/2019

Estimated repair cost for vehicle no: CB7901H TOYOTA REGIUS ACE 3.0 A '17

CHASSIS: KDH2010205776

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>Dented</i>		\$844.60
2	1	Front Bonnet Emblem Logo <i>new</i>		\$79.90
3	1	Front Bonnet Lock <i>new</i>		\$98.90
4	2	Front Head Lamp <i>fit</i>	\$898.90	\$1,797.80
5	1	Front Bumper <i>Deformed</i>		\$458.90
6	8	Front Bumper Clip <i>new</i>	\$6.50	\$52.00
7	2	Front Bumper Side Retainer <i>new</i>	\$179.90	\$359.80
8	1	Front Bumper Center Garnish <i>new</i>		\$274.45
9	1	Front Bumper Reinforcement <i>new</i>		\$328.90
10	2	Front Bumper Reinforcement Side Bracket <i>new</i>	\$174.90	\$349.80
11	1	Front Bumper <i>Upper</i> Reinforcement <i>Bent</i>		\$279.80
12	2	Front Bumper Fog Lamp <i>new</i>	\$335.00	\$670.00
13	1	Front Support Panel <i>new</i>		\$329.90
14	2	Front Support Panel Air Cover <i>new</i>	\$149.70	\$299.40
15	1	Front Air-Con Condenser <i>new</i>		\$1,686.00
16	1	Front Air-Con Section Pipe <i>new</i>		\$301.30
17	1	Front Air-Con Discharge Pipe <i>new</i>		\$282.60
18	1	Front Radiator		\$1,897.60
19	1	Front Radiator Fan Motor Assy		\$774.50
20	1	Front Air Cleaner Box Assy <i>new</i>		\$972.80
21	1	Front Air Cleaner Box Top Hose		\$172.10
22	1	Front Intercoolant <i>new</i>		\$1,712.10
23	1	Rear Boot Lid <i>Distorted</i>		\$1,712.45
24	2	Rear Boot Lid Hinge <i>new</i>	\$171.70	\$343.40
25	2	Rear Boot Lid Shock Absorber <i>new</i>	\$281.90	\$563.80
26	1	Rear Boot Lid Emblem Logo <i>new</i>		\$51.10
27	1	Rear Boot Lid RegiusACE Sticker <i>new</i>		\$63.70
28	1	Rear Boot Lid Centre Moulding <i>Crushed</i>		\$261.60

29	1	Rear Boot Lid Number Plate	new		\$50.00	+
30	2	Rear Boot Lid Number Plate Lamp	new	\$83.10	\$166.20	+
31	1	Rear Boot Lid Inner Lock	Damaged		\$374.25	✓
32	1	Rear Boot Lid Inner Lock Cover	new		\$162.00	+
33	1	Rear Boot Lid Inner Power Lock Motor	Damaged		\$581.45	✓
34	1	Rear Boot Lid Inner Rubber	new		\$281.35	✓
35	1	Rear Boot Lid Inner Trim Board	new		\$372.25	+
36	10	Rear Boot Lid Inner Trim Board Clip	new	\$6.50	\$65.00	+
37	1	Rear Boot Lid Windscreen Seal	new		\$105.00	✓
38	2	Rear Tail Lamp	new	\$374.45	\$748.90	✓
39	2	Rear Tail Lamp Lower Cover	new	\$182.10	\$364.20	x
40	2	Rear Tail Lamp Lower Cover Retainer	new	\$171.45	\$342.90	x
41	1	Rear Bumper	new		\$595.00	✓
42	10	Rear Bumper Clip	new	\$6.50	\$65.00	30
43	2	Rear Bumper Side Retainer	new	\$121.25	\$242.50	✓
44	1	Rear Bumper Centre Step Panel	new		\$271.85	✓
45	1	Rear End Panel Outer	Damaged		\$591.60	✓
46	1	Rear End Panel Inner	Damaged		\$781.90	✓
47	2	Rear Fender Air Duct	new	\$131.25	\$262.50	✓
48	2	Rear Fender Inner Trim Board	new	\$363.00	\$726.00	+
49	16	Rear Fender Inner Trim Board Clip	new	\$6.50	\$104.00	+
50	1	Rear Floor Panel	new		\$1,972.85	+
51	1	Rear Floor Panel Top Moulding	new		\$274.45	+
52	8	Rear Floor Panel Top Moulding Clip	new	\$6.50	\$52.00	+
53	1	Rear Spare Tyre Bracket	new		\$243.10	✓
54	1	Rear Exhaust	new		\$1,712.65	+
55	2	Rear Exhaust Mounting	new	\$61.75	\$123.50	+
56	1	Rear Centre Exhaust	new		\$1,829.10	+
57	4	Rear Bumper Lower Bracket	new	45 180 ✓		
				1062675	Subtotal :-	\$30,480.70
				797006		

S/n	Qty	Items / Special	Nett	U/price	Amount	
57	1	Front Bumper Number Plate	new		\$50.00	✓
58	1	Front Grille	new		\$1,600.00	650
59	1	Rear Boot Lid Number Plate	new		\$50.00	+
60	1	Rear Boot Lid 70km/H Sticker	new		\$20.00	10
61	1	Rear Boot Lid AWC ROV Sticker	new		\$30.00	20
62	1	Rear Boot Lid Limit 1250KG Sticker	new		\$20.00	✓
63	1	Rear Bumper Reverse Sensor	new		\$350.00	200
64	1	Rear Floor Panel Plywood	new		\$650.00	+
65	1	Rear Floor Panel Carpet	new		\$850.00	+

950 Subtotal :- \$3,620.00

Labour charges

To remove & refit air-con condenser, radiator, fan motor & top up gas	\$380.00 X
To remove & refit plywood & carpet	\$280.00 X
To remove & refit roof lining	\$280.00 X
To remove & refit reverse sensor	\$100.00 50
To remove & refit rear windscreen	\$120.00 ✓
Gum NEC	\$50.00 ✓
To remove & refit rear & center exhaust	\$380.00 80
To check wiring	\$100.00 60
Tuff kote	\$150.00 60
Panel beating	\$1,800.00 1500
Spray painting	\$2,000.00 1000.
To remove and refit rear camera 50 100	

Subtotal :- \$5,640.00

Total:- \$39,740.70

39920.70

total: 11850.06
45: 9.5K

10 Days

9.5K

10 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19008496/ATD3N2
Date: 26/06/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01010337
Claimant Vehicle No :	CB7901H	Insured Vehicle No :	SGX5237S
Date of Loss:	08/05/2019	Nature of Claim:	TP
		Claim No:	CMTD1902224

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	CB7901H	Engine No:	1KD2650069
Make & Model:	TOYOTA REGIUS, 3.0 D LXH43 (A)	Chassis No:	KDH2010205776
Reg. Date:	07/04/2017 (Man. Year: 2016)	Odometer:	46962 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80 R15	Rear Tyre Size:	195/80 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	34,330.70	9,048.81	25,281.89	73.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,590.00	2,870.00	2,720.00	48.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	39,920.70	11,918.81	28,001.89	70.14
Approved Total (Overridden) (\$\$)		9,500.00		
(\$\$)	39,920.70	9,500.00	30,420.70	76.20
+ GST 7.00/7.00% (\$\$)	2,794.45	665.00	2,129.45	76.20
Nett Amount (\$\$)	42,715.15	10,165.00	32,550.15	76.20

INSPECTION

Date of Assignment:	14/05/2019
Date Inspected:	15/05/2019 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
1 Kaki Bukit Ave 6, Blk C #01-43
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Jun 2019)	
Parts:	N/A	TOYOTA REGIUS 3.0 D LXH43 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for CB7901H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BONNET	Dented	844.60 F	*844.60 FL
2	1	*FRONT BONNET EMBLEM LOGO	Necessary	79.90 F	*79.90 FL
3	1	*FRONT BONNET LOCK	Not Necessary	98.90 F	*- FL
4	2	*FRONT HEAD LAMP	Cut	1,797.80 F	*1,797.80 FL
5	1	*FRONT BUMPER	Deformed	458.90 F	*458.90 FL
6	8	*FRONT BUMPER CLIP	Necessary	52.00 F	*30.00 FL
7	2	*FRONT BUMPER SIDE RETAINER	Necessary	359.80 F	*125.00 FL
8	1	*FRONT BUMPER CENTER GARNISH	Not Necessary	274.45 F	*- FL
9	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	328.90 F	*- FL
10	2	*FRONT BUMPER REINFORCEMENT SIDE BRACKET	Not Necessary	349.80 F	*- FL
11	1	*FRONT BUMPER UPPER REINFORCEMENT	Bent	279.80 F	*279.80 FL
12	2	*FRONT BUMPER FOG LAMP	Not Necessary	670.00 F	*- FL
13	1	*FRONT SUPPORT PANEL	Not Necessary	329.90 F	*- FL
14	2	*FRONT SUPPORT PANEL AIR COVER	Not Necessary	299.40 F	*- FL
15	1	*FRONT AIR-CON CONDENSER	Not Necessary	1,686.00 F	*- FL
16	1	*FRONT AIR-CON SECTION PIPE	Not Necessary	301.30 F	*- FL
17	1	*FRONT AIR-CON DISCHARGE PIPE	Not Necessary	282.60 F	*- FL
18	1	*FRONT RADIATOR	Not Necessary	1,897.60 F	*- FL
19	1	*FRONT RADIATOR FAN MOTOR ASSY	Not Necessary	774.50 F	*- FL
20	1	*FRONT AIR CLEANER BOX ASSY	Not Necessary	972.80 F	*- FL
21	1	*FRONT AIR CLEANER BOX TOP HOSE	Not Necessary	172.10 F	*- FL
22	1	*FRONT INTERCOOLANT	Not Necessary	1,712.10 F	*- FL
23	1	*REAR BOOT LID	Distorted	1,712.45 F	*1,712.45 FL
24	2	*REAR BOOT LID HINGE	Not Necessary	343.40 F	*- FL
25	2	*REAR BOOT LID SHOCK ABSORBER	Not Necessary	563.80 F	*- FL
26	1	*REAR BOOT LID EMBLEM LOGO	Necessary	51.10 F	*51.10 FL
27	1	*REAR BOOT LID REGIUS ACE STICKER	Necessary	63.70 F	*63.70 FL
28	1	*REAR BOOT LID CENTRE MOULDING	Cracked	261.60 F	*261.60 FL
29	1	*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
30	2	*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	166.20 F	*- FL
31	1	*REAR BOOT LID INNER LOCK	Damaged	374.25 F	*374.25 FL
32	1	*REAR BOOT LID INNER LOCK COVER	Not Necessary	162.00 F	*- FL
33	1	*REAR BOOT LID INNER POWER LOCK MOTOR	Damaged	581.45 F	*581.45 FL
34	1	*REAR BOOT LID INNER RUBBER	Cut	281.35 F	*281.35 FL
35	1	*REAR BOOT LID INNER TRIM BOARD	Not Necessary	372.25 F	*- FL
36	10	*REAR BOOT LID INNER TRIM BOARD CLIP	Not Necessary	65.00 F	*- FL
37	1	*REAR BOOT LID WINDSCREEN SEAL	Necessary	105.00 F	*105.00 FL
38	2	*REAR TAIL LAMP	Cracked	748.90 F	*748.90 FL
39	2	*REAR TAIL LAMP LOWER COVER	Repair	364.20 F	*- FL
40	2	*REAR TAIL LAMP LOWER COVER RETAINER	Not Necessary	342.90 F	*- FL
41	1	*REAR BUMPER	Deformed	595.00 F	*595.00 FL
42	10	*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
43	2	*REAR BUMPER SIDE RETAINER	Necessary	242.50 F	*242.50 FL
44	1	*REAR BUMPER CENTRE STEP PANEL	Bent	271.85 F	*271.85 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*REAR END PANEL OUTER	Dented	591.60 F	*591.60 FL
46	1	*REAR END PANEL INNER	Dented	781.90 F	*781.90 FL
47	2	*REAR FENDER AIR DUCT	Not Necessary	262.50 F	*- FL
48	2	*REAR FENDER INNER TRIM BOARD	Not Necessary	726.00 F	*- FL
49	16	*REAR FENDER INNER TRIM BOARD CLIP	Not Necessary	104.00 F	*- FL
50	1	*REAR FLOOR PANEL	Repair	1,972.85 F	*- FL
51	1	*REAR FLOOR PANEL TOP MOULDING	Not Necessary	274.45 F	*- FL
52	8	*REAR FLOOR PANEL TOP MOULDING CLIP	Not Necessary	52.00 F	*- FL
53	1	*REAR SPARE TYRE BRACKET	Bent	243.10 F	*243.10 FL
54	1	*REAR EXHAUST	Repair	1,712.65 F	*- FL
55	2	*REAR EXHAUST MOUNTING	Not Necessary	123.50 F	*- FL
56	1	*REAR CENTRE EXHAUST	Not Necessary	1,829.10 F	*- FL
57	4	*REAR BUMPER LOWER BRACKET	Bent	180.00 F	*180.00 FL
58	1	*FRONT BUMPER NUMBER PLATE	Cracked	50.00 FS	*50.00 FS
59	1	*FRONT GRILLE	Cracked	1,600.00 FS	*650.00 FS
60	1	*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 FS	*- FS
61	1	*REAR BOOT LID 70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
62	1	*REAR BOOT LID AWC ROV STICKER	Necessary	30.00 FS	*20.00 FS
63	1	*REAR BOOT LID LIMIT 1250KG STICKER	Necessary	20.00 FS	*20.00 FS
64	1	*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
65	1	*REAR FLOOR PANEL PLYWOOD	Not Necessary	650.00 FS	*- FS
66	1	*REAR FLOOR PANEL CARPET	Not Necessary	850.00 FS	*- FS
67	1	*GUM	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	34,330.70	11,731.75
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	2,682.94
Total Parts (\$\$)	34,330.70	9,048.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT AIR-CON CONDENSER,RADIATOR,FAN MOTOR & TOP UP GAS	New	380.00	0.00
2	TO REMOVE & REFIT PLYWOOD & CARPET	New	280.00	0.00
3	TO REMOVE & REFIT ROOF LINNING	New	280.00	0.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
6	TO REMOVE & REFIT REAR & CENTER EXHAUST	New	380.00	80.00
7	TO CHECK WIRING	New	100.00	60.00
8	TUFF KOTE	New	150.00	60.00
9	PANEL BEATING	New	1,800.00	1,500.00
10	SPRAY PAINTING	New	2,000.00	1,000.00
Gross Labour Cost (\$\$)			5,590.00	2,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >