



19 Lorong 8 Toa Payoh  
Singapore 319255



**ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR**

<b>REG NO: SFY5276K</b>	<b>MODEL : FORESTER 2.0I-L AWD CVT</b>
<b>REF NO: INS/IC/CHI/200/2019</b>	<b>YEAR: 28-OCT-2016</b>
<b>ENGINE NO: FB20Y448269</b>	<b>CHASSIS NO: JF1SJ5KC5GG078958</b>
<b>DOA: 13/05/2019</b>	<b>TOA: 0720HRS</b>
<b>TYPE OF CLAIM: 3RD PARTY</b>	<b>INS COMPANY: FWD</b>

<b>S/N</b>	<b>NATURE OF JOB</b>	<b>AMOUNT</b>
1.	REPAIR/REPLACE REAR BUMPER & END PANEL	\$2240.00
2.	RESPRAY REAR BUMPER & END PANEL	\$1680.00
3.	TO CONDUCT REAR LIGHTING TEST	\$50.00
4.	TO SUPPLY & INSTALL REVERSE SENSOR – 2 EYES	\$300.00
5.	SUNDRIES	\$100.00
6.		
7.		
8.		
9.		
10.		
	<b>Total Labour</b>	<b>\$4370.00</b>

<b>DATE APPROVAL:</b>	
<b>TIME APPROVAL:</b>	
<b>SURVEY BY:</b>	
<b>HP / EMAIL:</b>	/
<b>BEFORE PAINT:</b>	
<b>DAYS GIVEN:</b>	

### Estimate

Date 05 / 14 / 2019

001 / 001

Name	QUOTATION FOR SFY5276K	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ5DK7C
		Vin-Code	JF1SJ5KC5GG078958

Part Number	Part Code Name	Part Code	Q'ty	Price
57704SG012	BUMPER-FACE,REAR	FIG-591 57704A	1	540.00
57711SG0219P	BACK BEAM COMPLETE-REAR	FIG-591 57711D	1	288.00
E7710SG000	R BUMPER STEP S/S	FIG-591 57711D	1	460.00
57707SG080	BRACKET-REAR BUMPER SIDE,RIGHT	FIG-591 57707H	1	14.40
57707SG090	BRACKET-REAR BUMPER SIDE,LEFT	FIG-591 57707I	1	14.40
57707SG060	BRACKET-REAR BUMPER CORNER,RIG HT	FIG-591 57707AC	1	18.00
57707SG070	BRACKET-REAR BUMPER CORNER,LEF T	FIG-591 57707AD	1	18.00
57731SG010NN	COVER-REAR BUMPER	FIG-591 57731C	1	12.60
84281SC000	REFLEX REFLECTOR ASSEMBLY-RIGH T	FIG-842 84281	1	20.40
84281SC010	REFLEX REFLECTOR ASSEMBLY-LEFT	FIG-842 84281A	1	20.40
		Page-Total		1,406.20
		Sub-Total		1,406.20
		Total		1,406.20
		Tax		0.00
		Grand Total		1,406.20

Memo

Grand Total
1,406.20

--

Tel
-----