

ASS. REC. BY:

REF: CS/SMO19008500/JV d3

Special Instruction:

Surveyor: Hwu Jie**ASSIGNMENT (Office)**From (Person): melvin yeof SmoDate/Time: 14.5.19 1244 P.m

Estimated Cost: _____

Bill to: _____

OD / FP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJG 949HInsured: SJY 871Cat Workshop m/s Yew Tee AutomobileTel: 6765 3573of BK 6 woodland Road 399 FPolicy No: D18MTPV01018700Claim No: CMTD 1902255

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 9.5.2019

(Client's Record)

Apr 10.30am 0/writing

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement: _____

Date/Time: 14.5.19 1.32p.mPerson Contacted: VinixVehicle IN/OUT

Date/Time Action/Instruction (✓) Estimate

SJG 949H - XSJY 871C - X17/5/19Send preli revised via merimen

05/11/19

REF: SMO

Surveys: Hru Jie

ASSIGNMENT

From:

Date: 15.5.2019

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJG 949H

at Workshop m/s Yew Tee Automobile

of B1K 6 woodland Road 379 F

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh: After 10:30 A.M owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "up"

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SJG 949H

Yr Regn: 20 Jun 2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Airwave

C.C. 1496

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

125949

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GJ11208333

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 9/5/19

D.O.I. 15/5/19

Survey held at

Yew tee Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - \$24000

PV - \$15699

NV - \$8301

18/6/19 Continued L/S \$3100/- 5 days of repair. (Red 8965-88, 749)

RECEIVED 18 JUN 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

18/6 - typist

Report Format:

merimen

Lump Sum / I.B.I. (\$

3100/-

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, St

Photos

Others

TOTAL

350

11

361

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Melvin Ye	Date: 17 May 2019

Preliminary Advice

Insured Vehicle No	: SJY871C	Accident Date	: 09/05/2019
TP Vehicle No	: SJG949H	Assignment Date	: 14/05/2019
Make	: HONDA AIRWAVE	Est. Duration of Repair	: 5
Date of Inspection	: 15/5/2019		
Inspection At	: YEW TEE AUTOMOBILE TECH PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,065.88
Revised Amount	:S\$	3,901.08
Check Items (Estimated)	:S\$	2,500.36
Total	:S\$	6,401.44

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The above survey was conducted on a 'Without Prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 May 2019		14 May 2019 12:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAN CHOONG THEN, ID: S7273994I, Tel: +6597246393, Email: choong_then_tan@yahoo.com								
Main Claimant:	FATHIAH BINTE BORHAN, ID: S8522694J								
Vehicle Reg. No.:	SJG949H	Date of Loss:	09/05/2019 07:00 - :59						
Claim Type:	TP / CMTD1902255	Policy/Cover Note No.:	D18MTPV01018700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJY871C	Policy No. (Claimant):							
		Excess:							
Repairer:	Yew Tee Automobile Tech Pte Ltd (HQ) Blk 6 Woodlands Road 399F,, Yew Tee Ind Estate, 678006 Woodlands - Tel: 67622081								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Melvin Ye - 6322 4667]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/05/2019]								
Driver/Custodian (Insured):	TAN CHOONG THEN (46 / Male) , NRIC: S7273994I, Tel: +6597246393 Email: choong_then_tan@yahoo.com								
Adj Asg. Remarks:	WS: VINNIE 6765 3373								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Hwee Jie (LKK Auto)
Sent: Tuesday, 18 June 2019 9:32 AM
To: YT(HQ)
Cc: Veron Chen (LKKAUTO)
Subject: RE: SJG949H Finalize

Hi,

Finalized L/S \$3,100/- 5days of repair.

Best Regards,

Hwee Jie | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 9180 3151 | Email: Hweejie@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: YT(HQ) [mailto:info@yewteegroup.com]
Sent: Tuesday, 18 June, 2019 9:29 AM
To: Hwee Jie (LKK Auto)
Subject: SJG949H Finalize

Hi Hwee Jie,

Attached as per requested.

Thank you

Best Regards

Vinnie Lim



Yew Tee Automobile Tech Pte Ltd

HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 /6764 9042 Fax: 6760 4895

Email: utauto@singnet.com.sg

Branch Office:

Synergy@KB, 25 Kaki Bukit Road

Unit No #01-60/61

Singapore 417800

DID: 6702 3113

Email: utauto2@singnet.com.sg

Branch Office:

39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856

DID:62562081

Email: info@yewteegroup.com



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

Pixel 3a

Get a free Google Home Mini with every Pixel 3a or Pixel 3a XL purchase. Terms apply. Google Store

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

May 2015 Mercedes-Benz C-Class C180 Avantgarde



Cheapest Car In Market!
Owner: Full Servicing By C&C
No. New Car Condition
Auto Zoom Enterprise

• Free VICOM evaluation
 • Free grooming and 6 months maintenance
 • In-house workshop ensures quality service
 • Member of SVTA and hire purchase association
 • 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted 20 results/page

19 vehicles

Honda Airwave

Advanced Search

	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Airwave	Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Honda Airwave 1.5A M (COE till 10/2022) Elegant Silver, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In House Loan Packages Available. Prime Motor & Leasing Posted: 10-May-2019 Tags: 2007 Honda Airwave, 2007 honda airwave, Honda Airwave, honda airwave, Honda, Airwave, airwave, Used Honda	\$20,800	\$6,000 /yr	27-Oct-2007	1,496 cc	-	Stationwagon	Available
	Honda Airwave 1.5A M (COE till 04/2024) New Paintwork And Leather Seat. Superbly Well Maintained By Previous Fussy Owner. Gear Box And Engine Still In Excellent State. Quiet Undercarriage. No Further Repair Needed. Warranty Provided. Flexib... SmartCars Boutique Pte Ltd Posted: 10-May-2019 Tags: 2009 Honda Airwave, 2009 honda airwave, Honda Airwave, honda airwave, Honda, Airwave, airwave, Used Honda	\$29,800	\$5,990 /yr	05-May-2009	1,496 cc	107,156 km	Stationwagon	Available
	Honda Airwave 1.5A M (COE till 05/2028) Well Maintained. Regularly Servicing Done. No Repair Needed. Good To Go For The Many Years To Come. Lowest Depreciation Possible. Safe Buy With High Paper Value. \$4k Plus Per Year. Posted: 10-May-2019 Tags: 2008 Honda Airwave, 2008 honda airwave, Honda Airwave, honda airwave, Honda, Airwave, airwave, Used Honda	\$43,833	\$4,850 /yr	21-May-2008	1,496 cc	-	Stationwagon	Available
	Honda Airwave 1.5A M Skyroof (New 5-yr COE) Spacious Skyroof Model White Airwave! Purchase Comes With 6 Months Warranty, Full Loan, Bank And In House Finance Options Available! New Paintwork, 4 New Absorbers & Mountings Changed! What Else To Wor... Posted: 09-May-2019 Tags: 2009 Honda Airwave, 2009 honda airwave, Honda Airwave, honda airwave, Honda, Airwave, airwave, Used Honda	\$29,800	\$5,950 /yr	27-Apr-2009	1,496 cc	112,000 km	Stationwagon	Available
GET YOUR COE RENEWAL LOAN Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.								
	Honda Airwave 1.5A M Skyroof (COE till 08/2023) 100% Guaranteed Accident-Free, Well Maintained, Wear And Tear Replaced, 90% Loan At 3.18%, Guaranteed Loan For Bad Credit/Ex Bankruptcy, View After Lunch Till 11PM Daily, Please Call To Arrange Viewin... Posted: 09-May-2019 Tags: 2008 Honda Airwave, 2008 honda airwave, Honda Airwave, honda airwave, Honda, Airwave, airwave, Used Honda	\$25,800	\$5,980 /yr	13-Oct-2008	1,496 cc	138,000 km	Stationwagon	Available
	Honda Airwave 1.5A M Skyroof (New 5-yr COE) High Loan For COE Renewal Available! Well Kept And Maintained By 1 Owner, Original Paintwork With Clean And Neat Interior! 100% Loan Approval With Our Flexible In House Financing Options. All Enquire... Posted: 07-May-2019 Tags: 2009 Honda Airwave, 2009 honda airwave, Honda Airwave, honda airwave, Honda, Airwave, airwave, Used Honda	\$31,800	\$6,350 /yr	28-Apr-2009	1,496 cc	102,900 km	Stationwagon	Available
	Honda Airwave 1.5A M Skyroof (COE till 08/2023) 100% Guaranteed Accident-Free, Well Maintained, Wear And Tear Replaced, 90% Loan At 3.18%, Guaranteed Loan For Bad Credit/Ex Bankruptcy, View After Lunch Till 11PM Daily, Please Call To Arrange Viewin... Posted: 09-May-2019 Tags: 2008 Honda Airwave, 2008 honda airwave, Honda Airwave, honda airwave, Honda, Airwave, airwave, Used Honda	\$24,800	\$6,760 /yr	10-Jan-2008	1,496 cc	-	Stationwagon	Available

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2694J
Vehicle Details	
Vehicle No.:	SJG949H
Vehicle to be Exported:	No
Intended Deregistration Date:	17 May 2019
Vehicle Make:	HONDA
Vehicle Model:	AIRWAVE 1.5M CVT
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	L15A5159865
Chassis No.:	GJ11208333
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$14,057.00
Original Registration Date:	20 Jun 2008
First Registration Date:	20 Jun 2008
Transfer Count:	1
Actual ARF Paid:	\$14,057.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jun 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$19,107.00
COE Rebate Amount:	\$15,625.00
Total Rebate Amount:	\$15,625.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 17 May 2019

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Singapore NRIC

Owner ID:

2694J

Vehicle Details

Vehicle No.:

SJG949H

Vehicle to be Exported:

Yes

Intended Deregistration Date:

10 May 2019

Vehicle Make:

HONDA

Vehicle Model:

AIRWAVE 1.5M CVT

Primary Colour:

Silver

Manufacturing Year:

2008

Engine No.:

L15A5159865

Chassis No.:

GJ11208333

Maximum Power Output:

81.0 kW (108 bhp)

Open Market Value:

\$14,057.00

Original Registration Date:

20 Jun 2008

First Registration Date:

20 Jun 2008

Transfer Count:

1

Actual ARF Paid:

\$14,057.00

Intended PARF Rebate Details

PARF Eligibility:

Forfeited

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

19 Jun 2023

COE Category:

A - Car (1600cc & below)

COE Period(Years):

5

PQP Paid:

\$19,107.00

COE Rebate Amount:

\$15,699.00

Total Rebate Amount:**\$15,699.00****Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 May 2019

OK

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : SOMPO INSURANCE SINGAPORE PTE LTD

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	YTHQ/TP/1905/007
Policy No:	PNPV2018-00007437	Date of Loss:	09/05/2019
Vehicle Reg. No.:	SJG949H	Driveable?	yes
Driver Age:		Third Party Vehicle No.:	SJY871C
Any Injuries?	no	Contact No:	
Insured/Claimant:	FATHIAH BINTE BORHAN	Driver:	HIRWAN BIN SAINI

Make/Model:	Honda, Airwave	Vehicle Reg. Date:	20/06/2008
Vehicle Colour:	SILVER	Engine Number:	
Chassis No:	GJ11208333	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss: COLLISION - HEAD TO REAR
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

	Amount
Parts	8,100.88
Miscellaneous Items	470.00
Labour	2,270.00
Paintwork Labour	1,225.00
Towing	0.00
Gross Total(S\$):	12,065.88
GST 7.00%(S\$):	844.61
Nett Amount(S\$):	12,910.49

This claim is handled by: Sky Toh T C

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER CRA /	0.00	1,078.50	-20.00	862.80 ✓
2	1	REAR BUMPER SIDE RETAINER LH nxx	0.00	25.00	-20.00	20.00
3	1	REAR BUMPER SIDE RETAINER RH nxx	0.00	25.00	-20.00	20.00
4	2	REAR NUMBER PLATE LAMP nxx	0.00	77.20	-20.00	61.76
5	1	REAR TAILGATE BUC /	0.00	1,382.50	-20.00	1,106.00 ✓
6	1	REAR TAILGATE LOWER PROTECTOR DEF /	0.00	451.50	-20.00	361.20 ✓
7	1	REAR TAILGATE LOCK SVC X	0.00	138.50	-20.00	110.80
8	1	REAR TAILGATE LOCK CATCH nxx	0.00	24.20	-20.00	19.36
9	1	REAR TAILGATE RUBBER nxx	0.00	191.50	-20.00	153.20
10	1	REAR TAILGATE INNER BOARD nxx	0.00	401.20	-20.00	320.96
11	1	REAR TAILGATE AIRWAVE EMBLEM rec /	0.00	27.40	-20.00	21.92 ✓
12	1	REAR TAILGATE REFLECTOR LH nxx	0.00	245.20	-20.00	196.16
13	1	REAR TAILGATE REFLECTOR RH ? nxx	0.00	245.20	-20.00	196.16
14	1	REAR TAILGATE OUTER CHROME GARNISH ? nxx	0.00	288.00	-20.00	230.40
15	1	REAR WINDSCREEN GLASS MOULDING rec /	0.00	80.20	-20.00	64.16 ✓
16	1	REAR TAILLAMP LH nxx	0.00	258.00	-20.00	206.40
17	1	REAR TAILLAMP RH nxx	0.00	258.20	-20.00	206.56
18	1	REAR TAILLAMP PANEL LH nxx	0.00	130.00	-20.00	104.00
19	1	REAR TAILLAMP PANEL RH ? nxx	0.00	130.00	-20.00	104.00
20	1	REAR EXHAUST PIPE nxx	0.00	280.90	-20.00	224.72
21	1	REAR EXHAUST SILENCER nxx	0.00	750.00	-20.00	600.00
22	1	REAR EXHAUST HEAT SHIELD nxx	0.00	80.10	-20.00	64.08
23	1	REAR END PANEL ? nxx	0.00	508.70	-20.00	406.96
24	1	REAR END PANEL INNER GARNISH ? nxx	0.00	138.60	-20.00	110.88
25	1	REAR FENDER LH nxx	0.00	0.00	0.00	0.00
26	1	REAR FENDER RH nxx	0.00	0.00	0.00	0.00
27	1	REAR FENDER INNER TRIM BOARD LH nxx	0.00	730.00	-20.00	584.00
28	1	REAR FENDER INNER TRIM BOARD RH nxx	0.00	730.00	-20.00	584.00
29	1	REAR SPARE TYRE PANEL ? nxx	0.00	1,100.50	-20.00	880.40
30	1	REAR SPARE TYRE BOARD ? nxx	0.00	350.00	-20.00	280.00

Total Parts (\$\$) 8,100.88

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS rec /	0.00	45.00	0.00	45.00 30
2	1	REAR BUMPER SENSORS (SET) nxx	0.00	220.00	0.00	220.00
3	1	REAR NUMBER PLATE DEF /	0.00	45.00	0.00	45.00
4	1	REAR TAILGATE INNER BOARD CLIPS rec /	0.00	40.00	0.00	40.00 20
5	1	REAR WINDSCREEN SEALANT rec /	0.00	60.00	0.00	60.00
6	2	REAR EXHAUST MOUNTING nxx	0.00	60.00	0.00	60.00

Sub Total (\$\$) 470.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00 20
2	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	100.00	0.00	100.00 ✓
3	1	To Transfer Rear Tailgate.	80.00	80.00	0.00	80.00 50
4	1	To Disconnect and Reconnect, Check Electrical	30.00	30.00	0.00	30.00 ✓

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
		wiring Harness Wire, Sockets, Replace Damaged Parts.				
5	1	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	180.00	180.00	0.00	180.00 X
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	1,800.00	1,800.00	0.00	1,800.00 600
Gross Labour Cost (\$\$)						2,270.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	40.00	40.00	0.00	40.00 ? X
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	45.00	0.00	45.00 ? X
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	40.00	40.00	0.00	40.00 30
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	1,100.00	1,100.00	0.00	1,100.00 500
Gross Labour Cost (\$\$)						1,225.00

< END OF ESTIMATES >

12,065.88

[Signature]
17/5/19

Huee Jie-LKK
15/5/19
L/s 5 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total - \$3100/-

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19008500/JVD3N2

Date: 19/06/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01018700
Claimant Vehicle No :	SJG949H	Insured Vehicle No :	SJY871C
Date of Loss:	09/05/2019	Nature of Claim:	TP
		Claim No:	CMTD1902255

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG949H	Engine No:	L15A5159865
Make & Model:	HONDA AIRWAVE, 1.5 M (A)	Chassis No:	GJ11208333
Reg. Date:	20/06/2008 (Man. Year: 2008)	Odometer:	125949 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,570.88	2,571.08	5,999.80	70.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,495.00	1,330.00	2,165.00	61.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,065.88	3,901.08	8,164.80	67.67
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	12,065.88	3,100.00	8,965.88	74.31
+ GST 7.00/7.00% (S\$)	844.61	217.00	627.61	74.31
Nett Amount (S\$)	12,910.49	3,317.00	9,593.49	74.31

INSPECTION

Date of Assignment:	14/05/2019	
Date Inspected:	15/05/2019 Inspected At:	Yew Tee Automobile Tech Pte Ltd (HQ) Blk 6 Woodlands Road 399F., Yew Tee Ind Estate Singapore 678006

Estimated Period of Repair: 5.0 days

Adjuster: ONG HWEE JIE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 19 Jun 2019)
Parts: M1-MPV	HONDA AIRWAVE 1.5 M (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJG949H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	1,078.50 FL	*1,078.50 FL
2	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	25.00 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	25.00 FL	*- FL
4	2		*REAR NUMBER PLATE LAMP	Not Necessary	77.20 FL	*- FL
5	1		*REAR TAILGATE	Buckled	1,382.50 FL	*1,382.50 FL
6	1		*REAR TAILGATE LOWER PROTECTOR	Deformed	451.50 FL	*451.50 FL
7	1		*REAR TAILGATE LOCK	Serviceable	138.50 FL	*- FL
8	1		*REAR TAILGATE LOCK CATCH	Not Necessary	24.20 FL	*- FL
9	1		*REAR TAILGATE RUBBER	Not Necessary	191.50 FL	*- FL
10	1		*REAR TAILGATE INNER BOARD	Not Necessary	401.20 FL	*- FL
11	1		*REAR TAILGATE AIRWAVE EMBLEM	Necessary	27.40 FL	*27.40 FL
12	1		*REAR TAILGATE REFLECTOR LH	Not Necessary	245.20 FL	*- FL
13	1		*REAR TAILGATE REFLECTOR RH	Not Necessary	245.20 FL	*- FL
14	1		*REAR TAILGATE OUTER CHROME GARNISH	Not Necessary	288.00 FL	*- FL
15	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	80.20 FL	*80.20 FL
16	1		*REAR TAILLAMP LH	Not Necessary	258.00 FL	*- FL
17	1		*REAR TAILLAMP RH	Not Necessary	258.20 FL	*- FL
18	1		*REAR TAILLAMP PANEL LH	Not Necessary	130.00 FL	*- FL
19	1		*REAR TAILLAMP PANEL RH	Not Necessary	130.00 FL	*- FL
20	1		*REAR EXHAUST PIPE	Not Necessary	280.90 FL	*- FL
21	1		*REAR EXHAUST SILENCER	Not Necessary	750.00 FL	*- FL
22	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	80.10 FL	*- FL
23	1		*REAR END PANEL	Not Necessary	508.70 FL	*- FL
24	1		*REAR END PANEL INNER GARNISH	Not Necessary	138.60 FL	*- FL
25	1		*REAR FENDER LH (NPA)	Not Necessary	0.00 FL	*- FL
26	1		*REAR FENDER RH (NPA)	Not Necessary	0.00 FL	*- FL
27	1		*REAR FENDER INNER TRIM BOARD LH	Not Necessary	730.00 FL	*- FL
28	1		*REAR FENDER INNER TRIM BOARD RH	Not Necessary	730.00 FL	*- FL
29	1		*REAR SPARE TYRE PANEL	Not Necessary	1,100.50 FL	*- FL
30	1		*REAR SPARE TYRE BOARD	Not Necessary	350.00 FL	*- FL
31	1		*REAR BUMPER CLIPS	Necessary	45.00 FS	*30.00 FS
32	1		*SET REAR BUMPER SENSORS	Not Necessary	220.00 FS	*- FS
33	1		*REAR NUMBER PLATE	Deformed	45.00 FS	*45.00 FS
34	1		*REAR TAILGATE INNER BOARD CLIPS	Necessary	40.00 FS	*20.00 FS
35	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
36	2		*REAR EXHAUST MOUNTING	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,596.10	3,175.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,025.22	604.02
Total Parts (\$\$)	8,570.88	2,571.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	80.00	20.00
2	TO DISMANTLE AND REFIT REAR WINDSCREEN GLASS	New	100.00	100.00
3	TO TRANSFER REAR TAILGATE	New	80.00	50.00
4	TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS,REPLACE DAMAGED PARTS	New	30.00	30.00
5	TO REMOVE AND REFIT,STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REAR EXHAUST SILENCER AND MOUNTINGS	New	180.00	0.00
6	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,800.00	600.00
7	TO CARRY-OUT BODY CAVITY PRESERVATION	New	40.00	0.00
8	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	New	45.00	0.00
9	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	40.00	30.00
10	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	1,100.00	500.00
Gross Labour Cost (S\$)			3,495.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >