

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 16 May 2019

Preliminary Advice

Insured Vehicle No : SMH7031T

TP Vehicle No : SJT7373D

Make : LEXUS RX200T

Date of Inspection : 14/05/2019

Inspection At : Vifi Pte Ltd (Bukit Batok)
1 Bukit Batok Crescent #06-06, WCEGA Plaza
Singapore 658064

Accident Date : 01/05/2019

Assignment Date : 13/05/2019

Est. Duration of Repair : 2 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,298.20
Revised Amount	:S\$	4,950.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,950.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. Some of the parts items pending parts prices.