

SUPREME AUTO SERVICE PTE LTD

176 SIN MING AUTOCARE DRIVE #02-01 SINGAPORE 575721

TEL : 6452 8211 FAX 6451 7420

CO REG NO : 199404214H

ESTIMATE

CHIA JUN PING
c/o 46 Lentor Plain
Singapore 786548

KK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To survey damaged part(s)
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Date: 15/05/2019

Acknowledged by Repairer
Signature: _____
Date: _____

Quantity	Particulars	Amount (\$)
	RE : SLQ2574R / BMW 216D 1.5	
1 pc	Rear Boot Lid / Buc	
1 pc	Rear Boot Lock X NN	
1 pc	Rear Boot Lamp / CAT.	
1 pc	Rear Bumper / Be.	
1 pc	Rear Bumper Reinforcement ?	
1 pc	Rear Bumper Towing Cover - CAT	
1 pc	Rear Bumper Support Bracket ?	
1 pc	Rear Bumper Side Bracket X NN	
1 pc	Rear Bumper Reflector X	
1 pc	Rear Bumper Chrome Moulding / CMA	
1 pc	Rear Bumper Beam ?	
1 Set	Windscreen Glass Sealant / d.c.	
4 pcs	Reverse Sensor 2pc ?	
	Sub-total	\$ -
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	\$ 700.00 400
	To check wiring system	\$ 30.00 /
	To apply rust proofing on affected areas.	\$ 50.00 X NN
	To apply putty & spray painting on affected areas.	\$ 800.00 500
	To install reverse sensors	\$ 50.00 40
	To remove rear windscreen glass(es) to enable repair.	\$ 120.00 100
	To transfer rear boot lid accessories.	\$ 100.00 60.
	4 Days. 16/5/19.	
	Lumpsum Repair.	
	After repair photos.	
	Emo Qiang @ lkk auto. com	
	Sub-total	\$ 1,850.00
	Grand Total	

Emo Qiang - 82880282